

PDI TUAS

PDI TUAS

AYDEN ELIJAH KOH BOON TIH
55 COMPASSVALE BOW
#19-10
Singapore, 544986
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV039611
Quote No. SER/QUO/1800829
QuoteDate 21/05/18
Salesperson Nicholas Chua
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	SPORTSVAN 1.4 TSI CL	0	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SJX136Y	WVWZZZAUZJW527622	22/12/17	Nicholas Chua
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 879234	AM13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	6	UNIT		1680 5,040.00
P B&P MACP LABOUR	TRANSFER BOOT LID MECHANIS	1	UNIT		X 840.00
P B&P MACP LABOUR	R&R REAR W/SCREEN	1	UNIT		X 840.00
P B&P MACP PAINT	SPRAY PAINT	5	UNIT		1600 4,000.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		X 80.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		400.00✓
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00✓
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00✓
	Nett				
	Sum Labor				11,960.00
P 510945105	REFLECTOR LH	1	Pieces		? 55.94
P 510945106	REFLECTOR RH	1	Pieces		? 55.94
P 3CN945087	3RD BRAKE LIGHT	1	Pieces		X 204.89
P 510805945 041	REAR W/SCREEN SIDE TRIM LH	1	Pieces		X 96.46
P 510805946 041	REAR W/SCREEN SIDE TRIM RH	1	Pieces		X 92.83
P 510807393A	TAILLIGHT LOWER BRACKET LH	1	Pieces		? 75.84
P 510807393C	BUMPER SIDE BRACKET LH	1	Pieces		? 74.52
P 510807394A	TAILLIGHT LOWER BRACKET RH	1	Pieces		? 75.84
P 510807394C	BUMPER SIDE BRACKET RH	1	Pieces		? 74.52
P 510807417M GRU	REAR BUMPER	1	Pieces		? 1,388.00
	Predecessor 510807417J GRU				
P 510827025AA	REAR BOOT LID	1	Pieces		Repair 1,960.85
	Predecessor 510827025T				
P 510827469 FOD	MECHANISM	1	Pieces		X 736.02
	Sum carried forward				16,851.65

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

AYDEN ELIJAH KOH BOON TIH
55 COMPASSVALE BOW
#19-10
Singapore, 544986
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV039611
Quote No. SER/QUO/1800829
QuoteDate 21/05/18
Salesperson Nicholas Chua
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	SPORTSVAN 1.4 TSI CL	0	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SJX136Y	WVWZZZAUZJW527622	22/12/17	Nicholas Chua
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 879234	AM13HZ

Continued			16,851.65
P 510853675S 2ZZ	NAME PLATE -230 TSI	1 Pieces	62.55
P 5G6807568D 9B9	REAR SPOILER	1 Pieces	322.86
	Use Predecessor 5G6807568D		
P 5G9807305A	REINFORCEMENT	1 Pieces	460.18
P 8D0853419D	RR NUMBER PLATE PACKING	1 Pieces	14.61
P D 002000A2	CLEANER	1 Pieces	147.86
P D 004660M2	2K GLUE	1 Pieces	183.87
P D 00920002	PRIMER	1 Pieces	32.19
P D 00950025	APPLICATOR	2 Pieces	22.38
P D 181802M1	ACTIVATOR	1 Pieces	29.46
P WHT005263	CLIP	6 Pieces	10.20
P WHT007341	NUT	4 Pieces	10.04

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Explanations

P = Proportionately Charged

Payment Terms

No Credit

Payments to:

- BBN: - Acc.-No.:

Predecessor N 90766703
Sum Item

6,187.85

Sum Labor 11,960.00
Sum Item 6,187.85

Total SGD 18,147.85
7% GST 1,270.35
Total SGD Incl. GST 19,418.20

Rasmu
Hp 90010068
4 days
23/05/18 @ 1030