

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0592/2018/GW
Date : 22-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: SJP 9289 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Han Seng
Address : 18 Hooper Road
Singapore 229195
Telephone : HP +65 97456501
Type of Claim : Third Party Claims
Policy No. : 21000478967-01
Vehicle No : **SJR 8118 D**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Aug-16
Engine No : CVN 010792
Chassis No : WAUZZZF46GA095788
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-May-18
Place of Accident : Along Bukit Timah Towards Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJR 8118 D

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights ,horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1250.
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100.
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u><u>4,152.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJR 8118 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>del-d</i>	\$ 1,849.00	✓
2	FRONT BUMPER AIR GUIDE	\$ 73.00	✗
3	FRONT BUMPER AIR GUIDE GRILLE <i>fine</i>	\$ 118.00	✓
4	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	✗
5	FOAM FILLER PIECE <i>fine</i>	\$ 107.00	✗
6	FRONT BUMPER CARRIER	\$ 702.00	✗
7	FRONT FENDER-RH <i>Deited</i>	\$ 665.00	✓
8	FENDER ATTACHMENT PARTS <i>an</i>	\$ 45.00	✓
9	FRONT FENDER CLOSING ELEMENT-RH <i>an</i>	\$ 44.00	✗
10	FRONT FENDER BRACKET-RH ?	\$ 31.00	?
11	FRONT FENDER BRACE-RH ?	\$ 103.00	?
12	WHEEL HOUSING LINER-RH <i>an</i>	\$ 209.00	✗
13	WHEEL SHOUSING LINER ATTACHMENT PARTS ?	\$ 78.00	?
14	FRONT WHEEL SPOILER-RH <i>an</i>	\$ 63.00	✗
15	FRONT STONE CHIP GUARD <i>an</i>	\$ 44.00	✓
16	LED HEADLIGHT-RH <i>cut</i>	\$ 6,973.00	✓
17	HEADLIGHT LIFT CYLINDER-RH ?	\$ 184.00	?
18	SUNDRIES ?	\$ 200.00	?
TOTAL SPARE PARTS		: \$ 11,520.00	
TOTAL LABOUR CHARGES		: \$ 4,152.00	
GRAND TOTAL		: <u>\$ 15,672.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 24/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant