

CASE OWNER:

Hotelle Lee

CC 4/III1800 9242, R1pa3 9/

LKK:

IDAC:

Surveyor:

Rahul

DOI:

23/5/18

Date / Time:

17/05/18

Registered in Merimen:

21/5/18

Pre-assign / CCU / FTE

CHA 3834R



Insured Vehicle No.:

C1P2

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A 01/05/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Kwele Josephine

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MCT 1805 0008

Policy No.:

M com 007

Make / Model:

H Sonata

Place of Accident:

Amle (h) 1001 Spinal

OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLJ 8271L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Yew Tee add?



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/15

CAM

1/6/2018

25/7/2018

30/7/2018

SLJ 8271L - X

CHA 3834R - C12 / Pm 11222671 / M1P25: 104

Seek liability mandate from 132 (Approved)

lod. received

pass file to type mandate report.

\* WI issue - work. \$80 x 9 days. please check J handler for further issue.

RECEIVED 13 AUG 2018

upload his point photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

27/5/2018

Sent By:

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: (w/p)

SS 4,066.96

(5 days)

Reduction:

SS

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3/8/2018

Confirm with:

Shawn Toh

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

M1

If NO or B 28, Ass. Lin:

Repair Cost: (w/pst)

SS 4,351.64

Loss of Rental (LOR):

SS 500.00

(7 days)

x480.00

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 29.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 4,940.64

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4,940.64

Name 1:

Yew Tee Automobile Tech pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350.00

un 14/8/18

Ram

REF.

III

9/2/21

pa3

36310

SECTION 1

Form Date 23.05.2018

Estimated Cost

(D / TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No. SLJ 82712  
at Workshop n/s Yew Tee Automobile  
of Blk 6 Woodlands Rd 399F

Insured

Policy No.

Claims No.

Sum Insured Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bot. or Market Value

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs 5 days Res. Yes or No

Lum Sum 1.5% 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted

Vehicle IN / OUT

Date / Time Action / Instruction

SWIFT

SLJ 8271L Yr Reg 2016 M6C

Type ☒ Car / ☐ M-Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make Hyundai ELANTRA 1.6 << 1591

Colour BLUE A/C Insured / Std / NI / NA

Sp Reading 155984 T/Radio Insured / Std / NI / NA

Eng/No.

KMH0841CMHU199690

C/No

Gen. Cond. Good ☒ Fair ☐ Poor ☐ Burnt

Steering ☒ Normal ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake ☒ Normal ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod. Nil ☒ / ☐ R/Rim / ☐ STD A/Rim or

Tyre Size F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal 6 mm R/Bal 6 mm

L/Bal 6 mm L/Bal 6 mm

D.O.A. 01/05/18 D.O.I. 23/05/18

Survey held at YEW TEE AUTOMOBILE

Des. of Damages: Frt / Rear ☒ / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Plp: \$4,066.96 (Red: \$4,995.72 / 55%)

Copy/Take For Pass-By

☐

Prel. Report

or

☐

Final Report

Copy/Take For Return-By

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: ☐ Site Insp. (\$

☐ Trip (max) (\$

☐ Tech. Serv. (\$

☐ Assembly (\$

Report Format

Temp. Sum At B.U.S



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18009242/R1pa3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-05-2018		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 3834R	Veh. Inspected	SLJ 8271L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	01/05/2018	Inspection Date	23/05/2018	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

ON BEHALF OF OWNER :

## Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SLJ8271L	Excess.	\$ -
Policy No.	5086810910-01	Coverage.	Comprehensive
Claiming Against.	SHA3834R INDIA		
Insured Under.	NTUC		

## Vehicle Particulars & Condition

Make & Model	Hyundai Elantra
Engine No.	G4FGGU193707
Chassis No.	KMHD841CMHU199690
Odometer	
Engine CC.	1591
Year Of Reg.	2016
Colour.	BLUE
Parf/COE Rebate.	\$ 54,381.00

## Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

## Description Of Damages

R/H side damaged.

## General Information

Accident Date. 1/5/2018  
Survey held at

Yew Tee Automobile Tech Pte Ltd  
Blk 6 Woodlands Road 399F Yew Tee Ind Est S(678006)

## Remarks

A) THE SURVEY WAS CONDUCTED ON A "PART BY PART" BASIS  
KINDLY LET US HAVE THE APPROVAL SOON.

## Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

ON BEHALF OF OWNER :

## Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SLJ8271L	Excess.	\$ -
Policy No.	5086810910-01	Coverage.	Comprehensive
Claiming Against.	SHA3834R INDIA		
Insured Under.	NTUC		

## Vehicle Particulars & Condition

Make & Model	Hyundai Elantra
Engine No.	G4FGGU193707
Chassis No.	KMHD841CMHU199690
Odometer	
Engine CC.	1591
Year Of Reg.	2016
Colour.	BLUE
Parf/COE Rebate.	\$ 54,381.00

## Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

## Description Of Damages

R/H side damaged.

## General Information

Accident Date. 1/5/2018  
Survey held at

Yew Tee Automobile Tech Pte Ltd  
Blk 6 Woodlands Road 399F Yew Tee Ind Est S(678006)

## Remarks

A) THE SURVEY WAS CONDUCTED ON A "PART BY PART" BASIS  
KINDLY LET US HAVE THE APPROVAL SOON.

## Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

km 40 841cm - 2016

Qty.	Description Of Parts	Pricing
1	Front windscreen pillar RH	\$ 3,919.20 <i>Repair</i>
1	Front windscreen moulding	\$ 77.30 <i>X</i>
1	Front fender RH	Rpr <i>X</i> <i>lv</i>
1	Front fender quarter garnish RH	\$ 19.00 <i>X</i>
1	Front door RH	\$ 1,831.10 <i>BS</i>
1	Front door side mirror RH	750 \$ 1,054.60 <i>CM</i>
1	Front door glass outer moulding RH	\$ 52.30 <i>lv</i>
1	Front door outer chrome handle RH	\$ 197.10 <i>X</i> <i>CM</i>
1	Rear door RH	Rpr <i>lv</i>
1	Rear door glass outer moulding RH	\$ 85.10 <i>X</i> <i>lv</i>
1	Rear door outer chrome handle RH	\$ 197.10 <i>X</i> <i>lv</i>
1	Rear fender RH	Rpr <i>lv</i>
1	Rear taillamp RH	3346.20 519.70 \$ 876.80 <i>sv</i>
1	Rear bumper	Rpr <i>X</i> <i>lv</i>
		List \$ 8,309.60 <i>X</i>
		20% Less 20% \$ 1,661.92
		2676.96 Total \$ 6,647.68
1	Front windscreen sealant	\$ 60.00 <i>X</i> <i>lv</i>
1	ERP bracket	\$ 15.00 <i>X</i> <i>lv</i>
1	Front door black tape	\$ 80.00 <i>lv</i>
1	Rear door black tape	\$ 80.00 <i>X</i> <i>lv</i>
	S/N	\$ 235.00

60

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing.
<b>LABOUR</b>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 40.00
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ <del>40.00</del> 30
	To dismantle and refit front windscreen glass.	\$ 120.00 X
	To transfer door	\$ <del>80.00</del> 60
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ <del>700.00</del> 450
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	750 <del>600</del>
		\$ <del>1,200.00</del> 600

LABOUR \$ 2,180.00

Sub Total \$ 9,062.68

7% GST \$ 634.39

Grand Total \$ 9,697.07

2676.96  
60.00  
1336.00  
4066.96

5 days  
P/P  
      

Rasul  
Hp 90010068  
5 days  
P/P  
23/05/16 P1235  
Reg by paint

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Front windscreen pillar RH	\$ 3,919.20 <i>repair</i>
1	Front windscreen moulding	\$ 77.30 <i>X</i>
1	Front fender RH	Rpr <i>X</i>
1	Front fender quarter garnish RH	\$ 19.00 <i>X</i>
1	Front door RH	\$ 1,831.10 <i>Bst</i>
1	Front door side mirror RH	\$ 1,054.60 <i>CM</i>
1	Front door glass outer moulding RH	\$ 52.30 <i>me</i>
1	Front door outer chrome handle RH	\$ 197.10 <i>X CM</i>
1	Rear door RH	Rpr
1	Rear door glass outer moulding RH	\$ 85.10 <i>X</i>
1	Rear door outer chrome handle RH	\$ 197.10 <i>X</i>
1	Rear fender RH	Rpr
1	Rear taillamp RH	\$ 876.80 <i>sur</i>
1	Rear bumper	Rpr <i>X</i>
		List \$ 8,309.60 <i>X</i>
		Less 20% \$ 1,661.92
		Total \$ 6,647.68
1	Front windscreen sealant	\$ 60.00 <i>X</i>
1	ERP bracket	\$ 15.00 <i>X</i>
1	Front door black tape	\$ <del>80.00</del> 60.00 <i>me</i>
1	Rear door black tape	\$ 80.00 <i>X</i>
S/N		\$ 235.00

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
<b>LABOUR</b>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 40.00 ✓
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ <del>40.00</del> 30
	To dismantle and refit front windscreen glass.	\$ 120.00 X
	To transfer door	\$ <del>80.00</del> 60
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ <del>700.00</del> 450
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	750 <del>600</del>
		\$ <del>1,200.00</del> 600
	LABOUR	\$ 2,180.00
	Sub Total.	\$ 9,062.68
	7% GST	\$ 634.39
	Grand Total	\$ 9,697.07

Rasul  
Hp 90010068  
5 days  
7/P  
23/05/18 P1235  
Reg by paint

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Monday, 6 August 2018 11:46 AM  
**To:** 'YT(HQ)'  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: India ref: MCT18050008/01/NL -- Accident involving SJ8271L (NTUC) claiming against SHA3834R (India)  
**Attachments:** DV SJ 8271L.pdf  
**Importance:** High

### Without Prejudice

Our Ref: CC4/III18009242/R1pa3  
Your Ref: SJ 8271L

Dear Shaun,

### **ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SHA 3834R AND SJ 8271L ON 01/05/2018**

We refer to the above matter.

We thank you for your acceptance.

Please duly sign the **DV** enclosed and return with **Rental Agreement** for payment processing.

We need original copy DV.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Poh Kin (LKKAuto)

---

**From:** YT(HQ) <utauto@singnet.com.sg>  
**Sent:** Friday, 3 August 2018 1:25 PM  
**To:** Poh Kin (LKKAuto)  
**Cc:** Hsiao Tong (LKKAuto); info@yewteegroup.com  
**Subject:** RE: India ref: MCT18050008/01/NL -- Accident involving SU8271L (NTUC) claiming against SHA3834R (India)

**Categories:** clear

Hi

OK accept

Best Regards

*Shawn Teh LM*

9743 2262 / 8100 7999  
www.yewteegroup.com  
info@yewteegroup.com  
Like Us On Facebook

Managing Director of  
-YEW TEE AUTOMOBILE TECH PTE LTD  
-YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD  
-ULTIMAX LEASING PTE LTD  
-SKT TYRE & BATTERY SERVICES PTE LTD



WEST HQ:  
Blk 6 Woodlands Road 399F  
Yew Tee Ind. Est  
Singapore 678006  
DID: 6765 3373 / 6762 2081  
Fax: 6760 4895  
Email: utauto@singnet.com.sg

EAST Branch Office:  
Synergy@KB, 25 Kaki Bukit Road 4  
Unit No #01-60/61  
Singapore 417800  
DID: 6702 3113 (3 Lines)  
Fax: 6702 3773  
Email: utauto2@singnet.com.sg

NORTH Branch:  
Mega@Woodlands  
39 Woodlands Close #01-12  
Singapore 737856  
DID: 6256 2081 (3 Lines)  
Fax: 6256 2533  
Email: info@yewteegroup.com

*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Friday, 3 August 2018 1:22 PM  
**To:** 'utauto@singnet.com.sg'  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: India ref: MCT18050008/01/NL -- Accident involving SLJ8271L (NTUC) claiming against SHA3834R (India)

### Without Prejudice

Our Ref: CC4/III18009242/R1pa3  
Your Ref: SLJ 3834R

Dear Vinnie,

### **ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SHA 3834R AND SLJ 8271L ON 01/05/2018**

We refer to the above matter and your letter of demand dated 12<sup>th</sup> July 2018.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

1. Cost of Repair (\$4,066.95 +7% GST)	S\$ 4,351.64
2. GIA search fee	S\$ 29.00
3. Loss of Rentals (\$80.00 x 7days)	<u>S\$ 560.00</u>
	<u><b>S\$ 4,940.64</b></u>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Rasul (LKKAuto)

---

**From:** YT(HQ) <utauto@singnet.com.sg>  
**Sent:** Tuesday, 17 July, 2018 10:16 AM  
**To:** Rasul (LKKAuto)  
**Cc:** utauto@singnet.com.sg  
**Subject:** RE: SLJ8271L Finalize

Hi Rasul,

We are confirmed.

Thank you

Best Regards

*Vinnie Lim*



### Yew Tee Automobile Tech Pte Ltd

HQ:  
Blk 6 Woodlands Road 399F  
Yew Tee Ind. Est  
Singapore 678006  
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895  
Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch Office:  
Synergy@KB, 25 Kaki Bukit Road  
Unit No #01-60/61  
Singapore 417800  
DID: 6702 3113  
Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

Branch Office:  
39 Woodlands Close,  
#01-12 Mega@Woodlands  
Singapore 737856  
DID: 62562081  
Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

**From:** Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]  
**Sent:** Monday, 16 July, 2018 9:37 AM  
**To:** YT(HQ)  
**Subject:** RE: SLJ8271L Finalize

Hi Vinnie,

Refer to attachment

There is a slight adjustment on the parts price.

Finalise amount is \$ 4,066.96 / 5 days P/P

Kindly confirm

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** YT(HQ) [mailto:utauto@singnet.com.sg]  
**Sent:** Friday, 13 July, 2018 11:44 AM  
**To:** Rasul (LKKAuto)  
**Cc:** [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)  
**Subject:** SLJ8271L Finalize

**LAST REMINDER**

Hi Rasul,

Refer to the email below,

May I know when shall I expect a reply from you?

It has been 1 months and got no reply.

Thank you

Best Regards

*Vinnie Lim*



**Yew Tee Automobile Tech Pte Ltd**

HQ:

Blk 6 Woodlands Road 399F

## Print Received Message

This mail is associated with :

**\*SLJ8271L (MCT18050008)**

**[SHA3834R]**

TP

NEU V&E TECHNOLOGY

May 1 2018 5:00PM

[COMFORT TRANSPORTATION PTE LTD]

Yew Tee Automobile Tech Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 02/08/2018 14:30 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4940.65) - SLJ8271L - Claim Handler: NATALIE LEE

Approved:4940.65.

## Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	21 May 2018 20:31	Clim Veh Model Changed	(205169) HYUNDAI ELANTRA 1.6 AD GLS (A).		[A] HOW MEI KWAN
2	21 May 2018 20:31	Clim Created	Reg No: SLJ8271L, Acct Date: 2018/05/01, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		[A] HOW MEI KWAN
3	21 May 2018 20:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] HOW MEI KWAN
4	21 May 2018 20:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31		[A] HOW MEI KWAN
5	21 May 2018 20:31	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.		[A] HOW MEI KWAN
6	21 May 2018 20:32	Label Added	(30653):Direct Settlement.		[A] HOW MEI KWAN
7	21 May 2018 20:32	Adj Adjuster Assigned	[None] -> MARCUS CHUA		[A] HOW MEI KWAN
8	24 May 2018 20:03	Adj Adjuster Assigned	MARCUS CHUA -> MOHD RASUL		[A] HOW MEI KWAN
9	24 May 2018 20:04	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.		[A] HOW MEI KWAN
10	24 May 2018 20:04	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD, Claimant's ID: -> 199303 821R.		[A] HOW MEI KWAN
11	24 May 2018 20:06	Adj Rpt Initiated			[A] HOW MEI KWAN
12	24 May 2018 20:06	Clim Dtl Modified	JPJ Reg. Date: -> 2016/12/28.		[A] HOW MEI KWAN
13	24 May 2018 20:06	Clim Details Notified			[A] HOW MEI KWAN
14	01 Jun 2018 18:01	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% Remarks: Bola 26, passenger open the vehicle door into the path of other traffic		[A] Chong Poh Kin
15	04 Jun 2018 09:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31		[I] NATALIE LEE
16	04 Jun 2018 09:34	Adj Mandate Set	Approved:0.00.		[I] NATALIE LEE
17	01 Aug 2018 16:54	Adj Mandate Request	Cur.Reg:4940.65:PODS Liability: 100% Quantum: a)COR(w/gst): \$4,351.65 + b)LOR: \$560.00(\$80 x 7days) + c)GIA: \$29.00=\$4,940.65 Vehicle Model: Hyundai Elantra 1.6 (1591cc) For your approval		[A] Chong Poh Kin

Date From



Date To



Audit Type None

Go

### ACTIVITY

[08/07/2018 12:41] HOW MEI KWAN:  
PENDING FOR FINALIZE

17.07.18

India International Insurance Pte Ltd  
64 Cecil Street  
#04-00/#05-00 IOB Building  
Singapore 049711

**Attn: Motor Claims Department**

Dear Sirs,

**ACCIDENT INVOLVING VEHICLE: SLJ8271L and SHA3834R on 01.05.2018**

We are the authorized repair workshop for the owner of motor vehicle no: SLJ8271L which was involved in the captioned accident with your insured vehicle: SHA3834R . The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Part by part Repair	\$	4,066.95
02)	TP search fee	\$	27.10
		\$	4,094.05
	GST 7%	\$	286.58
	Sub Total	\$	4,380.63
	Rental fees 9 days @ \$80/day	\$	720.00
	Grand Total	<b>\$</b>	<b>5,100.63</b>

We enclosed herewith the following documents to support the claims:-

- a) GIA report
- b) Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you  
Yours faithfully

Shaun  
97432262

## LETTER OF AUTHORITY

To whom it may concern,

ACCIDENT INVOLVING : SLJ8271L and SHA3834R on 01/05/2018

I/We NEU V&E TECHNOLOGY Reg No. 53143631D

Owner of motor vehicle no : SLJ8271L do hereby appoint M/S YEW TEE AUTOMOBILE TECH PTE LTD as my/our authorized representative to write, negotiate and settle my/our claims against the other party involved in the abovementioned accident. M/S YEW TEE AUTOMOBILE TECH PTE LTD shall have absolute discretion to settle the matter at the best terms.

I/WE also confirm and instruct that any agreed settlement sum in respect of my/our claims be paid to M/S YEW TEE AUTOMOBILE TECH PTE LTD and such payment will constitute a full and final discharge of my/our claims.

I/WE further authorize M/S YEW TEE AUTOMOBILE TECH PTE LTD to execute the discharge voucher on my/our behalf.

Signature of Owner,

A handwritten signature in black ink is written over a circular stamp. The stamp contains the text "NEU V&E TECHNOLOGY" around the perimeter and "1997" at the bottom. There is a small 'x' mark to the left of the signature.

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: TP / MCT18050008  
 Claimant Ref: SLJ 8271L

We/I, Yew Tee Automobile Tech Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4,351.64 (repair cost), S\$ 560.00 (loss of ~~rental~~), S\$ 29.00 (search fee), vehicle no. SLJ 8271L that was damaged pursuant to the accident which occurred on 01/05/2018 (date) at Ang Mo Kio Hub Taxi Stand (location) involving vehicle no. SHA 3834R (insured vehicle). This is pursuant to the inspection conducted on 23/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NEU V&E Technology ("the third party claimant") of vehicle no. SLJ 8271L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLJ 8271L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,940.64 to Yew Tee Automobile Tech Pte Ltd

Dated this 6 day of August 20 18

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

**LKK AUTO CONSULTANTS PTE.**

51 Ubi Ave 1, #01-23  
 Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256 3561

**YEW TEE AUTOMOBILE TECH PTE LTD**

HQ: BLK 6 WOODLANDS ROAD 399-F YEW TEE IND EST S(678006)

BR: SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

BR: MEGA@WOODLANDS, 39 WOODLANDS CLOSE #01-12 S(737856)

GST Reg No. 200311009C

Singapore

67653373 67023113

INFO@YEWTEEGROUP.COM

WWW.YEWTEEGROUP.COM

Company Registration No. 200311009C

**ADDRESS**

INDIA INTERNATIONAL

INSURANCE PTE LTD

INDIA INTERNATIONAL

INSURANCE PTE LTD

**TP TAX INVOICE MC1807002****DATE 17/07/2018****VEHICLE NO.**

SLJ8271L

ACTIVITY	QTY	RATE	TAX	AMOUNT
PART BY PART REPAIR	1	4,066.95	7% SR	4,066.95
TP SEARCH FEE	1	27.10	7% SR	27.10
RENTAL FEE	9	80.00	Out of Scope	720.00

Cheque should be crossed & made payable to "YEW TEE AUTOMOBILE TECH PTE LTD" and strictly send to our HQ address.

SUBTOTAL

4,814.05

GST TOTAL

286.59

**TOTAL****SGD 5,100.64**

Accepted By

Accepted Date

ISSUED BY STAFF

E. &amp; O.E.

**ULTIMAX LEASING PTE LTD**

SYNERGY@KB, 25 KAKI  
BUKIT ROAD 4 #0-61  
S(417800)  
Singapore 417800  
ultimax8199@gmail.com

Tp Invoice 1001



**ADDRESS**

CHAI SWEE HENG

DATE  
27/06/2018

**TOTAL DUE**

**VEHICLE NO**

SJF5829T

**ACTIVITY**

**Sales**  
RENTAL FROM 22/05/2018 TO  
31/05/2018

QTY	RATE	AMOUNT
9	80.00	720.00

TOTAL 720.00

TOTAL DUE

THANK YOU

Accepted By

Accepted Date



## Car Rental Agreement

### 1. THE PARTIES TO THIS AGREEMENT ARE:

#### 1.1 THE OWNER:

**Company and Registration Number:**

ULTIMAX LEASING PTE LTD

ROC: 201612956R

**Physical Address:**

SYNERGY@KB 25 KAKI BUKIT ROAD 4, #01-61, SINGAPORE 417800

#### 1.2 THE RENTER:

Name as in NRIC:	Chai Swee Heng		
NRIC/FIN No.:	S1664176F	Contact No.:	98167183
Email:	vetech@smgnet.com.sg		

D.O.B:	17/11/1964	Age:	53+	Gender:	(M) / F
--------	------------	------	-----	---------	---------

Local Address:	41 #03-04, Bangkit Road
S(679978)	

### 2. THE OBJECT OF THE RENTAL IS:

Vehicle Number:	SJF5829T	Color:	GREY
Make and Model:	HONDA AIRWAVE	Capacity:	1.5

### 3. CONDITION OF VEHICLE:

3.1 The Owner states that to the best of his knowledge and belief that above-described vehicle is in sound and safe condition and free of any known defects or faults which would affect its safe operation under normal use.

3.2 Vehicle will be only use for:

☒ Uber / GrabCar ☐ Personal / Cooperate ☐ Wedding / Commercial / Events

☐

Others: \_\_\_\_\_

☐ Relief Driver

For: \_\_\_\_\_

\*\*(Relief Driver don't have to fill in Section 9, unless otherwise stated.)

### 4. QUALIFICATIONS:

4.1 The Renter states that he / she is physically and legally qualified to operate the above-described vehicle.

### 5. RENTAL PERIOD:

The Owner agrees to rent the above-described vehicle to the Renter for the following period:


5.1 Starting Date: 22/5/2018 Time: 11:05 (a.m. / p.m.)

5.2 Ending Date: 31/5/2018 Time: 1645 (a.m. / p.m.)

RENTER:

*[Signature]*

OWNER:



## 6. RENTAL RATE:

6.1 The Renter hereby agrees to pay the owner at the rate of S\$\_\_\_\_\_ per day / week or portion thereof, AND / OR at the rate of S\$\_\_\_\_\_ per hour for the use of the above-described vehicle when due to return.

6.2 All fuel used shall be paid for by the Renter.

## 7. EXCLUSIONS:

7.1 The rented vehicle shall not be used for any race or in any competition.

7.2 The rented vehicle shall not be used for any illegal purpose.

7.3 The Renter shall not operate the vehicle in a negligent manner.

7.4 The rented vehicle shall not be operated by any other person other than the Renter stipulated in 1.2 above without the written permission of the Owner.

## 8. INSURANCE:

8.1 The Renter hereby agrees that he / she shall be held fully responsible for any and all loss of or damage to the vehicle or equipment during the term of this Car Rental Agreement whether caused by collision, fire, flood, vandalism, theft or any other cause, except that which shall be determined to be caused by a fault or defect of the vehicle or equipment.

8.1.1 The Owner shall insure The Vehicle against:

- > all 3<sup>rd</sup> Party Risks and Liabilities;
- > Loss or theft to The Vehicle; and
- > Damage to The Vehicle, subject to the appended Non-Waiverable Insurance Excess:

OWN DAMAGE INSURANCE EXCESS & FEES PER ACCIDENT	
COUNTRY	AMOUNT
Singapore	As per insurance policy
3 <sup>rd</sup> PARTIES INSURANCE EXCESS & FEES PER ACCIDENT	
COUNTRY	AMOUNT
Singapore	As per insurance policy

## 9. DEPOSIT:

9.1 The Renter further agrees to make a deposit total sum of S\$\_\_\_\_\_ with the Owner, said deposit to be used, in the event of loss of or damage to the vehicle or equipment during the term of this Car Rental Agreement, to defray fully or partially the cost of necessary repairs or replacement.

9.2 Deposit paid: S\$\_\_\_\_\_ on \_\_\_\_ / \_\_\_\_ / \_\_\_\_

9.3 Deposit due to be paid: S\$\_\_\_\_\_ by \_\_\_\_ / \_\_\_\_ / \_\_\_\_

9.4 In the absence of damage or loss, said deposit shall be credited toward payment of the Rental Rate and any excess shall be returned to the Renter.

## 10. RETURN OF VEHICLE:

10.1 The Renter hereby agrees to return the above-described vehicle to the Owner at the physical address listed in 1.1. no later than \_\_\_\_ / \_\_\_\_ / \_\_\_\_ before \_\_\_\_ am/pm.

Signed on 22/5/2018

RENTER:

OWNER:





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**SEARCH RESULTS**

Our Ref No: GR-18-071295

Date of Request: 10/05/2018

Your Ref No:

Online Purchase

Yew Tee Automobile Tech Pte Ltd  
Blk 6 Woodlands Road 399F,  
Yew Tee Ind Estate  
Singapore 678006

Dear Sir/Madam,

**Your Search Criteria:**

Date of Accident: 01/05/2018

Place of Accident: ANG MO KIO HUB TAXI STAND

Client Vehicle No: SLJ8271L

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHA3834R	AMK HUB TAXI STAND	01/05/2018 17:20

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-071412

Date of Request: 11/05/2018

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd  
Blk 6 Woodlands Road 399F,  
Yew Tee Ind Estate  
Singapore 678006

Dear Sir/Madam,

Date of Accident: 01/05/2018

Vehicle No: SLJ8271L

Place of Accident: ANG MO KIO HUB TAXI STAND

Involving Vehicle No: SHA3834R

With reference to your application for the accident report, we have attached the following accident reports as requested

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA3834R	ANG MO KIO HUB TAXI STAND	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-071295  
Date of Request: 10/05/2018

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd  
Blk 6 Woodlands Road 399F,  
Yew Tee Ind Estate  
Singapore 678006

Dear Sir/Madam,

**Your Search Criteria:**

Date of Accident: 01/05/2018  
Place of Accident: ANG MO KIO HUB TAXI STAND  
Client Vehicle No: SLJ8271L

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement






































## CLAIM SUBFOLDER TRACKING



























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018 <a href="#">Edit Reg</a>		17 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,066.96</b> <a href="#">Edit Estimates</a>	<b>S\$4,066.96</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>NEU V&amp;E TECHNOLOGY</b> , Co. Reg. No.: 53143631D								
Vehicle Reg. No.:	<b>SLJ8271L</b>	Date of Loss:	01/05/2018 17:00 - :59 <b>[16 Months and 3 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / MCT18050008</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHA3834R</b>	Policy No. (Claimant):	5086810910-01(CLASSIC)						
		Excess:							
Repairer:	<b>Yew Tee Automobile Tech Pte Ltd (HQ)</b> Bk 6 Woodlands Road 399F,, Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>NATALIE LEE</b> - 63476100 ext 243]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 31/05/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>III_SG (02/08/2018): Alert - Adj Mandate Approved (S\$4940.65) - SLJ8271L - Claim Handler: NATALIE LEE</li> <li>III_SG (04/06/2018): Alert - Adj Mandate Approved (S\$0.00) - SLJ8271L - Claim Handler: NATALIE LEE</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLJ8271L (MCT18050008)  
[SHA3834R]  
TP  
NEU V&E TECHNOLOGY  
May 1 2018 5:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Yew Tee Automobile Tech Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail			Print		
1	01/08/18 16:38	Odometer Reading				Load JPG		<input checked="" type="checkbox"/>		
2	01/08/18 16:38	Chassis Number				Load JPG		<input checked="" type="checkbox"/>		
3	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
4	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
5	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
6	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
7	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
8	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
9	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
10	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
11	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
12	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
13	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
14	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
15	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
16	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
17	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
18	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
19	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
20	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
21	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
22	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
23	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
24	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
25	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
26	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
27	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
28	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
29	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
30	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
31	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
32	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
33	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
34	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
35	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
36	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		
37	01/08/18 16:38	General View				Load JPG		<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/08/18 16:38	General View	 Load JPG	<input checked="" type="checkbox"/>
39	01/08/18 16:38	General View	 Load JPG	<input checked="" type="checkbox"/>
40	01/08/18 16:38	General View	 Load JPG	<input checked="" type="checkbox"/>
41	01/08/18 16:38	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	01/08/18 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 20:32	ACKNOWLEDGEMENT EMAIL TO III DD 17.05.2018	 Load PDF	
2	21/05/18 20:32	TP ESTIMATE	 Load PDF	
3	21/05/18 20:32	TP GIA REPORT	 Load PDF	
4	27/05/18 14:22	TP ESTIMATE - MARKED	 Load PDF	
5	31/07/18 11:09	LOD	 Load PDF	
6	31/07/18 11:09	GIA SEARCH	 Load PDF	
7	14/08/18 15:10	WORKSHOP INVOICE	 Load PDF	
8	14/08/18 15:10	AUTHORISATION TO ACT FORM	 Load PDF	
9	14/08/18 15:10	DISCHARGE VOUCHER	 Load PDF	
10	14/08/18 15:10	RENTAL RECEIPT	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 08:39	Singapore Accident Statement	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009242/R1PA3Q2

Date: 14/08/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SLJ8271L Insured Vehicle No: SHA3834R  
 Date of Loss: 01/05/2018 Nature of Claim: TP Claim No: MCT18050008

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ8271L**  
 Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGGU193707  
 Reg. Date: 28/12/2016 (Man. Year: 2016) Chassis No: KMHD841CMHU199690  
 Colour: Blue Odometer: 155984 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,882.68	2,736.96	4,145.72	60.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,330.00	850.00	38.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,062.68</b>	<b>4,066.96</b>	<b>4,995.72</b>	<b>55.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>634.39</b>	<b>284.69</b>	<b>349.70</b>	<b>55.12</b>
<b>Nett Amount (S\$)</b>	<b>9,697.07</b>	<b>4,351.65</b>	<b>5,345.42</b>	<b>55.12</b>
<b>+ Car Rental (7.0 x S\$80.00/day) (S\$)</b>		560.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>4,940.65</b>		

### INSPECTION

Date of Assignment: 17/05/2018  
 Date Inspected: 23/05/2018 Inspected At: YEW TEE AUTOMOBILE TECH PL (HQ)  
 BLK 6 WOODLANDS ROAD 399F YEW  
 TEE IND. ESTATE  
 SINGAPORE 678006  
 Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLJ8271L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN PILLAR RH	Repair	3,919.20 FL	*- FL
2	1		*FRONT WINDSCREEN MOULDING	Not Necessary	77.30 FL	*- FL
3	1		*FRONT FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*FRONT FENDER QUARTER GARNISH RH	Not Necessary	19.00 FL	*- FL
5	1		*FRONT DOOR RH	Bent	1,831.10 FL	*1,831.10 FL
6	1		*FRONT DOOR SIDE MIRROR RH	Cracked	1,054.60 FL	*750.00 FL
7	1		*FRONT DOOR GLASS OUTER MOULDING RH	Necessary	52.30 FL	*52.30 FL
8	1		*FRONT DOOR OUTER CHROME HANDLE RH	Cracked	197.10 FL	*197.10 FL
9	1		*REAR DORO RH (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*REAR DOOR GLASS OUTER MOULDING RH	Not Necessary	85.10 FL	*- FL
11	1		*REAR DOOR OUTER CHROME HANDLE RH	Not Necessary	197.10 FL	*- FL
12	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR TAILLAMP RH	Scratched	876.80 FL	*515.70 FL
14	1		*REAR BUMPER (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*FRONT WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
16	1		*ERP BRACKET	Not Necessary	15.00 FS	*- FS
17	1		*FRONT DOOR BLACK TAPW	Necessary	80.00 FS	*60.00 FS
18	1		*REAR DOOR BLACK TAPE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,544.60</b>	<b>3,406.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,661.92</b>	<b>669.24</b>
<b>Total Parts (\$\$)</b>	<b>6,882.68</b>	<b>2,736.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	40.00	40.00
2	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS ,REPLACE DAMAGED PARTS	New	40.00	30.00
3	TO DISMANTLE AND REFIT FRONT WINDSCREEN GLASS	New	120.00	0.00
4	TO TRANSFER DOOR	New	80.00	60.00
5	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	700.00	450.00
6	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS ,CLEANING & SANDING OF SURFACES ,FINAL POLISING & WAXING ARE ALSO AVAILABLE	New	1,200.00	750.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,180.00</b>	<b>1,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >