

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SLJ8271L	Excess.	\$ -
Policy No.	5086810910-01	Coverage.	Comprehensive
Claiming Against.	SHA3834R INDIA		
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	Hyundai Elantra
Engine No.	G4FGGU193707
Chassis No.	KMHD841CMHU199690
Odometer	
Engine CC.	1591
Year Of Reg.	2016
Colour.	BLUE
Parf/COE Rebate.	\$ 54,381.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

R/H side damaged.

General Information

Accident Date. 1/5/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd
Blk 6 Woodlands Road 399F Yew Tee Ind Est S(678006)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "PART BY PART" BASIS
KINDLY LET US HAVE THE APPROVAL SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Front windscreen pillar RH	\$ 3,919.20
1	Front windscreen moulding	\$ 77.30
1	Front fender RH	Rpr
1	Front fender quarter garnish RH	\$ 19.00
1	Front door RH	\$ 1,831.10
1	Front door side mirror RH	\$ 1,054.60
1	Front door glass outer moulding RH	\$ 52.30
1	Front door outer chrome handle RH	\$ 197.10
1	Rear door RH	Rpr
1	Rear door glass outer moulding RH	\$ 85.10
1	Rear door outer chrome handle RH	\$ 197.10
1	Rear fender RH	Rpr
1	Rear taillamp RH	\$ 876.80
1	Rear bumper	Rpr
		List \$ 8,309.60
		Less 20% \$ 1,661.92
		Total \$ 6,647.68
1	Front windscreen sealant	\$ 60.00
1	ERP bracket	\$ 15.00
1	Front door black tape	\$ 80.00
1	Rear door black tape	\$ 80.00
		S/N \$ 235.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 40.00
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 40.00
	To dismantle and refit front windscreen glass.	\$ 120.00
	To transfer door	\$ 80.00
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 700.00
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,200.00
	LABOUR	\$ 2,180.00
	Sub Total.	\$ 9,062.68
	7% GST	\$ 634.39
	Grand Total	<u>\$ 9,697.07</u>

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.