

Surveyor:

MTH

DOI:

ASSIGNMENT

23/5/18

Date / Time:

21/5/18

Registered in Merimen:

21/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

ET 76280

Name of Insured:

ONG HAH LAY

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

15/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

EVA NG CHOW M

Driver Tel No.:

9008 3337

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBO 2473K



INSRS:

WSP:

Tel:

Liability:

RMKS:

million Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/11

2/11

GBO 2473K-X ; ET 76280-X

OED rear ended to TP.

20/11/18

DV seat

2/12/18

File -&gt; MK to close

\* WI figure different to settlement amount

RECEIVED 23 DEC 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7 TRIM By Email.  
616

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2782.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

320.00

(\$80 x 4

days)

Loss of Income (LOI):

S\$

(\$ x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

Legal Cost:

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320 + \$20.

Total:

S\$

3109.45

Global Sum S\$:

31W.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

31W.00

Name 1:

Million Auto Service

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$


Name 3:

Tanjong

ALH

INSURANCE

Policy No: 23052018  
 Estimated Cost:  
 (1) WS / TF RES / OD RES / EVA / INV / MV  
 For report vehicle No: 6BD 2473K  
 at Workshop: Million Auto  
 No. 4 Perjuru Place #01-12  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: Excess:  
 (Client's Record)  
 Make of veh:  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bat. or Market Value:  
 IDAC Accident Report Consistent? Yes or No  
 Gik. / PR Seen Consistent? Yes or No  
 Est. Repairs: 4 days Res. Yes or No  
 Lump Sum: 20- % 3 Val Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: Person Contacted:  
 Vehicle IN / OUT:



Reg No: 2473K  
 Type: M/Car / M/Truck / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or:  
 Make: Hyundai H1 Starax  
 Colour: Black  
 S/N Reading: 103672  
 Engine No: KMFWBX7RM E U664287  
 C/No:  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: M / SiRim / STD A/Rim or  
 Tyre Size: F: 215/70 R16  
 R: 215/70 R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Roadstone  
 Front: R/Bal: 6 mm L/Bal: 6 mm  
 Rear: R/Bal: 6 mm L/Bal: 6 mm  
 D.O.A.: 23/5/8 @ 10:30  
 Survey held at: Million Auto  
 Des. of Damages: Fnt / Rr / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision:

W # 260 Check # 245.4 / 539.

Date/Time: Preli. Report  
 Date/Time: Final Report

Days Of Repair:  
 Resurvey No. of Trip:

Survey Fee:  
 Insurance:

Add Fee: ☐ Site Insp: \$  
☐ Inter-view: \$  
☐ Temp. Insp: \$  
☐ Detail Insp: \$

Report Format:  
 Lump Sum / L.B. / ...

A large empty rectangular box for additional notes or signatures.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18009247/T1ua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-05-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	ET 7628D	Veh. Inspected	GBD 2473K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	15/05/2018	Inspection Date	23/05/2018	
Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# 萬汽車服務

## MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782

Website: <http://www.millionauto.com> Email: [wendy@millionauto.com](mailto:wendy@millionauto.com)

Tel: 6567 0817, 6264 9091 Fax: 6791 4716

Reg No: 317413/00-K GST Reg No: M90363176A

31-Jul-18

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way

#07-16 (S) 079120

WITHOUT PREJUDICE

Attention: Motor Claim Department

### ESTIMATE COST FOR REPAIR GBD2473K HYUNDAI H100 2.5 (A)

Rear lid	1996 2,495.00 bl ✓
Rear bumper	418.30 der ✓
Rear wheaterstrip	187.50 wt ✓
Rear bumper reinforcement	347.00 K/V ✓
Rear sensor	188.00 gw ✓ SN
Windscreen sealant	50.00 N/L ✓ SN
To dismantle & assembly rear windscreen	180.00 120
To dismantle & replace rear bumper, lid, rubber & sensor, To dismantle wiper motor, inner lock To knock & weld inner panel	890.00 400 }
To spray paint & putty rear lid, bumper & inner panel	800.00 400

Sub total : 5,555.80  
GST 7% : 388.91  
Total : 5,944.71

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2601.80  
20% - 2081.44

SN - 238

Leban - 920  
3239.44

45.9 2600 #

4 days.

## Hsiao Tong (LKKAuto)

---

**From:** Ms Chong <mschong@millionauto.com>  
**Sent:** Monday, 26 November 2018 1:39 PM  
**To:** Thin Thin (LKKAuto)  
**Subject:** RE: GBD2473K LOD

Dear Thin Thin,  
We confirmed acceptance your offer, please issue DV.  
Thanks !

Best Regards,  
Ms Chong  
Million Auto Service  
No.4 Penjuru Place #01-12,  
Singapore 608782  
62649091/82285020

---

**From:** Thin Thin (LKKAuto) [mailto:thinthin@lkkauto.com]  
**Sent:** Monday, November 26, 2018 1:16 PM  
**To:** Ms Chong <mschong@millionauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Subject:** RE: GBD2473K LOD

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the below matter.

On a without prejudice, for a quick and amicable settlement, we have our Principal instruction to propose the settlement at Global Sum S\$ 3,100.00 (all-in).

Kindly confirm the acceptance.

Thanks.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,  
**Thin Thin Hlaing** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

---

**From:** Thin Thin (LKKAuto)  
**Sent:** Friday, 23 November 2018 3:21 PM  
**To:** 'Ms Chong' <[mschong@millionauto.com](mailto:mschong@millionauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Subject:** RE: GBD2473K LOD

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the below matter.

On a without prejudice, for a quick and amicable settlement, we have our Principal instruction to propose the settlement at Global Sum S\$ 2,920.00 (all-in).

Kindly confirm the acceptance.

Thanks.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ms Chong <[mschong@millionauto.com](mailto:mschong@millionauto.com)>  
**Sent:** Friday, 14 September 2018 2:42 PM  
**To:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; Shu Pei (LKKAuto) <[shupe@lkkauto.com](mailto:shupe@lkkauto.com)>  
**Subject:** RE: GBD2473K LOD

Dear Thin Thin,  
Please refer to the attachments for GBD2473K LOD.  
We look forward on your favorable reply.  
Thanks !

Best Regards,

Ms Chong

Million Auto Service

No.4 Penjuru Place #01-12,

Singapore 608782

---

**From:** Thin Thin (LKKAuto) [mailto:thinthin@lkkauto.com]  
**Sent:** Wednesday, September 12, 2018 9:49 AM  
**To:** Ms Chong <mschong@millionauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Subject:** RE: GBD2473K estimate

Without Prejudice

Dear Ms Chong,

Enclosed herewith mark estimate for your perusal.

Thanks.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAuto)  
**Sent:** Wednesday, 1 August 2018 10:45 AM  
**To:** Ms Chong <mschong@millionauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** FW: GBD2473K estimate

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/AIG18009247/T1ua3	Taufikh / Thin Thin

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

**From:** Ms Chong <[mschong@millionauto.com](mailto:mschong@millionauto.com)>  
**Sent:** Tuesday, 31 July 2018 6:00 PM  
**To:** Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** ref: GBD2473K estimate

Dear Taufikh,  
Please refer to the attachment for GBD2473K estimate.  
Thanks !

Best Regards,  
Ms Chong  
Million Auto Service  
No.4 Penjuru Place #01-12,  
Singapore 608782  
62649091/82285020



## Hsiao Tong (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Wednesday, 6 June 2018 4:54 PM  
**To:** evangchaini@gmail.com  
**Subject:** ACCIDENT INVOLVING ET 7628D & GBD 2473K ON 15/05/2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18009247/T1ub3

06 JUNE 2018

**ONG MAH LAY**  
781 UPPER CHANGI ROAD EAST  
#09-27 SUNHAVEN  
SINGAPORE 486069

Dear Sir/Madam,

### **ACCIDENT INVOLVING ET 7628D & GBD 2473K ON 15/05/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## **AUTHORISATION LETTER**

I, **Eulay Chemical & Diesel (S) Pte Ltd** (the third party claimant") of **No.11 Tuas Link 3 (S) 638527** (address), owner of **GBD2473K** (vehicle no.). Hereby authorize **MILLION AUTO SERVICE** ("the workshop") to act for me with respect to my claim for repair cost and/or rental and/or loss of use ("claim") for my vehicle no. **GBD2473K** that was damaged pursuant to the accident which occurred on **15/05/2018** (date) along **PIE Twd Tuas Dir. Before Slip Rd To Bendenmeer (S)** (location) involving vehicle no/s **ET7628D** ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner the they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle/s is concerned.

Date this **23** (day) of **May** (month) **2018** (year)

Eulay Chemical & Diesel (S) Pte Ltd  
No.11 Tuas Link 3 Singapore 638527  
Tel: 68632123 (3 Lines) Fax: 68631160

-----  
Signed by "the third party claimant"

-----  
Signed by "the workshop"



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **MILLION AUTO SERVICE** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,100.00** (Global Sum) for vehicle no. **GBD 2473K** that was damaged pursuant to the accident which occurred on **15/05/2018** (date) along **PIE TWD TUAS BEFORE SLIP ROAD TO BENDEMEER** involving vehicle no/s **ET 7628D**.

This is pursuant to the inspection conducted on **23/05/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **EULAY CHEMICAL & DIESEL (S) PTE LTD** ("the third party claimant") of vehicle no. **GBD 2473K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GBD 2473K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 (day) of Dec (month) 2018 (year)



*MTH*

Signed by appointed surveyor

Signed by "the workshop" (with chop)

# 萬汽車服務

## MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782  
Website: <http://www.millionauto.com> Email: [wendy@millionauto.com](mailto:wendy@millionauto.com)  
Tel: 6567 0817, 6264 9091 Fax: 6791 4716  
Reg No: 317413/00-K GST Reg No: M90363176A

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

Attention : Motor Claim Department  
Contact : 64193000 Fax No.: 68357416

Final Repair bill : 79156

Date : 14/09/2018  
Vehicle Num : GBD2473K  
Make/Model : HYUNDAI H100 2.5 (A)  
Chassis/Eng# :  
Accident Date : 15/05/2018  
Claim No.: 2513300166SG003  
Reference : ET7628D  
Policy No.: DMCV17S010715

S/N	Quantity	Particular	Amount S\$
		Lump sum repair cost	2,600.00
		GST 7%:	182.00
			2,782.00
		Loss of use - 4 days x \$100	400.00
		LTA search	7.49
		Amount Due S\$:	3,189.49

SingDollars: Three Thousand One Hundred Eighty-Nine And Cents Forty-Nine Only

  
For Million Auto Service

&gt; Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 May 2018 / 13:42:24

Receipt Date/Time : 16 May 2018 / 13:42:24

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180516-001264

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - ET7628D

As at 15 May 2018/19:50:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - ET7628D

Enquiry Fee

20180516134012216646

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Enquiry

ABD 2472K

Paid By

xxxxxxxxxxxx8716	Credit Card:	7.45
	Visa/MasterCard	

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018 <a href="#">Edit Reg</a>		21 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>ONG MAH LAY</b> , ID: S1667510E									
Main Claimant: <b>EULAY CHEMICAL &amp; DIESEL (S) PTE LTD.</b> Co. Reg. No.: 200200231D									
Vehicle Reg. No.:	<b>GBD2473K</b>	Date of Loss:	15/05/2018 19:00 - :59 [45 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 2513300166SG</b>	Policy/Cover Note No.:	1800001657 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>ET7628D</b>	Policy No. (Claimant):	DMCV17S010715						
		Excess:							
Repairer: <b>Million Auto Service ( )</b> No. 4 Penjuru Place #01-12, 608782 Jurong East - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: <b>ERGO Insurance Pte. Ltd. (HQ)</b> - Tel: 6829 9199									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 31/05/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBD2473K (2513300166SG)  
[ET7628D]  
TP  
EULAY CHEMICAL & DIESEL (S) PTE LTD  
May 15 2018 7:00PM  
[ONG MAH LAY]  
Million Auto Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/18 07:52	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
2	30/11/18 07:52	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	30/11/18 07:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	01/12/18 10:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
26	01/12/18 10:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
27	01/12/18 10:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/05/18 21:04	ACKNOWLEDGEMENT EMAIL TO AIG DD 21.05.2018	1	Load PDF	
2	21/05/18 21:04	NOTIFICATION FROM WORKSHOP	1	Load PDF	
3	21/05/18 21:04	NOTIFICATION FROM WORKSHOP +TP GIA REPORT	1	Load TIF	
4	21/05/18 21:04	TP GIA REPORT	1	Load PDF	
5	05/12/18 13:58	WORKSHOP INVOICE	1	Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	05/12/18 13:58	AUTHORISATION TO ACT FORM	1	Load PDF	
7	05/12/18 13:58	Release Voucher	1	Load PDF	
8	05/12/18 13:58	LTA SEARCH	1	Load PDF	
9	05/12/18 13:58	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	22/05/18 09:36	OI GIA REPORT	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	ET7628D (Insd veh)	Model:	HYUNDAI H-1 STAREX 2.5 D
	GBD2473K (TP veh)		CRDI (A)
Date of Accident:	15/05/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ]	Yes	<input type="checkbox"/> [ ]	No
Repair Estimate	:	\$			5,944.71
Final Repair Cost	:	\$			3,100.00
Loss of Use	:	\$			4.00 days at \$80.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$			3,100.00

**Is Third Party Workshop GIA Registered?**    ☐ [ ]    **YES**    ☒ [ X ]    **NO**    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Million Auto Service	:	\$ 3,100.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Dec  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18009247/T1PA3Q2

Date: 05/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800001657

Claimant Vehicle No: GBD2473K

Insured Vehicle No: ET7628D

Date of Loss: 15/05/2018

Nature of Claim: TP

Claim No: 2513300166SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBD2473K

Make &amp; Model: HYUNDAI H-1 STAREX, 2.5 D CRDi (A)

Engine No: D4CBE558776

Reg. Date: 13/08/2014 (Man. Year: 2014)

Chassis No: KMFWBX7KMEU669287

Colour: Black

Odometer: 103672 km

Engine Capacity: 2497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/70 R16

Rear Tyre Size: 215/70 R16

Front Left Side: Roadstone 6 mm

Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm

Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,685.80	2,319.44	1,366.36	37.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	920.00	950.00	50.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,555.80</b>	<b>3,239.44</b>	<b>2,316.36</b>	<b>41.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
(S\$)	5,555.80	2,600.00	2,955.80	53.20
<b>+ GST 7.00/7.00% (S\$)</b>	<b>388.91</b>	<b>182.00</b>	<b>206.91</b>	<b>53.20</b>
<b>Nett Amount (S\$)</b>	<b>5,944.71</b>	<b>2,782.00</b>	<b>3,162.71</b>	<b>53.20</b>
<b>+ Loss of Use (4.0 x S\$80.00/day) (S\$)</b>		<b>320.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>3,109.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,100.00</b>		

## INSPECTION

Date of Assignment: 21/05/2018

Date Inspected: 23/05/2018 Inspected At: Million Auto Service  
No. 4 Penjuru Place #01-12  
Singapore 608782

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Bent	2,495.00 F	*1,996.00 FL
2	1		*REAR BUMPER	Deformed	418.30 F	*418.30 FL
3	1		*REAR WEATHERSTRIP	Cut	187.50 F	*187.50 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	347.00 F	*- FL
5	1		*REAR SENSOR	Not Working	188.00 FS	*188.00 FS
6	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,685.80</b>	<b>2,839.80</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>520.36</b>
<b>Total Parts (\$\$)</b>	<b>3,685.80</b>	<b>2,319.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & ASSEMBLY REAR WINDSCREEN	New	180.00	120.00
2	TO DISMANTLE & REPLACE REAR BUMPER ,LID ,RUBBER & SENSOR,TO DISMANTLE WIPER MOTOR ,INNER LOCK TO KNOCK &WELD INNER PANEL	New	890.00	400.00
3	TO SPRAY PAINT & PUTTY REAR LID ,BUMPER & INNER PANEL	New	800.00	400.00
Gross Labour Cost (S\$)			1,870.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >