



GST / ROC Company No : 201101753C

u
ASm

Third Party Insurer : AXA

Insured's Veh No : SKD2107L

Date of accident : 19/05/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

*Not Allowed all
klm pte. Behar goby
6/5/18
21/5/18*

Quotation No : AR/QO18/05-1020

Quotation Date : 21/05/2018

6416.85

Estimate To Repair TOYOTA PRIUS
Vehicle No : SLS853M
Chassis No : JTDKB3FU003569783

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	FRT BUMPER <i>n</i>	\$595.60
2	1PC	FRT BUMPER CENTRE LOGO <i>n</i>	\$92.10
3	1PC	FRT BUMPER INNER SPONGE <i>n</i>	\$80.60
4	1PC	NUMBER PLATE GARNISH <i>n</i>	\$129.80
5	1PC	REAR GATE <i>DS/2uc</i>	\$1,029.60
6	1PC	REAR GATE OUTER GARNISH <i>DS/2e</i>	\$951.20
7	1PC	REAR GATE OUTER GARNISH "PRIUS" PLATE <i>neu</i>	\$62.30
8	1PC	REAR GATE OUTER GARNISH "HYBRID" PLATE <i>neu</i>	\$68.90
9	1PC	REAR GATE OUTER GARNISH CENTRE LOGO <i>neu</i>	\$56.30
10	1PC	REAR BUMPER (TOP) <i>D.S</i>	\$483.90
11	1PC	REAR BUMPER (LOWER) <i>D.S</i>	\$592.30
12	2PC	REAR BUMPER RETAINER <i>n/s beef</i> 132.70	\$265.40
13	10PC	REAR BUMPER CLIPS <i>neu</i>	\$50.00
14	2PC	REAR CORNER BUMPER <i>n/s Tru</i> 2/5 R 2.5	\$500.00
15	1PC	REAR BUMPER REINFORCEMENT <i>D.S</i>	\$368.80
16	2PC	REAR TAIL LAMP (LOWER) <i>n</i>	\$1,053.60
17	1PC	REAR LH TAIL LAMP (TOP) <i>n</i>	\$927.40
18	1PC	REAR END PANEL <i>S.D.S.D.S</i>	\$669.80
19	1PC	REAR END PANEL TOP GARNISH <i>Tru</i>	\$220.00
20	6PC	TOP GARNISH CLIPS <i>neu</i>	\$30.00
21	1PC	REAR EXHAUST BOX <i>n</i>	\$1,273.90
22	1PC	REAR EXHAUST BOX HEAT SHIELD <i>n</i>	\$220.50
<i>25% Rear floor panel und covr Tru</i> 245 LESS 20% <i>Air duct</i> one — 60 <i>Rear gate lock actuator sensor one</i> 325			\$9,722.00 \$1,944.40 \$7,777.60
MISC ITEMS			
23	1PC	REAR WINDSCREEN GUM <i>neu</i>	\$60.00
24	1PC	REAR GATE GLASS GUM <i>neu</i>	\$60.00
25	1PC	REAR NUMBER PLATE <i>n</i>	\$40.00
26	1PC	REVERSE SENSOR <i>shard</i>	\$250.00
27	1PC	FRT NUMBER PLATE <i>beuf</i>	\$40.00
Total			\$330.00

Please conduct the survey at
Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
GARY 8338 8418



GST / ROC Company No : 201101753C

Third Party Insurer : AXA
 Insured's Veh No : SKD2107L
 Date of accident : 19/05/2018

Grab Rentals Pte Ltd
 18 Sin Ming Lane
 #01-08 Midview City
 Singapore 573960

Quotation No : AR/QO18/05-1020
 Quotation Date : 21/05/2018

Estimate To Repair TOYOTA PRIUS
 Vehicle No : SLS853M
 Chassis No : JTDKB3FU003569783

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		REMOVE & REFIX REAR GATE GLASS	\$80.00
4		R & R REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	\$150.00
5		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$120.00
6		REMOVE & REFIX EXHAUST BOX	17 \$150.00
7		LABOUR CHARGE	\$850.00
8		SPRAY PAINTING	\$900.00
Total			\$2,400.00
L- 5595.80 25 % 4196.85 SN 320 Le 900 <hr/> 6416.85			1900
Sub Total			\$6,482.00
GST (7.00%)			\$453.74
Total			\$6,935.74

✓
 ✓
 ✓
 60
 60
 750
 800

Pass to Marcus on 31/05/2018.
 Marcus -

Please conduct the survey at
 Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
 GARY 8338 8418



GST / ROC Company No : 201101753C

Third Party Insurer : AXA

Insured's Veh No : SKD2107L

Date of accident : 19/05/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/05-1020

Quotation Date : 31/05/2018

SUPPLEMENTARY

TOYOTA PRIUS

Vehicle No :

SLS853M

Chassis No :

JTDKB3FU003569783

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
		<u>LIST</u>	
1		REAR FENDER PANEL UNDER COVER <i>to 1</i>	\$245.00 ✓
2		AIR DUCT <i>one</i>	\$60.00 ✓
3		REAR GATE LOCK ACTUATOR <i>sensor one</i>	\$325.00 ✓
			\$630.00
		LESS 20% <i>25%</i>	\$126.00
			\$504.00
		Sub Total	\$504.00
		GST (7.00%)	\$35.28
		Total	\$539.28

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418