



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLK2002G
Chassis No : MRHFC5650GT000728
Model : CIVIC 1.6 VTI YM2016
Owner's Name : YEO AI KIANG
Ins Policy No. : AN3163319 (CN)
Date of Accident : 19/4/2018

Document No. : SQT18001649 Page 1
Date : 21. Apr 2018
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600987
Date | Time : 21. Apr 2018 10:34:43 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: SD17V00798/VPC2/R00 OWNER: YEO AI KIANG ACC DATE: 19/04/2018 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
33550-TEA-T01	TAILLIGHT ASSYL.	1	273.10 <i>Ch</i>		273.10	19.12	292.22
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20 <i>rel</i>		2.20	0.15	2.35
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER	1	617.20 <i>de</i>		617.20	43.20	660.40
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50 <i>rel</i>		11.50	0.81	12.31
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50 <i>X</i>		11.50	0.81	12.31
91505-TM8-003	CLIPBUMPER	7	2.00 <i>rel</i>		14.00	0.98	14.98
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60 <i>?</i>		7.60	0.53	8.13
Sum Item					<u>937.10</u>	<u>65.60</u>	<u>1,002.70</u>
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		160.00	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00		160.00	11.20	171.20
BKBU02R	REMOVE & RENEW RR BUMPER & DAMAGE PARTS.	1	1800.00 <i>840</i>		1800.00	126.00	1926.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00 <i>450</i>		1200.00	84.00	1284.00
Sum Labor					<u>3420.00</u>	<u>239.40</u>	<u>3,659.40</u>

Survey By

Date & Time

Excess

Status

Total Amount 4,357.10 305.00 4,662.10

Total (Inclusive of GST) 4,662.10

Tanpin 97495749
4/6/18 @ 4pm
wp
Resing before paint
sur @ luhcusto.com
4 days.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLK2002G
Chassis No : MRHFC5650GT000728
Model : CIVIC 1.6 VTI YM2016
Owner's Name : YEO AI KIANG
Ins Policy No. : AN3163319 (CN)
Date of Accident : 19/4/2018

Document No. : SQT18001649 Page 2
Date : 21. Apr 2018
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600987
Date | Time : 21. Apr 2018 10:34:43 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Signature							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 4/6/2018 9:52:04 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)