

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : AXA INSURANCE S'PORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

**Registration No** : SLK2002G

**Chassis No** : MRHFC5650GT000728

**Model** : CIVIC 1.6 VTI YM2016

**Owner's Name** : YEO AI KIANG

**Ins Policy No.** : AN3163319 (CN)

**Date of Accident** : 19/4/2018

**Document No.** : SQT18001649 **Page** 1

**Date** : 21. Apr 2018

**Customer No.** : WZA006

**Svc Advisor** : ANIKKA LAI SWEE KAM

**Engine No** : R16B21600987

**Date | Time** : 21. Apr 2018 10:34:43 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

| Item            | Description                                                                                                                                                                      | Qty | Unit Price | Disc % | Amount         | 0% GST Amount | Amount incld GST |
|-----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|----------------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: YEO AI KIANG<br>OWNER INSURER: LIBERTY<br>ACC DATE: 19/4/2018<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: AXA<br>TP VEH: FBG1225B |     |            |        |                |               |                  |
| 33550-TEA-T01   | TAILLIGHT ASSYL.                                                                                                                                                                 | 1   | 273.10     | 35     | 177.51         | 12.43         | 189.94           |
| 71555-TBA-A00   | BRACKETL.RR.BUMPER SIDE                                                                                                                                                          | 1   | 2.20       | 35     | 1.43           | 0.10          | 1.53             |
| 71500-TEC-Q00ZZ | FACE ASSYRR.BUMPER                                                                                                                                                               | 1   | 617.20     | 35     | 401.18         | 28.08         | 429.26           |
| 71593-TEA-T01   | SPACERR.RR.BUMPER SIDE                                                                                                                                                           | 1   | 11.50      | 35     | 7.47           | 0.52          | 7.99             |
| 71598-TEA-T01   | SPACERL.RR.BUMPER SIDE                                                                                                                                                           | 1   | 11.50      | 35     | 7.47           | 0.52          | 7.99             |
| 91505-TM8-003   | CLIPBUMPER                                                                                                                                                                       | 7   | 2.00       | 35     | 9.10           | 0.64          | 9.74             |
| 71508-TEA-T00   | GARNISHL.RR.BUMPER SIDE                                                                                                                                                          | 1   | 7.60       | 35     | 4.94           | 0.35          | 5.29             |
| Sum Item        |                                                                                                                                                                                  |     |            |        | <b>609.10</b>  | <b>42.64</b>  | <b>651.74</b>    |
| BOSUN           | SUNDRIES                                                                                                                                                                         | 1   | 50.00      |        | 50.00          | 3.50          | 53.50            |
| BML02I          | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER                                                                                                                                    | 1   | 160.00     |        | 160.00         | 11.20         | 171.20           |
| BA02R           | REMOVE & RENEW REVERSE SENSORS-4 PCS (N)                                                                                                                                         | 1   | 160.00     |        | 160.00         | 11.20         | 171.20           |
| BKBU02R         | REMOVE & RENEW RR BUMPER & DAMAGE PARTS.                                                                                                                                         | 1   | 2000.00    |        | 2000.00        | 140.00        | 2140.00          |
| BP02R           | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)                                                                                                                               | 1   | 1500.00    |        | 1500.00        | 105.00        | 1605.00          |
| Sum Labor       |                                                                                                                                                                                  |     |            |        | <b>3870.00</b> | <b>270.90</b> | <b>4,140.90</b>  |

Survey By

Date &amp; Time

Excess

**Total Amount** 4,479.10 313.54 4,792.64**Total (Inclusive of GST)** **4,792.64**

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

|                         |                                                                                         |                     |                            |                           |                |
|-------------------------|-----------------------------------------------------------------------------------------|---------------------|----------------------------|---------------------------|----------------|
| <b>Customer</b>         | : AXA INSURANCE S'PORE PTE LTD<br>8 SHENTON WAY<br>#27-01 AXA TOWER<br>SINGAPORE 068811 | <b>Document No.</b> | : SQT18001649              | <b>Page</b>               | 2              |
| <b>Registration No</b>  | : SLK2002G                                                                              | <b>Date</b>         | : 21. Apr 2018             | <b>Customer No.</b>       | : WZA006       |
| <b>Chassis No</b>       | : MRHFC5650GT000728                                                                     | <b>Svc Advisor</b>  | : ANIKKA LAI SWEE KAM      | <b>Engine No</b>          | : R16B21600987 |
| <b>Model</b>            | : CIVIC 1.6 VTI YM2016                                                                  | <b>Date   Time</b>  | : 21. Apr 2018 10:34:43 AM | <b>Surveyor Name</b>      | :              |
| <b>Owner's Name</b>     | : YEO AI KIANG                                                                          | <b>Survey Date</b>  | :                          | <b>Authorisation Date</b> | :              |
| <b>Ins Policy No.</b>   | : AN3163319 (CN)                                                                        |                     |                            |                           |                |
| <b>Date of Accident</b> | : 19/4/2018                                                                             |                     |                            |                           |                |

| Item      | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------|-------------|-----|------------|--------|--------|---------------|------------------|
| Status    |             |     |            |        |        |               |                  |
| Signature |             |     |            |        |        |               |                  |

Printed on 21/4/2018 11:10:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)