



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 8094A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACEFR. BUMPER (SN) (CONSISTENT)	DENTED / DEFORMED	349.65	349.65
1	GRILLEFR.BUMPER LOWER (SN) (CONSISTENT)	NOT NECESSARY	53.62	-
1	COVERFR.TOWING HOOK T99 (SN) (CONSISTENT)	CUT	11.62	11.62
1	BEAMR.FR.BUMPER UPPER (SN) (CONSISTENT)	BENT	17.92	17.92
1	BEAML.FR.BUMPER UPPER (SN) (CONSISTENT)	BENT	17.92	17.92
1	SPACERR.FR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	7.80	7.80
1	SPACERL.FR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	7.80	7.80
11	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	16.50	16.50
1	BEAM COMPFR BUMPER (SN) (CONSISTENT)	* CHECK	187.20	-
1	HEADLIGHT ASSY,R (SN) (CONSISTENT)	HOLDER CRACKED	261.15	261.15
1	BASEFR.GRILLE (SN) (CONSISTENT)	CRACKED	142.50	142.50
1	MOLDINGFR.GRILLE (SN) (CONSISTENT)	CRACKED	98.10	98.10
1	BARR.FR.GRILLE MOLDING (SN) (CONSISTENT)	CRACKED	42.90	42.90
1	BARL.FR.GRILLE MOLDING (SN) (CONSISTENT)	* CHECK	42.90	-
1	EMBLEMFR (SN) (CONSISTENT)	NECESSARY	19.42	19.42
2	NUTPUSH 3MM (SN) (CONSISTENT)	NECESSARY	2.85	2.85
6	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	9.00	9.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	30.00	10.00
			1,318.85	1,015.13
LABOUR				
INSPECT FR LIGHTING MECHANISMS & FOCUS.			80.00	80.00
REMOVE & INSTALL RADIATOR WITH FITTINGS.			180.00	-
REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.			230.00	-
STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.			1,400.00	1,120.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.			1,700.00	1,125.00
			3,590.00	2,325.00
GRAND TOTAL			4,908.85	3,340.13



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$230.10 NETT)			3,340.13
--	--	--	-----------------

Report Ref No. CC4/ASM18009258/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.