

INS CASE OWNER: PC

CC 4 / ASM 1800 Y2600, Taxi

CAA: 45532
IDAC: 16/5/2018

ASSIGNMENT

Surveyor: Tan Jik

DOI: 11/12/17

Date/Time: 3/1/18

registered in Merimen: 16/5/2018

Pre-assign / CCU / FTE



Insured Vehicle No. : GT 8892B

Claim No. : 18M00F48

Name of Insured : MRS G. P. L.

Policy No. : GA334943/1

Insured Tel No. : HP

Make / Model : Nissan Van

Excess Sec II : SS D.O.A: 21/4/18

Place of Accident : Jongly Island Highway

Is driver the owner? (YES / NO) NO Nature of Accident :

If NO, Driver Name / Age: Ang Long Hong

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : 97732992 (VZ: YES / NO)

Insured Liability : % Final ? Yes / No

XD 578 C → GT 48KIU →

GT 8892B → SJJ 2801 X



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS: 01



INSRS:
WSP: Sing Ah Tee
Tel:
Liability: TP
RMKS:

Date/Time	STAGE	DATE / PIC
<u>2/1/18</u>	Non-Reporting Itr (1st):	
<u>2/1/18</u>	Non-Reporting Itr (2nd):	
<u>2/1/18</u>	Non-Reporting Itr (Final):	
<u>2/1/18</u>	Notification Itr (if non-pickup):	
<u>2/1/18</u>	Call OI:	<u>3/20/5/18/18</u> <u>ah 3/1/18</u>
<u>2/1/18</u>	After call Itr to OI:	
<u>2/1/18</u>	Documentation Check List: Handler	
<u>2/1/18</u>	Documentation Check List: Typist	
<u>2/1/18</u>	Notification Itr (if non-pickup)	
<u>2/1/18</u>	After call Itr to OI:	
<u>2/1/18</u>	Authorization To Act:	
<u>2/1/18</u>	Release Voucher:	
<u>2/1/18</u>	Final Repair Bill:	
<u>2/1/18</u>	Car Rental Invoice:	
<u>2/1/18</u>	Towing Invoice:	
<u>2/1/18</u>	LTA / GIA :	
<u>2/1/18</u>	Medical Bill:	
<u>2/1/18</u>	PIR:	
<u>2/1/18</u>	Mandate/Reject Instruction:	
<u>2/1/18</u>	LOD:	
<u>2/1/18</u>	Payment Breakdowns Form:	
<u>2/1/18</u>	Post-Repair Photos:	
<u>2/1/18</u>	Others:	

to request OI's employment letter.

Link to M. Koh at 4822 S&S. Confirmed Incident Statement, Police and M&S. Agreed to settle and waive ACD will be with Mail deal letter to OI via Email. EIU Reply - pending documents gets

5/1/2018 Email reply clear to TP workshop.

3/1/2018 Pass file to Hulle, TP not ready. IA and mandate updated - Approved

2/1 - off - GIC \$2460 (pending assistance)
12/17 - send OI GIC \$2460, OI send (pending OI)
- DV in, for pass me to close.

After repair photo

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: Tan Jik

Repair Cost: US \$S 1700.00 (4 days) Reduction: 4239.70 % 61

FINAL SETTLEMENT Date/Time: 9/1/2018 Confirm with: JANICE Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28

Repair Cost: (w/amt) \$S 1879.00

Loss of Rental (LOR): \$S 642.00 (6 days) x 6107 (w/amt)

Loss of Use (LOU): \$S - (\$ x days)

Loss of Income (LOI): \$S - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$S 2.00

Medical: \$S -

Disbursement: \$S - (e.g. Tow/Independent)

Legal Cost: \$S -

Total: \$S 2460.00 Global Sum \$S: 2460.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 2460.00 Name 1: Sing Ah Tee motor & panel service Pte Ltd

Payee 2: (Strike if N.A.) \$S _____ Name 2: _____

Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

COPY SENT
12/13/2018

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$2501

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003889

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01

AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE : 05/06/2018
ACCIDENT DATE : 21/04/2018
VEHICLE NO : SJJ2801X
CHASSIS/ENG.NO : JMYSTCY4A8U004753
VEHICLE MODEL : MIT.LANCER
CLAIM NO :
POLICY NO :
REMARK : 2801 AXA TP AGST
GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	815.00	20	652.00	de 652.00
2	6	PC	REAR BUMPER CLIPS	3.00	20	2.40	us 14.40
3	2	PC	REAR BUMPER SIDE RETAINER ^{2na} LH+RH	13.00	20	10.40	(1pc) 20.80
4	2	PC	REAR BUMPER BRACKET ^{2na} LH+RH	18.00	20	14.40	(1pc) 28.80
5	1	PC	REAR BUMPER REINFORCEMENT	210.00	20	168.00	nn X 168.00
6	1	PC	REAR BUMPER TOW COVER	21.00	20	16.80	us 16.80
7	1	PC	REAR BUMPER REFLECTOR(RH)	22.00	20	17.60	us 17.60
8	1	PC	REAR END PANEL	506.00	20	404.80	Rx 404.80
9	1	PC	REAR END PANEL TOP GARNISH	149.00	20	119.20	nn X 119.20
10	1	PC	REAR END PANEL CLIPS	4.00	20	3.20	nn 3.20
11	2	PC	REAR TAIL LAMP ⁿⁿ LH-RH	320.00	20	256.00	(1pc) 512.00
12	4	PC	REAR TAIL LAMP CLIPS ⁿⁿ LH-RH	6.00	20	4.80	(1pc) 19.20
13	2	PC	REAR TAIL LAMP PANEL	86.00	20	68.80	nn X 137.60
14	1	PC	REAR BOOT	693.00	20	554.40	Rx 554.40
15	1	PC	REAR BOOT EMBLEM	47.00	20	37.60	us 37.60
16	1	PC	REAR BOOT "LANCER" LOGO	52.00	20	41.60	us 41.60
17	1	PC	REAR BOOT "EX" LOGO	39.00	20	31.20	us 31.20

SUB-TOTAL: 2,779.20

1103.20

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003889

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01
 AXA Tower (S) 068811

ATTENTION :
 CONTACT : -

FAX NO: 68804838

DATE : 05/06/2018
 ACCIDENT DATE : 21/04/2018
 VEHICLE NO : SJJ2801X
 CHASSIS/ENG.NO : JMYSTCY4A8U004753
 VEHICLE MODEL : MIT.LANCER
 CLAIM NO :
 POLICY NO :
 REMARK : 2801 AXA TP AGST
 GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** SPECIAL NETT PRICE **							
1	1	PC	REAR REVERSE SENSOR	180.00			180.00 X ^m
							SUB-TOTAL 180.00
** WORK LABOUR **							
TO KNOCK, WELD, REMOVE AND REPLACE ABOVE PARTS				700.00			700.00 ⁵⁰⁰
TO PUTTY RESPRAY PAINTING ON AFFECTED AREAS				700.00			700.00 ⁵⁰⁰
TO CHECK WIRING				30.00			30.00 ✓
							SUB-TOTAL 1,430.00

Handwritten notes:
 \$1000
 Tanjun 97495769
 4 days
 WP
 6/6/18 @ 1pm
 Repair after repair
 snc@kkuauto.com
 init
 \$4.5k - Poh Khin

Handwritten notes:
 total \$ 2133.20
 less 20% = \$1706.56
 R \$1700 - 4/5
 ok? pls revert.
 Shann
 21/2019

JOYCE 

PAGE: 2 of 2

SUB-TOTAL : S\$ 4,389.20
 ADD 7% GST. S\$ 307.24
 GRAND TOTAL : S\$ 4,696.44

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E&O.E

Disclaimer clause:
 The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
 Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003889

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01
AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE : 05/06/2018
ACCIDENT DATE : 21/04/2018
VEHICLE NO : SJJ2801X
CHASSIS/ENG.NO : JMYSTCY4A8U004753
VEHICLE MODEL : MIT.LANCER
CLAIM NO :
POLICY NO :
REMARK : 2801 AXA TP AGST
GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	815.00	20	652.00	de 652.00
2	6	PC	REAR BUMPER CLIPS	3.00	20	2.40	na 14.40
3	2	PC	REAR BUMPER SIDE RETAINER LHX, RH- ^{na}	13.00	20	10.40	20.80
4	2	PC	REAR BUMPER BRACKET LHX, RH- ^{na}	18.00	20	14.40	28.80
5	1	PC	REAR BUMPER REINFORCEMENT	210.00	20	168.00	X? 168.00
6	1	PC	REAR BUMPER TOW COVER	21.00	20	16.80	na 16.80
7	1	PC	REAR BUMPER REFLECTOR(RH)	22.00	20	17.60	na 17.60
8	1	PC	REAR END PANEL	506.00	20	404.80	Rx 404.80
9	1	PC	REAR END PANEL TOP GARNISH	149.00	20	119.20	X 119.20
10	1	PC	REAR END PANEL CLIPS	4.00	20	3.20	X 3.20
11	2	PC	REAR TAIL LAMP LH-X, RH- ^{na}	320.00	20	256.00	512.00
12	4	PC	REAR TAIL LAMP CLIPS LH-X, RH- ^{na}	6.00	20	4.80	19.20
13	2	PC	REAR TAIL LAMP PANEL	86.00	20	68.80	X 137.60
14	1	PC	REAR BOOT	693.00	20	554.40	Rx 554.40
15	1	PC	REAR BOOT EMBLEM	47.00	20	37.60	na 37.60
16	1	PC	REAR BOOT "LANCER" LOGO	52.00	20	41.60	na 41.60
17	1	PC	REAR BOOT "EX" LOGO	39.00	20	31.20	na 31.20
----- SUB-TOTAL:							2,779.20

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003889

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01
AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE : 05/06/2018
ACCIDENT DATE : 21/04/2018
VEHICLE NO : SJJ2801X
CHASSIS/ENG.NO : JMYSTCY4A8U004753
VEHICLE MODEL : MIT.LANCER
CLAIM NO :
POLICY NO :
REMARK : 2801 AXA TP AGST
GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	MISC/MARKUP	TOTAL AMT
** SPECIAL NETT PRICE **							
1	1	PC	REAR REVERSE SENSOR	180.00		180.00 X?	180.00
SUB-TOTAL							180.00
** WORK LABOUR **							
			TO KNOCK, WELD , REMOVE AND REPLACE ABOVE PARTS	700.00		500 700.00	700.00
			TO PUTTY RESPRAY PAINTING ON AFFECTED AREAS	700.00		50 700.00	700.00
			TO CHECK WIRING	30.00		✓ 30.00	30.00
SUB-TOTAL							1,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Tanjun 97495729
4 days
WP
6/6/18 1pm
Resurvey after repair
sun@lkkauto.com

JOYCE



PAGE: 2 of 2

SUB-TOTAL : S\$ 4,389.20
ADD 7% GST. S\$ 307.24
GRAND TOTAL : S\$ 4,696.44

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6044Z
Vehicle Details	
Vehicle No.:	SJJ2801X
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 2.0L MIVEC GT 6-CVT SUNROOF
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	4B11BR8394
Chassis No.:	JMYSTCY4A8U004753
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$19,357.00
Original Registration Date:	08 Sep 2008
First Registration Date:	08 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$19,357.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2018
PARF Rebate Amount:	\$9,678.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$13,389.00
COE Rebate Amount:	\$328.00
Total Rebate Amount:	\$10,006.00

The information contained herein is correct as at 15 May 2018

OK

◀ Service Request Details

Claim
S8M00F48

Reference
None 

Loss Date
April 21, 2018

Request Date
May 16, 2018

Due Date
May 23, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

*16052018 @ 941am
Janice veh not in*

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
SJJ2801X

Make
TPVD MITSUBISHI

Service Address

...

Primary Contact/Insured

UTESCO ENGINEERING PTE LTD
5063 ANG MO KIO IND PARK 2, #01-1373, 569566, Singapore
64825069
ADMIN@IAGENCY.SG

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 5 July 2018 2:29 PM
To: 'admin@sngahtee.com'
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJJ2801X AND YOUR INSURED VEHICLE GT8892B ON 21/04/2018 *** LKK REF: CC4/ASM18009260/pa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/ASM18009260/T1pa3
Your Ref: SJJ 2801X

Dear Joyce,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE GT 8892B, SJJ 2801X AND OTHER ON 21/04/2018

We refer to above matter and our tele conversation on 04/07/2018.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:<S8M00F48 > IA with mandate uploaded

Type

🔔 Question

Message

PLS PROCEED FOR DS, QUANTUM AS PROPOSED.

Reply

<< <S8M00F48 > IA with mandate uploaded

Type

📍 Question

Message

The said chain collision involved 4 vehicles whereby our insured was the 2nd vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be withheld for the time being. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. Propose settlement amount is between \$ 2,546.49 to \$2,867.49. All the relevant documents had been uploaded in SMART CLAIM. For your kind attention and instruction, Thank you-Pohkin 03/09/2018

[Reply](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 03/09/2018

Survey Details:

Date of loss	21-Apr-18
Date of appointment	16-May-18
Date of survey	6-Jun-18
Location of survey	SNG AH TEE MOTOR & PANEL PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJJ 2801X
Make and Model	MITSUBISHI LANCER 2.0L -1998cc
Date of registration	8/9/2008
Excess	
Market Value	\$15,000
Part Rebate	\$10,000
Nett Loss	\$5,000

Repair details:

Initial Estimate	\$	4,389.20
------------------	----	----------

Proposed/Revised repair cost:

Parts	\$	1,101.60
Check items (estimate)	\$	348.00
Labour	\$	1,030.00
Total	\$	2,479.60
Lump Sum(if applicable)	\$	-

Number of days for repair		4
---------------------------	--	----------



Remarks:

Estimate for Rental: \$120 x 6 days = \$720.00

Mandate:

Liability(TP)	100%		100%	
Check item	with check item		no check item	
Proposed repair cost(w/gst)	(\$2,000.00 + 7% GST)	\$2,140.00	(\$1,700.00 + 7% GST)	\$1,819.00
Loss of use	\$	-	\$	-
Loss of rental (estimate)	\$	720.00	\$	720.00
Loss of income	\$	-	\$	-
LTA search fees	\$	7.49	\$	7.49
Others	\$	-	\$	-
Proposed Total	\$	2,867.49	\$	2,546.49

Poh Kin (LKKAuto)

From: Taufikh (LKKAuto)
Sent: Friday, 5 July 2019 5:09 PM
To: 'Sharon Sng'
Cc: Poh Kin (LKKAuto)
Subject: Fwd: SJJ2801X -FINALISE & AFTER PAINT
Attachments: 20180824_114557.jpg; 20180824_144517.jpg; 20180824_144550.jpg; 20180824_144637.jpg; img-190102120216[9119].pdf

Hi Sharon,

COR L/S \$1700 , 4 DAYS, subject to Insurance approval.

Regards
Taufikh
Lkk Auto

Get [Outlook for Android](#)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, July 3, 2019 4:12:42 PM
To: Taufikh (LKKAuto); SUR; Poh Kin (LKKAuto); Admin A
Subject: FW: SJJ2801X -FINALISE & AFTER PAINT

REMINDER

From: Sharon Sng
Sent: Wednesday, March 6, 2019 4:27 PM
To: 'SUR' <sur@lkkauto.com>
Subject: FW: SJJ2801X -FINALISE & AFTER PAINT

REMINDER

From: Sharon Sng <sharon@sngahtee.com>
Sent: Tuesday, January 8, 2019 5:50 PM
To: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Subject: FW: SJJ2801X -FINALISE & AFTER PAINT

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, January 2, 2019 12:34 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Subject: SJJ2801X -FINALISE & AFTER PAINT

Best Regards

Sharon Sng

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200510440N

INVOICE. SO003877

AXA INSURANCE PTE LTD

8 Shenton Way #24-01
 AXA Tower (S) 068811

ATTENTION :
 CONTACT : -

FAX NO: 68804838

DATE : 20/07/2019
 ACCIDENT DATE : 21/04/2018
 VEHICLE NO : SJJ2801X
 CHASSIS/ENG.NO : JMYSTCY48AU004753
 VEHICLE MODEL : MIT.LANCER
 CLAIM NO : CC4/ASM18009260/pa3
 POLICY NO : SURVEY BY LKK
 REMARK : 2801AXA TP AGST
 GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	JISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

**** LIST PRICE ****

SUB-TOTAL: 0.00

**** WORK LABOUR ****

TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	0.00	0.00
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	0.00	0.00
TO CHECK WIRING	0.00	0.00
TOTAL AS PER AGREED LUMP SUM	1700.00	1,700.00
	SUB-TOTAL	1,700.00

JANICE



PAGE: 1 of 1

SUB-TOTAL : S\$ 1,700.00
 ADD 7% GST. S\$ 119.00
GRAND TOTAL : S\$ 1,819.00

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

◀ Re:<S8M00F48 > IA with mandate uploaded

Type

🔔 Question

Message

PLS PROCEED FOR DS, QUANTUM AS PROPOSED.

Reply

Cecilia Chong (LKK Auto)

From: Mei Kwan (LKKAuto)
Sent: Sunday, 1 March 2020 11:37 AM
To: Janice Chang; Cecilia Chong (LKK Auto)
Cc: Admin A
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJJ2801X AND YOUR INSURED VEHICLE GT8892B ON 21/04/2018 *** LKK REF: CC4/ASM18009260/T1ga3
Attachments: SJJ2801X.PDF

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Cecilia,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Chang [mailto:janice@sngahtee.com]

Sent: Saturday, 29 February 2020 5:04 PM

To: Admin A

Subject: FW: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJJ2801X AND YOUR INSURED VEHICLE GT8892B ON 21/04/2018 *** LKK REF: CC4/ASM18009260/pa3

Importance: High

REMINDER

Hi OI,

We refer to the above and have finalized with your surveyor.

Here is our LOD.

Quantum is as per below:-

COR = \$1,819.00

LOR= \$856.00

SEARCH FEE = \$2.00

TOTAL = \$2,677.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009260/T1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 19-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GT 8892B	Veh. Inspected	SJJ 2801X
Policy No.	GA334943/1	Coverage (\$)	0.00
Claim No.	S8M00F48	Excess (\$)	0.00
Assign From		Assign Date	16/05/2018

2. Vehicle Particulars & Condition

Make & Model	mitsubishi LANCER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JMYSTCY4A8U004753	Colour	MAROON
Odometer	240138	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	YOKOHAMA	6 mm
L/H Front Tyre	225/40 R18	YOKOHAMA	6 mm
R/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm
L/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/04/2018	Inspection Date	06/06/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 2801X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	815.00	815.00
6	REAR BUMPER CLIPS @\$3.00 (CONSISTENT)	NECESSARY	18.00	18.00
2	REAR BUMPER SIDE RETAINER @\$13.00 (CONSISTENT)	N/S NOT NECESSARY / O/S NECESSARY	26.00	13.00
2	REAR BUMPER BRACKET @\$36.00 (CONSISTENT)	N/S NOT NECESSARY / O/S NECESSARY	36.00	18.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	210.00	-
1	REAR BUMPER TOW COVER (CONSISTENT)	MISSING	21.00	21.00
1	REAR BUMPER REFLECTOR (RH) (CONSISTENT)	CRACKED	22.00	22.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	506.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	149.00	-
2	REAR END PANEL CLIPS @\$4.00(CONSISTENT)	NECESSARY	8.00	8.00
2	REAR TAIL LAMP @\$320.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	640.00	320.00
4	REAR TAIL LAMP CLIPS @\$6.00 (CONSISTENT)	N/S NOT NECESSARY / O/S NECESSARY	24.00	6.00
2	REAR TAIL LAMP PANEL @\$86.00 (CONSISTENT)	NOT NECESSARY	172.00	-
1	REAR BOOT (CONSISTENT)	TO REPAIR SEE LABOUR	693.00	-
1	REAR BOOT EMBLEM (CONSISTENT)	NECESSARY	47.00	47.00
1	REAR BOOT 'LANCER' LOGO (CONSISTENT)	NECESSARY	52.00	52.00
1	REAR BOOT 'EX' LOGO (CONSISTENT)	NECESSARY	39.00	39.00
	LESS 20% DISCOUNT		-695.60	-275.80
			2,782.40	1,103.20
SPECIAL NETT ITEMS				
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
			180.00	-

Report Ref No. CC4/ASM18009260/T1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK ,WELD,REMOVE AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR BOOT .		700.00	500.00
	TO PUTTY RESPRAY PAINTING ON AFFECTED AREAS.		700.00	500.00
	TO CHECK WIRING .		30.00	30.00
			1,430.00	1,030.00
	GRAND TOTAL		4,392.40	2,133.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CC4/ASM18009260/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim: SRM00F48
 Reference: CC4/ASM18009260/TTa352
 Loss Date: 21 April 2018
 Report Date: 25 Apr 2018 12:00:00 AM
 Request Date: 30 May 2019
 Due Date:
 Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)
 Type of Loss: Third Party Vehicle Damage
 Services: Pending verification - Direct Settlement

ACTIONS

Next Step: Wait for Approve Invoice

Vehicle Information

Incident Vehicle Registration #: SUJ2801X
 Make: TPVD MITSUBISHI
 Model: LANCER-2.0L MIVEC (A)
 Service Address:
 ...

Primary Contact/Insured

UTESCO ENGINEERING PTE LTD
 5063 ANG MO KIO IND PARK 2, #01-1373,
 569566, Singapore
 64825067
 ADMIN@IAGENCY.SG

Claim Handler

ANG Yvonne
 65688D461
 Yvonne.ang@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type:

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020
 LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FOIBK.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 September 2018
 Immediate Advice (with mandated) dated 03.09.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	3 September 2018
 PRAF and COE rebate form.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 September 2018
 Letter to OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	3 September 2018
 Authorization Letter - Company Vehicle.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 July 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 June 2018
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2018
 GIA REPORT OF 5/2201X (TP).pdf	Reports & Statement	GIA Report	KADRI Mästen	16 May 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 GIA REPORT OF GT881928 (INSEQ).PDF	Reports & Statement	GIA Report	KADRI Msteeen	16 May 2018
 EMAIL.MSE	Letters and Correspondence	Others	KADRI Msteeen	16 May 2018