



GST / ROC Company No :

201101753C

u

Third Party Insurer :

AXA

Insured's Veh No :

SJK9009R

Date of accident :

12/05/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Estimate To Repair

Vehicle No :

Chassis No :

HONDA VEZEL HYBRID 1.5X AUTO

SLR1815Y

RU3-1223574

Quotation No : AR/QO18/05-1014

Quotation Date : 15/05/2018

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	REAR GATE	\$1,010.00
2	4PC	REAR WINDSCREEN MOULDING @\$60	\$240.00
3	1PC	REAR GATE "VEZEL" PLATE	\$75.00
4	1PC	REAR GATE "HYBRID" PLATE	\$80.00
5	1PC	REAR BUMPER	\$867.00
6	10PC	REAR BUMPER CLIPS	\$55.00
1405 - 20%			\$2,327.00
1124			\$465.40
			\$1,861.60
MISC CHARGE			
7	1PC	REAR WINDSCREEN GUM	\$60.00
8	1PC	REVERSE SENSOR	\$250.00
Total			\$310.00
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	\$120.00
		LABOUR CHARGE	\$500.00
		SPRAY PAINTING	\$500.00
Total			\$1,270.00
Sub Total			\$3,441.60
GST (7.00%)			\$240.91
Total			\$3,682.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before starting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418

Signature:

Date: