

ASS. REC. BY

REF

CS/MSG18009270/Uqd3et

Special Instruction

SA/2018/01
Menmen

Marcelus

ASSIGNMENT (Office)

From (Person)

catherine thia

of

MSIG

Date/Time

22/5/18 @ 9:35am

Estimated Cost

Bill to

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 2986C

Insured:

at Workshop w/z

Yew Tee Automobile

Tel:

6702 3113

of

Blk 25 Kaki Bukit Rd 4 # 01-61

Policy No.

D27945520QMX

Claim No:

558270

Sum Insured

Excess:

\$300.00

Make of Vch:

(Client's Record)

D.O.A.

12/05/2018

CA / ☒ REV

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

10:25am @ 22/5/18

Person Contacted:

May

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 2986C-X

22/5/18 @

2:58pm VASST to Catherine Thia via Menmen.

23/5/18 @

5:17pm They Ni informed C/A via Menmen.

24/5/18 @

3:33pm Informed Shawn C/A B EX: \$300 by email.

10/6/18

Final Prg B 3761.59, Marwan finalised with Shawn.
no lapses

176

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKP2986Cat Workshop m/s Yan Wei

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 300

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 77k.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / RE / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP2986C Yr Regn: 8114Type: M2 / M.Cycle / Bus / Van / Lorry / Taxi / Prima Mover /Truck / Trailer or GAMake: Nissan Teana cc 2488Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 72887 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MNTBCAL3320002594Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/55R17

BS / DUN / ENOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

R/Bal: 6 mmL/Bal: 6 mmD.O.A. 2/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A 60433 Rep 10500

RECEIVED 13 JUN 2018

Data/Time, File Pass to/

1/2/16

Data/Time, File Return to/

2/

Report Format: MEH-OPLump Sum / I.B.I. (\$) 3261.59Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ -RS- \$

Photo

Others

TOTAL

150
10
160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009270/Uqd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-05-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKP 2986C
Policy No.	D27945520QMX	Coverage (\$)	0.00
Claim No.	558270	Excess (\$)	300.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/05/2018	Inspection Date	22/05/2018
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018 Sendback Est	21 May 2018 16:39 \$5,896.00	22 May 2018 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	CHOO WAI YING , ID: S1654315B, Tel: +6596314991								
Vehicle Reg. No.:	SKP2986C	Date of Loss:	12/05/2018 23:00 - :59 [44 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 558270	Policy/Cover Note No.:	D27945520QMX (Comprehensive) Coverage: 28/08/2017 - 27/08/2018						
		Excess:	S\$300.00						
Repairer:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/05/2018]								
Driver/Custodian:	WOO TAT MENG WILLIAM (60 / Male), NRIC: S1285478A, Tel: +6583039399								
Adj Asg. Remarks:	Car in, pls survey today and revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 24 May 2018 3:33 PM
To: 'YT(HQ)'
Cc: info@yewteegroup.com; SUR
Subject: RE: SKP2986C - DOA - 12/05/2018- Nissan Teana 2.5L CVT

Dear Shawn,

As instructed by our client, please proceed to repair the insured vehicle **SKP 2986C (excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vimimala D/O Raja Singam [mailto:vimmala_rajasingam@sg.msig-asia.com]
Sent: Wednesday, 23 May 2018 9:44 AM
To: 'YT(HQ)' <utauto@singnet.com.sg>
Cc: info@yewteegroup.com; SUR <sur@lkkauto.com>
Subject: RE: SKP2986C - DOA - 12/05/2018- Nissan Teana 2.5L CVT
Importance: High

Hi May

Thank you for the addendum.

Are you aware effect 01/04/2018, all our authorised panel workshops have to use the Audatex system to put up the estimate?

We have informed our surveyor LKK to liaise with you.

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingam@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	15 May 2018 10:25	Cim Veh Model Changed	(204793) NISSAN TEANA 2.5L CVT 2.5 (A).		[I] Pang Xiu Shi
2	15 May 2018 10:25	Cim Created	Reg No: SKP2986C. Policy No: D27945520QMX. Acct Date: 2018/05/12. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS;MSME18062746		[I] Pang Xiu Shi
3	21 May 2018 16:26	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[I] Toh Lei Ming
4	21 May 2018 16:39	Cim Submitted	5896.00.		[R] Toh Lei Ming
5	21 May 2018 16:43	Cim Registration Modified	Init.Est.:>5,000 - 6,000.		[I] Vimmala D/O Raja Singam
6	21 May 2018 16:45	Cim Registration Modified	Excess: -> 300.00.		[I] Vimmala D/O Raja Singam
7	21 May 2018 16:47	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert.		[I] Vimmala D/O Raja Singam
8	21 May 2018 16:47	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/05/22		[I] Vimmala D/O Raja Singam
9	21 May 2018 16:47	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Vimmala D/O Raja Singam
10	22 May 2018 08:38	Assignment 1st Accessed			[A] Crystal Lee
11	22 May 2018 09:33	Adj Assignment Cancelled	Car in, IHS unable to attend (Appt Full)		[I] Pauline Soh Li Ping
12	22 May 2018 09:33	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Pauline Soh Li Ping
13	22 May 2018 09:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, pls survey today and revert.		[I] Pauline Soh Li Ping
14	22 May 2018 09:35	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/05/23		[I] Pauline Soh Li Ping
15	22 May 2018 09:35	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Pauline Soh Li Ping
16	22 May 2018 10:09	Assignment 1st Accessed			[A] Nivitha Govindasamy
17	22 May 2018 14:49	Adj Adjuster Assigned	[None] -> MARCUS CHUA		[A] Nivitha Govindasamy
18	22 May 2018 14:54	Adj Rpt Initiated			[A] SHIAU CHAN
19	22 May 2018 14:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/21		[A] SHIAU CHAN
20	22 May 2018 14:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/21		[A] SHIAU CHAN
21	22 May 2018 14:58	Adj Mandate Request	Cur.Req:3472.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.		[A] SHIAU CHAN
22	23 May 2018 15:56	Adj Mandate Request Cancelled			[A] SHIAU CHAN
23	23 May 2018 16:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/21		[A] SHIAU CHAN
24	23 May 2018 16:00	Adj Mandate Request	Cur.Req:3472.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.		[A] SHIAU CHAN
25	23 May 2018 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/21, Mandate Remarks: Check items \$797 to be verified and confirmed		[I] Eng Huey NI
26	23 May 2018 17:12	Adj Mandate Set	Approved:2675.50:Check items \$797 to be verified and confirmed		[I] Eng Huey NI

Date From



Date To



Audit Type None

Go

ACTIVITY

[22/05/2018 09:33] Pauline Soh Li Ping:
Car in, IHS unable to attend (Appt Full)
[22/05/2018 08:53] Crystal Lee:
No one pick call.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1810554	21/05/2018 16:26	Motor	Yew Tee Automobile Tech Pte Ltd (HQ)	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	SKP2986C		xx.xx
1811634	22/05/2018 14:54	Motor	LKK Auto Consultants Pte	LKK Auto Consultants Pte	SKP2986C		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmaia D/O Raja Singam

Date: 23 May 2018

Preliminary Advice

Vehicle No	: SKP2986C	Accident Date	: 12/05/2018
Make	: NISSAN TEANA 2.5L CVT	Policy No.	: D27945520QMX
Assignment Date	: 22/05/2018	Excess	: S\$300.00
Date of Inspection	: 22/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT) BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,896.00
Revised Amount	:S\$	2,362.99
Check Items (Estimated)	:S\$	797.00
Total	:S\$	3,159.99

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	60,433.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,567.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 22 May 2018

Preliminary Advice

Vehicle No	: SKP2986C	Accident Date	: 12/05/2018
Make	: NISSAN TEANA 2.5L CVT	Policy No.	: D27945520QMX
Assignment Date	: 22/05/2018	Excess	: S\$300.00
Date of Inspection	: 22/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT) BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,896.00
Revised Amount	:S\$	2,675.50
Check Items (Estimated)	:S\$	797.00
Total	:S\$	3,472.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	60,433.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,567.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4315B

Vehicle Details

Vehicle No.: SKP2986C
Vehicle to be Exported: No
Intended De-registration Date: 22 May 2018
Vehicle Make: NISSAN
Vehicle Model: TEANA 2.5L CVT
Primary Colour: Black
Manufacturing Year: 2014
Engine No.: QR25040957L
Chassis No.: MNTBCAL33Z0002594
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$25,688.00
Original Registration Date: 28 Aug 2014
First Registration Date: 28 Aug 2014
Transfer Count: 0
Actual ARF Paid: \$27,964.00 13982

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Aug 2024
PARF Rebate Amount: \$20,973.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2024
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$63,001.00
COE Rebate Amount: \$39,460.00
Total Rebate Amount: \$60,433.00

The information contained herein is correct as at 22 May 2018

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Login

Sign up

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Corolla Altis 1.6A

\$2800 Downpayment! Monthly

\$588 Onwards! Lowest 3.68%

P.a @ GV Cars Financing!

GV Credit Pte Ltd StarAd

click here to view

our PRISTINE USED CARS

at GREAT PRICES

Browse by Category

Sort by Date Posted

20 results/page

6 vehicles

Nissan Teana

Advanced Search

Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection: Nissan Teana Any Any 2014 Any Any Any Available								
	Nissan Teana 2.0A	\$83,688	\$10,810 /yr	26-Dec-2014	1,997 cc	45,000 km	Luxury	Available
1 Of The Cheapest In The Market! 1 Owner And Fully Maintained With Agent! Extremely Low Mileage, Full Black Interior, Original Paintwork! High Comfort Level With Superb Sound Proofing! Spacious And Qu...								
Katz Automobile								
Posted: 20-May-2018 Tags: 2014 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan								
	Nissan Teana 2.0A XL	\$75,800	\$9,990 /yr	29-Sep-2014	1,997 cc	43,000 km	Luxury	Available
New Model! Low Mileage Done, Agent Maintained Under Warranty, Very Good Condition From Interior To Exterior. Excellent Condition. In House Loan And Trade In Available. Price Negotiable.								
Posted: 17-May-2018 Tags: 2014 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan								
	Nissan Teana 2.5A	\$84,800	\$11,360 /yr	14-Aug-2014	2,488 cc	77,150 km	Luxury	Available
6th Generation Nissan Teana, Decent All Round Machine. Very Well Maintained By 1 Owner, Road Tax Till Aug 2017, Neat, Comfortable, Comfortable Leg Room Space! Safe As It Received The Highest Assessment...								
Prem Roy Motoring								
Posted: 16-May-2018 Tags: 2014 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan								
	Nissan Teana 2.5A	\$79,888	\$10,920 /yr	05-Jun-2014	2,488 cc	48,000 km	Luxury	Available
Best Condition In The Market! Value For Money Luxury Sedan. High Loan, High Overtrade, Bank And In-House Available. 2.68%. Number Plate To Be Retained. 110% Accident Free. Maintained By Tan Cheong Mot...								
Posted: 07-May-2018 Tags: 2014 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan								
Car Buying			Car Selling			Car Ownership		
Car Aftermarket			On The Move			Lifestyle		
Buy Types Online! Latest Special Offers from Topical!								
	Nissan Teana 2.5A	\$85,800	\$10,950 /yr	11-Dec-2014	2,488 cc	60,000 km	Luxury	Available
Road Tax Fully Paid Till Dec 2018, 1 Owner Only, Low Mileage, 100% Accident Free, Easy To Maintain Black Interior, Immaculate Condition, Original Paintwork. Please Feel Free To Call Our Friendly Sales...								
Car Linguel								
Posted: 05-Apr-2018 Tags: 2014 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan								
	Nissan Teana 2.5A	\$82,800	\$11,020 /yr	21-Aug-2014	2,488 cc	-	Luxury	Available
Evaluated By VICOM, Free 6 Months Maintenance And 1 Grooming. High COE & PARF								
Yong Lee Seng Motor								
Posted: 24-Mar-2018 Tags: 2014 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan								

Save this search criteria, to get email alerts whenever a match is found.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 16:58
Date Of Accident	12/05/2018 23:40
Exact Location Of Accident	MAYNE ROAD TO BT TIMAH ROAD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP2986C
Insured/Policyholder	
Name Of Registered Owner	CHOO WAI YING
NRIC No	S1654315B
Email Address	CHRISTINE.CHOO@FUJIFILM.COM
Mobile Phone No	(LOCAL) +65-96314991
Alternative Phone No	OFFICE-96314991

Vehicle Particulars

Manufacturer	NISSAN
Model	TEANA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D27945520QMX
Cover Note Number	

Driver

Name of Driver	WOO TAT MENG WILLIAM
NRIC No	S1285478A
Date Of Birth	16/01/1958
Occupation	INDOOR
Date Of Driving Pass	17/05/1993
Driving Experience	24 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83039399
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	3 JALAN ANAK BUKIT #19-02
Postcode	2158
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHRISTINE CHOO GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA9510M
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Hazards Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to attack

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/ID No.:

Car B : Maureen Chia
Driver: HP 93897528

Car : Nissan
Number : SLA9510M



Date of Accident : 12 May 18.

Time of Accident : about 11.40 pm.

I was on Lane 1 of Mayne Rd junction with Bukit Timah Rd. When the traffic was clear, I turn left onto Lane A.

Car B was on Lane 2 of Mayne Rd junction. The car turn at the same time but into my Lane A instead of Lane B, hitting my car left side, both passenger doors were damaged and the rear part of the car.

William

William Woo Tat Meng.

~~License~~ Ic No: S1285478A

HP No: 83039399

Car Number.

SKP 2986C.

Nissan Teana
Black.

Yew Tee Automobile Tech Pte Ltd (Co Reg No.200311009G)

BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT

Singapore 417800

Fax: 67023773 Email: info@yewteegroup.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	YTKB/OD/1805/016
Policy No:	D27945520QMX	Date of Loss:	12/05/2018
Vehicle Reg. No.:	SKP2986C	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOO WAI YING	Contact No:	+6596314991
Driver:	WOO TAT MENG WILLIAM		
Make/Model:	NISSAN TEANA 2.5L CVT, 2.5 (A)	Vehicle Reg. Date:	28/08/2014
Vehicle Colour:	BLACK		
Engine No:	QR25040957L	Chassis No:	MNTBCAL33Z0002594
Odometer:	72000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	SKP2986C COLLIDED WITH SLA9510M		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT)		

not relevant
hbr
to be ph to be ph
EXPRESS 300
22/5/18
Sdy

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	
Labour	
Paintwork Labour	
Towing	
	0.00
	Calculated Gross Total (S\$) 5,896.00
	- Excess (S\$) 300.00
	(S\$) 5,596.00
	+ GST 7.00% (S\$) 391.72
	Nett Amount (S\$) 5,987.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This claim is handled by: **TOH LEI MING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 May 2018)
Parts: 143 NISSAN TEANA 2.5L CVT 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKP2986C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.



Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	530	*FRONT DOOR LH <i>3.650</i>	530	0.00	0.00	*400.00 F <i>✓</i>
2	1	95	*FRONT DOOR LOCK LH <i>shush</i>	100	0.00	0.00	*200.00 F <i>✓</i>
3	1	85	*FRONT DOOR OUTER HANDLE LH <i>5.12/0.00</i>	125	0.00	0.00	*155.00 <i>✓</i>
4	1	65	*FRONT DOOR RUBBER LH <i>rer</i>	70	0.00	0.00	*95.00 F <i>✓</i>
5	1		*FRONT DOOR LOCK CATCH LH <i>17</i>		0.00	0.00	*20.00 F <i>+</i>
6	1	75	*FRONT DOOR GLASS OUTER MOULDING LH <i>one</i>	75	0.00	0.00	*220.00 F <i>✓</i>
7	1		*FRONT DOOR GLASS REGULATOR LH <i>11</i>		0.00	0.00	*120.00 F <i>x</i>
8	1	770	*FRONT DOOR GLASS REGULATOR MOTOR LH <i>jm</i>	250	0.00	0.00	*380.00 F <i>✓</i>
9	1	530	*REAR DOOR LH <i>body 20</i>	530	0.00	0.00	*420.00 F <i>✓</i>
10	1	38	*REAR DOOR HINGE TOP LH <i>7w1</i>	38	0.00	0.00	*45.00 F <i>✓</i>
11	1	38	*REAR DOOR HINGE BOTTOM LH <i>7w1</i>	38	0.00	0.00	*45.00 F <i>✓</i>
12	1		*FRONT DOOR INNER BOARD LH <i>11</i>		0.00	0.00	*850.00 F <i>x</i>
13	1	65	*REAR DOOR RUBBER LH <i>rer</i>	65	0.00	0.00	*90.00 F <i>✓</i>
14	1		*REAR FENDER LH <i>12</i>		0.00	0.00	*F <i>x</i>
15	1		*REAR BUMPER <i>12</i>		0.00	0.00	*F <i>x</i>
16	1		*REAR SPORT RIM LH <i>12</i>		0.00	0.00	*520.00 F <i>y</i>

F=Franchise part.

Sub Total (S\$)	3,560.00
+ Margin on L,N Items 10.00% (S\$)	356.00
Total Parts (S\$)	3,916.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT DOOR INNER BOARD CLIPS	121 50.00 ✓
Sub Total (S\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To Carry-Out Body Cavity Preservation.	New	NZ 60.00 X
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	750 800.00
<u>Labour Items</u>			
3	To Transfer Door.	New	160.00 120
4	To Dismantle and Refit Rear Undercarriage.	New	17 120.00 X
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New	50.00 20
6	To Conduct Computer Wheel Alignment.	New	80.00 ✓
7	To Reset Power Window.	New	60.00 ?
8	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	-
9	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	600.00 550
Gross Labour Cost (S\$)			1,930.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Total Panel / Mechanical 8615
Total Paintwork 8490
Total Paint / Material costs 8212.49

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT DOOR INNER BOARD CLIPS	50.00
Sub Total (\$\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To Carry-Out Body Cavity Preservation.	New	80.00
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	800.00
<u>Labour Items</u>			
3	To Transfer Door.	New	160.00
4	To Dismantle and Refit Rear Undercarriage.	New	120.00
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New	50.00
6	To Conduct Computer Wheel Alignment.	New	80.00
7	To Reset Power Window.	New	80.00
8	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	-
9	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	800.00
Gross Labour Cost (\$\$)			1,930.00

Report was unsubmitted during this print-out.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: YTKB/OD/1805/016
Assessment Number: MSIG0001
Version: LKKAUTOC/2
Date Calculated: 23/05/2018 08:52

Full Report - V1
Registration: SKP2986C
Printed: 23/05/2018 15:52

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	12/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	YTKB/OD/1805/016	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	Teana
Sub Model:	BASE MODEL
Model Sheet Number:	Z9E 01
Registration:	SKP2986C
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 04/2014	AUTO AIR CON
REAR VENTILAT OUTLET	ELEC/HEATED D/MIRROR
XENON HEADLAMPS	AUTO LIGHT SENSOR
RAIN SENSOR	RAD GRILLE CHROME
ULTRASONIC PARK SYS	2.5 LTR 127/137KW
CVT AUTO GEARBOX	PRODUCT THAILAND
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	23/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$995.00
Total Paint/Material	\$212.49
Total Parts	\$1,842.50
Total of Additional Costs	\$50.00
Repair Cost Exc GST:	\$3,099.99
Overall Discount (0.0%):	- \$0.00
Excess:	-\$300.00
After Deduction -	
Grand Total Exc GST:	\$2,799.99
7 % GST:	\$196.00
Grand Total Inc GST:	\$2,995.99

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	JOB ALLOWANCE	5.0	25.00
3040A1	RENEW L/F OUTER DOOR PANEL INCLUDES: R + R DOOR AND NECESSARY ATTACHED PARTS, ADJUST DOOR, APPLY CORROSION PREVENTIVE DOES NOT INCLUDE: R + R WINDOW REGULATOR AND DOOR LOCK	50.0	250.00
4192A1	R + R LEFT FRONT DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	4.0	20.00
UH26A1)	R + R LEFT FRONT DOOR LOCK (DOOR TRIM REMOVED)	1.0	5.00
3020A1	RENEW LEFT REAR DOOR INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, DOOR ADJUSTMENT, APPLY RUST PROOFING WAX	28.0	140.00
2583	REPAIR REAR BUMPER	5.0*	25.00
3481	REPAIR L/R SIDE PANEL	10.0*	50.00

LABOUR COST

Total Work Units	103.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	10.3HRS	\$515.00
Paint Labour	9.6HRS	\$480.00
Total Labour	19.9HRS	\$995.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1485	L/F DOORSKIN NEW PART PAINTING	15.0	
1781	L/R DOOR NEW PART PAINTING	16.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	17.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
LABOUR COST - PAINT			
	TIME(PAINT)	63.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	96.0	
	Total Paintwork Labour	9.6HRS	\$480.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$88.23
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$24.23
	Repair Painting Plastic		\$58.73
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$212.49
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$212.49

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1485	1	L/F DOORSKIN	H0153 3TUMA	Bodypro	0% 400.00 *520 ✓
1509	1	L/F DOOR SEAL	80831 3TU0A	rec	0% 95.00 *65 ✓
1551	1	L/F WINDOW MOTOR	80731 3SF1B	jm	0% 380.00 *230 ✓
1577	1	L/F DOOR LOCK	80501 3TU0A	shock/jm	0% 200.00 *95 ✓
1781	1	L/R DOOR	H210A 3TUMA	Bodypro	0% 420.00 *520 ✓
1787	1	L/R UPPER DOOR HINGE	82401 3GF0A	set	0% 45.00 *38 ✓
1795	1	L/R LOWER DOOR HINGE	80400 JN00A	set	0% 45.00 *38 ✓
1809	1	L/R DOOR SEAL	82831 3TU0A	rec	0% 90.00 *65 ✓
f: OEM Parts			Sub Total		\$1,675.00
g: Original			Mark Up From Cost	(10 %)	\$167.50
h: Secondhand			Total Parts		\$1,842.50
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT DR INN BOARD SPECIALIST	0%	\$50.00
CLI		
Total Extras		\$50.00

Final Calculation

Total Parts	\$1,842.50
Labour	

Total Panel/Mechanical

frt door outer moulding als one 75 ✓ \$515.00
 frt door outer handle als scn fr ✓

Total Paintwork	\$480.00	\$995.00
Total Labour		
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$50.00	
Total of Additional Costs		\$50.00
Total Paint/Material Costs		\$212.49
Repair Costs Excludes GST		\$3,099.99
Deductions		
Deduction for Excess (Fixed)	-\$300.00	
Total Deductions		-\$300.00
Grand Total Excludes GST (After Deduction)		\$2,799.99
GST @ 7 %		\$196.00
Grand Total Includes GST (After Deduction)		\$2,995.99

Assessment Notes

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No:200311009C)

BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT

Singapore 417800

Fax: 67023773 Email: info@yewteegroup.com

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	YTKB/OD/1805/016
Policy No:	D27945520QMX	Date of Loss:	12/05/2018
Vehicle Reg. No.:	SKP2986C	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOO WAI YING	Contact No:	+6596314991
Driver:	WOO TAT MENG WILLIAM		
Make/Model:	NISSAN TEANA 2.5L CVT, 2.5 (A)	Vehicle Reg. Date:	28/08/2014
Vehicle Colour:	BLACK		
Engine No:	QR25040957L	Chassis No:	MNTBCAL33Z0002594
Odometer:	72000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	SKP2986C COLLIDED WITH SLA9510M		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT)		

COST OF CLAIMS	Amount
Parts	3,916.00
Miscellaneous Items	50.00
Labour	1,070.00
Paintwork Labour	860.00
Towing	0.00
Calculated Gross Total (S\$)	5,896.00
- Excess (S\$)	300.00
(S\$)	5,596.00
+ GST 7.00% (S\$)	391.72
Nett Amount (S\$)	5,987.72

This claim is handled by: TOH LEI MING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 May 2018)
 Parts: 143 NISSAN TEANA 2.5L CVT 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKP2986C)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	520	*FRONT DOOR LH 3-550	530	0.00	*400.00 F
2	1	95	*FRONT DOOR LOCK LH Shubb	100	0.00	*200.00 F
3	1	85	*FRONT DOOR OUTER HANDLE LH 75 scd/002	125	0.00	*155.00 F
4	1	65	*FRONT DOOR RUBBER LH	70	0.00	*95.00 F
5	1		*FRONT DOOR LOCK CATCH LH		0.00	*20.00 F
6	1	75	*FRONT DOOR GLASS OUTER MOULDING LH 75	75	0.00	*220.00 F
7	1		*FRONT DOOR GLASS REGULATOR LH		0.00	*120.00 F
8	1	230	*FRONT DOOR GLASS REGULATOR MOTOR LH JM	250	0.00	*380.00 F
9	1	520	*REAR DOOR LH 500	530	0.00	*420.00 F
10	1	38	*REAR DOOR HINGE TOP LH	38	0.00	*45.00 F
11	1	38	*REAR DOOR HINGE BOTTOM LH	38	0.00	*45.00 F
12	1		*FRONT DOOR INNER BOARD LH		0.00	*850.00 F
13	1	65	*REAR DOOR RUBBER LH	65	0.00	*90.00 F
14	1		*REAR FENDER LH		0.00	*FX
15	1		*REAR BUMPER		0.00	*FD
16	1		*REAR SPORT RIM LH		0.00	*520.00 F

F=Franchise part

Sub Total (S\$) 3,560.00
 + Margin on L.N Items 10.00% (S\$) 356.00

Total Parts (S\$) 3,916.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

9-1731
 102
 1904.1

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT DOOR INNER BOARD CLIPS	121 50.00 ✓
Sub Total (S\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To Carry-Out Body Cavity Preservation.	New	NI 60.00 X
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	750 800.00
<u>Labour Items</u>			
3	To Transfer Door.	New	160.00 120
4	To Dismantle and Refit Rear Undercarriage.	New	17 120.00 X
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New	50.00 20
6	To Conduct Computer Wheel Alignment.	New	80.00 ✓
7	To Reset Power Window.	New	60.00 ?
8	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	-
9	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	600.00 550
Gross Labour Cost (S\$)			1,930.00

Report was unsubmitted during this print-out
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parts	\$ 1821.00
+ 10%	\$ 182.10
	\$ 2003.10
Miscellaneous	\$ 50.00
	\$ 2053.10
Paint Labour	\$ 750.00
Labour	\$ 831.00
	\$ 3633.10

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62982158, 62942354, 62935021
Email: ftrpnet@mbbox3.singnet.com.sg
ICB Reg No.: 198301435R

(CASH) YEW TEE AUTOMOBILE TECH PTE C/
KAKI BUKIT RD 4,
L-61, SYNERGY@KB
SINGAPORE 417800
2986C

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
110A-3TUMA			(SIN)	(SIN)
1501-3TU0A		1	520.000	520.00
110A-3TUMA		1	95.000	95.00
1831-3TU0A		1	520.000	520.00
1731-3SF1A		1	65.000	65.00
1640-3TS0A		1	230.000	230.00
1831-3TU0A		1	85.000	85.00
		1	65.000	65.00

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62982158, 62942354, 62935021
Email: ftrpnet@mbbox3.singnet.com.sg
ICB Reg No.: 198301435R

(CASH) YEW TEE AUTOMOBILE TECH PTE C/
KAKI BUKIT RD 4,
L-61, SYNERGY@KB
SINGAPORE 417800
2986C

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
			(SIN)	(SIN)
			GST Excl Amount :	1580.00
			Special Discount :	
			GST @ 7 % :	110.60

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1690.60

REPRINT BY :

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA
TEL: 62954551
67409954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67492588

MAZDA/FORD DIV
TEL: 62935722
67420366

AIRCON/W/S GLASS
TEL: 62952336
67495997

TAX INVOICE

TAX INVOICE NO.: CL384401

INVOICE DATE : 24/05/2018

CREDIT TERMS : COD

SALES ORDER NO.:

SALESMAN : LHK

PAGE(S)

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA
TEL: 62954551
67409954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67492588

MAZDA/FORD DIV
TEL: 62935722
67420366

AIRCON/W/S GLASS
TEL: 62952336
67495997

TAX INVOICE

TAX INVOICE NO.: CL384401

INVOICE DATE : 24/05/2018

CREDIT TERMS : COD

SALES ORDER NO.:

SALESMAN : LHK

PAGE(S)

豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 216115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
RCB Reg No.: 198301438R

AUTHORISED STOCKISTS:



(CASH) YEW TEE AUTOMOBILE TECH PTE C/
KAKI BUKIT RD 4,
L-61, SYNERGY@KB
SINGAPORE 417800
22986C

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV
TEL: 62954551
67498954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62905722
67420388

AIRCON/W/S GLASS
TEL: 62952338
67495987

TAX INVOICE

TAX INVOICE NO.: CL384418

INVOICE DATE : 25/05/2018

CREDIT TERMS : CDD

SALES ORDER NO.:

SALESMAN : LHK

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC	QUANTITY	UNIT PRICE	
2401-3GFOA RR.DR.TOP HINGE LH		1✓	(SIN) 38.000	(SIN) 38.00
3400-JN00A FR.DR.HINGE RH-UP LH-LOW		1✓	38.000	38.00
3821-3TU0A F.DR.OUTER MLDG LH 3TU08		1✓	75.000	75.00
GST Excl Amount :				151.00
Special Discount :				
GST @ 7 % :				10.57

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

161.57

PRINT BY :

LHK 25/05/2018 10:32:54

SIGNATURE

SIGNATURE

1731

**Yew Tee Automobile
Blk 6 Woodlands Rd
Singapore 678006**

Claim Reference: YTKB/OD/1805/016
Assessment Number: MSIG0001
Version: YEWTEEA1/1
Date Calculated: 23/05/2018 06:33

Full Report - V1
Registration: SKP2986C
Printed: 23/05/2018 13:33

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Shaun Toh	Date of Incident:	12/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	YTKB/OD/1805/016	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle	Model Specs
Manufacturer:	FROM 04/2014
Model:	REAR VENTILAT OUTLET
Sub Model:	XENON HEADLAMPS
Model Sheet Number:	RAIN SENSOR
Registration:	ULTRASONIC PARK SYS
Registration Month:	CVT AUTO GEARBOX
Registration Year:	TWO COAT METALLIC
VIN Number:	AUTO AIR CON
Odometer:	ELEC/HEATED D/MIRROR
Colour:	AUTO LIGHT SENSOR
Engine Number:	RAD GRILLE CHROME
Fuel Level:	2.5 LTR 127/137KW
	PRODUCT THAILAND
	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	23/05/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Yew Tee Automobile

Claim Reference: YTKB/OD/1805/016

Assessment Number: MSIG0001



Version: YEWTEEA1/1

Date Calculated: 23/05/2018 06:33

Full Report - V1

Registration: SKP2986C

Printed: 23/05/2018 13:33



Addresses

Cost Summary

Total Labour	\$1,030.00
Total Paint/Material	\$212.49
Total Parts	\$3,012.80
Excess:	TBA
Grand Total Exc GST:	\$4,255.29
7 % GST:	\$297.87
Grand Total Inc GST:	\$4,553.16

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	JOB ALLOWANCE	5.0	25.00
3040A1	RENEW L/F OUTER DOOR PANEL INCLUDES: R + R DOOR AND NECESSARY ATTACHED PARTS, ADJUST DOOR, APPLY CORROSION PREVENTIVE DOES NOT INCLUDE: R + R WINDOW REGULATOR AND DOOR LOCK	50.0	250.00
4192A1	R + R LEFT FRONT DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	4.0	20.00
3020A1	RENEW LEFT REAR DOOR INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, DOOR ADJUSTMENT, APPLY RUST PROOFING WAX	28.0	140.00
PW10A1)	R + R LEFT REAR WHEEL	2.0	10.00
PW10A1)	R + R AND BALANCE TYRES (ADD/WORK)	6.0	30.00
2583	REPAIR REAR BUMPER	5.0*	25.00
3481	REPAIR L/R SIDE PANEL	10.0*	50.00

LABOUR COST

Total Work Units	110.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	11.0HRS	\$550.00
Paint Labour	9.6HRS	\$480.00
Total Labour	20.6HRS	\$1,030.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Yew Tee Automobile

Claim Reference: YTKB/OD/1805/016

Assessment Number: MSIG0001

Version: YEWTEEA1/1

Date Calculated: 23/05/2018 06:33

Full Report - V1

Registration: SKP2986C

Printed: 23/05/2018 13:33

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1485	L/F DOORSKIN NEW PART PAINTING	15.0	
1781	L/R DOOR NEW PART PAINTING	16.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	17.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
LABOUR COST - PAINT			
	TIME(PAINT)	63.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	96.0	
	Total Paintwork Labour	9.6HRS	\$480.00
MATERIAL COST - PAINT			
	Cost Price		
	New Part Painting		\$88.23
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$24.23
	Repair Painting Plastic		\$58.73
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$212.49
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$212.49

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1577	1	L/F DOOR LOCK	80501 3TU0A	shub / ym	0% 95 200.00*
1565	1	L/F DOOR OUT HANDLE	82640 3TS0A	scn	0% 85 155.00*
1509	1	L/F DOOR SEAL	80831 3TU0A	scn	0% 85 95.00*
1485	1	L/F DOORSKIN	H0153 3TUMA	1.0500	0% 420 400.00*
1625	1	L/F OUT CHANNEL SEAL	80821 3TU0A	1.1	0% 220 220.00*
1551	1	L/F WINDOW MOTOR	80731 3SF1B	3.1	0% 230 380.00*
1547	1	L/F WINDOW REGULATOR	80721 3TU0A	scn	0% 120 120.00*
1781	1	L/R DOOR	H210A 3TUMA	3.0500	0% 420 420.00*
1809	1	L/R DOOR SEAL	82831 3TU0A	scn	0% 65 90.00*
1795	1	L/R LOWER DOOR HINGE	80400 JN00A	scn	0% 38 45.00*
1787	1	L/R UPPER DOOR HINGE	82401 3GFOA	scn	0% 38 45.00*
9551	1	L/R WHEEL	D0300 3TU2A	cur LR 4 80.5	0% 520 520.00*
f: OEM Parts			Sub Total		\$2,690.00
g: Original			Mark Up From Cost	(10 %)	\$269.00
h: Secondhand			Sundry Parts	(2 %)	\$53.80
p: Parallel			Total Parts		\$3,012.80
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

Final Calculation

Total Parts		\$3,012.80
Labour		
Total Panel/Mechanical	\$550.00	
Total Paintwork	\$480.00	
Total Labour		\$1,030.00
Total Paint/Material Costs		\$212.49



51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: YTKB/OD/1805/016
Assessment Number: MSIG0001
Version: LKKAUTOC/4
Date Calculated: 12/06/2018 02:46

Full Report - V1
Registration: SKP2986C
Printed: 12/06/2018 09:46

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	12/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	YTKB/OD/1805/016	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	Teana
Sub Model:	BASE MODEL
Model Sheet Number:	Z9E 01
Registration:	SKP2986C
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 04/2014	AUTO AIR CON
REAR VENTILAT OUTLET	ELEC/HEATED D/MIRROR
XENON HEADLAMPS	AUTO LIGHT SENSOR
RAIN SENSOR	RAD GRILLE CHROME
ULTRASONIC PARK SYS	2.5 LTR 127/137KW
CVT AUTO GEARBOX	PRODUCT THAILAND
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	23/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$1,095.00
Total Paint/Material	\$212.49
Total Parts	\$1,904.10
Total of Additional Costs	\$50.00
Repair Cost Exc GST:	\$3,261.59
Overall Discount (0.0%):	- \$0.00
Excess:	-\$300.00
After Deduction -	
Grand Total Exc GST:	\$2,961.59
7 % GST:	\$207.31
Grand Total Inc GST:	\$3,168.90

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	JOB ALLOWANCE	5.0	25.00
3040A1	RENEW L/F OUTER DOOR PANEL INCLUDES: R + R DOOR AND NECESSARY ATTACHED PARTS, ADJUST DOOR, APPLY CORROSION PREVENTIVE DOES NOT INCLUDE: R + R WINDOW REGULATOR AND DOOR LOCK	50.0	250.00
4192A1	R + R LEFT FRONT DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	4.0	20.00
UH26A1)	R + R LEFT FRONT DOOR LOCK (DOOR TRIM REMOVED)	1.0	5.00
3020A1	RENEW LEFT REAR DOOR INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, DOOR ADJUSTMENT, APPLY RUST PROOFING WAX	28.0	140.00
2583	REPAIR REAR BUMPER	5.0*	25.00
3481	REPAIR L/R SIDE PANEL	10.0*	50.00
1000	REPAIR L/R WHEEL	20.0*	100.00
LABOUR COST			
Total Work Units		123.0	
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		12.3HRS	\$615.00
Paint Labour		9.6HRS	\$480.00

Total Labour **21.9HRS** **\$1,095.00**

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1485	L/F DOORSKIN NEW PART PAINTING	15.0	
1781	L/R DOOR NEW PART PAINTING	16.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	17.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
LABOUR COST - PAINT			
	TIME(PAINT)	63.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	96.0	
	Total Paintwork Labour	9.6HRS	\$480.00
MATERIAL COST - PAINT			
	New Part Painting		\$88.23
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$24.23
	Repair Painting Plastic		\$58.73
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$212.49
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$212.49

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
1485	1	L/F DOORSKIN	H0153 3TUMA		520.00*
1509	1	L/F DOOR SEAL	80831 3TU0A		65.00*
1551	1	L/F WINDOW MOTOR	80731 3SF1B		230.00*
1577	1	L/F DOOR LOCK	80501 3TU0A		95.00*
1781	1	L/R DOOR	H210A 3TUMA		520.00*
1787	1	L/R UPPER DOOR HINGE	82401 3GF0A		38.00*
1795	1	L/R LOWER DOOR HINGE	80400 JN00A		38.00*
1809	1	L/R DOOR SEAL	82831 3TU0A		65.00*
1000	1	LH FRT DR OUTER MOU	Renew		75.00*
1000	1	LH FRT DR OUTER HNDL	Renew		85.00*

f: OEM Parts
 g: Original
 h: Secondhand
 p: Parallel
 x: Exchange

Sub Total **\$1,731.00**
 Mark Up From Cost (10 %) **\$173.10**
Total Parts \$1,904.10

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT DR INN BOARD SPECIALIST	0%	\$50.00
CLI		
Total Extras		\$50.00

Final Calculation

Total Parts		\$1,904.10
Labour		
Total Panel/Mechanical	\$615.00	
Total Paintwork	\$480.00	
Total Labour		\$1,095.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$50.00	
Total of Additional Costs		\$50.00
Total Paint/Material Costs		\$212.49
Repair Costs Excludes GST		\$3,261.59
Deductions		
Deduction for Excess (Fixed)	-\$300.00	
Total Deductions		-\$300.00
Grand Total Excludes GST (After Deduction)		\$2,961.59
GST @ 7 %		\$207.31
Grand Total Includes GST (After Deduction)		\$3,168.90

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018 Sendback Est	21 May 2018 16:39 \$55,896.00	22 May 2018 09:35 Edit Adj Rpt	\$53,261.59 Edit Estimates	\$53,261.59 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHOO WAI YING , ID: S1654315B, Tel: +6596314991									
Vehicle Reg. No.: SKP2986C		Date of Loss: 12/05/2018 23:00 - :59 [44 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 558270		Policy/Cover Note No.: D27945520QMX (Comprehensive) Coverage: 28/08/2017 - 27/08/2018							
		Excess: S\$300.00							
Repairer: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/06/2018]									
Driver/Custodian: WOO TAT MENG WILLIAM (60 / Male), NRIC: S1285478A, Tel: +6583039399									
Adj Asg. Remarks: Car in, pls survey today and revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (23/05/2018): Alert - Adj Mandate Approved (\$52675.50) - SKP2986C - Claim Handler: Vimmala D/O...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKP2986C (558270)
OD
May 12 2018 11:00PM
[CHOO WAI YING]
Yew Tee Automobile Tech Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Letters/Correspondences							1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	15/05/18 10:36	Acknowledgement Letter to OI		 Load PDF				
Assessment Reports							1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print			
1	14/05/18 17:06	Accident Statement		 Load HTM				
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print			
1	21/05/18 16:39	Repairer Estimates		 Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	22/05/18 14:58	Adjuster Immediate Advice		 Load HTM				
2	23/05/18 16:00	Adjuster Immediate Advice		 Load HTM				
Photos/Images							3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print			
1	14/05/18 17:04	CERT INS [Linked Accident Report Documents]		 Load JPG	☒			
2	14/05/18 17:04	Driving License [Linked Accident Report Documents]		 Load JPG	☒			
3	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
4	14/05/18 17:04	Identification Card [Linked Accident Report Documents]		 Load JPG	☒			
5	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
6	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
7	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
8	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
9	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
10	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
11	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
12	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
13	14/05/18 17:04	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	22/05/18 18:21	Chassis Number		 Load JPG	☒			
2	22/05/18 18:21	Odometer Reading		 Load JPG	☒			
3	22/05/18 18:22	General View		 Load JPG	☒			
4	22/05/18 18:22	General View		 Load JPG	☒			
5	22/05/18 18:22	General View		 Load JPG	☒			
6	22/05/18 18:22	General View		 Load JPG	☒			
7	22/05/18 18:22	General View		 Load JPG	☒			
8	22/05/18 18:22	General View		 Load JPG	☒			
9	22/05/18 18:22	General View		Load JPG	☒			
10	22/05/18 18:22	General View		Load JPG				

Letters/Correspondences				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
					☒
11	22/05/18 18:22	General View	1	Load JPG	☒
12	22/05/18 18:22	General View	1	Load JPG	☒
13	22/05/18 18:22	General View	1	Load JPG	☒
14	22/05/18 18:22	General View	1	Load JPG	☒
15	22/05/18 18:22	General View	1	Load JPG	☒
16	22/05/18 18:22	General View	1	Load JPG	☒
17	22/05/18 18:22	General View	1	Load JPG	☒
18	22/05/18 18:22	General View	1	Load JPG	☒
19	22/05/18 18:22	General View	1	Load JPG	☒
20	22/05/18 18:22	General View	1	Load JPG	☒
21	22/05/18 18:22	General View	1	Load JPG	☒
22	22/05/18 18:22	General View	1	Load JPG	☒
23	22/05/18 18:22	General View	1	Load JPG	☒
24	22/05/18 18:22	General View	1	Load JPG	☒
25	22/05/18 18:22	General View	1	Load JPG	☒
26	22/05/18 18:22	General View	1	Load JPG	☒
27	22/05/18 18:22	General View	1	Load JPG	☒
28	22/05/18 18:22	General View	1	Load JPG	☒
29	22/05/18 18:22	General View	1	Load JPG	☒
30	22/05/18 18:22	General View	1	Load JPG	☒
31	22/05/18 18:22	General View	1	Load JPG	☒
32	22/05/18 18:22	General View	1	Load JPG	☒
33	22/05/18 18:22	General View	1	Load JPG	☒
34	22/05/18 18:22	General View	1	Load JPG	☒
35	22/05/18 18:22	General View	1	Load JPG	☒
36	22/05/18 18:22	General View	1	Load JPG	☒
37	22/05/18 18:22	General View	1	Load JPG	☒
38	22/05/18 18:22	General View	1	Load JPG	☒
39	22/05/18 18:22	General View	1	Load JPG	☒
40	22/05/18 18:22	General View	1	Load JPG	☒
41	22/05/18 18:22	General View	1	Load JPG	☒
42	22/05/18 18:22	General View	1	Load JPG	☒
43	22/05/18 18:22	General View	1	Load JPG	☒
44	22/05/18 18:22	General View	1	Load JPG	☒
45	22/05/18 18:22	General View	1	Load JPG	☒
46	22/05/18 18:22	General View	1	Load JPG	☒
47	22/05/18 18:22	General View	1	Load JPG	☒
48	22/05/18 18:22	General View	1	Load JPG	☒
49	22/05/18 18:22	General View	1	Load JPG	☒
50	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
51	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
52	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
53	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
54	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
55	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
56	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
57	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
58	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒
59	28/05/18 15:02	Reinspection Photo	1	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On		Thumbnail	Print
60	28/05/18 15:02	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Reinspection Photo	Load JPG	☒
61	28/05/18 15:02	Reinspection Photo	Load JPG	☒
62	28/05/18 15:02	Reinspection Photo	Load JPG	☒
63	28/05/18 15:02	Reinspection Photo	Load JPG	☒
64	28/05/18 15:02	Reinspection Photo	Load JPG	☒
65	28/05/18 15:02	Reinspection Photo	Load JPG	☒
66	28/05/18 15:02	Reinspection Photo	Load JPG	☒
67	28/05/18 15:02	Reinspection Photo	Load JPG	☒
68	28/05/18 15:02	Reinspection Photo	Load JPG	☒
69	28/05/18 15:02	Reinspection Photo	Load JPG	☒
70	28/05/18 15:02	Reinspection Photo	Load JPG	☒
71	28/05/18 15:02	Reinspection Photo	Load JPG	☒
72	28/05/18 15:02	Reinspection Photo	Load JPG	☒
73	28/05/18 15:02	Reinspection Photo	Load JPG	☒
74	28/05/18 15:02	Reinspection Photo	Load JPG	☒
75	28/05/18 15:02	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	14/05/18 17:03	SME Motor Pte Ltd (Kaki Bukit) Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	14/05/18 17:03	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
3	14/05/18 17:03	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 14:53	ESTIMATE	Load PDF	
2	23/05/18 16:01	AUDATEX	Load PDF	
3	13/06/18 12:15	Parts Invoice	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On		Thumbnail	Print
1	14/05/18 17:06	SME Motor Pte Ltd (Kaki Bukit) Accident Statement	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/18 09:53	Addendum Sheet	Load JPG	☒
2	23/05/18 09:53	Accident Statement Addm. #1	Load HTM	
3	23/05/18 09:55	Accident Statement Addm. #2	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On		Thumbnail	Print
1	14/05/18 17:04	SME Motor Pte Ltd (Kaki Bukit) CERT INS	Load JPG	☒
2	14/05/18 17:04	Driving License	Load JPG	☒
3	14/05/18 17:04	Accident Photo	Load JPG	☒
4	14/05/18 17:04	Identification Card	Load JPG	☒
5	14/05/18 17:04	Accident Photo	Load JPG	☒
6	14/05/18 17:04	Accident Photo	Load JPG	☒
7	14/05/18 17:04	Accident Photo	Load JPG	☒
8	14/05/18 17:04	Accident Photo	Load JPG	☒
9	14/05/18 17:04	Accident Photo	Load JPG	☒
10	14/05/18 17:04	Accident Photo	Load JPG	☒
11	14/05/18 17:04	Accident Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
12	14/05/18 17:04	Accident Photo	 Load JPG	☒
13	14/05/18 17:04	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/05/18 17:03	Accident Sketch Plan	 Load TIF	
2	14/05/18 17:03	Accident Sketch Plan	 Load TIF	
3	14/05/18 17:03	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LXX Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18009270/UQD3E2

Date: 13/06/2018

REFERENCE

Insured/Claimant:	CHOO WAI YING	Policy No:	D27945520QMX	Claim No:	558270
Date of Loss:	12/05/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP2986C	Engine No:	QR25040957L
Make & Model:	NISSAN TEANA 2.5L CVT, 2.5 (A)	Chassis No:	MNTBCAL33Z0002594
Reg. Date:	28/08/2014 (Man. Year: 2014)	Odometer:	72887 km
Colour:	Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,916.00	1,904.10	2,011.90	51.38
Miscellaneous Items	50.00	50.00	0.00	0.00
Labour	1,070.00	1,307.49	-237.49	-22.20
Paintwork Labour	860.00	0.00	860.00	100.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,896.00	3,261.59	2,634.41	44.68
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,596.00	2,961.59	2,634.41	47.08
+ GST 7.00/7.00% (S\$)	391.72	207.31	184.41	47.08
Nett Amount (S\$)	5,987.72	3,168.90	2,818.82	47.08

INSPECTION

Date of Assignment:	22/05/2018 Present Location:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)
Date Inspected:	22/05/2018 Inspected At:	BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT Singapore 417800
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
Parts: 143	NISSAN TEANA 2.5L CVT 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKP2986C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH (WCP)	Badly Dented	400.00 F	*520.00 F
2	1		*FRONT DOOR LOCK LH (WCP)	Shorted	200.00 F	*95.00 F
3	1		*FRONT DOOR OUTER HANDLE LH (WCP)	Scratched / Damaged	155.00 F	*85.00 F
4	1		*FRONT DOOR RUBBER LH (WCP)	Necessary	95.00 F	*65.00 F
5	1		*FRONT DOOR LOCK CATCH LH (WCP)	Not Necessary	20.00 F	*- F
6	1		*FRONT DOOR GLASS OUTER MOULDING LH (WCP)	Cracked	220.00 F	*75.00 F
7	1		*FRONT DOOR GLASS REGULATOR LH (WCP)	Not Necessary	120.00 F	*- F
8	1		*FRONT DOOR GLASS REGULATOR MOTOR LH (WCP)	Jammed	380.00 F	*230.00 F
9	1		*REAR DOOR LH (WCP)	Badly Dented	420.00 F	*520.00 F
10	1		*REAR DOOR HINGE TOP LH (WCP)	Twisted	45.00 F	*38.00 F
11	1		*REAR DOOR HINGE BOTTOM LH (WCP)	Twisted	45.00 F	*38.00 F
12	1		*FRONT DOOR INNER BOARD LH (WCP)	Not Necessary	850.00 F	*- F
13	1		*REAR DOOR RUBBER LH (WCP)	Necessary	90.00 F	*65.00 F
14	1		*REAR FENDER LH (NPA)(WCP)	Repair	0.00 F	*- F
15	1		*REAR BUMPER (NPA)(WCP)	Repair	0.00 F	*- F
16	1		*REAR SPORT RIM LH (WCP)	Repair	520.00 F	*- F

F=Franchise part.

Sub Total (S\$)	3,560.00	1,731.00
+ Margin on L,N Items 10.00/10.00% (S\$)	356.00	173.10
Total Parts (S\$)	3,916.00	1,904.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT DOOR INNER BOARD CLIPS (NECESSARY)	50.00	50.00
Sub Total (\$\$)			50.00	50.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To Carry-Out Body Cavity Preservation.	New	60.00	0.00
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	800.00	0.00
<u>Labour Items</u>				
3	To Transfer Door.	New	160.00	0.00
4	To Dismantle and Refit Rear Undercarriage.	New	120.00	0.00
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New	50.00	0.00
6	To Conduct Computer Wheel Alignment.	New	80.00	0.00
7	To Reset Power Window.	New	60.00	0.00
8	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. (NPA)	New	-	0.00
9	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	600.00	0.00
10	Total Panel / Mechanical	New	-	615.00
11	Total Paint Work	New	-	480.00
12	Total Paint / Material Costs	New	-	212.49
Gross Labour Cost (\$\$)			1,930.00	1,307.49

Report was unsubmitted during this print-out.

< END OF ESTIMATES >