

Wed 30/05 @ 10am
S&R

SFT6100D

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 MAY 2018

Estimate No.	: b1 47007	Page No. : 1 of 2
Date Estimated	: 21/05/2018	
Prepared By	: Han Kwan Yong	

- ESTIMATE REPAIR FOR - TAN ENG CHAI 110 Woodlands Avenue 5 #07-21 Singapore 739015	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT6100D	V926367	25/04/2018	216d CAT	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray rear bumper	934 1,038.00
To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.	561 ? 661.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1:	3,408.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER PANEL PRIMED (PDC)	1	966.25	de 966.25
REAR BUMPER CARRIER	1	423.80	bb 423.80
SUPPORT	1	37.35	? 37.35
RR BUMPER LH INNER SIDE GUIDE	1	58.55	? 58.55
RR BUMPER RH INNER SIDE GUIDE	1	58.55	? 58.55
REAR BUMPER HEAT INSULATOR	1	59.15	? 59.15
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	? 42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	? 40.50
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	de 10.10
ULTRASONIC SENSOR IMPERIALBLAU(WA89	2	368.80	? 737.60
Total Parts :			2,433.95



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47007
Date Estimated : 21/05/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT6100D	V926367	25/04/2018	216d CAT	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>20/5/18</u>	Excess \$ _____
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97445749</u>	Authorized <u>Yes / No</u>
Authorized Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR <u>Yes / No</u> <u>Yes / No</u>	
Surveyor's E-mail <u>tanjiah@lkkauto.com</u>	
No. of Working Days Recommend <u>03 days</u>	

Labour 1	:	3,408.00
Parts	:	2,433.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	408.94
Grand Total	:	<u>6,250.89</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **