

ASS. REC. BY: Adrian Ling

REF:

RC3 / A/H 18009279 / Asbez**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$600/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 128KIDAC Accident Report: _____ Consistent? : **Yes** or NoGIA / PR Seen: _____ Consistent? : **Yes** or NoEst. Repairs: 09 days Res.: **Yes** or NoLum Sum: _____ % 3 Val.: **Yes** or No**CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SLH2085H Yr Regn: 2016 / Oct.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan cc 1395Colour: Bronze A/C: **Insured / Std / NI / NA**Sp. Reading: 39121 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: WAVU222F41 HA029215Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: **Nil / S/Rim / STD A/Rim** orTyre Size: F: 205/50R16R: 205/50R16**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or Continental

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.L. 22/05/18Survey held at PremiumDes. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop** orThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time Action / Instruction

07 AUG.SLH 2085H - X

RECEIVED 12 DEC 2018

23/05/18 @ 15:27 pm. Revised IA to Norsaezan via memo.23/05/18 @ 15:29 pm. mandate requested authorize repair to Norsaezan via memo24/05/18 @ 11:43 am. mandate approved by Victor Koh24/05/18 @ 12:10 pm. revert authorize repair to repair via email29/10/18 - Confirmed P/P \$ 28,033.56 @ 9 days with Adrian.
(\$ 18,534.44 Red - 40%)Date/Time, File Pass to? ☐ : Prel. Report12/12/181) Typist ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9Resurvey No. of Trip: 1Survey Fee: 200

Transportation: _____

S + RS. \$ _____

Photos _____

Others 10

TOTAL

210

Report Format: _____

Lump Sum / I.B.I.: (\$ 28,033.56 P/P)Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3863G
Vehicle Details	
Vehicle No.:	SLH2085H
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CVN017989
Chassis No.:	WAUZZZF41HA029215
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,161.00
Original Registration Date:	26 Oct 2016
First Registration Date:	26 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$27,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$20,269.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,410.00
COE Rebate Amount:	\$47,508.00
Total Rebate Amount:	\$67,777.00

The information contained herein is correct as at 23 May 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 12 November 2018 5:03 PM
To: 'Boo seng yak'
Cc: Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLH2085H - OD AIG - SURVEYED 22 MAY 18

Dear Mr Boo,

Confirmed final fig \$ 28,033.56 @ 9 days of repairs before excess \$600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Thursday, 19 July 2018 8:29 PM
To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLH2085H - OD AIG - SURVEYED 22 MAY 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$28,033.56 @ 9 days of repairs.

Mr. Rasul re-inspected vehicle on 25 May 18 for checked items.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 24 May 2018 12:10 PM
To: 'Claims Dept'
Cc: 'SUR'
Subject: FW: OD claim for SLH 2085 H
Attachments: SLH 2085 H - 19052018 GIA.PDF; PA05912018 - SLH 2085 H - A4 Sedan 1.4 TFSI-FRONT (AIG).xls

Dear Kee Siang/Phua,

As instructed by our client, please proceed to repair the insured vehicle **SLH 2085H (Excess \$ 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 22 May 2018 10:00 AM
To: 'SUR' <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: OD claim for SLH 2085 H

Good morning all ,

Here are the attachment of GIA report and Estimate for SLH 2085 H Own Damage Claim for your kind reference .

Kindly assist .

Thank you.

Best Regards,

Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road | Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SLH2085H (39749112625G)**

OD

May 19 2018 10:00AM

[GOOI GEOK YANG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/11/2018 15:31 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$28033.56) - SLH2085H - Claim Handler: Mohd Zawaye, Norsazani

Approved:28033.56.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLH2085H (3974911262SG)**

OD

May 19 2018 10:00AM

[GOOI GEOK YANG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 24/05/2018 11:43 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$27972.00) - SLH2085H - Claim Handler: Mohd Zawaye, Norsazani

Approved:27972.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 29 Oct 2018

Preliminary Advice

Vehicle No	: SLH2085H	Accident Date	: 19/05/2018
Make	: AUDI A4	Policy No.	: 2100487728
Assignment Date	: 22/05/2018	Excess	: S\$600.00
Date of Inspection	: 22/05/2018	Est. Duration of Repair	: 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,568.00
Revised Amount	:S\$	28,033.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	28,033.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	128,000.00
COE / PARF Rebate	:S\$	67,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,223.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 23 May 2018

Preliminary Advice

Vehicle No	: SLH2085H	Accident Date	: 19/05/2018
Make	: AUDI A4	Policy No.	: 2100487728
Assignment Date	: 22/05/2018	Excess	: S\$600.00
Date of Inspection	: 22/05/2018	Est. Duration of Repair	: 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,568.00
Revised Amount	:S\$	27,972.00
Check Items (Estimated)	:S\$	5,436.00
Total	:S\$	33,408.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	128,000.00
COE / PARF Rebate	:S\$	67,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,223.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 09:44
Date Of Accident	19/05/2018 10:15
Exact Location Of Accident	ALONG PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2085H
Insured/Policyholder	
Name Of Registered Owner	GOOI GEOK YANG
NRIC No	S7673863G
Email Address	ANGLISSANGLISS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96917488
Alternative Phone No	OTHERS-96917488

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100487728-01
Cover Note Number	

Driver

Name of Driver	GOOI GEOK YANG
NRIC No	S7673863G
Date Of Birth	01/06/1976
Occupation	INDOOR
Date Of Driving Pass	15/07/2002
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96917488
Fax Number	
Contact Number	OTHERS-96917488
Email Address	ANGLISSANGLISS@GMAIL.COM

Address	BLK 490 ADMIRALTY LINK #14-99
Postcode	750490
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG PIE, THE FRONT VEHICLE EMERGENCY BRAKE. I COULD NOT BRAKE ON TIME, THEN I COLLIDED INTO HIS CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBE3456Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KIRI NG YONG WEN
NRIC/Passport Number	S9703668C
Contact Number	97533617
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: LIM KEE SENG
NRIC/FIN No.: 990512345678

Sketch Plan #2

SKETCH PLAN



A: SLH 2085 H
B: SBE 3456 Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along A7E, the front vehicle emergency brake. I could not brake on time, then I collided into his car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: LIM BOE SENG
NRIC/PIN No: 6085216947

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7673863G**

Name
GOOI GEOK YANG

Birth Date **01 Jun 1976**
Issue Date **07 Jan 2004**

001075447A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7673863G



Name
GOOI GEOK YANG

魏若洋

Race
CHINESE

Date of birth
01-06-1976

Sex
M

Country/Place of birth
MALAYSIA

S7673863G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	15 Jul 2002
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	15 Jul 2002

NP 439A

Licence No: S7673863G

5767234

57673863G

57673863G

Date of issue
12-07-2017

Address
**APT BLK 490 ADMIRALTY LINK
#14-09
SINGAPORE 750490**

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : GOOI GEOK YANG
Period of Insurance : 26 Oct 2017 To 25 Oct 2018
Engine No. : CVN017989
Chassis No. : WAUZZZF41HA029215

Vehicle No. : SLH2085H
Policy No. : 2100487728-01
Endorsement No. :
Issued Date : 21 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

GOOI GEOK YANG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63602323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPENC

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0591/2018/GW
Date : 21-May-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Gool Geok Yang
Address : Blk 490 Admiralty link
#14-99
Singapore 750490
Telephone : HP +65 96917488
Type of Claim : Own Damage Claim
Policy No. : 2100487728-01
Vehicle No : **SLH 2085 H**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Oct-16
Engine No : CVN 017989
Chassis No : WAUZZZF41HA029215
Mileage : -
Date In : 19-May-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-May-18
Place of Accident : Along PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 2085 H.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlight, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To remove and transfer aircon condenser ,radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,100.00 ? ✓
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,400.00 3250 ✓
4	To remove both front door panel trims, dismantle wing mirror assy and renew both door chrome moldings.	S/N \$ 600.00 300 ✓ 600
5	To respray front bumper, both front fenders, bonnet, hinges and both front doors.	\$ 4,500.00 3300 ✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 12,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 2085 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	S 1,849.00 ✓	1479.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	S 245.00 ✓	
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 S 60.00 ✓	
4	FRONT BUMPER GRILLE <i>new</i>	S 171.00 ✓	
5	FRONT BUMPER CLOSING ELEMENT <i>new</i>	S 180.00 ✓	
6	FRONT BUMPER AIR GUIDE-LH/RH <i>new</i>	2 S 146.00 ✓	
7	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>new</i> <i>RA</i>	2 S 236.00 ✓	94
8	FOAM FILLER PIECE <i>new</i>	S 107.00 ✓	85.20
9	FRONT BUMPER CARRIER <i>Best</i>	S 702.00 ✓	541.60
10	FRONT BUMPER SUPPORT-LH/RH <i>Distorted</i>	2 S 48.00 ?	38.24
11	FRONT BUMPER BRACKET LOCK CARRIER <i>new</i>	S 118.00 ✓	94
12	FRONT BUMPER COVER <i>Distorted</i>	S 109.00 ✓	87.20
13	RELEASE LEVER <i>new</i>	S 12.00 ?	9.44
14	SIGN 'CAUTION' <i>new</i>	S 12.00 ✓	9.28
15	AIR CONDITIONER STICKER <i>new</i>	S 7.00 ✓	4.88
16	RADIATOR GRILLE <i>new</i>	S 972.00 ✓	777.20
17	FRONT FENDER-LH/RH <i>RH Buckled</i>	2 S 1,330.00 ✓	665 532
18	FRONT FENDER ATTACHMENT PARTS <i>RH new</i>	2 S 90.00 ✓	45 X
19	FRONT FENDER CLOSING ELEMENT-LH/RH <i>new</i>	2 S 88.00 ?	X
20	FRONT FENDER BRACKET-LH/RH <i>RH Best</i>	2 S 62.00 ✓	31 24.16
SUB-TOTAL SPARE PARTS		S 6,544.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 2085 H.

S/N	Parts Description			Damage Parts & Prices	
				S/NETT	REMARKS
21	FRONT FENDER BRACKET DEFORMATION ELEMENT	2 S	86.00	43	34.56
22	FRONT FENDER BRACE-LH/RH	2 S	206.00	7	X
23	FRONT STONE CHUP GUARD	2 S	88.00	44	34.56
24	LED HEADLIGHT-LH/RH	2 S	13,946.00	✓	11,156.80
25	LED HEADLIGHT POWER MODULE	2 S	1,389.00	+	
26	LED HEADLIGHT CONTROL UNIT	2 S	1,314.00	+	
27	HOSE	2 S	60.00	+	
28	COMPENSATING PIECE	2 S	75.00	?	X
29	LED HEADLIGHT ASSY SPACER	2 S	70.00	?	X
30	LIFT CYLINDER BRACKET-LH/RH	2 S	11.00	?	X
31	LIFT CYLINDER-LH/RH	2 S	368.00	?	294.40
32	CORRUGATED PIPE	S	79.00	+	
33	BONNER	S	2,163.00	✓	1730.40
34	BONNET ATTACHMENT PARTS	S	105.00	+	X
35	BONNET LID HINGE-LH/RH	2 S	532.00	+	
36	BONNET IMPACT PROTECTION-LH/RH	2 S	48.00	✓	37.76
37	BONNET IMPACT PROTECTION-CENTRE	S	24.00	✓	18.88
38	BONNET COVER-LH/RH	2 S	106.00	?	X
39	BONNET STRIKER-LH/RH	2 S	88.00	+	
40	BONNET LID LOCK	2 S	376.00	?	X
SUB-TOTAL SPARE PARTS			:	\$ 21,134.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 2085 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	BONNET BOWDEN CABLE <i>new</i>	2 S	100.00 + 40
42	LID LOCK CABLE <i>Not new</i>	S	64.00 ? X
42	LOCK CARRIER MOUNTING <i>behind</i>	S	891.00 ? 712.80
44	AIR GUDIE-LH/RH	2 S	46.00 ? 36.80
45	INNER DUCT-LH/RH <i>changed</i>	2 S	20.00 ? 15.36
46	INNER DUCT- UPPER	S	14.00 ? 10.56
47	A/C CONDENSER <i>Best</i>	S	540.00 ✓ 432
48	PRESSURE SENSOR <i>new</i>	S	170.00 +
49	VALVE <i>new</i>	S	46.00 +
50	COOLER FOR COOLANT <i>Best</i>	S	585.00 ? 468
51	RUBBER BUSH-LOWER <i>new</i>	2 S	16.00 ? 12.48
52	RADIATOR INSULATOR-LOWER <i>new</i>	2 S	22.00 ? 17.44
53	ADDITIONAL COOLER FOR COOLANT-LOWER CENTRE <i>new new</i>	S	455.00 ? X
54	COOLANT CONCENTRATE <i>new new</i>	4 S	133.00 ? 65.28
55	FAN RING <i>Not new</i>	S	230.00 + ? X
56	RADIATOR FAN CONTROL UNIT <i>new</i>	S	2,055.00 +
57	FRONT WINDOW SLOT SEAL-LH/RH <i>RH cut</i>	2 S	530.00 - 265.212
58	BONNET SOUND ABS <i>new</i>	S	296.00 +
59	FRONT NO. PLATE <i>Best</i>	S/N S	25.00 ✓
60	SUNDRIES <i>new</i>	S	500.00 ? 30.08
TOTAL SPARE PARTS		:	\$ 34,416.00
TOTAL LABOUR CHARGES		:	\$ 12,152.00
GRAND TOTAL		:	\$ 46,568.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 22/05/13
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 09 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0591/2018/GW
Date	:	21-May-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
9 days - ok - jb - 19 JUL 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Gooi Geok Yang
Address	:	Blk 490 Admiralty link #14-99 Singapore 750490
Telephone	:	HP +65 96917488
Type of Claim	:	Own Damage Claim
Policy No.	:	2100487728-01
Vehicle No	:	SLH 2085 H
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Oct-16
Engine No	:	CVN 017989
Chassis No	:	WAUZZZF41HA029215
Mileage	:	-
Date In	:	19-May-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-May-18
Place of Accident	:	Along PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 2085 H.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlight, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To remove and transfer aircon condenser ,radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N	\$ 1,100.00	\$	1,100.00
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed. (Lock carrier replaced)		\$ 5,400.00	\$	3,250.00
4	To remove both front door panel trims, dismantle wing mirror assy and renew both door chrome moldings.	S/N	\$ 600.00	\$	600.00
5	To respray front bumper, both front fenders, bonnet, hinges and both front doors.		\$ 4,500.00	\$	3,300.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,152.00	\$	8,802.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 2085 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 60.00	
4	FRONT BUMPER GRILLE	\$ 171.00	
5	FRONT BUMPER CLOSING ELEMENT	\$ 180.00	
6	FRONT BUMPER AIR GUIDE-LH/RH	2 \$ 146.00	
7	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 236.00	\$ 94.00
8	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
9	FRONT BUMPER CARRIER	\$ 702.00	\$ 561.60
10	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	\$ 38.24
11	FRONT BUMPER BRACKET LOCK CARRIER	\$ 118.00	\$ 94.00
12	FRONT BUMPER COVER	\$ 109.00	\$ 87.20
13	RELEASE LEVER	\$ 12.00	\$ 9.44
14	SIGN 'CAUTION'	\$ 12.00	\$ 9.28
15	AIR CONDITIONER STICKER	\$ 7.00	\$ 4.88
16	RADIATOR GRILLE	\$ 972.00	\$ 777.20
17	FRONT FENDER-LH/RH	2 \$ 1,330.00	\$ 532.00
18	FRONT FENDER ATTACHMENT PARTS	2 \$ 90.00	
19	FRONT FENDER CLOSING ELEMENT-LH/RH	2 \$ 88.00	
20	FRONT FENDER BRACKET-LH/RH	2 \$ 62.00	\$ 24.16
SUB-TOTAL SPARE PARTS		\$ 6,544.00	\$ 3,796.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 2085 H.

S/N	Parts Description		Damage Parts & Prices		REMARKS
			S/NETT		
		<i>c/f</i>		\$	3,796.40
21	FRONT FENDER BRACKET DEFORMATION ELEMENT	2 \$	86.00	\$	34.56
22	FRONT FENDER BRACE-LH/RH	2 \$	206.00		
23	FRONT STONE CHUP GUARD	2 \$	88.00	\$	34.56
24	LED HEADLIGHT-LH/RH	2 \$	13,946.00	\$	11,156.80
25	LED HEADLIGHT POWER MODULE	2 \$	1,389.00		
26	LED HEADLIGHT CONTROL UNIT	2 \$	1,314.00		
27	HOSE	2 \$	60.00		
28	COMPENSATING PIECE	2 \$	75.00		
29	LED HEADLIGHT ASSY SPACER	2 \$	70.00		
30	LIFT CYLINDER BRACKET-LH/RH	2 \$	11.00		
31	LIFT CYLINDER-LH/RH	2 \$	368.00	\$	294.40
32	CORRUGATED PIPE	\$	79.00		
33	BONNER	\$	2,163.00	\$	1,730.40
34	BONNET ATTACHMENT PARTS	\$	105.00		
35	BONNET LID HINGE-LH/RH	2 \$	532.00		
36	BONNET IMPACT PROTECTION-LH/RH	2 \$	48.00	\$	37.76
37	BONNET IMPACT PROTECTION-CENTRE	\$	24.00	\$	18.88
38	BONNET COVER-LH/RH	2 \$	106.00		
39	BONNET STRIKER-LH/RH	2 \$	88.00		
40	BONNET LID LOCK	2 \$	376.00		
SUB-TOTAL SPARE PARTS		:	\$ 21,134.00	\$	17,103.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 2085 H.

S/N	Parts Description		Damage Parts & Prices		REMARKS
			S/NETT		
		<i>c/f</i>		\$	17,103.76
41	BONNET BOWDEN CABLE	2	\$ 100.00	\$	40.00
42	LID LOCK CABLE		\$ 64.00		
42	LOCK CARRIER MOUNTING		\$ 891.00	\$	712.80
44	AIR GUDIE-LH/RH	2	\$ 46.00	\$	36.80
45	INNER DUCT-LH/RH	2	\$ 20.00	\$	15.36
46	INNER DUCT- UPPER		\$ 14.00	\$	10.56
47	A/C CONDENSER		\$ 540.00	\$	432.00
48	PRESSURE SENSOR		\$ 170.00		
49	VALVE		\$ 46.00		
50	COOLER FOR COOLANT		\$ 585.00	\$	468.00
51	RUBBER BUSH-LOWER	2	\$ 16.00	\$	12.48
52	RADIATOR INSULATOR-LOWER	2	\$ 22.00	\$	17.44
53	ADDITIONAL COOLER FOR COOLANT-LOWER CENTRE		\$ 455.00		
54	COOLANT CONCENTRATE	4	\$ 133.00	\$	65.28
55	FAN RING		\$ 230.00		
56	RADIATOR FAN CONTROL UNIT		\$ 2,055.00		
57	FRONT WINDOW SLOT SEAL-LH/RH	2	\$ 530.00	\$	212.00
58	BONNET SOUND ABS		\$ 296.00		
59	FRONT NO. PLATE	S/N	\$ 25.00	\$	25.00
60	SUNDRIES		\$ 500.00	\$	80.08
	TOTAL SPARE PARTS	:	\$ 34,416.00	\$	19,231.56
	TOTAL LABOUR CHARGES	:	\$ 12,152.00	\$	8,802.00
	GRAND TOTAL	:	\$ 46,568.00	\$	28,033.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLH 2085 H

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0591/2018/MAS

30 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLH 2085 H, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLH 2085 H**, claimant, **Mr. Gooi Geok Yang**, please find the related document per attached.

1. A copy of the Original invoice no. 85013195 – S\$29,353.91
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLH 2085 H

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6388 2223
Fax: 6388 2223
Email: 6417 6119

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
150 Ubi Road 1
Singapore 408722
Telephone: 6388 2223
Telefax: 6475 1023

Customer Service
Service Appointment: 6388 2223
24-hour Breakdown Service: 9828 1288
Email: customer.care@premiumauts.com.sg

INS TAX INVOICE

Company Reg. No. Y99902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013195 Date : 26/11/2018 Order : SLH2085H Term : 30	Account: 00006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLH2085H (V 31167)	Regn Date: 26/10/2016	Mileage: 46285	WIP No.: 10756
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF41HA029215	Engine: CVN 017989	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (43)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M:	25.00	1.00	25.00
Q	EXC	M: 8888 TO SUPPLY VEHICLE NUMBER PLATE Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M:	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	1100.00	1.00	1,100.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	3250.00	1.00	3,250.00
		M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.			
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119958
State Telephone 6388 7771
Fax 6388 7771
Page 2 of 2

Alexandra Service Centre
281 Alexandra Road
Singapore 119958
Telephone 6388 7771
Fax 6471 1023

INS TAX INVOICE
Company Reg. No. 199302271W
GST Reg. No. 199302271W

Customer Service
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
8888 2323
8888 1233

Invoice: B5013195	Account: A0005 (T 01)
RIG ASIA PACIFIC INSURANCE PTE LTD	RIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
RIG BUILDING	RIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 26/11/2018	
Order : SLH2085H	
Term : 30	

Regn No.: SLH2085H (V 31167) Regn Date: 26/10/2016 Mileage: 46205 WIP No.: 10756

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF41H9029215 Engine: CVN 017989 Dept: U

VSF No.:

You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	REINSTALL ALL PARTS REMOVED			
		M:	600.00	1.00	600.00
		TO REMOVE BOTH FRONT DOOR PANEL TRIMS, DISMANTLE WING MIRROR ASSY AND REPAIR BOTH DOOR CHROME MOLDINGS.			
S	BODYWORK	M:	3300.00	1.00	3,300.00
		TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH FRONT DOOR.			
S	BODYWORK	M:	192.00	1.00	192.00
		TO CARRY OUT DIAGNOSTIC CHECK			
X	ABW0853651 3FZ	GRILLE	1.00	971.50	777.20
X	ABW0941773A	(SK) HEADLIGHT	1.00	6973.00	5,578.40
X	ABW0941774A	HEADLIGHT	1.00	6973.00	5,578.40
X	ABW0821106A	FENDER	1.00	665.00	532.00
X	ABW0807081	COVER	1.00	109.00	87.20
X	ABW0121251K	RADIATOR	1.00	585.00	468.00
X	ABW0816421H	CONDENSER	1.00	540.00	432.00
X	ABW0805594	(SK) CARRIER	1.00	891.00	712.80

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
261 Alexandra Road
Singapore 119938
After Telephone: 6396 2225
Fax: 6396 2225

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6396 2225
Telex: 6435 1023

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer_care@premiumaudi.com.sg
6396 2323
6396 1333

Invoice: 85013195	Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 26/11/2018	
Order : SLH2085H	
Term : 30	

Regn No.: SLH2085H (V 31167) Regn Date: 26/10/2016 Mileage: 46205 WIP No.: 10756

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF41HA029215 Engine: CVN 017989 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (43)

		Details		Qty	Unit Price	Amount
X	A8W0807550A	FOAM INGER	Less 020%	1.00	106.50	85.20
X	A8W0807113	(SK) BRACKET	Less 020%	1.00	782.00	561.60
X	AG A13040M2	PREMITX-COOLANT	Less 020%	4.00	20.40	65.28
X	A8W0823029A	HOOD	Less 020%	1.00	2163.00	1,730.40
X	A8W0807065C GRU	COVER	Less 020%	1.00	1049.00	1,479.20
X	A3D0260749C	WASHER	Less 020%	2.00	3.80	6.08
X	A4E0260749A	WASHER	Less 020%	2.00	3.20	5.12
X	A4M0121275A	MOUNTING	Less 020%	2.00	7.80	12.48
X	A4M0121268A	MOUNTING	Less 020%	2.00	10.90	17.44
X	A8W0121292B	AIR DUCT	Less 020%	1.00	13.20	10.56
X	A8W0807334	SUPPORT	Less 020%	1.00	23.90	19.12
X	A8W0807333	SUPPORT	Less 020%	1.00	23.90	19.12
X	A8W0821468	BRACKET	Less 020%	1.00	30.20	24.16
X	A8W0821092	PLATE	Less 020%	1.00	43.20	34.56
X	A8W0121673A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	A8W0121674A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	A8W0823661D	LEVER	Less 020%	1.00	11.80	9.44
X	A8W0820536	BRACKET	Less 020%	1.00	15.60	12.48

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
251 Alexandra Road
Singapore 119938
Main Telephone: 6345 2221
Fax: 6345 2222

Alexandra Service Centre
251 Alexandra Road
Singapore 119938
Telephone: 6345 2221
Telefax: 6475 1523

INS TAX INVOICE
Company Regn No: 199902271W
GST Reg No: 199902271W

Customer Service
Service Appointment: 6344 2323
24-hour Breakdown Service: 9828 1232
Email: customer.care@premiumaudi.com.sg

Invoices: 85013195	Accounts: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 26/11/2018	
Order : SLH2085H	
Term : 30	

Regn No.: SLH2085H (V 31167) Regn Date: 26/10/2016 Mileage: 46205 WTP No.: 10756
Model: AA SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF41HA029215 Engine: CVN 017989 Dept: U
VSB No.:

You have been assisted by :- UB-Jiayee (43)

		Details		Qty	Unit Price	Amount
X	ABW0023745	COVER	Less 020%	1.00	19.20	15.36
X	ABW0023746	COVER	Less 020%	1.00	19.20	15.36
X	ABW0023125	PROTECTION	Less 020%	1.00	23.60	18.88
X	ABW0023126	(SK) PROTECTION	Less 020%	1.00	23.60	18.88
X	ABW00053998	BOLT	Less 020%	2.00	1.50	2.40
X	ABW0023529E	BOND CABLE	Less 020%	1.00	50.00	40.00
X	ABW0053024B 989	STONEGUARD	Less 020%	1.00	43.20	34.56
X	ABW0007681B 989	GRILL	Less 020%	1.00	117.50	94.00
X	ABW0020582B	COVER	Less 020%	1.00	26.30	21.04
X	ABW0955101	CYLINDER	Less 020%	1.00	184.00	147.20
X	ABW0955102	CYLINDER	Less 020%	1.00	184.00	147.20
X	ABW0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	ABW0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	ABW0121283AA	AIR DUCT	Less 020%	1.00	23.00	18.40
X	ABW0121284AL	(SK) AIR DUCT	Less 020%	1.00	23.00	18.40
X	ABW0007771	BRACKET	Less 020%	1.00	117.50	94.00
X	AN 91093901	RIVET	Less 020%	4.00	0.70	2.24
X	ABW0053204B 2ZT	WINDOW SLD	Less 020%	1.00	265.00	212.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6388 2222
Fax: 6388 2222

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6388 2222
Telefax: 6475 1023

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 192302271W

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6388 2222
6428 1222

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013195 Date: 26/11/2018 Order: SLH2085H Term: 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SLH2085H (V 31167) Regn Date: 26/10/2016 Mileage: 46285 WTP No.: 10756
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF41HA029215 Engine: CVN 017989 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
X	850023124	PROTECTION Less 020%	1.00	23.60	18.88

Parts	19,206.56	Sub-Total	27,433.56
Labour	0.00		
Sublet	8,827.00	7% GST	1,920.35
Menus	0.00		
Lubricant	0.00	Grand Total	29,353.91

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLH 2085 H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0591/2018/KS
2ND JUNE 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi A4 Sedan 1.4 TFSI S
Vehicle Chassis No. : WAUZZZF41HA029215
Vehicle Regn No. : SLH 2085 H
Vehicle Mileage : 39120 KM
Vehicle Owner : Mr. Gooi Geok Yang
Certificate No : 2100487728-01
Policy Excess : S\$642.00 (inclusive GST)
Accident Date : 19th May 2018
Place : Along PIE
Repair Cost : \$ 29,353.91
WIP No. : 10756
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

1228

Date :

2/June/18

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7673863G**

Name
GOOI GEOK YANG

Birth Date: **01 Jun 1976**
Issue Date: **07 Jan 2004**

001075447A



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7673863G



Name

GOOI GEOK YANG

魏若洋

Race
CHINESE

Date of birth
01-06-1976

Country/Place of birth
MALAYSIA

Sex
M

S7673863G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	15 Jul 2002
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	15 Jul 2002

NP 428A



S767234



NRIC No: **S7673863G**



Date of issue
12-07-2017

Address

**APT BLK 490 ADMIRALTY LINK
#14-99
SINGAPORE 750490**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : GOOI GEOK YANG
Period of Insurance : 26 Oct 2017 To 25 Oct 2018
Engine No. : CVN017989
Chassis No. : WAUZZZF41HA029215

Vehicle No. : SLH2085H
Policy No. : 2100487728-01
Endorsement No. :
Issued Date : 21 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

GOOI GEOK YANG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VL

261 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159538

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPEMC

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018		22 May 2018 15:10 Edit Adj Rpt	\$528,033.56 Edit Estimates	\$528,033.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: GOOI GEOK YANG , ID: S7673863G, Tel: +6596917488, Email: ANGLISSANGLISS@GMAIL.COM									
Vehicle Reg. No.: SLH2085H		Date of Loss: 19/05/2018 10:00 - :59 [18 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 3974911262SG		Policy/Cover Note No.: 2100487728 (Comprehensive) Coverage: 26/10/2017 - 25/10/2018							
		Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/06/2018]									
Driver/Custodian: GOOI GEOK YANG (41 / Male), NRIC: S7673863G, Tel: +6596917488									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (09/11/2018): Alert - Adj Mandate Approved (\$528033.56) - SLH2085H - Claim Handler: Mohd Zaway... - AIG_SG (24/05/2018): Alert - Adj Mandate Approved (\$527972.00) - SLH2085H - Claim Handler: Mohd Zaway... - AIG_SG (23/05/2018): SLH2085H / OD / 19/05/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH2085H (3974911262SG)
 OD
 May 19 2018 10:00AM
 [GOOI GEOK YANG]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	23/05/18 15:27	Adjuster Immediate Advice													Load HTML					
2	29/10/18 13:33	Adjuster Immediate Advice													Load HTML					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	23/05/18 15:25	General View													Load JPG	☒				
2	23/05/18 15:25	Chassis Number													Load JPG	☒				
3	23/05/18 15:25	General View													Load JPG	☒				
4	23/05/18 15:25	General View													Load JPG	☒				
5	23/05/18 15:25	General View													Load JPG	☒				
6	23/05/18 15:25	General View													Load JPG	☒				
7	23/05/18 15:25	General View													Load JPG	☒				
8	23/05/18 15:25	General View													Load JPG	☒				
9	23/05/18 15:25	General View													Load JPG	☒				
10	23/05/18 15:25	General View													Load JPG	☒				
11	23/05/18 15:25	General View													Load JPG	☒				
12	23/05/18 15:25	General View													Load JPG	☒				
13	23/05/18 15:25	General View													Load JPG	☒				
14	23/05/18 15:25	General View													Load JPG	☒				
15	23/05/18 15:25	General View													Load JPG	☒				
16	23/05/18 15:25	General View													Load JPG	☒				
17	23/05/18 15:25	General View													Load JPG	☒				
18	23/05/18 15:25	General View													Load JPG	☒				
19	23/05/18 15:25	General View													Load JPG	☒				
20	23/05/18 15:25	General View													Load JPG	☒				
21	23/05/18 15:25	General View													Load JPG	☒				
22	23/05/18 15:25	General View													Load JPG	☒				
23	23/05/18 15:25	General View													Load JPG	☒				
24	23/05/18 15:25	General View													Load JPG	☒				
25	23/05/18 15:25	General View													Load JPG	☒				
26	23/05/18 15:25	General View													Load JPG	☒				
27	23/05/18 15:25	General View													Load JPG	☒				
28	23/05/18 15:25	General View													Load JPG	☒				
29	23/05/18 15:25	General View													Load JPG	☒				
30	23/05/18 15:25	General View													Load JPG	☒				
31	23/05/18 15:25	General View													Load JPG	☒				
32	23/05/18 15:25	General View													Load JPG	☒				
33	23/05/18 15:25	General View													Load JPG	☒				
34	23/05/18 15:25	General View													Load JPG	☒				

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	23/05/18 15:25	General View	 Load JPG	☒
36	23/05/18 15:25	General View	 Load JPG	☒
37	23/05/18 15:25	General View	 Load JPG	☒
38	23/05/18 15:25	General View	 Load JPG	☒
39	23/05/18 15:25	General View	 Load JPG	☒
40	23/05/18 15:25	General View	 Load JPG	☒
41	23/05/18 15:25	General View	 Load JPG	☒
42	23/05/18 15:25	General View	 Load JPG	☒
43	23/05/18 15:25	General View	 Load JPG	☒
44	23/05/18 15:25	General View	 Load JPG	☒
45	23/05/18 15:25	General View	 Load JPG	☒
46	23/05/18 15:25	General View	 Load JPG	☒
47	23/05/18 15:25	General View	 Load JPG	☒
48	23/05/18 15:25	General View	 Load JPG	☒
49	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
50	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
51	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
52	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
53	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
54	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
55	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
56	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
57	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
58	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
59	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
60	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
61	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
62	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
63	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
64	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
65	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
66	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
67	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
68	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
69	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
70	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
71	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
72	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
73	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
74	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
75	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
76	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
77	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
78	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
79	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
80	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
81	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
82	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
83	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
84	29/10/18 10:22	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
86	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
87	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
88	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
89	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
90	29/10/18 10:22	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/05/18 15:21	ESTIMATE	 Load PDF	
2	23/05/18 15:21	IC & DRIVING DOC	 Load PDF	
3	29/10/18 13:27	ESTIMATE MARKED.pdf	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/05/18 10:27	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/05/18 10:23	Accident Photo	 Load JPG	☒
2	21/05/18 10:23	Accident Photo	 Load JPG	☒
3	21/05/18 10:23	Accident Photo	 Load JPG	☒
4	21/05/18 10:23	Accident Photo	 Load JPG	☒
5	21/05/18 10:23	Accident Photo	 Load JPG	☒
6	21/05/18 10:23	Accident Photo	 Load JPG	☒
7	21/05/18 10:23	Accident Photo	 Load JPG	☒
8	21/05/18 10:23	Accident Photo	 Load JPG	☒
9	21/05/18 10:23	Accident Photo	 Load JPG	☒
10	21/05/18 10:23	Accident Photo	 Load JPG	☒
11	21/05/18 10:23	Accident Photo	 Load JPG	☒
12	21/05/18 10:23	Accident Photo	 Load JPG	☒
13	21/05/18 10:23	Accident Photo	 Load JPG	☒
14	21/05/18 10:23	Accident Photo	 Load JPG	☒
15	21/05/18 10:23	Accident Photo	 Load JPG	☒
16	21/05/18 10:23	Accident Photo	 Load JPG	☒
17	21/05/18 10:23	Accident Photo	 Load JPG	☒
18	21/05/18 10:23	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/05/18 10:16	Sketch Plan	 Load JPG	☒
2	21/05/18 10:16	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18009279/ASBE2

Date: 19/12/2018

REFERENCE

Insured/Claimant: GOOI GEOK YANG Policy No: 2100487728
Date of Loss: 19/05/2018 Nature of Claim: OD Claim No: 3974911262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH2085H
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN017989
Reg. Date: 26/10/2016 (Man. Year: 2016) Chassis No: WAUZZZF41HA029215
Colour: Bronze Odometer: 39121 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$128,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,416.00	19,231.56	15,184.44	44.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,152.00	8,802.00	3,350.00	27.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,568.00	28,033.56	18,534.44	39.80
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	45,968.00	27,433.56	18,534.44	40.32
+ GST 7.00/7.00% (S\$)	3,217.76	1,920.35	1,297.41	40.32
Nett Amount (S\$)	49,185.76	29,353.91	19,831.85	40.32

INSPECTION

Date of Assignment: 22/05/2018
Date Inspected: 22/05/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	171.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH/RH	Not Necessary	146.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	O/S Damaged	236.00 FS	*94.00 FS
8	1		*FOAM FILLER PIECE	Cracked	107.00 FS	*85.20 FS
9	1		*FRONT BUMPER CARRIER	Bent	702.00 FS	*561.60 FS
10	2		*FRONT BUMPER SUPPORT - LH/RH	Damaged	48.00 FS	*38.24 FS
11	1		*FRONT BUMPER BRACKET LOCK CARRIER	Cracked	118.00 FS	*94.00 FS
12	1		*FRONT BUMPER COVER	Deformed	109.00 FS	*87.20 FS
13	1		*RELEASE LEVER	Damaged	12.00 FS	*9.44 FS
14	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
15	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*4.88 FS
16	1		*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
17	1		*FRONT FENDER - LH/RH	O/S Buckled	1,330.00 FS	*532.00 FS
18	2		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
19	2		*FRONT FENDER CLOSING ELEMENT - LH/RH	Not Necessary	88.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - LH/RH	O/S Bent	62.00 FS	*24.16 FS
21	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT	O/S Necessary	86.00 FS	*34.56 FS
22	2		*FRONT FENDER BRACE - LH/RH	Not Necessary	206.00 FS	*- FS
23	1		*FRONT STONE CHUP GUARD	O/S Necessary	88.00 FS	*34.56 FS
24	2		*LED HEADLIGHT - LH/RH	Cracked	13,946.00 FS	*11,156.80 FS
25	2		*LED HEADLIGHT POWER MODULE	Not Necessary	1,389.00 FS	*- FS
26	2		*LED HEADLIGHT CONTROL UNIT	Not Necessary	1,314.00 FS	*- FS
27	2		*HOSE	Not Necessary	60.00 FS	*- FS
28	2		*COMPENSATING PIECE	Not Necessary	75.00 FS	*- FS
29	2		*LED HEADLIGHT ASSY SPACER	Not Necessary	70.00 FS	*- FS
30	2		*LEFT CYLINDER BRACKET - LH/RH	Not Necessary	11.00 FS	*- FS
31	2		*LIFT CYLINDER - LH/RH	Cracked	368.00 FS	*294.40 FS
32	1		*CORRUGATED PIPE	Not Necessary	79.00 FS	*- FS
33	1		*BONNET	Distorted	2,163.00 FS	*1,730.40 FS
34	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
35	2		*BONNET LID HINGE - LH/RH	Not Necessary	532.00 FS	*- FS
36	2		*BONNET IMPACT PROTECTION - LH/RH	Necessary	48.00 FS	*37.76 FS
37	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	24.00 FS	*18.88 FS
38	2		*BONNET COVER - LH/RH	Not Necessary	106.00 FS	*- FS
39	2		*BONNET STRIKER - LH/RH	Not Necessary	88.00 FS	*- FS
40	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
41	2		*BONNET BOWDEN CABLE	Necessary	100.00 FS	*40.00 FS
42	1		*LID LOCK CABLE	Not Necessary	64.00 FS	*- FS
43	1		*LOCK CARRIER MOUNTING	Deformed	891.00 FS	*712.80 FS
44	2		*AIR GUIDE - LH/RH	Damaged	46.00 FS	*36.80 FS
45	2		*INNER DUCT - LH/RH	Damaged	20.00 FS	*15.36 FS
46	1		*INNER DUCT - UPPER	Damaged	14.00 FS	*10.56 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*A/C CONDENSER	Bent	540.00 FS	*432.00 FS
48	1		*PRESSURE SENSOR	Not Necessary	170.00 FS	*- FS
49	1		*VALVE	Not Necessary	46.00 FS	*- FS
50	1		*COOLER FOR COOLANT	Bent	585.00 FS	*468.00 FS
51	2		*RUBBER BUSH - LOWER	Necessary	16.00 FS	*12.48 FS
52	2		*RADIATOR INSULATOR - LOWER	Necessary	22.00 FS	*17.44 FS
53	1		*ADDITIONAL COOLER FOR COOLANT - LOWER CENTRE	Not Necessary	455.00 FS	*- FS
54	4		*COOLANT CONCENTRATE	Necessary	133.00 FS	*65.28 FS
55	1		*FAN RING	Not Necessary	230.00 FS	*- FS
56	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,055.00 FS	*- FS
57	1		*FRONT WINDOW SLOT SEAL - LH/RH	O/S Cut	530.00 FS	*212.00 FS
58	1		*BONNET SOUND ABS	Not Necessary	296.00 FS	*- FS
59	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
60	1		*SUNDRIES	Necessary	500.00 FS	*80.08 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	34,416.00	19,231.56
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,100.00	1,100.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	3,250.00
4	TO REMOVE BOTH FRONT DOOR PANEL TRIMS, DISMANTLE WING MIRROR ASSY AND RENEW BOTH DOOR CHROME MOLDINGS	New	600.00	600.00
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT DOORS	New	4,500.00	3,300.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,152.00	8,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >