

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

EQ

Name : Chan Chin Keat

Accident Date : 16-May-18

Vehicle No : JSH 4956

Vehicle Model : Yamaha YZF R25

## Estimated Repair Costs

| Qty | Description             |                         | Amount S(\$) |
|-----|-------------------------|-------------------------|--------------|
|     | <u>List Items</u>       |                         |              |
| 1   | Windshield              | not replaced            | 155.00 ✓     |
| 1   | Top fairing             | cr                      | 285.00 ✓     |
| 1   | Front fender            | cr                      | 90.00 ✓      |
| 2   | Fork inner tubes        | cr                      | 440.00 q     |
| 2   | Fork outer tubes        | cr                      | 480.00 q     |
| 1   | Fork under bracket      | h/s                     | 225.00 x     |
| 1   | Front brake disc        | 4dy                     | 360.00 x     |
| 1   | Front rim shaft         | 11                      | 48.00 q      |
| 1   | Front rim bearing       | 11                      | 38.00 x      |
| 1   | Side mirror -L/H        | blue photo of the upper | 78.00 ✓      |
| 1   | Headlamp                | 24/5/18                 | 380.00 ?     |
| 1   | Lamp stay               |                         | 90.00 ?      |
| 1   | Handle bar -L/H         | 34                      | 125.00 ✓     |
| 1   | Handle bar end          | scr                     | 35.00 ✓      |
| 1   | Hand grip (1 set)       | 11                      | 48.00 x      |
| 1   | Clutch lever            | scr                     | 45.00 ✓      |
| 1   | Front signal            | scr                     | 68.00 ✓      |
| 1   | Headlamp outer garnish  | cr                      | 158.00 ✓     |
| 1   | Side panel -L/H         | cr                      | 135.00 ✓     |
| 1   | Side outer fairing -L/H | cr                      | 225.00 ✓     |
| 1   | Side inner fairing      | cr                      | 185.00 ✓     |
| 1   | Centre inner fairing    |                         | 145.00 ?     |
| 1   | Lower fairing           | cr                      | 190.00 x     |
| 1   | Front footrest -L/H     | 11                      | 50.00 x      |
| 1   | Front footrest bracket  | 11                      | 90.00 x      |
| 1   | Gear pedal              | scr                     | 45.00 ✓      |
| 1   | Rear footrest -L/H      | 11                      | 60.00 x      |
| 1   | Rear footrest bracket   | 11                      | 155.00 x     |
| 1   | Rear tailboard          | cr                      | 105.00 x     |
| 1   | Rear fender             | 11                      | 85.00 x      |
| 1   | Fuel tank side cover    | TR                      | 215.00 x     |
|     |                         |                         | \$ 4,833.00  |
|     |                         | Less 10%                | \$ 483.30    |
|     |                         |                         | \$ 4,349.70  |

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chan Chin Keat

Accident Date : 16-May-18

Vehicle No : JSH 4956

Vehicle Model : Yamaha YZF R25

## Estimated Repair Costs

| <u>Special Nett Items</u> |                          |           |          |
|---------------------------|--------------------------|-----------|----------|
| 1                         | Number plate (1 set)     | net \$ 10 | 28.00    |
| 2                         | Fork oils                | net \$    | 30.00 ✓  |
| 2                         | Fork oil seals           | net \$    | 56.00 ✓  |
| 1                         | Steering cone (1 set)    | net \$    | 95.00 ✓  |
| 1                         | ERP IU                   | 11 \$     | 170.00 X |
| 1                         | Swing arm slider (1 set) | cu) \$    | 80.00 ✓  |
|                           |                          | \$        | 459.00   |

| <u>S/No.</u> | <u>Labour</u>                                |         |        |
|--------------|----------------------------------------------|---------|--------|
| 1            | To provide towing service.                   | \$ 35   | 50.00  |
| 2            | To check wiring and reset headlamp focusing. | \$ 11 X | 80.00  |
| 3            | To provide labour.                           | \$ 300  | 380.00 |
|              |                                              | \$      | 510.00 |

Grand Total

\$ 5,318.70

Dollars: Five Thousand Three Hundred Eighteen And Seventy Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: