

SK Automobile Pte Ltd  
 (Co Reg. No. 201500047H)  
 23 Kaki Bukit Ave 4, #03-01  
 Vicom Inspection Centre (S415933)  
 Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 12-May-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SKS4397T
ADDRESS	:	MODEL	: TOYOTA ALTIS
TEL. NO.	:	CHASSIS NO	: MROS3REH104528071
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	:	XIONG 8121 0478	

**QUOTATION SUMMARY**

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehard</i>	1	\$783.00	\$ 783.00
2	REAR BUMPER SENSOR <i>Pangd</i>	2	\$389.10	\$ 778.20
3	REAR BUMPER REFLECTOR <i>Ne Nr</i>	2	\$125.00	\$ 250.00
4	REAR BUMPER RETAINER <i>Ne Nr</i>	2	\$105.00	\$ 210.00
5	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$459.00	\$ 459.00
6	BOOTLID <i>Dented</i>	1	\$989.00	\$ 989.00
7	BOOTLID REFLECTOR <i>Ne Nr</i>	2	\$456.00	\$ 912.00
8	BOOTLID STOPPER <i>Ne Nr</i>	4	\$75.00	\$ 300.00
9	BOOT LID HINGE <i>Ne Nr</i>	2	\$148.00	\$ 296.00
10	BOOT LID DETECTOR	1	\$302.00	\$ 302.00
11	BOOTLID TOP LOCK <i>Pangd</i>	1	\$398.00	\$ 398.00
12	BOOTLID LOWER LOCK <i>Ne Nr</i>	1	\$40.00	\$ 40.00
13	BOOTLID WEATHERSTRIP <i>ht</i>	1	\$220.00	\$ 220.00
14	BOOTLID LOGO	1	\$75.00	\$ 75.00
15	BOOTLID EMBLEM 'COROLLA' <i>Ne Nr</i>	1	\$65.00	\$ 65.00
16	BOOTLID EMBLEM 'ALTIS'	1	\$75.00	\$ 75.00

530.20  
 Sw  
 +  
 ✓  
 362.70  
 755.90  
 +  
 +  
 +  
 4.  
 323.40  
 +  
 185.50  
 -  
 -  
 -

17	TAILLAMP <i>cracked</i>	2	\$498.00	\$ <del>996.00</del>	891
18	TAILLAMP LOWER BARCKET <i>cracked</i>	2	\$90.00	\$ <del>180.00</del>	74.40
19	REAR NUMBER PLATE LAMP <i>new</i>	2	\$112.00	\$ 224.00	+
20	REAR FENDER INNER COWLING <i>new</i>	2	\$358.00	\$ 716.00	+
21	REAR FENDER INNER TRIM <i>new</i>	2	\$770.00	\$ 1,540.00	+
22	REAR WINDSCREEN MOULDING <i>new</i>	1	\$212.00	\$ 198.00	+
23	REAR END PANEL <i>cracked</i>	1	\$695.00	\$ <del>695.00</del>	595
24	REAR END PANEL TOP GARNISH <i>del</i>	1	\$280.00	\$ <del>280.00</del>	✓
25	REAR FLOOR PANEL TOP BOARD <i>del</i>	1	\$387.00	\$ <del>387.00</del>	✓

5310-10  
3982-57

TOTAL PRICE \$ 11,368.20  
LESS 25% \$ 2,842.05  
SUB TOTAL PRICE \$ 8,526.15

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS <i>new</i>	10	\$ 6.50	\$ <del>65.00</del>	30
3	REAR WINDSCREEN INNER SEAL <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 50.00	+
5	BOOT LID INSULATOR CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	+
6	TAILLAMP CLIPS <i>new</i>	4	\$ 8.00	\$ 32.00	15
7	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+
8	REAR FENDER COWLING CLIPS <i>new</i>	12	\$ 6.50	\$ 78.00	+
9	REAR FENDER INNER TRIM CLIPS <i>new</i>	12	\$ 6.50	\$ 78.00	+
10	REAR FENDER INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	+
11	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	6	\$ 6.50	\$ 39.00	10
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	200

315

TOTAL \$ 1,537.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,500.00	1600	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	1800	
3	TUFF COAT	\$250.00	60	
4	WIRING CHECK	\$80.00	30	

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$150.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	
7	REAR CHASSIS ALIGNMENT	\$250.00	X	
8	TRANFER BOOTLID MECHANISM	\$60.00	✓	
9	CONDUCT WATER LEAKAGE TEST	\$100.00	X.	

**TOTAL**

**\$3,670.00**

2360

TOTAL PARTS COST : \$ 10,063.15  
TOTAL LABOUR COST : \$ 3,670.00  
TOTAL REPAIR COST : \$ 13,733.15

**APPROVED DETAILS**

EXCESS :  
NO. OF WORKING DAYS :  
RE-SURVEY :  
PART BY PART OR LUMP SUM :  
DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

Abianking.  
H/S 14/05/18.

total: 6657.57  
L/S = 5.3K.

07 Days.

5.3K

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: