

INS. CASE OWNER:

Lynthia

CC4 / AXA1800

9285, T1 66352

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Tautikh

DOI:

11/6/2018

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJT 1748P

Name of Insured:

ONG BENG LEONG

Insured Tel No.:

HP: 96001866

Excess Sec II :\$

D.O.A.:

19/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8M00110 / 46899

Policy No.:

6A144182

Make / Model:

BMW

Place of Accident:

ANNA 24 AT ANNA ST 32

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJT 707X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

8/5/18

vinn

SJT 707X - X

SJT 1748P - X

Smartclaim

23/5/18

Called Mr Ong confirm accident details inform TP claim. agree to settle. letter sent out

26/9/18

email workshop liability clear.

File pass to typist to type report

12/12/18

16/11/18, 30/11/18 Seele vendali via SMART

RECEIVED 26 SEP 2018

Need After repair photo X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

16/11/2018

Sent By:

LRF

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

1,930.60

(3 days)

Reduction:

60

%

Email

Call

FINAL SETTLEMENT

Date/Time:

12/12/18

Confirm with:

woline

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

N/L

Repair Cost: (w/loss)

SS

2065.74

Loss of Rental (LOR):

SS

385.20

(3 days)

x 120.00

+ GST

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

Total:

SS

2452.94

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,452.94

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: ASM(AXA)

W

ASSIGNMENT

From:

Date:

11.062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

ST 707X

at Workshop m/s

Performance

of

303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Chua

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

997K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

2-B-3

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

ST 707X

Yr Regn:

2012 Sep.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 528I

c.c 1997.

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

123991

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA XG 32060AX 82710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11/6/18 ellaw

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2808

5/9/18 Confirm 2-B-2 \$1930.60 with 3 working days

(Ad-# 265-66
601)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18009285/wb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 22-05-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJZ 1748P	Veh. Inspected	SJT 707X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/05/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 MAY 2018

@ 6pm

Estimate No. : b1 47020
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Chia Wee Jin Christopher
65 Jalan Leban

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 577602

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528iA	0

DESCRIPTION

Replace front M bumper and remove attachment etc include
knock on accident dent

Spray painting front bumper

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

Sundries.

Body outer quoting sealant from outside workshop

VALUE

765 850 1,275.00

840.60 934 1,038.00

135 150 177.00

net 40.00

Any receipt? 150.00

Total Labour 1: 2,680.00

DESCRIPTION

GRILLE AIR INLET RH (M)
COVERING TOWING FRT PRIMED (M)
COVERING RH (M)
FRT TRIM COVER BUMPER PRIMERED (M-S)
BUMPER RIVET
SET MOUNTS PDC SENSOR FRT (M)
EMBLEM GROMMET
BMW EMBLEM

QTY	PRIC
1	63.30
1	55.70
1	46.65
1	1,533.10
2	0.50
1	31.65
2	0.80
1	69.50

VALUE

x 63.30

x 55.70

x 46.65

R 1,533.10

x 1.00

x 31.65

x 1.60

x 69.50

Total Parts : 1,802.50

4482.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47020
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chia Wee Jin Christopher
65 Jalan Leban

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 577602

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To supply Quartz coating sealant to front bumper (See owner's receipts)	150.00	0.00	150.00 <i>nel</i>
--	--------	------	-------------------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	150.00
Total Parts :	
Total Labour & Parts :	150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47020
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chia Wee Jin Christopher
65 Jalan Leban

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 577602

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the front bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident.	850.00	10.00	765.00	
To spray paint front bumper	934.00	10.00	840.60	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	10.00	135.00	
# To supply Cquartz coating sealant to front bumper (See owner's receipts)	150.00	0.00	150.00	
Sundries	40.00	0.00	40.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour :	1,930.60
Total Parts :	0.00
Total Labour & Parts :	1,930.60
Deduction for Excess :	0.00
Total Repair Costs less Excess:	1,930.60
GST @7%:	135.14
Grand Total :	2,065.74



Supremo Car Detailer Pte Ltd

7 Soon Lee Street, iSpace,
#02-01 S(627608)
reach@supremocar.com
+65 8828 9398 | +65 8239 2922
UEN : 201530846H

TAX INVOICE

Invoice No : 2663
Date : 16/06/2018

Billing To : Mr Chris
65 Jalan Leban, Singapore,
Singapore

Vehicle Plate BMW [SJT 707 X]

Description	Quantity	Rate	Amount
CQuartz Restoration & Recoating Service	1	\$150.00	\$150.00
Front bumper			
	Subtotal		\$150.00
	Total		\$150.00
	Paid		\$0.00
Balance Due			\$150.00

Comments

All cheques should be crossed and made payable to : Supremo Car Detailer Pte Ltd

Terms and Conditions

These terms apply to all contracts for the sale of goods by Supremo Car Detailer Pte Ltd.

The customer acknowledges that Supremo Car Detailer Pte Ltd or any of its employees will not be liable for any damage after service is rendered, accepted and paid in full by the customer.

Prices determined at the time of order and, prior to the payment of the deposit, are subject to change without notice.



Supremo Car Detailer Pte Ltd

7 Soon Lee Street, iSpace,
#02-01 S(627608)
reach@supremocar.com
+65 8828 9398 | +65 8239 2922
UEN: 201530846H

TAX INVOICE

Invoice No : 2611
Date : 11/05/2018

Billing To : Mr Chris
65 Jalan Leban, Singapore,
Singapore

Vehicle Plate [SJT 707 X] [SJY 9366 K]

Description	Quantity	Rate	Amount
Full CQuartz Maintenance Session	2	\$250.00	\$500.00
		Subtotal	\$500.00
		Total	\$500.00
		Paid	\$0.00
Balance Due			\$500.00

Comments

All cheques should be crossed and made payable to : Supremo Car Detailer Pte Ltd

Terms and Conditions

These terms apply to all contracts for the sale of goods by Supremo Car Detailer Pte Ltd.

The customer acknowledges that Supremo Car Detailer Pte Ltd or any of its employees will not be liable for any damage after service is rendered, accepted and paid in full by the customer.

Prices determined at the time of order and, prior to the payment of the deposit, are subject to change without notice.



Tel: 8828-9398

NO: 1737

HP: 96605030

Address: Bmw 520 817 707X

* Application Done: 14/10/16

In discovery of any defect in service or goods, The customer must immediately notify the company prior to acceptance of this invoice.

\$1460

Balance

Authorised Signature

Received By

Authorized Signature

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47020
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528ia	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 11/6/18 09:11am Excess S\$ _____

Surveyor's Name Tan Jia Min Sign [Signature]

Surveyor's Tel 97498749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tan.jia.min@pml.com.sg

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	2,680.00
Parts	:	1,802.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.78
Grand Total	:	<u>4,796.28</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559K GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



11/6/2018
morning 4 repin
Hertz

GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 MAY 2018

@ 6pm

Estimate No. : b1 47020
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Chia Wee Jin Christopher
65 Jalan Leban

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 577602

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528iA	0

DESCRIPTION

Replace front M bumper and remove attachment etc include
knock on accident dent

850 1,275.00

Spray painting front bumper

934 1,038.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries.

✓ 40.00

Body outer quoting sealant from outside workshop

? 150.00

call informed supplier need to (Tafite Ltk) produce invoice receipt for submission

Any receipt?

Total Labour 1: 2,680.00

DESCRIPTION

GRILLE AIR INLET RH (M)
COVERING TOWING FRT PRIMED (M)
COVERING RH (M)
FRT TRIM COVER BUMPER PRIMERED (M S
BUMPER RIVET
SET MOUNTS PDC SENSOR FRT (M)
EMBLEM GROMMET
BMW EMBLEM

QTY	PRIC	VALUE
1	63.30	X63.30
1	55.70	X55.70
1	46.65	X46.65
1	1,533.10	Rx1,533.10
2	0.50	? 1.00
1	31.65	? 31.65
2	0.80	ui 1.60
1	69.50	ni 69.50

Total Parts : 1,802.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47020
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528iA	0

Claims OD / <u>3rd</u> Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>11/6/18 2:11pm</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jie Min</u>	Sign <u>Tan Jie Min</u>
Surveyor's Tel <u>97495749</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail <u>tan.jie.min@pml.com.sg</u>	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	2,680.00
Parts	:	1,802.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.78
Grand Total	:	4,796.28

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **




Service Request Details

Claim

S8M00110

Reference

None 

Loss Date

May 19, 2018

Request Date

May 22, 2018

Due Date

May 30, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

22052018 @ 11:57am
Caroline vehnot in
Email to Wlop

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJT707X

Make

TPVD BMW

Service Address

Primary Contact/Insured

ONG BENG LEONG
73 SPRINGLEAF GARDEN, 788222, Singapore

MICHAEL@CAPSTONE.SG

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Saturday, 12 January 2019 3:05 PM
To: PBSP
Cc: Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: RE: PRE-SIGNED DV - SJT707X AND SJZ1748P ON 19/05/2018 *LKK REF: CC4/ASM18009285/T1wb3s2
Attachments: DV SJT 707X.pdf

WITHOUT PREJUDICE

LKK REF: CC4/ASM18009285/T1wb3s2
Your Ref: SJT 707X

Dear Caroline,

We refer to the above matter.

Please be informed that we just receive the mandate approval from our principal.

We hereby confirmed settlement as follow:-

1. Cost of Repair	S\$ 2,065.74
2. Loss of Rental (\$120.00 x 3 days)+7%gst	S\$ 385.20
3. GIA search fee	S\$ 2.00
	S\$ 2,452.94

Please duly sign the DV enclosed and return for payment processing.

In the meantime, we appreciate if you could furnish us a copy of the after repair photo for our file record.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.


In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

PR

Hsiao Tong (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 7 January 2019 4:26 PM
To: Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: Re: PRE-SIGNED DV - SJT707X AND SJZ1748P ON 19/05/2018

URGENT REMINDER

From: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Sent: Friday, 30 November 2018 1:27:22 PM
To: PBSP
Subject: RE: PRE-SIGNED DV - SJT707X AND SJZ1748P ON 19/05/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Caroline,

We refer to the email below .

We are pending our principal mandate approval.

We will get back to you for an update/offer in due course

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 30 November, 2018 12:25 PM
To: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Subject: Fw: PRE-SIGNED DV - SJT707X AND SJZ1748P ON 19/05/2018

GENTLE REMINDER

From: PBSP

Sent: Wednesday, 14 November 2018 5:21 PM

To: Vivian Lau; CS A Team

Subject: Re: PRE-SIGNED DV - SJT707X AND SJZ1748P ON 19/05/2018

From: PBSP

Sent: Wednesday, 14 November 2018 4:39:58 PM

To: Vivian Lau; CS A Team

Subject: PRE-SIGNED DV - SJT707X AND SJZ1748P ON 19/05/2018

Dear Sirs

Payment reminder (pre-signed dv enclosed).

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601



Re:RE: S8M00I10- mandate approval

Type

🔗 Question

Message

APPROVED

Reply



S8M00I10- mandate approval

Type

🔔 Question

Message

Dear Cynthia, We refer to the above matter. Enclosed is IA Liability(TP) 100% Proposed repair cost \$2,065.74 Loss of use no. of days Loss of rental \$385.20 no. of days 3daysx \$ 120.00 +GST Loss of income no. of days LTA search fees \$2.00 Others Proposed Total \$2,452.94 Thank you Vivian Lau (16.11.18)

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJZ 1748P (Insd veh)	Model:	B.M.W. 528i
	SJT 707X (TP veh)		
Date of Accident:	19/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,796.28
Final Repair Cost	:	\$	2,065.74
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	385.20 3 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	2,452.94

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LTD	:	\$ 2,452.94

NUR SHAQILAH BTE ABDOL
WAHAB

22/01/2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009285/T1fb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 22-01-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 1748P	Veh. Inspected	SJT 707X
Policy No.	GA144182	Coverage (\$)	0.00
Claim No.	S8M00I10	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 528i	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAXG32060DX82710	Colour	BLACK
Odometer	123991	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40R19	MICHELIN	6 mm
L/H Front Tyre	245/40R19	MICHELIN	6 mm
R/H Rear Tyre	245/40R19	MICHELIN	6 mm
L/H Rear Tyre	245/40R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/05/2018	Inspection Date	11/06/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 707X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	GRILLE AIR INLET RH (SN) (CONSISTENT)	NOT NECESSARY	63.30	-
1	COVERING TOWING FRT PRIMED (SN) (CONSISTENT)	NOT NECESSARY	55.70	-
1	COVERING RH (SN) (CONSISTENT)	NOT NECESSARY	46.65	-
1	FRT TRIM COVER BUMPER PRIMED (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,533.10	-
2	BUMPER RIVET (SN) (CONSISTENT)	NOT NECESSARY	1.00	-
1	SET MOUNTS PDC SENSOR FRT (SN) (CONSISTENT)	NOT NECESSARY	31.65	-
2	EMBLEM GROMMET (SN) (CONSISTENT)	NOT NECESSARY	1.60	-
1	BMW EMBLEM (SN) (CONSISTENT)	NOT NECESSARY	69.50	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			1,842.50	40.00
LABOUR				
REPLACE FRONT M BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT. INCLUSIVE OF THE REPAIR OF FRT TRIM COVER BUMPER PRIMED.			1,275.00	765.00
SPRAY PAINTING FRONT BUMPER.			1,038.00	840.60
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.			177.00	135.00
BODY OUTER QUOTING SEALANT FROM OUTSIDE WORKSHOP.			150.00	150.00
			2,640.00	1,890.60
GRAND TOTAL			4,482.50	1,930.60
RECOMMENDED COST OF REPAIRS				1,930.60

Report Ref No. CC4/ASM18009285/T1fb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.