

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 8480B

| Qty | Description of Parts   | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted<br>(\$) |
|-----|--|-------------------------|-------------------------------|----------------------|
|     | REPLACEMENT OF PARTS   |                         |                               |                      |
| 1   | REAR SLIDING DOOR RH (CONSISTENT)  | BUCKLED                 | 1,320.00                      | 1,320.00             |
| 1   | REAR SLIDING DOOR MOTOR RH (CONSISTENT)  | JAMMED                  | 980.00                        | 980.00               |
| 1   | REAR BUMPER (CONSISTENT)   | TO REPAIR SEE<br>LABOUR | 1,055.00                      | -                    |
| 1   | REAR FENDER RH (CONSISTENT)  | TO REPAIR SEE<br>LABOUR | 1,255.30                      | -                    |
| 1   | REAR WHEEL HUP LH (CONSISTENT)   | NOT NECESSARY           | 260.00                        | -                    |
| 1   | REAR WHEEL HUP BEARING LH (CONSISTENT)   | NECESSARY               | 222.00                        | 222.00               |
| 1   | REAR SHOCK ABSORBER LH (CONSISTENT)  | NOT NECESSARY           | 530.00                        | -                    |
| 1   | REAR AXLE (CONSISTENT)   | NOT NECESSARY           | 1,800.00                      | -                    |
|     | LESS 20% DISCOUNT  |                         | -1,484.46                     | -504.40              |
|     |  |                         | 5,937.84                      | 2,017.60             |
|     | SPECIAL NETT ITEMS   |                         |                               |                      |
| 1   | REAR BUMPER CLIPS (SN) (CONSISTENT)  | NECESSARY               | 20.00                         | 20.00                |
| 2   | FRONT FENDER SEALANT @\$60.00 (SN) (CONSISTENT)  | NOT NECESSARY           | 120.00                        | -                    |
| 1   | SET TYRE RIM (SN) (CONSISTENT)   | CUT                     | 800.00                        | 300.00               |
| 1   | WHEEL TYRE (SN) (CONSISTENT)   | NOT NECESSARY           | 350.00                        | -                    |
|     |  |                         | 1,290.00                      | 320.00               |
|     | LABOUR   |                         |                               |                      |
|     | PANEL BEATING ,REMOVING AND REPLACING<br>PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER<br>RH AND REAR BUMPER. |                         | 1,200.00                      | 500.00               |
|     | SPRAY PAINTING TO AFFECTED AREA.   |                         | 1,000.00                      | 600.00               |
|     | WIRING CHECK .   |                         | 250.00                        | 30.00                |
|     | FOUR WHEEL ALIGNMENT.  |                         | 120.00                        | 60.00                |
|     | TO REMOVE AND REFIX REAR UNDERCARRIAGE.  | NOT NECESSARY           | 250.00                        | -                    |
|     | TO PRESS REAR WHEEL BEARING.   |                         | 150.00                        | 50.00                |
|     | TO TRANSFER REAR DOOR MECHANISM .  |                         | 150.00                        | 60.00                |
|     |  |                         | 3,120.00                      | 1,300.00             |
|     | GRAND TOTAL  |                         | 10,347.84                     | 3,637.60             |

Report Ref No. CC4/ASM18009297/Gps3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 2,700.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  |          |

Report Ref No. CC4/ASM18009297/Gps3q2

XING GUO QIANG

M.MATAI, AMSAE-A

**Automotive Assessor** 

mont

**HO LEONG CHUAN** 

**Automotive Assessor**