

ASS. REC. BY

REF (S/FCT) 18009300/Urd3n2

Special Instruction

Surveyor  
CWS

Marcus

ASSIGNMENT (Office)

From (Person):

Laurene juw

of

pef

Date/Time:

23/5/18 @ 2:44pm

Estimated Cost:

Bill to:

OD  WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 60144

Insured:

SHD 88504

at Workshop in/s

Pegasus Engineering  
51 Defu Lane 10

Tel:

68 58 1846

of

Policy No:

Claim No:

D18004124MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

22/05/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

2:48pm @ 23/5/18

Person Contacted:

Alvin

Vehicle  IN / OUT

Date/Time

Action/Instruction

( ) Estimate

Revert this email

(08/11/13) waf  
ASS. REC. BY: Marcus

REF: fci/

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / P / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SAP60144  
at Workshop m/s: Perkasus  
of \_\_\_\_\_  
Insured: SMD 8804  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SAP60144 Yr Regn: 6, 17  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CAI  
Make: Toyota vios C.C. 1496  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 81371 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MHFB29F3102011574  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 195/50R16  
R: \_\_\_\_\_

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front 6 mm R/Bal. 6 mm  
R/Bal. 6 mm L/Bal. 6 mm  
L/Bal. 6 mm D.O.A. 22/5/18 D.O.I. 22/5/18  
Survey held at \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
CA / PR Seen: 3 Consistent?: Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear O/S  
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction  
22/5/18 confirmed 2/5 @ 1250 with william

Red: 85467.15, 81%

Just follow assignent date & inspection date.

RECEIVED 24 MAY 2018

Date/Time, File Pass to?  : Preli. Report  
1) typist  : Final Report

Days Of Repair: 3  
Resurvey No. of Trip: -

Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_  
Report Format: TP  
Lump Sum / H.B.I: (\$ 1250)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	<u>145</u>
Transportation:	<u>50</u>
Photos	<u>42</u>
Others	
TOTAL	<u>237</u>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009300/Urd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-05-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 8850U	Veh. Inspected	SLP 6014U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	22/05/2018	Inspection Date	22/05/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D18004124MFSH

Our Ref: CS/FCI18009300/Urb

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 6014U .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.05.2018 at the premises of M/s PEGASUS ENGINEERING & TRADING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,717.15</u> .
Revised Estimate Amount	: S\$ <u>1,585.58</u> .
"Check" Items Amount	: S\$ <u>          </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:  
The vehicle sustained damages  
at rear o/s portion.



Yours faithfully  
MARCUS  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	23-05-2018	<b>Our Ref No.</b> D18004124MFSH
<b>Accident Date</b>	22-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD8850U	<b>Third Party Vehicle.</b> SLP6014U
<b>Survey Location</b>	51 DEFU LANE 10	
<b>Contact Person.</b>	ALVIN LOW	
<b>Contact No.</b>	68581846/ 0	<b>Fax No.</b> 68476070
<b>Survey Type</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PEGASUS ENGINEERING & TRADING PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	LURENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240679)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18004124MFSH	<b>Policy No</b>	D-18088937MFSH	<b>Claimant S.No &amp; Name</b>	1 & PEGASUS PTE LTD
<b>Workshop Name</b>	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	<b>Survey Location &amp; Contact Details</b>	51 DEFU LANE 10 <b>Mobile:</b> 0 , <b>Phone:</b> 68581846 , <b>Fax:</b> 68476070 <b>EmailId:</b> CLAIMS@PEGASUSENGR.G.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
<b>Insured Name</b>	CITYCAB PTE LTD	<b>Insured Vehicle No</b>	SHD8850U	<b>TP Vehicle No</b>	SLP6014U
<b>PRI Recieved Date</b>	23-05-2018 05:02:46 PM	<b>Surveyor Appointed Date</b>	23-05-2018 02:43:20 PM	<b>Surveyor Accept Date</b>	23-05-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	23-05-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

### Vehicle Details

Vehicle No.: SLP6014U

Vehicle to be Exported: Yes

Intended De-registration Date: 22 May 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS 1.5E CVT

Primary Colour: Grey

Manufacturing Year: 2017

Engine No.: 2NRX156846

Chassis No.: MHFB29F3102011574

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$12,855.00

Original Registration Date: 12 Jun 2017

First Registration Date: 12 Jun 2017

Transfer Count: 0

Actual ARF Paid: \$7,855.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Jun 2027

PARF Rebate Amount: \$5,891.00

### Intended COE Rebate Details

COE Expiry Date: 11 Jun 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$51,600.00

COE Rebate Amount: \$41,280.00

**Total Rebate Amount: \$47,171.00**

The information contained herein is correct as at 22 May 2018

OK

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

*not allowed*

<b>From :</b>
<b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 SINGAPORE 539216
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

<b>Customer :</b>
<b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : <i>confirmed</i> Tel : <i>with Marcus</i> Fax : <i>22.05-0078</i>

*n/s # 1250/5*  
*30 days*  
*21/5/18*  
*take photo after repair*

<b>Quotation No :</b> QO18/05-1236	<b>Quotation Date :</b> 22/05/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No :</b> SLP6014U	<b>Chassis No :</b> MHFB29F3102011574	<b>Third Party Insurer :</b>
<b>Model :</b> VIOS	<b>Date of Accident :</b>	
<b>Remarks :</b> TP INSURER: MSFCI, TP INSURED VEHICLE NO: SHD8850U, DOA: 22.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
1	O/S REAR FENDER <i>11</i>	1	969.7000	969.70	X
2	O/S REAR END PANEL <i>1</i>	1	694.7000	694.70	X
3	REAR FENDER INNER LINER <i>11</i>	1	395.1000	395.10	X
4	O/S REAR LAMP ASSY <i>11</i>	1	375.8000	375.80	X
5	REAR BUMPER <i>Dis</i>	1	504.0000	504.00	✓
6	REAR BUMPER REINFORCEMENT <i>cut</i>	1	323.3000	323.30	✓
7	REAR BUMPER SIDE RETAINER <i>cut o/s</i>	2	116.3000	232.60	inc
8	REAR BUMPER REFLECTOR <i>one o/s</i>	2	130.5000	261.00	inc
9	REAR BUMPER CLIPS <i>Rec</i>	8	5.0000	40.00	✓
10	LESS 25% (ITEM 1 - 9)	1	-949.0500	-949.05	
11	REAR BUMPER PARKING SENSOR <i>11</i>	1	450.0000	450.00	X
12	REAR WINDSCREEN GLASS SEALANT <i>11</i>	1	180.0000	180.00	X
13	REAR WINDSCREEN GLASS INNER SPONGE SEAL <i>11</i>	1	100.0000	100.00	X
14	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	80.0000	80.00	20
15	TO REMOVE AND REFIT REAR WINDSCREEN GLASS. <i>11</i>	1	180.0000	180.00	X
16	TO RUST-PROOFING OF THE AFFECTED AREAS. <i>11</i>	1	150.0000	150.00	X
17	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	130.0000	130.00	50
18	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,200.0000	1,200.00	280
19	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	1,400.0000	1,400.00	400

1114.10  
835.57  
1585.57  
1268.46

*1-1114.1*  
*257*  
*835.57*  
*1585.57*

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
<b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 SINGAPORE 539216
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

<b>Customer :</b>
<b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

<b>Quotation No :</b> QO18/05-1236	<b>Quotation Date :</b> 22/05/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No :</b> SLP6014U	<b>Chassis No :</b> MHFB29F3102011574	<b>Third Party Insurer :</b>
<b>Model :</b> VIOS	<b>Date of Accident :</b>	
<b>Remarks :</b> TP INSURER: MSFCI, TP INSURED VEHICLE NO: SHD8850U, DOA: 22.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<b>Sub Total</b>	6,717.15
<b>Discount(25.00%)</b>	(949.05)
<b>GST(7.00%)</b>	403.77
<b>Total (SGD)</b>	6,171.87

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009300/Urd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8850U	Veh. Inspected	SLP 6014U	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004124MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	23/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFB29F3102011574	Colour	GREY	
Odometer	81371	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/05/2018	Inspection Date	22/05/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 6014U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	O/S REAR FENDER	NOT NECESSARY	969.70	-
1	O/S REAR END PANEL	TO REPAIR SEE LABOUR	694.70	-
1	REAR FENDER INNER LINER	NOT NECESSARY	395.10	-
1	O/S REAR LAMP ASSY	NOT NECESSARY	375.80	-
1	REAR BUMPER	DISTORTED	504.00	504.00
1	REAR BUMPER REINFORCEMENT	BENT	323.30	323.30
2	REAR BUMPER SIDE RETAINER @\$116.30	O/S BENT	232.60	116.30
2	REAR BUMPER REFLECTOR @\$130.50	O/S CRACKED	261.00	130.50
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
	LESS 25% DISCOUNT		-949.05	-278.53
			2,847.15	835.57
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER PARKING SENSOR (SN)	NOT NECESSARY	450.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN GLASS INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			730.00	-
<b>LABOUR</b>				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	20.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		130.00	50.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF O/S REAR END PANEL.		1,200.00	280.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	400.00
			3,140.00	750.00
<b>GRAND TOTAL</b>			<b>6,717.15</b>	<b>1,585.57</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00
---	--	--	----------

Report Ref No. CS/FCI18009300/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.