

ASS. REC. BY:

REF: CS/FCU18009302/Ktbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCI Date/Time: 22052018 3:21pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GGG 2031L Insured: SHC 8728X

at Workshop m/s Optima Werkz Tel: 6484 9919

of 9A Serungoon North Ave 5

Policy No: Claim No: D18003057 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 17042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp 31.05.2018 @ 2pm H.O.D. Endorsement:

Date/Time: 22052018 3:28pm Person Contacted: Lily Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GGG 2031L - X
	SHC 8728X - NS / INC 18007236 / Ktbn2 D.O.A: 17042018
	Client (Tp) dont want to repair the car.
	Submit Prel Report

REF: FCL

ASSIGNMENT

From: Date: 31/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 2031L

at Workshop no/s: Optima Werkz
of: 9A Serangoon North Ave 5

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

2pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 865k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lump Sum: 1.B.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

1/6 File pass to Catherine

Veh No: GBC 2031L Tr Reg: 06 17

Type: M/Car / M/Cycle / Bus / van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Hiace 2P82

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 1774P T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal: 8 mm

L/Bal: 8 mm

D.O.A: 17/4/18 D.O.I: 3/15/18

Survey held at: ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to: ☒ Preli. Report26/10 Typist ☒ Final Report

Date/Time: File Return to:

Days Of Repair: 2

Resurvey No. of Trip:

Report Format:

Lump Sum / L.B.1 / 15

TP

Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Tech. Insp: \$☐ Workshop: \$

Survey Fee: 100

Transportation: 50

J. S. P. S. 10

Photo: 10

Other: 10

Total: 160

RECEIVED 29 OCT 2018

MOTOR SURVEY ASSIGNMENT

Date	19-04-2018	Our Ref No. D18003057MFSH
Accident Date	17-04-2018	Claim Type. Third Party
Insured Vehicle	SHC8728X	Third Party Vehicle. GBG2031L
Survey Location	6 KUNG CHONG ROAD	
Contact Person.	LILY LOI	
Contact No.	64721313/ 0	Fax No. 64722112
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	OPTIMA WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Lily.loi@ow.sg
Sent: Friday, 26 October 2018 9:06 AM
To: Denise Tay (LKKAUTO)
Subject: RE: GBG2031L / FIRST CAPITAL / DOA:17042018

Dear Denise,

This client don't want to repair the car.
Therefore we close case at our side.
Thank you.

--

Thanks & Best Regards,

Lily Loi (Ms)
Motor Claims Department
Serangoon Branch

OPTIMA WERKZ PTE LTD

6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 |
9A Serangoon North Avenue 5 Singapore 554500 | Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011 |
551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 |

www.ow.sg

www.facebook.com/optimawerkz

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Thursday, 25 October, 2018 3:37 PM
To: Lily.loi@ow.sg
Subject: GBG 2031L / FIRST CAPITAL / DOA:17042018

Dear Lily,

Can check for me if this case has been repair? Can finalized? Still claiming?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 21 May 2018

Third Party Insurer: FIRST CAPITAL

Vehicle No: GBG2031L

Third Party Veh No: SHC8728X

Model: TOYOTA HIACE

Date of Accident: 17 APR 2018

Chassis:

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	<i>Ref / Lm</i>	\$427.80 ✓
1	REAR BUMPER RH SIDE RETAINER		<i>2m</i> \$36.70 X
8	REAR BUMPER CLIPS	\$5.71	<i>nn</i> \$45.68 ✓
SUB TOTAL			\$510.18
Less 25%			-\$127.55
PARTS TOTAL			\$382.64

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$400.00 *30d*

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$400.00 *25cl*

TO TUFF KOTE / ANTI-RUST

nn \$40.00 X

LABOUR TOTAL \$840.00

WINSON

TOTAL \$1,222.64

*Not Notified
Resurvey After Paint
2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009302/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8728X	Veh. Inspected	GBG 2031L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003057MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010215985	Colour	WHITE	
Odometer	17749	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	BRIDGESTONE	8 mm	
L/H Front Tyre	195/80 R15	BRIDGESTONE	8 mm	
R/H Rear Tyre	195/80 R15	BRIDGESTONE	8 mm	
L/H Rear Tyre	195/80 R15	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2018	Inspection Date	31/05/2018	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2031L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / CUT	427.80	427.80
1	REAR BUMPER RH SIDE RETAINER	SERVICEABLE	36.70	-
8	REAR BUMPER CLIPS @\$5.71	NECESSARY	45.68	45.68
	LESS 25% DISCOUNT		-127.54	-118.37
			382.64	355.11
LABOUR				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.		400.00	300.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		400.00	250.00
	TO TUFF KOTE/ANTI-RUST.	NOT NECESSARY	40.00	-
			840.00	550.00
GRAND TOTAL			1,222.64	905.11
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				905.11

Report Ref No. CS/FCI18009302/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.