

ASS. REC. REC.

REF CS3/AIG18009303/N 24d3/2 Serial Instruction:

Surveyor:

N/A

ASSIGNMENT (Office)

From (Person):

Elin Lee Ying

of

AIG

Date/Time: 22/5/18 @ 1:43pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 75064

Insured:

GBG 84322

at Workshop m/s:

Yap Lee Motor

Tel:

6844 1555

of

1 Kaki Bkt Ave 6 # 01-26 Autobay

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vehl:

(Client's Record)

D.O.A. 18/05/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

1:58pm 02/5/18

Person Contacted:

Shirley

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (x) Estimate

GBA 7506 H-X


GBG 84322 - cc6/AIG 18009303/Ueb3

DoA: 18/5/18

After repair 25/05/2018

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: GBA 7506 H
 at Workshop n/s: YAP LEE MOTOR
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Sal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBA 7506 H Page: 19 NOV 2007
 Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: TOYOTA DYNA 2982
 Colour: BLUE Insured Std / Nil / NA
 Sp. Reading: 262,979 Paid: Insured / Std / Nil / NA
 Eng No: _____
 C No: JTFAT35 Y50300 1307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: GOODRIDGE 195 R15 (FR RIGHT), YOKOHAMA
 R: FALKEN 155 R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5(5)</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5(5)</u> mm
D.O.A. <u>18/5/18</u>	D.O.I. <u>22/5/18</u>

Survey held at: YAP LEE MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
28/5/18 SUBMIT DAR Report.

RECEIVED 30 MAY 2018

Date/Time File Pass to: ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp 5
☐ : Inter. Insp 5
☐ : Tech. Insp 5
☐ : Resurvey 5

Survey Fee
 Transportation

Report Format :
 Lump Sum / L.B. : 5

180
 20
 200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
GBG8432Z AND GBA7506H ON 18/05/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 22/5/2018 1:43:31 PM

Attachments:  Notice to AIG to conduct PRI (YLM)GBA7506H.PDF  FaxC14F.TIF

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



883 North Bridge Road
#19-05 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No: 201333127N)

Our Ref : CY(YLM)GBA7506H(AC)hh
Please email to: helen@yoga-legal.com
Your Ref : Vehicle GBG8432Z

21st May 2018

The Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD

By Email

Attention: Lim Sheng Yang

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING GBA7506H, SLW9086E & GBG8432Z ON 18.05.2018 @ 13:15 HRS
ALONG DEFU LANE 10 EXITING MAIN ROAD

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose M/r. Alan Cheong K.H of M/s. C L Appraiser Pte Ltd to conduct a Pre-Repair inspection.


Please be informed that the said vehicle can be inspected at:

Name of workshop	:	M/s. Yap Lee Motor
Address	:	1 Kaki Bukit Avenue 6 #01-26 Autobay @ Kaki Bukit, Singapore 417883
Contact person	:	Shirley Lee
Telephone number	:	68441555
Fax	:	68441311

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a "single joint expert".

If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.

Yours faithfully,


C. Yogarajah LLC

c.c. clients
Enthral Engineering Pte Ltd
c/o Yap Lee Motor
By Fax: 68441311 (Attention: Ms Shirley Lee)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. **Disclaimer:** Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

YOGARAJAH LLC

ADVOCATES & SOLICITORS

883 North Bridge Road
#19-05 Southbank
Singapore 198765
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No. 201333127N)

Our Ref : CY(YLM)GBA7506H(AC)hh
Please email to: helen@yogarajah-legal.com
Your Ref : Your insured vehicle SLW9086E (NTUC)
Your insured vehicle GBG8432Z (AIG)

21st May 2018

Yeoh Wei Ling / Lim Chwee Yee
c/o The Motor Claims Department
NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Jue Man Hing Ship's Laundry Management Services
c/o The Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD

By Fax: 6338 1604

By Fax: 68357416

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING GBA7506H, SLW9086E & GBG8432Z ON 18.05.2018 @ 13:15 HRS
ALONG DEFU LANE 10 EXITING MAIN ROAD

We are instructed by Entrhal Engineering Pte Ltd to notify you of a road traffic accident on 18th May 2018 at about 13:15 hours along Defu Lane 10 Exiting main road involving our client's vehicle GBA7506H and vehicles number SLW9086EK and GBG8432Z driven by you /your respective insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

C. Yogarajah LLC

Enc
c.c. clients, Entrhal Engineering Pte Ltd
c/o Yap Lee Motor
By Fax: 68441311
(Attention: Ms Shirley Lee)

For Surveyor Please Initial here after completion of pre-repair inspection. Thank you. Name: Signature: Date & Time of Pre-repair inspection: / /
--

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to the sender and then delete it from your system. Do not read, copy, use or circulate the information contained in this message. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, the sender does not accept any liability for the accuracy or completeness of the information contained in this message. If you wish to receive this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/05/2018 17:32
 Date Of Accident 18/05/2018 13:15
 Exact Location Of Accident DEFU LANE 10
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBA7506H

Insured/Policyholder

Name Of Registered Owner ENTHRAL ENGINEERING PTE LTD
 Co Reg No 201709743C
 Email Address ENTHRALENG@GMAIL.COM
 Mobile Phone No
 Alternative Phone No OFFICE-69259287

Vehicle Particulars

Manufacturer TOYOTA
 Model DYNA 150 MANUAL
 Exact Purpose for which vehicle was being used at time of accident WORK
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy NO
 Policy Number DMCVSN3029761800
 Cover Note Number

Driver

Name of Driver ROY TUNG YANG BOON
 NRIC No S1728867I
 Date Of Birth 18/10/1965
 Occupation OUTDOOR
 Date Of Driving Pass 08/10/1984
 Driving Experience 33 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97995858
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLOCK 621A EDGEFIELD WALK #13-03
 Postcode 821621
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: MIN YE AUNG
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS STATIONARY WAITING FOR THE TRAFFIC TO BE CLEAR BEFORE EXITING TO THE MAIN ROAD. VEHICLE B, SLW9086E ALSO WAS STATIONARY THEN SUDDENLY VEHICLE C, GBG8432Z COLLIDED ONTO THE REAR PORTION OF VEHICLE B AND VEHICLE B COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLW9086E
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver YEOH WEI LING
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBG8432Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

Passenger 1

NAME: :

GENDER: :

Passenger 2

NAME: :

GENDER: :

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process

- I understand, acknowledge, agree and consent that:

- 
 STUDENT'S SIGNATURE

Driver's Signature _____
If driver is not the policyholder:
Date & Time _____

Reporting Centre Personnel's Signature
Name: Cassandra
DOB: 11/1/90

Accident Sketch Plan

SKETCH PLAN



A GBA 1506H

B SLW 9086E

C GBA 81132X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary waiting for the traffic to be clear before existing to the main road, vehicle B also was stationary then suddenly vehicle C collide onto the rear portion of vehicle B and vehicle B collide onto the rear portion of my vehicle

DECLARATION

I/We declare that the particulars are true in every particular

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Cassandra
SPR: 111111



5/23/2018

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.: GBA7506H
 Vehicle Type: B31 - Goods (Open) Lorry (Metal Body)/Pickup
 Vehicle Attachment 1: With Hood
 Vehicle Scheme: Normal
 Vehicle Make: TOYOTA
 Vehicle Model: DYNA 150 MANUAL
 Chassis No.: JTFAT35Y503001307
 Propellant: Diesel
 Engine No.: 1KD1680321
 Engine Capacity: 2982 cc
 Maximum Power Output: -
 Maximum Laden Weight: 3500 kg
 Unladen Weight: 1760 kg
 Year Of Manufacture: 2007
 Original Registration Date: 19 Nov 2007
 Lifespan Expiry Date: 18 Nov 2027
 COE Category: C - Goods Vehicle & Bus
 PQP Paid: \$17,920.00
 COE Expiry Date: 31 Aug 2022
 Road Tax Expiry Date: 18 Nov 2018
 Inspection Due Date: 18 Nov 2018
 Intended Transfer Date: 23 May 2018
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	25.00	-	25.00

Transfer Fee:

Total Amount Payable:

Message

This vehicle has a road tax Over Payment of \$80.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.
 Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

You may print this page for reference.

OK

Print

VAN / LORRY (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	DM	✓	
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel	DD	✓	
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD	✓	
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	CUT	✓	
2054	993700	Rear Rubber Stopper	CUT	✓	
2055	993701	Rear Rubber Stopper Bracket	Deform	✓	
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock	DD	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge	Deform	✓	
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993434	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

Vehicle No: GBA 7506 H

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker Tailgate	NEC	✓	

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2018 Edit Reg		22 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Jue Man Hing Ship's Laundry Management Services, Co. Reg. No.: 46893300W								
Main Claimant:	ENTHRAL ENGINEERING PTE LTD, Co. Reg. No.: 201709743C								
Vehicle Reg. No.:	GBA7506H	Date of Loss:	22/05/2018 13:00 - :59 [126 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0522960596SG	Policy/Cover Note No.:	1700078818						
Vehicle Reg. No. (Insured):	GBG8432Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 04/06/2018]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
- AIG_SG (24/05/2018): No OI GIA Report - AIG_SG (24/05/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBA7506H (0522960596SG)
[GBG8432Z]

TP

ENTHRAL ENGINEERING PTE LTD

May 22 2018 1:00PM

[Jue Man Hing Ship's Laundry Management Services]
Yap Lee Motor

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 18:52	General View	 Load JPG	☒
2	24/05/18 18:52	General View	 Load JPG	☒
3	24/05/18 18:52	General View	 Load JPG	☒
4	24/05/18 18:52	General View	 Load JPG	☒
5	24/05/18 18:52	General View	 Load JPG	☒
6	24/05/18 18:52	General View	 Load JPG	☒
7	24/05/18 18:52	General View	 Load JPG	☒
8	24/05/18 18:52	General View	 Load JPG	☒
9	24/05/18 18:52	General View	 Load JPG	☒
10	24/05/18 18:52	General View	 Load JPG	☒
11	24/05/18 18:52	General View	 Load JPG	☒
12	24/05/18 18:52	General View	 Load JPG	☒
13	24/05/18 18:52	General View	 Load JPG	☒
14	24/05/18 18:52	General View	 Load JPG	☒
15	24/05/18 18:52	General View	 Load JPG	☒
16	24/05/18 18:52	General View	 Load JPG	☒
17	24/05/18 18:52	General View	 Load JPG	☒
18	24/05/18 18:52	General View	 Load JPG	☒
19	24/05/18 18:52	General View	 Load JPG	☒
20	24/05/18 18:52	General View	 Load JPG	☒
21	24/05/18 18:52	General View	 Load JPG	☒
22	24/05/18 18:52	General View	 Load JPG	☒
23	24/05/18 18:52	General View	 Load JPG	☒
24	24/05/18 18:52	General View	 Load JPG	☒
25	24/05/18 18:52	General View	 Load JPG	☒
26	24/05/18 18:52	General View	 Load JPG	☒
27	24/05/18 18:52	General View	 Load JPG	☒
28	24/05/18 18:52	General View	 Load JPG	☒
29	24/05/18 18:52	General View	 Load JPG	☒
30	24/05/18 18:52	General View	 Load JPG	☒
31	24/05/18 18:52	General View	 Load JPG	☒

Documents Checklist

	Reset	Save	Print
DOCUMENTS CHECKLIST There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009303/NZ4D3E2
Date: 31/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700078818
Claimant Vehicle No: GBA7506H Insured Vehicle No: GBG8432Z
Date of Loss: 22/05/2018 Nature of Claim: TP Claim No: 0522960596SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBA7506H Engine No: 1KD1680321
Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Chassis No: JTFAT35Y503001307
Reg. Date: 19/11/2007 (Man. Year: 2007) Odometer: 262979 km
Colour: Blue
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C (D)
Front Left Side: Yokohama 5 mm Rear Left Side: Falken 5/5 mm
Front Right Side: Goodride 5 mm Rear Right Side: Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/05/2018
Date Inspected: 22/05/2018 Inspected At: Yap Lee Motor (HQ)
1 Kaki Bukit Avenue 6, #01-26 Autobay @
Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Damaged	0.00 F	*- F
2	1		*REAR BUMPER STEP PANEL	Dented	0.00 F	*- F
3	1		*REAR LH TAILLAMP PANEL	Dented	0.00 F	*- F
4	1		*TAILGATE	Cut	0.00 F	*- F
5	1		*REAR RUBBER STOPPER	Cut	0.00 F	*- F
6	1		*REAR RUBBER STOPPER BRACKET	Deformed	0.00 F	*- F
7	1		*TAILGATE LOCK	Dented	0.00 F	*- F
8	1		*TAILGATE HINGE	Deformed	0.00 F	*- F
9	1		*STICKER TAILGATE	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >