

ASS. REC. BY

REP: CS/FCT18009306 / T1-H3

Special Instruction: n2

SURVEYOR

ASSIGNMENT (Office)

From (Person):

Tanyah
Sithara

of

FCT

Date/Time:

22/5/2018 @ 2:58pm

Estimated Cost:

Bill to:

OD / (H) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 700R

Insured:

SHA 9342D

at Workshop m/s:

Weames Automotive
219 Alexandra Rd

Tel:

9129 4556

of

Policy No:

Claim No:

D18009025 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/05/18

23/5/18 @ 1pm-3pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

'wp'

Date/Time:

3:05pm @ 22/5/18

Person Contacted:

Michelle

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate	
	SLT 700R - CS/FCT1800189/T1-H3	DOA: 12/01/18
	SHA 9342D - NSI/INC18082953/K/qbn2	DOA: 12/02/2018
28/5-	Revert email preli advise.	
	Part by Part \$3550.07: (Red: 3210-33; 47%)	

Signature

Tamplin

REF: FCI

ASSIGNMENT

From: _____ Date: 23/5/2018

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: SLT 700R
at Workshop m/s: Wearnes Automotive

of 249 Alexandra Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

1pm - 3pm
Michelle

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^(up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: SLT 700R Yr Regn: 2017, Oct.

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Renault Megane c.c. 1197

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 4847 T/Radio: Insured / Std / NI / NA

Eng/No: VFIRFB0035.7730998

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 23/5/18

Survey held at Wearnes Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

25/6 Typist

Date/Time: File Return to?

2)

☐ : Prel. Report
☒ : Final Report

Report Format: TP

Lump Sum (I.B.): (\$ 3550.07)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: _____
Transportation: _____

1 \$ + RS. \$

Photos

Other

TOTAL

145
50
50
39
284



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009306/T1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9342D	Veh. Inspected	SLT 700R
Policy No.		Coverage (\$)	0.00
Claim No.	D18004025MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/05/2018	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004025MFSH

Date: 28/5/2018

Our Ref: CS/FCI18009306/T1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 700R.

Please be informed that we had conducted the inspection of the abovementioned vehicle
23/05/2018 at the premises of M/s Wearnes and have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,760.40</u>
Revised Estimate Amount	: S\$ <u>3,712.30</u>
"Check" Items Amount	: S\$ <u>1,298.10</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the
rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-05-2018	Our Ref No. D18004025MFSH
Accident Date	17-05-2018	Claim Type. Third Party
Insured Vehicle	SHA9342D	Third Party Vehicle. SLT700R
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	MICHELLE ONG	
Contact No.	0/ 91294556	Fax No. 62647137
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240552)



PRI Documents



Close



PRI Header Details

Claim No	D18004025MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : MICHELLE ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 91294556 , Phone: 0 , Fax: 62647137 EmailId: MICHELLE.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9342D	TP Vehicle No	SLT700R
PRI Recieved Date	22-05-2018 12:33:05 PM	Surveyor Appointed Date	22-05-2018 02:57:32 PM	Surveyor Accept Date	22-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-05-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 28 May 2018 10:46 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004025MFSH/1
Attachments: PRELI ADVISED SLT 700R..pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLT 700R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 22 May 2018 3:09 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004025MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 22 May 2018 2:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004025MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

SERVICE ESTIMATE

93779 - C00001 SL: SERVICE SALES - PC

Mr Lai Shih Kae

21 Jalan Raja Udang

#08-03

Singapore 329215

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 21/05/2018

WIP No. : 61546

Veh.In/Out:

*Tel.No. : Mobile: 93210611

Reg.No. : SLT700R

Reg.date. : 13/10/2017

Mileage : 0

Chassis No: VF1RFB00357730998

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Lai Shih Kae

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, ETC	450. 0	1800.00	0		1,800.00 S	900.
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER SPOILER, ETC	400. 0	1650.00	0		1,650.00 S	800. ✓
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00 S	61. ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	330.00	0		330.00 S	✓ ✓

BUMPER REAR M4S	1.0 EA	833.60	833.60 S	del ✓	750.24
BUMPER REAR INNER SI	1.0 EA	240.90	240.90 S	? X	
BUMPER REAR OUTER SI	1.0 EA	167.20	167.20 S	? X	
BUMPER REAR SIDE SUP	1.0 EA	198.50	198.50 S	? X	
BUMPER RR SIDE TRIM	1.0 EA	91.80	91.80 S	? X	
BUMPER PAD LOWER M4S	1.0 EA	363.30	363.30 S	ant ✓	326.97
TAILAMP-REAR LH M4	1.0 EA	263.00	263.00 S	? X	
TAILAMP-REAR RH M4	1.0 EA	336.70	336.70 S	? X	

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpik 97495749

WP
25/5/18 @ 1430

Resurvey before paint

sur @ lkkauto.com

4 days

[Signature]
30/5/18

SERVICE ESTIMATE

93779 - C00001 SL: SERVICE SALES - PC
 Mr Lai Shih Kae
 21 Jalan Raja Udang
 #08-03

Singapore 329215

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Lai Shih Kae

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 2
 Inv.date : 21/05/2018
 WIP No. : 61546
 Veh.In/Out:
 *Tel.No. : Mobile: 93210611
 Reg.No. : SLT700R
 Reg.date : 13/10/2017
 Mileage : 0
 Chassis No: VF1RFB00357730998

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	ADHESIVE SEALER FL2	1.0 EA	425.40			425.40	smc ✓ 382.80

			Gross Total.	6,760.40
Labour Total	3,840.00	Net.....	6,760.40	
Parts Total	2,920.40	GST @ 7.0%	473.23	
Package Total	0.00	Total.....	7,233.65	
			Paid.....	0.00
			Please Pay..	7,233.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

93779 - C00001
Mr Lai Shih Kae
21 Jalan Raja Udang
#08-03

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
Inv.date. : 04/06/2018
WIP No. : 61546
Veh.In/Out: 28/05/2018 02/06/2018
*Tel.No. : Mobile: 93210611
Reg.No. : 3LT700R
Reg.date : 13/10/2017
Mileage : 10,412
Chassis No: VF1RFB00357730998

Singapore 329215

Closed by : Michelle Ong Siew Be
Svc Consultant : ACC
Remarks : Mr Lai Shih Kae

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR	0	900.00	0		900.00	S
	BRACKET, REAR LOWER SPOILER, ETC	0	800.00	0		800.00	S
800	TO PUTTY SPRAY PAINT ON REAR	0	60.00	0		60.00	S
	BUMPER, REAR LOWER SPOILER, ETC	0	330.00	0		330.00	S
R06	TO INSTALL REAR NUMBER PLATE	0					
	INCLUDE HOLDER	0					
280	TO CHECK WIRING INCLUDE						
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	1 BUMPER REAR M4S	1.0 EA	833.60	10		750.24	S
	2 BUMPER PAD LOWER M4S	1.0 EA	363.30	10		326.97	S
	3 ADHESIVE SEALER FL2	1.0 EA	425.40	10		382.86	S

Gross Total. 3,550.07

Labour Total 2,090.00
Parts Total 1,460.07
Package Total 0.00

Net..... 3,550.07
GST @ 7.0% 248.50
Total..... 3,798.55
Paid..... 0.00
Please Pay.. 3,798.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009306/T1td3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-06-2018



Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SHA 9342D	Veh. Inspected	SLT 700R
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18004025MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	22/05/2018

Vehicle Particulars & Condition

2.

Make & Model	RENAULT MEGANE	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1RFB00357730998	Colour	BRONZE
Odometer	9847	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre	205/50 R17	CONTINENTAL	6 mm
L/H Front Tyre	205/50 R17	CONTINENTAL	6 mm
R/H Rear Tyre	205/50 R17	CONTINENTAL	6 mm
L/H Rear Tyre	205/50 R17	CONTINENTAL	6 mm

Description of Damages

4.

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

General Information

5.

Accident Date	17/05/2018	Inspection Date	23/05/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

Remarks

5a.

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Estimate Days of Repair

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 700R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR M4S (SN)	DEFORMED	833.60	750.24
1	BUMPER REAR INNER SI (SN)	NOT NECESSARY	240.90	-
1	BUMPER REAR OUTER SI (SN)	NOT NECESSARY	167.20	-
1	BUMPER REAR SIDE SUP (SN)	NOT NECESSARY	198.50	-
1	BUMPER RR SIDE TRIM (SN)	NOT NECESSARY	91.80	-
1	BUMPER PAD LOWER M4S (SN)	CUT	363.30	326.97
1	TAILAMP-REAR LH M4 (SN)	NOT NECESSARY	263.00	-
1	TAILAMP-REAR RH M4 (SN)	NOT NECESSARY	336.70	-
1	REAR NUMBER PLATE INCLUDE HOLDER (SN)	BENT	60.00	60.00
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	425.40	382.86
			2,980.40	1,520.07
	LABOUR			
	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, ETC.		1,800.00	900.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER SPOILER, ETC.		1,650.00	800.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		330.00	330.00
			3,780.00	2,030.00
	GRAND TOTAL		6,760.40	3,550.07
	RECOMMENDED COST OF REPAIRS			3,550.07

Report Ref No. CS/FC118009306/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.