



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Mok Chun Kwong Jeffrey  Blk 253 Bangkit Road #01-242 Singapore 670253  Contact No Mobile: 96569631JEFFERY	Cust No/Name	/Mr Mok Chun Kwong Jeffrey
	Reg No/Reg Date	SLS7866E / 04/10/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MJ5747145
	Engine No	G4FGHH682299
	Make/Model	KIA/CERATO K3 1.6 A EX BWY
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	19/05/2018/ 10:30	QUD	247 / DonBong	28880			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, BUMPER RETAINER, REPAIR LH REAR FENDER, REPAIR LH REAR DOOR								1650 2200.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								60 80.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER FACE, LH REAR FENDER, LH REAR DOOR AND AFFECTED PORTION								1260 1680.00
M SUNDRY PERFORM RUST PREVENTION								40 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30 50.00
A 30000001 RENEW LH REAR WHEEL HUB BEARING AND AFFECTED PARTS								photo 225? 550.00
M SUNDRY SUPPLY LH REAR SPORT RIM SSW266								ab 400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								✓ 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								1 ✓ 200.00
M SUNDRY SUNDRIES								20 50.00
M	COVER-RR BUMPER				1.00	688.00	00.00	dr 688.00
M	BRACKET-RR BUMPER SIDE MTG,LH				1.00	29.00	00.00	nes 29.00
M	BRACKET-RR BUMPER SIDE MTG,RH				1.00	29.00	00.00	? 29.00
M	COVER-RR BUMPER,CTR				1.00	347.00	00.00	x 347.00
M	RETAINER-BUMPER SIDE MTG				2.00	1.00	00.00	2.00
M	RETAINER				4.00	2.00	00.00	8.00
M	LAMP ASSY-REAR COMBINATION,LH				1.00	788.00	00.00	? 788.00
M	GUARD ASSY-REAR WHEEL,LH				1.00	75.00	00.00	? 75.00
M	HUB ASSY-RR WHEEL				1.00	340.00	00.00	? 340.00
SURVEYOR NAME : <u>Taufik</u>								
SURVEYOR SIGNATURE : <u>Taufik</u>								

SURVEYOR NAME : Tayfkh

SURVEYOR SIGNATURE :

I, KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

DATE : 25/5/18 @ 1115

REMARKS : Resurvey before paint

sur@kkhauto.com

6-7 days

Nett

7716.00

7,716.00

540.12

Total Payable

8,256.12

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.