

NS CASE OWNER: GEORGE

CC 6/AIG1800

9310, Ambly

LKK

IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

21/5/18

Date / Time

21/5/18

Registered in Merimen:

22/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJR 34342

Name of Insured:

LEE MING HO

Insured Tel No.:

HP:

Excess See II :SS

D.O.A.:

18/5/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE MING HO

Driver Tel No.:

(VL: ☒ YES / NO)

Claim No.:

589326042656

Policy No.:

200416459

Make / Model:

TOYOTA

Place of Accident:

near of WYNN BKT & TEMPLES AVE

OI GIA REPORT: YES / NO

☒ YES / NO

TP GIA REPORT: YES / NO

☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SJW 8089C

INSRS:

WSP:

Tel:

Liability:

RMKS:

Kang Car

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time		STAGE	DATE / PIC
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Non-Reporting ltr (1st):	
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Non-Reporting ltr (2nd):	
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Non-Reporting ltr (Final):	
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Notification ltr (if non-pickup):	
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Call OI:	
<u>21/5/18</u>	<u>SJR 34342 - F</u>	After call ltr to OI:	
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Documentation Check List:	Handler Typist
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Notification ltr (if non-pickup):	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	After call ltr to OI:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Authorisation To Act:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Release Voucher:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Final Repair Bill:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Car Rental Invoice:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Towing Invoice:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	LTA / GIA:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Medical Bill:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	PIR:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Mandate/Reject Instruction:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	LOD:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Payment Breakdown Form:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Post-Repair Photos:	☒
<u>21/5/18</u>	<u>SJR 34342 - F</u>	Others:	☒

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	<u>40</u>	SS <u>9,000.00</u>	9 days) Reduction: <u>53</u> %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.:	<u>5</u>
Repair Cost:	<u>(W/loss)</u>	SS <u>9,630.00</u>	
Loss of Rental (LOR):	SS <u>1,200.00</u>	(10 days) x 120	
Loss of Use (LOU):	SS <u>—</u>	(5 x days)	
Loss of Income (LOI):	SS <u>—</u>	(5 x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search:	SS <u>2.00</u>		
Medical:	SS <u>—</u>		
Disbursement:	SS <u>—</u>	(e.g. Tow/Independent)	
Legal Cost:	SS <u>—</u>		
Total:	SS <u>10,832.00</u>	Global Sum SS:	<u>10,800.00</u>
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS <u>10,800.00</u>	Name 1:	<u>KANG CAR FORMKERS PTE LTD</u>
Payee 2: (Strike if N.A.)	SS <u>—</u>	Name 2:	<u>—</u>
Payee 3: (Strike if N.A.)	SS <u>—</u>	Name 3:	<u>—</u>

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: 4320.00

ASS. REC. BY: Adrian Ling

ASSIGNMENT

25/02/09.
2009, Feb

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 9 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SSW08089C Yr Regn: 2009, Feb
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mit Lancer cc 1998
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 19659 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JMY8TCY4A9U000346
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R17
R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm
D.O.A. _____		D.O.I. <u>21/09/18</u>

Survey held at Kang
Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Frnt o/s, u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ALG</u>
	<u>LIS - \$ 9000+ (Red: \$ 10351.10 / 53.1)</u>
	<u>MV: 19K</u>
	<u>TV: 10HK</u>
	<u>Nett: 8.6K</u>

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18009310/Amb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 22-05-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 3434Z	Veh. Inspected	SJW 8089C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/05/2018	Inspection Date	21/05/2018	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000

FAX: 68357416

ATTN: Motor Claim Department

Estimate No: EST1800143

Date: 21 May 2018

Veh Reg No: SJW8089C

Make/Model: MITSUBISHI LANCER
2.0L MIVEC

Chasis No: JMYSTCY4A9U000346

Reg. Date: 25/02/2009

Your Ref No: SJR3434Z

Claim Type: Third Party

Accident Date: 18/05/2018

TP Veh Reg No: SJR3434Z

LKK-21/5/18

Benon

Estimate Repair Cost to Vehicle No :SJW8089C

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BONNET RUBBER new <i>cut</i>	36.00	✓
2	1 PC BONNET LOCK new <i>Drpd</i>	121.00	✓
3	2 PCS BONNET HINGE <i>Best</i>	108.00	✓
4	1 PC FRT FENDER RH <i>Dischd</i>	496.00	✓
5	1 PC FRT FENDER COWLING RH <i>Dischd</i>	105.00	✓
6	1 PC FRT FENDER RH SIGNAL LAMP <i>new</i>	51.00	✓
7	1 PC FRT SUPPORT PANEL <i>Buckled</i>	885.00	✓
8	1 PC FRT SUPPORT PANEL TOP COVER <i>Detond</i>	155.00	✓
9	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	326.00	✓
10	1 PC FRT BUMPER TOP BRACKET <i>new</i>	212.00	✓
11	1 PC FRT BUMPER TOP RUBBER <i>new</i>	81.00	✓
12	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	62.00	✓
13	1 PC HEADLAMP RH <i>cracked</i>	1,036.00	✓
14	1 PC HEADLAMP LH <i>cracked</i>	1,036.00	✓
15	1 PC FRT WIPER WATER TANK <i>Dischd</i>	174.00	✓
16	1 PC FRONT WIPER WATER TANK MOTOR <i>new</i>	128.00	✓
17	1 PC AIR CONDENSER <i>new</i>	909.00	✓
18	1 PC RADIATOR <i>new</i>	963.00	✓
19	1 PC RADIATOR UNDER COVER <i>new</i> <i>6228</i>	136.00	✓
20	1 PC FRT SHOCK ABSORBER RH <i>Best</i>	401.00	✓
21	1 PC FRT SHOCK ABSORBER MOUNTING RH <i>new</i> <i>5608-20</i>	99.00	✓
22	1 PC FRT LOWER ARM RH <i>Best</i>	392.00	✓
23	1 PC FRT KNUCKLE ARM RH <i>Best</i>	408.00	✓
24	1 PC FRT BEARING RH <i>new</i>	139.00	✓
25	1 PC FRT WHEEL HUB RH <i>Drpd</i>	212.00	✓
26	1 PC FRT DRIVE SHAFT RH <i>new</i>	1,180.00	✓
27	1 PC STEERING RACK & PINION <i>new</i>	1,828.00	✓
		11,679.00	
	Less 10%	1,167.90	10.511.10

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay II, Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800143
Date: 21 May 2018
Veh Reg No: SJW8089C
Make/Model: MITSUBISHI LANCER
2.0L MIVEC
Chassis No: JMYSTCY4A9U000346
Reg. Date: 25/02/2009
Your Ref No: SJR3434Z

Claim Type: Third Party
Accident Date: 18/05/2018
TP Veh Reg No: SJR3434Z

Estimate Repair Cost to Vehicle No :SJW8089C

Quantity	Description	List Price SS	Amount SS
Special Net			
28	1 PC BONNET <i>Builed</i>	1,500.00 <i>1000</i>	
29	1 SET FRT FENDER COWLING CLIPS RH <i>in</i>	40.00 <i>30</i>	
30	1 PC FRT FENDER GARNISH RH <i>new 2nd</i>	180.00 <i>80</i>	
31	1 SET FRT SUPPORT PANEL TOP COVER CLIPS <i>in</i>	40.00 <i>20</i>	
32	1 PC FRT BUMPER <i>Distorted</i>	1,300.00 <i>1000</i>	
33	1 SET FRT BUMPER CLIPS <i>in</i>	60.00 <i>30</i>	
34	1 PC FRT FOG LAMP COVER RH <i>3 new</i>	60.00 <i>+</i>	
35	1 SET RADIATOR UNDER COVER CLIPS	40.00 <i>2</i>	
36	1 PC FRT SPORTS RIM RH <i>ut</i>	800.00 <i>+50</i>	
37	1 PC FRT TYRE RH <i>ut</i>	150.00 <i>150</i>	
		4,470.00	4,470.00
Labour			
38	1 TOWING	60.00 <i>2930</i>	
39	1 TO CHECK WIRING	50.00 <i>30</i>	
40	1 TO REFILL AIRCON GAS	120.00 <i>100</i>	
41	1 TO REMOVE AND REFIT UNDERCARRIAGE	500.00 <i>220</i>	
42	1 (FRONT) TO CHECK WHEEL ALIGNMENT	120.00 <i>80</i>	
43	1 TO SPRAY UNDERSEAL	120.00 <i>40</i>	
44	1 (FRONT) TO SPRAY PAINTING	1,600.00 <i>1200</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 18/05/2018
TP Veh Reg No: SJR3434Z

Estimate No: EST1800143
Date: 21 May 2018
Veh Reg No: SJW8089C
Make/Model: MITSUBISHI LANCER
2.0L MIVEC
Chasis No: JMYSTCY4A9U000346
Reg. Date: 25/02/2009
Your Ref No: SJR3434Z


Estimate Repair Cost to Vehicle No :SJW8089C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 19,351.10
	Add GST @ 7%		1,354.58
	Total Amount Payable		<u>S\$ 20,705.68</u>

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SEVEN HUNDRED AND FIVE AND CENTS SIXTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

21/5/18-surveyed
adrian

total: 11325.20
4/5 9k

0920

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Received Message

This mail is associated with :

***SJW8089C (5893260436SG)**

[SJR3434Z]

TP

TAN JIA EN

May 18 2018 9:00AM

[LEE JUNG HO]

Kang Car Repairers Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 17/12/2018 09:14 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10832.00) - SJW8089C - Claim Handler: Lee, Ming-Yao

Approved:10832.00:Please do your utmost to settle claim at best.



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883

TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg

Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0520188089AIG
Your Ref : SJR3434Z

Date : 13 SEP 2018

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933
Attention : Motor Claim Department

Dear Sirs,

Accident involving SJW8089C and SJR3434Z on 18.05.2018 at Junction of Loyang Ave/Tampines Ave 7.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SJR3737Z.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Ms Chen Jia En, the owner of motor-vehicle no: SJW8089C, we submit her claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 9,630.00
Loss of rental (10 days x \$120.00)	\$ 1,200.00
GIA search	\$ 2.00
	\$ 10,832.00
	=====

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1800532
- 2) GIA report of SJW8089C
- 3) Police Report No: T/20180518/2163
- 4) Rental invoice and rental agreement
- 5) GIA search fee & invoice

We hope to receive your early reply soon.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD

.....



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: **CC6/AIG18009310/Amb3**

28 MAY 2018

LEE JUNG HO
50 FLORA DRIVE
#02-01
SINGAPORE 506868

Dear Sir/Madam,

ACCIDENT INVOLVING SJR 3434Z AND SJW 8089C ON 18/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)


I, Tan Jia En ("the third party claimant")
of Blk 156 Bishan St 13 #08-90 S570156 (address),
owner of SJW8089C (vehicle no.) hereby authorize
Kang Car Repairers Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJW8089C that was
damaged pursuant to the accident which occurred on 18.05.18 (date) along
Junction of Tampines Ave 7 /Loyang Ave (location)
involving vehicle no/s SJR3434Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 18 day of May (month) 20 18 (year)


Signed by "the third party claimant"

KANG CAR REPAIRERS PTE. LTD.

Signed by "the workshop"

This Discharge Voucher applies strictly for Claimant's claim for personal-injury/ property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, KANG CAR REPAIRERS PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$10,800.00 (Global Sum – all in) for vehicle no. SJW 8089C that was damaged pursuant to the accident which occurred on 18/05/2018 (date) along JUNCTION OF LOYANG AVENUE AND TAMPINES AVENUE 7 (location) involving vehicle no/s SJR 3434Z. This is pursuant to the inspection conducted on 21/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN JIA EN ("the third party claimant") of vehicle no. SJW 8089C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJW 8089C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ (day) of 16 FEB 2019 (month) 2019 (year)



Signed by appointed surveyor

KANG CAR REPAIRERS PTE. LTD.

Signed by "the workshop" (with chop)



江氏修理汽車私人有限公司

KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Your Ref No: SJR3434Z
Claim Type: Third Party
Accident Date: 18/05/2018
TP Veh Reg No: SJR3434Z

Final No: KCR-INV1800532
Claim No: EST1800143
Date: 10 Sep 2018
Policy No: 5098369115
Veh Reg No: SJW8089C
Make/Model: MITSUBISHI LANCER
2.0L MIVEC
Chassis No: JMYSTCY4A9U000346
Engine No: 4B11CA2594
Reg. Date: 25/02/2009

Tax Invoice to Vehicle No :SJW8089C

PAGE:1

Description	Quantity	List Price	Amount
		SS	SS
As recommended by surveyor to proceed repair at total cost/lumpsum cost			SS 9,000.00
Add GST @ 7%			630.00
Total Amount payable			SS 9,630.00

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SIX HUNDRED THIRTY ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
JHANGIR KHAN BIN MOHAMED AYUB BLK 101 BEDOK NORTH AVENUE 4 #07-1968 SINGAPORE 460101

DATE	INVOICE NO.
12-Jun-2018	A 37808

DESCRIPTION	VHA NO.	DUE DATE	VEH. NO.
	A 37808	12-Jun-2018	SJR 9474 T
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 18 MAY 2018 TO 28 MAY 2018 YOUR REF: SJW 8089 C	10	112.1495	1,121.50
GST @ 7%			\$78.50
TOTAL			\$1,200.00

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.



VEHICLE HIRING AGREEMENT
HIRER'S PARTICULARS

Name (as in VC) *Mr. [illegible]*
 NRIC/Passport No: *S1201246* Date of Birth: *12/11/1958*
 Address: *111-111, Road, North, No. 2* Age: *40*
111-111 S: *(40101)*
 Name & Address of Employer: _____
 Occupation: _____ Driving Exp: _____
 Driving Licence No: _____ Passed Date: *21/12/1999*
 D/L Type: Local/Int'l/Other: _____
 Tel: () () HP: *88260851*

DRIVER'S PARTICULARS


Name (as in VC) *Mr. [illegible]*
 NRIC/Passport No: *S1201246* Date of Birth: *12/11/1958*
 Address: *111-111, Road, North, No. 2* Age: *40*
111-111 S: *(40101)*
 Occupation: _____ Driving Exp: _____ Yrs: _____
 Driving Licence No: _____ Passed / Expiry Date: *21/12/1999*
 D/L Type: Local/Int'l/Other: _____ Contact No: _____

Hirer's Own Vehicle No: *111-111* Replace Veh No: _____
 Loan Vehicle No: *111-111* VR No: _____
 Make & Model: *T. 111* Auto/Manual Group: _____
CHARGES \$ cts
 Daily *10* day @ \$ *125* Per day *1250* ✓
 Weekly/Monthly week @ \$ Per week/Monthly _____
 Others _____
 CDW/PAI @ \$ Per day/Monthly _____
 Delivery/Collection Svc _____
 GST _____
 OR No: (A) SUB-TOTAL *31200* ✓
 Petrol Level & Surcharge
 OUT E 1/4 1/2 3/4 F
 IN _____
 First _____ km FREE per day GST _____
 Excess mileage is chargeable at _____ cents per km TOTAL CHARGES _____

Security Deposit : \$ _____ Bank: _____
 CASH/NETS/VISA/MC/AMEX/CHQ No: _____
 Expiry Date: _____ Card ID No: _____
 Name as in Card: _____

NON WAIVER EXCESS (Subject to GST) \$ *2000*
ACCESSORIES CHECK
☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature : _____ Additional Driver's Signature : _____
SINGAPORE Use Only _____



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given BKW Rent A Car Pte Ltd in connection with this agreement is true.

- IMPORTANT:**
- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
 - All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5.00 or top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
 - No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
 - Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
 - Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
 - The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
 - The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
 - Smoke or permit smoking and transport of pass in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair, between \$200 - \$400.
 - The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
 - In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
 - The hirer/driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is still and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
 - All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
 - I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
<i>28/5/18</i>	<i>12:15 PM</i>	<i>123234</i>	<i>Ausell</i>	

Return Of Vehicle: The Hirer Driver is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc.)

Date In	Time In	Mileage	Check By	Remarks
<i>28/5/18</i>	<i>11 am</i>	<i>123234</i>	<i>[Signature]</i>	



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-075856

Date of Request: 18/05/2018

Your Ref No: Online Purchase

Kang Car Repairers Pte Ltd
No 1 Kaki Bukit Ave 6
#02-06 AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 18/05/2018
Enquiry By Yee Mei Cheng
TP Vehicle No. SJR3434Z
Accident Date 18/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJR3434Z	AIG Asia Pacific Insurance Pte. Ltd.	19/06/2017-18/06/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-075856
Date of Request: 18/05/2018

Your Ref No: Online Purchase

Kang Car Repairers Pte Ltd
No 1 Kaki Bukit Ave 6
#02-06 AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 18/05/2018
Enquiry By Yee Mei Cheng
TP Vehicle No. SJR3434Z
Accident Date 18/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2018 Edit Reg		21 May 2018 00:00 Edit Adj Rpt	\$9,000.00 Edit Estimates	\$9,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE JUNG HO, ID: S6865875F								
Main Claimant:	TAN JIA EN, ID: S93496461								
Vehicle Reg. No.:	SJW8089C	Date of Loss:	18/05/2018 09:00 - :59 [110 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5893260436SG	Policy/Cover Note No.:	2100416459 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJR3434Z	Policy No. (Claimant):	5098369115						
		Excess:							
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (17/12/2018): Alert - Adj Mandate Approved (\$10832.00) - SJW8089C - Claim Handler: Lee, Ming-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW8089C (5893260436SG)
[SJR3434Z]
TP
TAN JIA EN
May 18 2018 9:00AM
[LEE JUNG HO]
Kang Car Repairers Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/08/18 18:32	General View							Load JPG ☒		
2	27/08/18 18:32	General View							Load JPG ☒		
3	27/08/18 18:32	General View							Load JPG ☒		
4	27/08/18 18:32	General View							Load JPG ☒		
5	27/08/18 18:32	General View							Load JPG ☒		
6	27/08/18 18:32	General View							Load JPG ☒		
7	27/08/18 18:32	General View							Load JPG ☒		
8	27/08/18 18:32	General View							Load JPG ☒		
9	27/08/18 18:32	General View							Load JPG ☒		
10	27/08/18 18:32	General View							Load JPG ☒		
11	27/08/18 18:32	General View							Load JPG ☒		
12	27/08/18 18:32	General View							Load JPG ☒		
13	27/08/18 18:32	General View							Load JPG ☒		
14	27/08/18 18:32	General View							Load JPG ☒		
15	27/08/18 18:32	General View							Load JPG ☒		
16	27/08/18 18:32	General View							Load JPG ☒		
17	27/08/18 18:32	General View							Load JPG ☒		
18	27/08/18 18:32	General View							Load JPG ☒		
19	27/08/18 18:32	General View							Load JPG ☒		
20	27/08/18 18:32	General View							Load JPG ☒		
21	27/08/18 18:32	General View							Load JPG ☒		
22	27/08/18 18:32	General View							Load JPG ☒		
23	27/08/18 18:32	General View							Load JPG ☒		
24	27/08/18 18:32	General View							Load JPG ☒		
25	27/08/18 18:32	General View							Load JPG ☒		
26	27/08/18 18:32	General View							Load JPG ☒		
27	27/08/18 18:32	General View							Load JPG ☒		
28	27/08/18 18:32	General View							Load JPG ☒		
29	27/08/18 18:32	General View							Load JPG ☒		
30	27/08/18 18:32	General View							Load JPG ☒		
31	27/08/18 18:32	General View							Load JPG ☒		
32	27/08/18 18:32	General View							Load JPG ☒		
33	27/08/18 18:32	General View							Load JPG ☒		
34	27/08/18 18:32	General View							Load JPG ☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	27/08/18 18:32	General View	 Load JPG	☒
36	27/08/18 18:32	General View	 Load JPG	☒
37	27/08/18 18:32	General View	 Load JPG	☒
38	27/08/18 18:32	General View	 Load JPG	☒
39	27/08/18 18:32	General View	 Load JPG	☒
40	27/08/18 18:32	General View	 Load JPG	☒
41	27/08/18 18:32	General View	 Load JPG	☒
42	27/08/18 18:32	General View	 Load JPG	☒
43	27/08/18 18:32	General View	 Load JPG	☒
44	27/08/18 18:32	General View	 Load JPG	☒
45	27/08/18 18:32	General View	 Load JPG	☒
46	27/08/18 18:32	General View	 Load JPG	☒
47	27/08/18 18:32	General View	 Load JPG	☒
48	27/08/18 18:32	General View	 Load JPG	☒
49	27/08/18 18:32	General View	 Load JPG	☒
50	27/08/18 18:32	General View	 Load JPG	☒
51	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
52	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
53	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
54	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
55	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
56	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
57	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
58	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
59	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
60	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
61	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
62	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
63	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
64	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
65	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
66	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
67	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
68	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
69	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
70	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
71	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
72	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
73	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
74	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
75	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
76	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
77	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
78	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
79	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
80	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
81	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
82	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
83	27/08/18 18:32	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
85	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
86	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
87	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
88	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
89	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
90	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
91	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
92	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
93	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
94	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
95	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
96	27/08/18 18:32	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 17:47	TP GIA REPORT.	 Load PDF	
2	05/12/18 15:09	RENTAL RECEIPT	 Load PDF	
3	05/12/18 15:09	GIA SEARCH	 Load PDF	
4	05/12/18 15:09	LETTER TO OI	 Load PDF	
5	01/03/19 12:12	WORKSHOP INVOICE	 Load PDF	
6	01/03/19 12:12	AUTHORISATION TO ACT FORM	 Load PDF	
7	01/03/19 12:12	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/05/18 13:46	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJR3434Z (Insd veh)	Model:	MITSUBISHI LANCER 2.0 L
	SJW8089C (TP veh)		MIVEC (A)
Date of Accident:	18/05/2018		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$	20,705.68	
Final Repair Cost	:	\$	10,800.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		10 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$	10,800.00	

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown

1)	Kang Car Repairers Pte Ltd	:	\$	10,800.00
2)		:	\$	
3)		:	\$	

JOANNE LEE KHANG MIN

01 Mar
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18009310/AHB3Q2

Date: 01/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100416459
 Claimant Vehicle No: SJW8089C Insured Vehicle No: SJR3434Z
 Date of Loss: 18/05/2018 Nature of Claim: TP Claim No: 5893260436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW8089C Engine No: 4B11CA2594
 Make & Model: MITSUBISHI LANCER, 2.0 L MIVEC (A) Chassis No: JMYSTCY4A9U000346
 Reg. Date: 25/02/2009 (Man. Year: 2008) Odometer: 195659 km
 Colour: White
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,981.10	8,395.20	6,585.90	43.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	2,930.00	1,440.00	32.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,351.10	11,325.20	8,025.90	41.48
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	19,351.10	9,000.00	10,351.10	53.49
+ GST 7.00/7.00% (S\$)	1,354.58	630.00	724.58	53.49
Nett Amount (S\$)	20,705.68	9,630.00	11,075.68	53.49
+ Car Rental (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,832.00		
Global Sum Settlement (S\$)		10,800.00		

INSPECTION

Date of Assignment: 21/05/2018
 Date Inspected: 21/05/2018 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET RUBBER	Cut	36.00 FL	*36.00 FL
2	1		*BONNET LOCK	Damaged	121.00 FL	*121.00 FL
3	2		*BONNET HINGE	Bent	108.00 FL	*108.00 FL
4	1		*FRT FENDER RH	Distorted	496.00 FL	*496.00 FL
5	1		*FRT FENDER COWLING LH	Deformed	105.00 FL	*105.00 FL
6	1		*FRT FENDER RH SIGNAL LAMP	Not Necessary	51.00 FL	*- FL
7	1		*FRT SUPPORT PANEL	Buckled	885.00 FL	*885.00 FL
8	1		*FRT SUPPORT PANEL TOP COVER	Deformed	155.00 FL	*155.00 FL
9	1		*FRT BUMPER REINFORCEMENT	Bent	326.00 FL	*326.00 FL
10	1		*FRT BUMPER TOP BRACKET	Not Necessary	212.00 FL	*- FL
11	1		*FRT BUMPER TOP RUBBER	Not Necessary	81.00 FL	*- FL
12	2		*FRT BUMPER SIDE RETAINER	Necessary	62.00 FL	*62.00 FL
13	1		*HEADLAMP RH	Cracked	1,036.00 FL	*1,036.00 FL
14	1		*HEADLAMP LH	Cracked	1,036.00 FL	*1,036.00 FL
15	1		*FRT WIPER WATER TANK	Deformed	174.00 FL	*174.00 FL
16	1		*FRONT WIPER WATER TANK MOTOR	Not Necessary	128.00 FL	*- FL
17	1		*AIR CONDENSER	Not Necessary	909.00 FL	*- FL
18	1		*RADIATOR	Not Necessary	963.00 FL	*- FL
19	1		*RADIATOR UNDER COVER	Torn	136.00 FL	*136.00 FL
20	1		*FRT SHOCK ABSORBER RH	Bent	401.00 FL	*401.00 FL
21	1		*FRT SHOCK ABSORBER MOUNTING RH	Not Necessary	99.00 FL	*- FL
22	1		*FRT LOWR ARM RH	Bent	392.00 FL	*392.00 FL
23	1		*FRT KNUCKLE ARM RH	Bent	408.00 FL	*408.00 FL
24	1		*FRT BEARING RH	Necessary	139.00 FL	*139.00 FL
25	1		*FRT WHEEL HUB RH	Damaged	212.00 FL	*212.00 FL
26	1		*FRT DRIVE SHAFT RH	Not Necessary	1,180.00 FL	*- FL
27	1		*STEERING RACK & PINION	Not Necessary	1,828.00 FL	*- FL
28	1		*BONNET	Buckled	1,500.00 FS	*1,000.00 FS
29	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	40.00 FS	*30.00 FS
30	1		*FRT FENDER GARNISH RH	Deformed	180.00 FS	*80.00 FS
31	1		*SET FRT SUPPORT PANEL TOP COVER CLIPS	Necessary	40.00 FS	*20.00 FS
32	1		*FRT BUMPER	Distorted	1,300.00 FS	*1,000.00 FS
33	1		*SET FRT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
34	1		*FRT FOG LAMP COVER RH	Not Necessary	60.00 FS	*- FS
35	1		*SET RADIATOR UNDER COVER CLIPS	Not Necessary	40.00 FS	*- FS
36	1		*FRT SUPPORT RIM RH	Cut	800.00 FS	*450.00 FS
37	1		*FRT TYRE RH	Cut	450.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,149.00	9,018.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,167.90	622.80
Total Parts (\$\$)	14,981.10	8,395.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	60.00	60.00
2	TO CHECK WIRING	New	50.00	30.00
3	TO REFILL AIRCON GAS	New	120.00	100.00
4	TO REMOVE AND REFIT UNDERCARRIAGE	New	500.00	220.00
5	(FRONT) TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
6	TO SPRAY UNSEAL	New	120.00	40.00
7	(FRONT) TO SPRAY PAINTING	New	1,600.00	1,200.00
8	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			4,370.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >