

INS. CASE OWNER:

Joel

CC 6/EQ1800

9711

Unsub 6391

LKK-
ADAC

Surveyor:

marms

DOI:

ASSIGNMENT

21/5/18

Date / Time:

21/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFE 18749

Name of Insured:

TEO TEUK HWEE

Insured Tel No.:

HP:

9740065

Excess Sec II :SS

D.O.A.:

21/5/18

Is driver the owner?

(YES ☒)

Nature of Accident:

If NO, Driver Name / Age:

TEO HEN EIU

Driver Tel No.:

(VAL ☒ YES / NO)

Claim No.:

DM18100 1284-79

Policy No.:

DMPPH18-000674

Make / Model:

PERMANI

Place of Accident:

TPE (PIE) 84 EPE (EUP)

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SFE 8220C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fatech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

21/5/18
Buran

SFE 8220C

SFE 18749

18/5/19
19/5/19

Email PA to Joel (EAI)
File pass to Shu Pei to close case.

STAGE DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	☒	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☐	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice:	☐	☐
LTA / GIA:	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

18/5/19

Email ☒ Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

28-5(11)

If NO at B 28, Ass. Lia:

Repair Cost:

SS

6420.00

010 3 new cc 010

Loss of Rental (LOR):

SS

1200.00 (12 days)

X 100.00

Loss of Use (LOU):

SS

- (\$ x days)

Loss of Income (LOI):

SS

- (\$ x days)

LOR only ☒ LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost:

SS

-

Total:

SS

7622.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

7622.00

Name 1:

Fatech Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:

4400.00

COPY SENT

010 (93)
al

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJKf220Cat Workshop n/s: Rp.

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 13800

IMAC Accident Report: _____ Consistent? : Yes or No

SIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJKf220C Yr Regn: 5/11 08Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or UA /Make: Honda Jazz o.o. 1339Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 149365 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JHMG E685095205990

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: _____ mm R/Bal: _____ mm

L/Bal: 6 mm L/Bal: 6 mmD.O.A. 21/5/18 D.O.I. 24/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/11	2747610	5 mth plus. net 6190
home G14		

30/5/18 1/5 \$6000 confirmed with Aler.

MV: \$13800.00
 LTP Repairs: \$7610.00
 Net value: \$6190.00

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ > RS. \$ _____

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18009311/Umb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 22-05-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 1874G	Veh. Inspected	SJK 8220C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/05/2018	Inspection Date	22/05/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

not attached
the
1/5 @ 6000/-
13 day.
22/5/18

Qty	Particular	SSK 8220C	Amount S\$
<u>List Item:</u>			
1PCS	REAR WINDSCREEN MOULDING	nee	\$68.50 ✓
1PCS	TAILGATE	3.6/5.0	\$718.20 ✓
1PCS	TAILGATE JAZZ EMBLEM	nee	\$32.90 ✓
1PCS	TAILGATE INNER LOCK	10/5/18	\$145.50 ✓
1PCS	TAILGATE LOCK STRIKER	1.1	\$68.20 X
1PCS	TAILGATE INNER TRIM BOARD	1.1	\$232.60 X
1SET	TAILGATE INNER TRIM BOARD CLIPS	1.1	\$45.00 X
1PCS	TAILGATE OUTER GARNISH	1.1	\$288.20 X
1PCS	TAILGATE 'H' LOGO	1.1	\$38.20 X
1PCS	TAILGATE REAR WIPER MOTOR	1.1	\$625.30 X
2PCS	TAILLAMPS @\$382.50	2/5/18	\$765.00 1/2 C
1PCS	REAR BUMPER	10/5	\$493.70 ✓
2PCS	REAR BUMPER SIDE RETAINERS @\$22.50	sent	\$45.00 ✓
1SET	REAR BUMPER CLIPS	nee	\$39.00 ✓
2PCS	REAR BUMPER SIDE GARNISHES @\$48.50	1.5	\$97.00 X
1PCS	TAILGATE WEATHERSTRIP	1.1	\$92.30 ✓
2PCS	REAR REVERSE SENSORS @\$185.00	shut	\$370.00 2005. 2
1PCS	TAILLAMP HOUSING PANEL 0/S	10	\$166.20 ✓
2PCS	REAR FENDER @\$845.30	MS R 0/5 suc	\$1690.60 1/2 C
2PCS	REAR FENDER INNER TRIM BOARD @\$266.30	0/5 D.S	\$532.60 1/2 C
2PCS	REAR DOORS @\$765.30	1	\$1530.60 X
1PCS	REAR FLOOR PANEL	1.1	\$845.20 X
1PCS	REAR FLOOR PANEL TOP BOARD	1.1	\$266.90 X

2018

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	REAR FLOOR PANEL SIDE MEMBER O/S	1 \$185.60 X
1PCS	REAR FLOOR PANEL TOOLS SPONGE	7011 \$422.50 ✓
1PCS	REAR END PANEL	Sub \$269.80 ✓
1PCS	REAR END PANEL TOP GARNISH	4m \$60.80 ✓
1PCS	REAR WINDSCREEN	11 \$1050.20 X
2PCS	REAR TAILGATE INNER TOP SIDE GARNISH @\$112.50	11 \$225.00 X
1PCS	REAR EXHAUST	2 \$464.80 X
2PCS	REAR EXHAUST MOUNTING @\$20.50	11 \$41.00 X
1PCS	REAR EXHAUST HEAT SHIELD	Sub \$64.50 ✓
1PCS	REAR AIR VENT	11 \$26.00 X
2PCS	REAR DOOR INNER TRIM BOARDS @\$301.30	11 \$602.60 X
2PCS	REAR DOOR INNER LOCKS @\$186.20	11 \$372.40 X
1PCS	REAR DOOR GLASS OUTER MOULDING N/S	11 \$49.60 X
2SET	REAR DOOR FRAME STICKERS @\$20.00	11 \$40.00 X
2PCS	REAR DOOR HINGES N/S @\$65.40	11 \$130.80 X
2PCS	REAR DOOR WEATHERSTRIP @\$166.20	11 \$332.40 X
1PCS	REAR BACK SEAT REST	11 \$688.30 X
1PCS	REAR BACK SEAT BELT N/S	11 \$466.20 X
2PCS	REAR SHOCK ABSORBER @\$115.30	11 \$230.60 X
1PCS	REAR WHEEL HUB BEARING N/S	11 \$332.30 X
1PCS	REAR AXLE BEAM	11 \$865.40 X
1PCS	REAR QUARTER GLASS N/S	11 \$285.30 X

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	ROOF PANEL	1 \$869.20 X
1PCS	ROOF PANEL INNER LINING	11 \$766.30 X
1PCS	FRONT DOOR N/S	11 \$785.20 X
1PCS	FRONT DOOR GLASS OUTER MOULDING N/S	11 \$52.30 X
1PCS	BONNET	Buc \$433.60 /
2PCS	BONNET HINGES @\$35.00	11 \$70.00 X
1PCS	BONNET LOCK	1w1 \$89.30 /
1PCS	BONNET RUBBER SEAL	nee \$18.60 ✓
1PCS	FRONT BUMPER	D.S \$523.50 /
1PCS	FRONT BUMPER TOW COVER	Torn \$15.00 /
1PCS	FRONT BUMPER CENTRE GRILLE	11 \$95.60 X
2PCS	FRONT BUMPER SIDE RETAINERS @\$20.50	3rd \$41.00 /
1PCS	FRONT BUMPER REINFORCEMENT	3rd \$245.00 /
1PCS	FRONT GRILLE	3rd \$137.50 /
1PCS	FRONT GRILLE LOGO	nee \$28.80 /
2PCS	HEADLAMPS @\$643.00	Cne \$1286.00 /
2PCS	HEADLAMP LOWER BRACKETS @\$28.80	11 \$57.60 X
1PCS	FRONT SUPPORT PANEL	3rd \$428.00 /
1PCS	HORN UNIT	11 \$46.70 X
1PCS	AIR CON CONDENSER	2nd/2nd \$762.80 /
2PCS	AIR CON CONDENSER TOP BRACKETS @\$10.80	11 \$21.60 X
1PCS	AIRCON COOLING PIPE	11 \$211.30 X
1PCS	AIR CON DISCHARGE PIPE	11 \$320.50 X

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	AIR CON SUCTION PIPE	1 1 \$285.40 X
1PCS	AIRCON FAN COWLING	one \$91.00 /
1PCS	AIRCON FAN MOTOR	1 1 \$266.50 X
1PCS	AIRCON FAN BLADE	1 1 \$92.20 X
1PCS	RADIATOR	3mt/2m \$1137.00 /
1PCS	RADIATOR FAN BLADE	1 1 \$91.00 X
1PCS	RADIATOR FAN MOTOR	1 1 \$354.60 X
1PCS	RADIATOR FAN COWLING	one \$95.20 /
2PCS	RADIATOR TOP BRACKETS @\$10.80	1 1 \$21.60 X
1PCS	RADIATOR TOP HOSE	1 1 \$23.50 X
1PCS	RADIATOR SPARE TANK	one \$66.30 /
2PCS	FRONT FENDERS @\$352.20	1 \$704.40 X
2PCS	FRONT FENDER INNER SHIELDS @\$69.30	1 1 \$138.60 X
1SET	FRONT FENDER INNER SHIELD CLIPS	1 1 \$45.00 X
1PCS	WASHER TANK	1 1 \$68.30 X
1PCS	RELAY BOX	1 1 \$385.00 X
1PCS	FRONT WIRE HARNESS	1 1 \$936.90 X
1PCS	ALTERNATOR	1 1 \$780.50 X
1PCS	ALTERNATOR BELT	1 1 \$59.40 X
1PCS	AIR CLEANER BOX TOP	1 1 \$44.70 X
1PCS	AIR CLEANER BOX BOTTOM	1 1 \$107.30 X
1PCS	ENGINE INLET MANIFOLD	1 1 \$565.50 X

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	ABS PUMP	11 \$1911.20 X
3PCS	ABS PUMP PIPES @\$98.20	11 \$294.60 X
1PCS	WIPER PANEL GARNISH	11 \$165.10 X
1SET	WIPER PANEL GARNISH CLIPS	11 \$30.00 X
1PCS	FRONT WINDSCREEN	11 \$1150.30 X
1PCS	FRONT WINDSCREEN MOULDING	11 \$85.00 X
2PCS	HEADLAMP VERTICAL PANELS @\$118.50	11 \$237.00 X
1PCS	AIR DUCT	11 \$42.50 X
1PCS	AIR CON COMPRESSOR	11 \$1715.80 X
2PCS	FRONT WHEEL HOUSING PANELS @\$665.20	11 \$1330.40 X
2PCS	FRONT CHASSIS MEMBERS @\$545.50	11 \$1091.00 X
1PCS	BRAKE BOOSTER PUMP	11 \$572.60 X
1PCS	ENGINE MOUNTING BRACKET O/S	11 \$322.30 X
1PCS	ENGINE ROCKER GARNISH	11 \$185.60 X
1PCS	FRONT EXHAUST HEAT SHIELD	11 \$105.30 X
1PCS	OXYGEN SENSOR	11 \$196.20 X
1PCS	EGR VALVE	11 \$315.60 X
1PCS	AIR BAG STEERING	11 \$1802.30 X
1PCS	AIR BAG PASSENGER	11 \$2120.60 X
1PCS	AIR BAG CRASH SENSOR	11 \$145.30 X
1PCS	AIR BAG CONTROL UNIT	11 \$750.00 X
1PCS	AIR BAG IMPACT SENSOR	11 \$125.00 X

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
-----	------------	------------

List Item:

1PCS	DASHBOARD	11 \$580.30 X
1PCS	ENGINE UNDER COVER	11 \$63.60 X

List Item Total:

\$45,405.70 9361.6
7488.4

Special Nett Item:

1SET	REAR REVERSE SENSOR	Regud \$280.00 X
1PCS	REAR LICENCE PLATE W/HOLDER	Bul \$50.00 40
1PCS	REAR WINDSCREEN SEALANT	rec \$50.00 40
1PCS	REAR WINDSCREEN SOLAR FILM	11 \$200.00 X
1PCS	REAR QUARTER GLASS SEALANT	rec \$50.00 30
1PCS	REAR SPORT RIM N/S	11 \$380.00 X
1PCS	REAR TYRE N/S	11 \$200.00 X
1SET	REAR DOOR VISOR	11 \$100.00 X
1PCS	FRONT LICENCE PLATE W/HOLDER	Bul \$50.00 40
1PCS	FRONT WINDSCREEN SOLAR FILM	11 \$200.00 X
1BOL	RADIATOR COOLANT	rec \$50.00 ✓

Special Nett Total:

\$1610.00

Labour Charge:

TOWING CHARGE KINGROLLER.	\$150.00 50
TO CHECK WIRING.	\$100.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR.	\$80.00 50
TO DISMANTLE & REPLACING REAR WINDSCREEN.	\$150.00 120

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>Labour Charge:</u>		
	TO DISMANTLE & REFIX REAR SEAT ,CUSHION UPHOLSTERY.	\$300.00 80
11	TO CONDUCT WHEEL ALIGNMENT.	\$100.00 X
11	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE.	\$380.00 X
11	TO DISMANTLE & REFIX PETROL TANK.	\$100.00 X
11	TO MOUNT VEHICLE ON CAR-O-LINER.	\$380.00 X
	TO DISMANTLE & REPLACING QUARTER GLASS O/S.	\$100.00 60
11	TO TRANFER REAR DOOR MECHANISM.	\$180.00 X
	TO REFILL AIR CON GAS.	\$150.00 100
	TO DISMANTLE & REFIX FRONT ENGINE ,GEAR BOX FOR FACILITATE	
11	REPAIR FRONT CHASSIS.	\$500.00 X
11	TO DISMANTLE & REPLACING FRONT WINDSCREEN.	\$150.00 X
	TO SPRAY ANTI RUST PROOFING.	\$200.00 100
11	TO DISMANTLE & REPLACING FRONT DASHBOARD.	\$380.00 X
11	TO DISMANTLE & REPLACING FRONT AIR BAG & REPROGRAMME.	\$500.00 X
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.	\$5000.00 1800
	TO PUTTY & SPRAY PAINTING.	\$3800.00 1600
Labour Charge Total:		\$12,700.00 11 629.28 9303

ESTIMATE PARTS AND LABOUR GRAND TOTAL* \$59,715.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8406A

Vehicle Details

Vehicle No.: SJK8220C
Vehicle to be Exported: No
Intended De-registration Date: 22 May 2018
Vehicle Make: HONDA
Vehicle Model: HONDA JAZZ 1.3L A
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: L13Z11005991
Chassis No.: JHMGE68509S205990
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$17,997.00
Original Registration Date: 05 Nov 2008
First Registration Date: 05 Nov 2008
Transfer Count: 3
Actual ARF Paid: \$14,228.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Nov 2018
PARF Rebate Amount: \$7,114.00

Intended COE Rebate Details

COE Expiry Date: 04 Nov 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$4,098.00
COE Rebate Amount: \$496.00
Total Rebate Amount: \$7,610.00

The information contained herein is correct as at 22 May 2018

OK



CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

Click here to start the hunt!

Honda Jazz

Price Range

Depreciation

2008

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Straits Drive Pte Ltd > Honda Jazz 1.3A L

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Digital Analytics Course



Learn how to improve your marketing ROI through detailed data driven analysis.

Compare

Honda Jazz 1.3A L

OverviewFinancialAccessoriesSimilarResearchPhotosMap

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$13,800

Depreciation

\$9,470 /yr

View models with similar depreciation

Reg Date

24-Nov-2008

(6mths 1day COE left)

Manufactured

2008

Mileage

108,993 km (11.5k /yr)

Transmission

Auto

Engine Cap

1,339 cc

Road Tax

\$590 /yr

Power

73.0 kW (97 bhp)

View specs of the Honda Jazz (2008-2014)

Curb Weight

1,090 kg

Features

1.3L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Paddle Shifters, Reverse Sensors, Multi Function Steering Control, Knockdown Rear Seats.

Accessories

Sports Rims, 2 x Tones Leather Seats, Fog Lamps, Reverse Sensors, Retractable Mirrors With Signal Indicators.

Description

Only Cost \$28 Daily Cheaper Than Rental! Drive 6 Months And Get Back Minimum \$9000 Or More! Selling Near Scrap! Must View. Cash Deal Available.

COE

\$13,289

OMV

\$17,997

ARF

\$17,997

Dereg Value

\$9,672 as of today (change)

No. of Owners

2

Type of Veh

Hatchback

Category

FAAF Car, Premium Ad Car

Availability

Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 21-May-2018 | Last Updated on: 21-May-2018

Tags: Honda Jazz, 2008 Honda Jazz, Honda Jazz, Used Honda

Upfront Payment

more Financial info

Transfer Fee

\$25

Down Payment

\$4,140 (change)

Maximum 70% Loan







Location Map

Price Analysis

Seller Information

Company

Straits Drive Pte Ltd

dealer's pricelist

23 vehs sold | 10 vehs available

Address

201 Henderson Road #03-10

Search cars nearby this location

Location

Apex @ Henderson

Office No

62545731

Contact Person(s)

Mlow Koh91527779

Joe Chua90066521

Useful Services

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation

http://www.sgcarmart.com/used_cars/info.php?ID=739400&DI=3080

22-May-18



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Honda Jazz

Price Range

Depreciation

2008

Vehicle Type

Submit

Advanced Search

Home > Used Cars > High Speed Motor > Honda Jazz 1.5M L

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS & UNIQUE Vehicle No.

Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!

Click here to see all Auspicious Numbers!

Honda Jazz 1.5M L

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

CAR DETAILS

Price	\$13,800	
Depreciation	\$10,800 /yr	
Reg Date	24-Nov-2008 (6mths 1day COE left)	
Manufactured	2008	
Mileage	124,000 km (13.1k /yr)	
Transmission	Manual	
Engine Cap	1,497 cc	
Road Tax	\$684 /yr	
Power	88.0 kW (118 bhp)	
Curb Weight	1,080 kg	
Features	1.5L DOHC I-VTEC Engine, SRS Airbags, Multi Function Steering Wheel.	
Accessories	Leather Seats, Sports Rims, Factory Fitted Audio System, Reverse Sensors, Retractable Side Mirrors With Indicators, Knockdown Rear Seats, Solar Film.	
Description	Smooth And Powerful, A Real Joy To Drive! Original Condition With No Touch Up Done! Engine And Manual Gear System Still In Excellent Condition! 100% Accident Free, Fully Service By Agent, Flexible Loan And Trade In Are Welcome, Please Contact Our Friendly Sales Consultant For A Viewing Appointment Before It's Gone! Free 1 Service And Car Polish.	
COE	\$4,927	
OMV	\$19,964	
ARF	\$16,649	
Dereg Value	\$8,574 as of today (change)	
No. of Owners	2	
Type of Veh	Hatchback	
Category	PAARF Car	
Availability	Available	



Seller Information

Company	High Speed Motor
Address	28 Sin Ming Lane #01-137
Location	Midview City
Office No	64568190
Contact Person(s)	Harjinder Singh 93386317 Manjit Singh 98581265

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Add to Shortlist Add to Compare Add a Note

Posted on: 12-May-2018 | Last Updated on: 19-May-2018
Tags: Honda Jazz, 2008 Honda Jazz, Honda, Jazz, Used Honda

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 13 March 2019 2:20 PM
To: 'jason@fastechauto.com.sg'
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: Your Ref: SJK8220C *Our Ref: CC6/EQI18009311/Umb3 [ACCIDENT INVOLVING SKE 1874G(EQI) & SJK 8220C ON 21/05/2018]

Your Ref: **SJK8220C** Without Prejudice
Our Ref: CC6/EQI18009311/Umb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SKE 1874G(EQI) & SJK 8220C ON 21/05/2018

We refer to the above matter.

We confirm settlement as follow:

Cost Of Repair (W/GST)	\$ 6,420.00
Loss Of Rental (12 days x \$100)	\$ 1,200.00
GIA Search Fee	\$ 2.00
Total	\$ 7,622.00

We will proceed to close case.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

DATE : 16.06.2018

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SJK82220C AND SKE1874G ON 21.05.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SJK8220C**, which was involved in the captioned accident with your insured vehicle no: **SKE1874G**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	6,420.00
2) Loss Of Rental	\$	1,200.00
3) GIA Search Fee	\$	2.00
	<u>\$</u>	<u>7,622.00</u>

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) Rental Agreement/Invoice | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Report/ GIA Search |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.
Yours faithfully,


Jason Tang (jason@fastechauto.com.sg)
For Fastech Auto Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/EQI18009311/Umb3

28 MAY 2018

TEO TECK HWEE
BK260B SENGKANG EAST WAY
#07-448
SINGAPORE 542260

Dear Sir/Madam,

ACCIDENT INVOLVING SKE 1874G / SJK 8220C / OTHERS ON 21/05/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

DATE : 21 May 2018

TO : EQ Insurance Company Limited

RE : ACCIDENT INVOLVING VEHICLE NO. SJK 8220C, SKE 1874A,
SLE 8702G, SJH 216 & SKL 3075V

ALONG TPE Towards ECP before Lor Flakes

ON SJK 8220 C.

I/We, Lee May Li Ellen

of (NRIC No./ROC No.) S1728406A

of BLK 134 Rivervale Street #06-722 S540134

owner of vehicle no. SJK 8220C in consideration of M/s FASTECH AUTO
PTE LTD repairing my/our vehicle SJK 8220C at my/our instruction and hereby
authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever
amount settled/payable by the Insurance Company and/or third party or to commence legal
proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use,
etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and
all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost
which may arisen therewith.

Signature of Owner :

Name of Owner :


Ellen Lee May Li

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax.Reg No: 200006262D

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Attn: Motor Claim Department

Tax Invoice : 20304

Date: 16.06.2018
Vehicle No: SJK8220C
Make/Model: HONDA JAZZ

Accident Date: 21.05.2018
Claim No : 0518-20304
Reference :
Policy No :

	Amount
To proceed on lump sum repair	SS 6,000.00

E. & O. E.	Total : SS	6,000.00
	GST @ 7% : SS	420.00
	Amount Due : SS	6,420.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: LEE MAY LI

Invoice : DCR-2018-06-07

Date : 02.06.2018

Agreement No : 20017

Payment Term: LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle : SKS5871P (0518-20304) \$ 1,200.00

Rental Period from 21.05.2018 to 02.06.2018 .

E. & O. E.

Total \$ 1,200.00

NANCY LAM

for Dynamic Car Rental

Dynamic Car Rental

DCR-2018-06-07

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883.

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

RENTAL TERMS AND CONDITIONS

No. 20017

Name <u>Lee May Li</u>			REG. No. <u>SK 5871P</u>		MAKE MODEL:	
ADDRESS					DIESEL ☐ PETROL ☐ E ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ F ☐	
			KM IN		DATE & TIME IN <u>2/6/18 @ 17:20pm</u>	
			KM OUT		DATE & TIME OUT <u>2/5/18 @ 10am</u>	
			KM DRIVEN		TIME USED	
NAMED DRIVER <u>Lim Yony Peng</u>						
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	HOURS		@S\$	
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	12 DAYS		@S\$ 100	1200
ADD NAMED DRIVER			WEEKS		@S\$	
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS		@S\$	
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)		SUB-TOTAL	1200
IMPORTANT NOTES: This vehicle is licenced to carry 04 passengers only. No refund will be given for vehicle returns early. No refund will be given for period left in vehicle. Hirer is liable to pay first \$2000 under section i & ii in any accident plus loss of earnings while damaged vehicle is under repair. Hirer is liable to pay all parking fee and traffic summonses. Vehicle return during office hour only. No Service on Public Holiday and Sunday. ADDITIONAL CONDITIONS: * Geographical areas: Singapore & West Malaysia. * Driver must be: a) 18 years old and above; b) holding a valid relevant class of driving license. * Additional Own Damage Excess of \$51,000 is applicable for any named/unnamed drivers who: a) age 22 to 23 years old; b) age 66 to 70 years old; c) with driving experience of 1 year to less than 2 years in Singapore on the relevant classes of driving license. * Additional All Claims excess of \$52,000 is applicable for any named/unnamed drivers who: a) is 18 years old to 21 years old and/or b) is 71 years old and above and/or c) with driving experience of less than 1 year on the relevant classes of driving license. * Upon returning the replacement vehicle, you must ensure that all expensive and important items to be removed away from this replacement vehicle. We'll will not be responsible for any reporting of such losses. * Hirer is liable to pay first \$2000 under section i & ii in any accident plus loss of earning while damage vehicle is under repair. Hirer is responsible for Additional \$2,000.00 Excess to the THIRD PARTY DAMAGE / INJURY claims.			TOTAL RENTAL			
			DELIVERY FEE			
			COLLECTION FEE			
			X PER DAY \$ PER WEEK \$ PER MONTH \$			
BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.) X PER DAY \$ PER WEEK \$ PER MONTH \$			PREPAYMENT		TOTAL CHARGE	
			CHECK		DEPOSIT	
			CASH			
			RECEIPT NO.		NETT CHARGE	
AMOUNT DUE / REFUND						
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF.						
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____						
X <u>[Signature]</u> DYNAMIC CAR RENTAL			X <u>[Signature]</u> RENTER'S/DRIVER'S SIGNATURE			

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-076519

Date of Request: 21/05/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 21/05/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SKE1874G
Accident Date 21/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKE1874G	EQ Insurance Company Ltd	14/02/2018-13/02/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-076519

Date of Request: 21/05/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 21/05/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SKE1874G
Accident Date 21/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 20/03/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKE 1874G (Insd Veh)	Your Ref. No. : DM18HO01284-JG
	SJK 8220C (TP Veh)	Our Ref. No. : CC6/EQI18009311/Upb3q2
Date of Accident	21/5/2018	

Liability	100%	
Final Repair Cost	: \$ 6,420.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 1,200.00	12 days
Others:	: \$ 2.00	
	: \$	
	7,622.00	
Final Settlement Sum	: \$ 7,622.00	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	FASTECH AUTO PTE LTD	: \$ 7,622.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI18009311/Upb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 20-03-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 1874G	Veh. Inspected	SJK 8220C	
Policy No.	DMPPHQ18-000624	Coverage (\$)	0.00	
Claim No.	DM18HO01284-JG	Excess (\$)	0.00	
Assign From		Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMGE68509S205990	Colour	BLACK	
Odometer	149365	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/45 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/45 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/45 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/05/2018	Inspection Date	22/05/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 8220C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	68.50	68.50
1	TAILGATE	BADLY DENTED	718.20	718.20
1	TAILGATE JAZZ EMBLEM	NECESSARY	32.90	32.90
1	TAILGATE INNER LOCK	DENTED / JAMMED	145.50	145.50
1	TAILGATE LOCK STRIKER	NOT NECESSARY	68.20	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	232.60	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	45.00	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	288.20	-
1	TAILGATE 'H' LOGO	NOT NECESSARY	38.20	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	625.30	-
2	TAILLAMPS @\$382.50	O/S BROKEN	765.00	382.50
1	REAR BUMPER	DISTORTED	493.70	493.70
2	REAR BUMPER SIDE RETAINERS @\$22.50	BENT	45.00	45.00
1	SET REAR BUMPER CLIPS	NECESSARY	39.00	39.00
2	REAR BUMPER SIDE GARNISHES @\$48.50	NO SUCH PARTS	97.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	92.30	92.30
1	TAILLAMP HOUSING PANEL O/S	DENTED	166.20	166.20
2	REAR FENDER @\$845.30	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	1,690.60	845.30
2	REAR FENDER INNER TRIM BOARD @\$266.30	O/S DISTORTED	532.60	266.30
2	REAR DOORS @\$765.30	TO REPAIR SEE LABOUR	1,530.60	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	845.20	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	266.90	-
1	REAR FLOOR PANEL SIDE MEMBER O/S	TO REPAIR SEE LABOUR	185.60	-
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	422.50	422.50
1	REAR END PANEL	BADLY DENTED	269.80	269.80
1	REAR END PANEL TOP GARNISH	TWISTED	60.80	60.80
1	REAR WINDSCREEN	NOT NECESSARY	1,050.20	-

Report Ref No. CC6/EQ18009311/Upb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILGATE INNER TOP SIDE GARNISH @\$112.50	NOT NECESSARY	225.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	464.80	-
2	REAR EXHAUST MOUNTING @\$20.50	NOT NECESSARY	41.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	64.50	64.50
1	REAR AIR VENT	NOT NECESSARY	26.00	-
2	REAR DOOR INNER TRIM BOARDS @\$301.30	NOT NECESSARY	602.60	-
2	REAR DOOR INNER LOCKS @\$186.20	NOT NECESSARY	372.40	-
1	REAR DOOR GLASS OUTER MOULDING N/S	NOT NECESSARY	49.60	-
2	SET REAR DOOR FRAME STICKERS @\$20.00	NOT NECESSARY	40.00	-
2	REAR DOOR HINGE N/S @\$65.40	NOT NECESSARY	130.80	-
2	REAR DOOR WEATHERSTRIP @\$166.20	NOT NECESSARY	332.40	-
1	REAR BACK SEAT REST	NOT NECESSARY	688.30	-
1	REAR BACK SEAT BELT N/S	NOT NECESSARY	466.20	-
2	REAR SHOCK ABSORBER @\$115.30	NOT NECESSARY	230.60	-
1	REAR WHEEL HUB BEARING N/S	NOT NECESSARY	332.30	-
1	REAR AXLE BEAM	NOT NECESSARY	865.40	-
1	REAR QUARTER GLASS N/S	NOT NECESSARY	285.30	-
1	ROOF PANEL	TO REPAIR SEE LABOUR	869.20	-
1	ROOF PANEL INNER LINING	NOT NECESSARY	766.30	-
1	FRONT DOOR N/S	NOT NECESSARY	785.20	-
1	FRONT DOOR GLASS OUTER MOULDING N/S	NOT NECESSARY	52.30	-
1	BONNET	BUCKLED	433.60	433.60
2	BONNET HINGES @\$35.00	NOT NECESSARY	70.00	-
1	BONNET LOCK	TWISTED	89.30	89.30
1	BONNET RUBBER SEAL	NECESSARY	18.60	18.60
1	FRONT BUMPER	DISTORTED	523.50	523.50
1	FRONT BUMPER TOW COVER	TORN	15.00	15.00
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	95.60	-
2	FRONT BUMPER SIDE RETAINERS @\$20.50	BENT	41.00	41.00
1	FRONT BUMPER REINFORCEMENT	BENT	245.00	245.00
1	FRONT GRILLE	BENT	137.50	137.50
1	FRONT GRILLE LOGO	NECESSARY	28.80	28.80

Report Ref No. CC6/EQ18009311/Upb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	HEADLAMPS @\$643.00	CRACKED	1,286.00	1,286.00
2	HEADLAMP LOWER BRACKETS @\$28.80	NOT NECESSARY	57.60	-
1	FRONT SUPPORT PANEL	BENT	428.00	428.00
1	HORN UNIT	NOT NECESSARY	46.70	-
1	AIR CON CONDENSER	BENT / PUNCTURE	762.80	762.80
2	AIR CON CONDENSER TOP BRACKETS @\$10.80	NOT NECESSARY	21.60	-
1	AIRCON COOLING PIPE	NOT NECESSARY	211.30	-
1	AIR CON DISCHARGE PIPE	NOT NECESSARY	320.50	-
1	AIR CON SUCTION PIPE	NOT NECESSARY	285.40	-
1	AIRCON FAN COWLING	CRACKED	91.00	91.00
1	AIRCON FAN MOTOR	NOT NECESSARY	266.50	-
1	AIRCON FAN BLADE	NOT NECESSARY	92.20	-
1	RADIATOR	BENT / PUNCTURE	1,137.00	1,137.00
1	RADIATOR FAN BLADE	NOT NECESSARY	91.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	354.60	-
1	RADIATOR FAN COWLING	CRACKED	95.20	95.20
2	RADIATOR TOP BRACKETS @\$10.80	NOT NECESSARY	21.60	-
1	RADIATOR TOP HOSE	NOT NECESSARY	23.50	-
1	RADIATOR SPARE TANK	DEFORMED	66.30	66.30
2	FRONT FENDERS @\$352.20	TO REPAIR SEE LABOUR	704.40	-
2	FRONT FENDER INNER SHIELDS @\$69.30	NOT NECESSARY	138.60	-
1	SET FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	45.00	-
1	WASHER TANK	NOT NECESSARY	68.30	-
1	RELAY BOX	NOT NECESSARY	385.00	-
1	FRONT WIRE HARNESS	NOT NECESSARY	936.90	-
1	ALTERNATOR	NOT NECESSARY	780.50	-
1	ALTERNATOR BELT	NOT NECESSARY	59.40	-
1	AIR CLEANER BOX TOP	NOT NECESSARY	44.70	-
1	AIR CLEANER BOX BOTTOM	NOT NECESSARY	107.30	-
1	ENGINE INLET MANIFOLD	NOT NECESSARY	565.50	-
1	ABS PUMP	NOT NECESSARY	1,911.20	-
3	ABS PUMP PIPES @\$98.20	NOT NECESSARY	294.60	-

Report Ref No. CC6/EQ18009311/Upb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER PANEL GARNISH	NOT NECESSARY	165.10	-
1	SET WIPER PANEL GARNISH CLIPS	NOT NECESSARY	30.00	-
1	FRONT WINDSCREEN	NOT NECESSARY	1,150.30	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	85.00	-
2	HEADLAMP VERTICAL PANELS @\$118.50	NOT NECESSARY	237.00	-
1	AIR DUCT	NOT NECESSARY	42.50	-
1	AIR CON COMPRESSOR	NOT NECESSARY	1,715.80	-
2	FRONT WHEEL HOUSING PANELS @\$665.20	TO REPAIR SEE LABOUR	1,330.40	-
2	FRONT CHASSIS MEMBERS @\$545.50	NOT NECESSARY	1,091.00	-
1	BRAKE BOOSTER PUMP	NOT NECESSARY	572.60	-
1	ENGINE MOUNTING BRACKET O/S	NOT NECESSARY	322.30	-
1	ENGINE ROCKET GARNISH	NOT NECESSARY	185.60	-
1	FRONT EXHAUST HEAT SHIELD	NOT NECESSARY	105.30	-
1	OXYGEN SENSOR	NOT NECESSARY	196.20	-
1	EGR VALVE	NOT NECESSARY	315.60	-
1	AIR BAG STEERING	NOT NECESSARY	1,802.30	-
1	AIR BAG PASSENGER	NOT NECESSARY	2,120.60	-
1	AIR BAG CRASH SENSOR	NOT NECESSARY	145.30	-
1	AIR BAG CONTROL UNIT	NOT NECESSARY	750.00	-
1	AIR BAG IMPACT SENSOR	NOT NECESSARY	125.00	-
1	DASHBOARD	NOT NECESSARY	580.30	-
1	ENGINE UNDER COVER	NOT NECESSARY	63.60	-
	LESS 20% DISCOUNT		-	-1,902.32
			45,035.70	7,609.28
	SPECIAL NETT ITEMS			
2	REAR REVERSE SENSORS @\$185.00 (SN)	SHORTED	370.00	200.00
1	SET REAR REVERSE SENSOR (SN)	REPEATED	280.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	200.00	-
1	REAR QUARTER GLASS SEALANT (SN)	NECESSARY	50.00	30.00
1	REAR SPORT RIM N/S (SN)	NOT NECESSARY	380.00	-

Report Ref No. CC6/EQI18009311/Upb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TYRE N/S (SN)	NOT NECESSARY	200.00	-
1	SET REAR DOOR VISOR (SN)	NOT NECESSARY	100.00	-
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	FRONT WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	200.00	-
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	50.00
			1,980.00	400.00
	LABOUR			
	TOWING CHARGE KINGROLLER.		150.00	50.00
	TO CHECK WIRING		100.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX REAR SEAT CUSHION UPHOLSTERY.		300.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX PETROL TANK	NOT NECESSARY	100.00	-
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REPLACING QUARTER GLASS O/S		100.00	60.00
	TO TRANFER REAR DOOR MECHANISM.	NOT NECESSARY	180.00	-
	TO REFILL AIR CON GAS.		150.00	100.00
	TO DISMANTLE & REFIX FRONT GRILLE ,GEAR BOX FOR FACILITATE REPAIR FRONT CHASSIS	NOT NECESSARY	500.00	-
	TO DISMANTLE & REPLACING FRONT WINDSCREEN.	NOT NECESSARY	150.00	-
	TO SPRAY ANTI RUST RUST PROOFING.		200.00	100.00
	TO DISMANTLE & REPLACING FRONT DASHBOARD	NOT NECESSARY	380.00	-
	TO DISMANTLE & REPLACING FRONT AIR BAG & REPROGRAMME.	NOT NECESSARY	500.00	-
	LABOUR FOR PANEL		5,000.00	1,800.00
	BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S,REAR DOORS,REAR FLOOR PANEL,REAR FLOOR PANEL SIDE MEMBER O/S,REAR EXHAUST,ROOF PANEL,FRONT FENDERS AND FRONT WHEEL HOUSING PANELS.			

Report Ref No. CC6/EQI18009311/Upb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.: 6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		3,800.00	1,600.00
			12,700.00	3,990.00
GRAND TOTAL			59,715.70	11,999.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CC6/EQI18009311/Upb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Wednesday, 20 March 2019 4:55 PM
To: 'Joel Goh'
Subject: TP Direct Settlement - Accident Involving SKE 1874G (OI) and SJK 8220C (TP) on 21/05/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933