

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHC 3362A

DATE 21/5/2018 10:08

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (LH) <i>X repair</i>			\$ 1,935.90
	Rear Fender Inner Lining (LH) <i>X su</i>			\$ 74.10
	Rear Windscreen Moulding <i>X m</i>			\$ 60.00
	Rear Door (LH) <i>X repair</i>			\$ 1,294.70
	Rear Door Protector(LH) <i>X repair</i>			\$ 54.50
	Front Door Protector (LH) <i>X repair</i>			\$ 74.90
	Frt Wheel Hup-Cap (LH) <i>— hup</i>			\$ 145.00
	Front Fender (LH) <i>X repair</i>			\$ 593.10
	Front Fender Shield (LH) <i>X su</i>			\$ 86.00
	Front Bumper Cover <i>X repair</i>			\$ 538.80
	Front Bumper Bracket Top (LH) <i>X su</i>			\$ 22.40
	<i>LH wing mirror X repair</i>			
	SUB TOTAL			\$ 4,879.40
	LESS 20%			\$ 975.88
	DISCOUNTED TOTAL			\$ 3,903.52
	Rear Bumper Rubber Mat <i>X m</i>			\$ 50.00 Nett
	Rear Windscreen Sealant <i>X m</i>			\$ 46.00 Nett
	Rear Door Tel No. Sticker (LH) <i>— m</i>			\$ 10.00 Nett
	Front Door Coloured Comfort Logo (LH) <i>— m</i>			\$ 75.00 Nett
				\$ 181.00
	Labour Charge			<i>400</i>
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,500.00 <i>1200</i>
	Wiring Charge			\$ 50.00 <i>X m</i>
	Tuff Kote			\$ 50.00 <i>X m</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>X m</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X m</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X m</i>
	Transfer of Door			\$ 120.00 <i>X m</i>
	Frt Wheel Alignment			\$ 120.00 <i>X m</i>
	TOTAL LABOUR			\$ 3,730.00
	ESTIMATE TOTAL			\$ 7,814.52
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				