

08/03/2008

ASS. REC. BY:

REF:

CS/msh18009318 / Gsp / x

Special Instruction:

Survivor

G12

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSTG

Date/Time:

22052018 236pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 81122

Insured:

PC 3841P

at Workshop m/s

Allswell Motor

Tel:

6679 1146

of

25 Delta Lane 9

Policy No:

2A077065MKT

Claim No:

558949

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21052018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

28052018 @ 11am

H.O.D. Endorsement:

Date/Time:

22052018 315pm

Person Contacted:

Chai Yee

Vehicle-IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SH 81122 - X

PC 3841P - X

31/5/18 @ 11:31am revised to Lionel Tan via Merimer.

25/7/18 @ 5:42pm Chai Yee (Wksp) informed this case already private settle.

XPR

REF: MS19

C25418

ASSIGNMENT

From: Date: 28/5/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 8 112 Z
at Workshop m/s: Alls Well Motor
of: 25 Defu Lane 9

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record) 11am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time: Action / Instruction

Veh No: SLH 8/12 Z Yr Regn: 18 Nov 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel CC: 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 109665 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU31220218

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 28-05-18

Survey held at: w/s 11:15AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 26 JUL 2018

Date/Time: File Pass to?

11/2/2018

Date/Time: File Return to?

2:

Report Format :

Lump Sum / I.B.I: (\$

☒ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

Survey Fee:

Transportation

1.3 - RS \$

Photos

Others

TOTAL

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2541Z
Vehicle Details	
Vehicle No.:	SLH8112Z
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5920267
Chassis No.:	RU31220218
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$27,014.00
Original Registration Date:	18 Nov 2016
First Registration Date:	18 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,206.00
COE Rebate Amount:	\$47,587.00
Total Rebate Amount:	\$51,337.00

The information contained herein is correct as at 30 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/05/2018 18:39
Date Of Accident 21/05/2018 11:25
Exact Location Of Accident JALAN SULTAN
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH8112Z
Insured/Policyholder
Name Of Registered Owner ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No 201432541Z
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-64625405

Vehicle Particulars

Manufacturer HONDA
Model VEZEL-1.5 HYBRID X (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY


Vehicle Category PRIVATE HIRE

Insurance Company


Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number 5085700497-01
Cover Note Number

Driver

Name of Driver EDMOND HO KOON PENG
NRIC No S2160976E
Date Of Birth 04/03/1956
Occupation OUTDOOR
Date Of Driving Pass 02/11/1977
Driving Experience 40 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97879495
Fax Number
Contact Number
Email Address NOEMAIL


Policyholder's Signature
Date & Time: 21/5/18


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: VEEV VEEV
NRIC/IDN No.: 21/5/18

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel: +65 6679 1146

email: enail@allswellmotor.com.sg

(3rd party claim against

• This survey is on a "Without Prejudice" basis

• No alteration/modification(s) is allowed

Estimate repair

Vehicle No.

Make & Model

Chassis No.

Date of survey

SLH81122

Honda Vezel Hybrid

Submitted by

COE expiry

Engine No.

3Days.
part by part.
before paint photos
(for RH side bumper)
After repair photos.

Eno G. S.

28/5/18

Bun

16/18

17-11-2026

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	R/H Tail lamp (rear)	01	\$597.3	✓ CBA	490
02	R/H Tailgate lamp (rear)	01	\$698.1	✓ CBA	282.2
03	Tailgate	01	\$1,219	X repair	X repair
04	Rear bumper	01	\$997.0	✓ CBA	762.7
05	Rear R/H rear side lamp	01	\$495.0	X repair	X repair
	Special Mett.				1393.8
01	Clips @ \$11.00 each	02	\$22.0	✓ CBA	20%: 1115.04
	Labour Description				
01	Dismantle / Assembly of 02 lamps / rear bumper /	01	\$160	30	
02	Panel beating / putty / grind tailgate / rear side bumper	01	\$660.0	200	
03	Spray painting of all affected parts (tailgate side bumper / rear lamp)	01	\$800.0	300	
					1667.04

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018		22 May 2018 14:36 Edit Adj Rpt	S\$2,385.92 Edit Estimates	S\$2,385.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Ren Ci Hospital , Co. Reg. No.: 201018593M								
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD , Co. Reg. No.: 201432541Z								
Vehicle Reg. No.:	SLH8112Z	Date of Loss:	21/05/2018 00:00 - :59 [18 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 558949	Policy/Cover Note No.:	29077065MKF (Comprehensive) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	PC3841P	Policy No. (Claimant):							
		Excess:							
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]								
Adj Asg. Remarks:	SJE Agree Please appoint LKK contact Chai Yee @ 6679 1146 Liability (Non- reporting)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH8112Z (558949)
[PC3841P]
TP
ALLSWELL LEASING & LIMOUSINE PTE LTD
May 21 2018 12:00AM
[Ren Ci Hospital]
Allswell Motor Traders

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Assessment Reports						1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail		Print	
1	31/05/18 11:31	Adjuster Immediate Advice				Load HTML	
Photos/Images						3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail		Print	
1	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
2	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
3	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
4	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
5	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
6	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
7	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
8	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
9	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
10	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
11	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
12	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
13	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
14	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
15	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
16	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
17	25/07/18 17:45	General View				Load JPG <input checked="" type="checkbox"/>	
18	25/07/18 17:45	Odometer Reading				Load JPG <input checked="" type="checkbox"/>	
19	25/07/18 17:45	Chassis Number				Load JPG <input checked="" type="checkbox"/>	
Documentation						1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail		Print	
1	22/05/18 12:33	Third Party Accident Report				Load PDF	
2	22/05/18 14:01	response from workshop				Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009318/GQBQ2

Date: 14/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29077065MKF

Claimant Vehicle No: SLH8112Z

Insured Vehicle No: PC3841P

Date of Loss: 21/05/2018

Nature of Claim: TP

Claim No: 558949

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH8112Z

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: LEB5920267

Reg. Date: 18/11/2016 (Man. Year: 2016)

Chassis No: RU31220218

Colour: White

Odometer: 109665 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,028.40	1,855.92	2,172.48	53.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	530.00	1,090.00	67.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,648.40	2,385.92	3,262.48	57.76
+ GST 7.00/7.00% (S\$)	395.39	167.01	228.38	57.76
Nett Amount (S\$)	6,043.79	2,552.93	3,490.86	57.76

INSPECTION

Date of Assignment: 22/05/2018

Date Inspected: 28/05/2018

Inspected At:

Allswell Motor Traders (HQ)

25 Defu Lane 9

Singapore 539266

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH8112Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/H TAILLAMP (REAR)	Cracked	597.30 F	*597.30 FL
2	1		*R/H TAILGATE LAMP (REAR)	Cracked	698.10 F	*698.10 FL
3	1		*TAILGATE	Repair	1,219.00 F	*- FL
4	1		*REAR BUMPER	Deformed	997.00 F	*997.00 FL
5	1		*REAR RH REAR SIDE BUMPER	Repair	495.00 F	*- FL
6	2		*CLIPS	Necessary	22.00 FS	*22.00 FS
					Sub Total (S\$)	4,028.40
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00
					Total Parts (S\$)	4,028.40
						1,855.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISMANTLE /ASSEMBLY OF 02 LAMPS /REAR BUMPER	New	160.00	30.00
2	PANEL BEATING /PUTTY /GUIDE TAILGATE /REAR SIDE BUMPER	New	660.00	200.00
3	SPRAY PAINTIN OF ALL AFFECTED PARTS (TAILGATE SIDE BUMPER /REAR BUMPER)	New	800.00	300.00
Gross Labour Cost (\$\$)			1,620.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >