

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 MAY 2018

Estimate No. : b1 47032
Date Estimated : 22/05/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Lam Wai
10 Bedok Reservoir
#09-29

Singapore 479236

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD7235E	5F01248	28/06/2016	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper upp, rear bumper lower & all attachments cause by accident

VALUE
850 2,550.00

Painting on rear bumper assembly

934 1,038.00

To check electrical wiring systems at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 3,845.00

DESCRIPTION

RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER TRIM BOTTOM (LINES)
REAR BUMPER TOWING EYE COVER
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	456.90	? 456.90
1	36.60	? 36.60
1	99.85	? 99.85
1	142.55	? 142.55
1	142.55	? 142.55
1	723.45	Rp 723.45
1	227.90	de 227.90
1	217.05	de 217.05
1	35.55	x 35.55
4	5.05	? 20.20

Total Parts : 2,102.60

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 47032**
Date Estimated : **22/05/2018**
Prepared By : **Kevin Leong Wai Kit**Page No. : **2 of 2**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD7235E	5F01248	28/06/2016	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 1/6/18 Excess S\$ _____

Surveyor's Name Tan Jia Sign Tan Jia

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date wp' Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail Tan Jia @ lkkant.com

No. of Working Days Recommend 03 days

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,845.00
Parts	:	2,102.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	416.33
Grand Total	:	6,363.93

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY******** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****