

ASSIGNMENT

Sum Insured:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

S\$ 1,300.00

(3)

days

Reduction:

80

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed)

Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/Car)

S\$ 1,904.60

Loss of Rental (LOR):

S\$

284.00

(4)

days

x

\$ 71.00

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

31.00

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

2,219.60

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2,219.60

Name 1:

-

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$300.00

AUTO INSURE PPS LTD

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 73k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 - days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP50254 Yr Regn: 7/6/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: Mazda 3 cc 1496

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 64947 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JmCBN 2248H015874

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16 Toyo

R: " Triangle

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 17/5/18 D.O.I: 21/5/18

Survey held at: Auto Insure

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP \$1,780.00
CRAB: \$7,450.00 (80%)

1780

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) 3 + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18009321/Sua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 22-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFM 3389U	Veh. Inspected	SLP 5025U	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00HP8	Excess (\$)	0.00	
Assign From		Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/05/2018	Inspection Date	21/05/2018	
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto Insure Pte. Ltd.

Blk 3, 891A Woodlands Road
Yew Tee Industrial Estate
Singapore (677954)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6368 2788 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLP5025U
Your Ref: SFM3389U

Date: 21-May-18

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT
email: motor.survey@axa.com.sg

8 Shenton way
#27-01/02 AXA Tower
Singapore 068811

Assessed Vehicle No : SLP5025U
Car Make and Model : MAZDA3 1.5L SDN
Date of Accident : 17-May-18
Date of Assessment : 21-May-18

We have carried out a physical assessment of SLP5025U at our workshop Auto Insure Pte Ltd
sustained damages to the REAR portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had
sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : \$ 10,100.00
Est. Repair Days : 5



** Considering that our vehicle is less than 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a **"WITHOUT PREJUDICE"** basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated
as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.
No liability or responsibility whatsoever shall be held by
AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SLP5025U
Your Ref: SFM3389U

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER ✓ Deform		\$ 1,125.50
2	2	REAR BUMPER SIDE RETAINER *		\$ 118.00
3	1	REAR REINFORCEMENT *		\$ 589.90
4	1	REAR END PANEL *		\$ 822.80
5	1	REAR END PANEL INNER GARNISH X		\$ 437.20
6	1	BOOT R		\$ 1,965.00
7	2	BOOT HINGE X		\$ 260.00
8	1	BOOT EMBLEM ✓ NEC		\$ 210.00
9	1	REAR BOOT LOCK UPPER X		\$ 365.50
10	1	REAR BOOT LOCK LOWER X		\$ 355.10
SUB TOTAL				\$ 6,450.00
LESS 20%				\$ 1,290.00
TOTAL AMOUNT				\$ 5,160.00

1075.00
nn

nn
75.00
nn

1150.00
- 20%
\$ 920.00

Our Ref: SLP5025U
Your Ref: SFM3389U

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	2	REAR REVERSE SENSOR *		\$ 280.00
2	1 SET	REAR BUMPER CLIPS ✓ NEC		\$ 30.00
3	1	REAR END PANEL SEALANT *		\$ 80.00
SUB TOTAL				\$ 420.00
TOTAL PARTS COST				\$ 5,580.00

nn

nn
30.00

Our Ref: SLP5025U
Your Ref: SFM3389U

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 400 1,200.00
2	TOWING CHARGE	\$ 120.00
3	TO REMOVE AND REFIX AIRCON CONDENSOR AND RADIATOR	\$ -
4	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 250.00
	TO CONDUCT HEADLAMP FOCUS	\$ -
	TO CONDUCT WHEEL ALIGNMENT	\$ -
	LABOR FOR UNDERCARRIDGE	\$ -
5	REMOVE AND REFIX REAR WINDSCREEN	\$ -

X 1.1

X 2.2

nn

nn

nn

nn

6	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$	200.00	X
7	TO REMOVE / INSTALL REAR REVERSE SENSOR ?	\$	180.00	X
8	TO REMOVE / INSTALL REAR BOOT MACHANISM	\$	200.00	X
9	TO REMOVE / REFIX UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$	-	
10	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$	-	
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$	400 1,000.00	
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS ?	\$	200.00	X
13	TO VACUUM, WAXING & CLEAN	\$	100.00	X
14	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$	30 200.00	
TOTAL BEFORE GST		\$	9,230.00	
GST 7%		\$	646.10	
TOTAL (PARTS & LABOUR):		\$	9,876.10	

830.00

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$10,100.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

\$1780.00

LIS - \$1400+

3 days.

Sebastian
21/5/18.

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint

90036121

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto Insure Pte. Ltd.

Blk 3, 391A Woodlands Road
Yew Tee Industrial Estate
Singapore (677964)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6368 2788 F: 6368 0081
GST No.: 201437380M

Page No. 1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLP5025U
Your Ref: SFM3389U

Date: 21-May-18

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

email: motor.survey@axa.com.sg

8 Shenton way
#27-01/02 AXA Tower
Singapore 068811

Assessed Vehicle No : SLP5025U
Car Make and Model : MAZDA3 1.5L SDN
Date of Accident : 17-May-18
Date of Assessment : 21-May-18

We have carried out a physical assessment of SLP5025U at our workshop Auto Insure Pte Ltd sustained damages to the REAR portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : \$ 10,100.00
Est. Repair Days : 5



** Considering that our vehicle is less than 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a **"WITHOUT PREJUDICE"** basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.
No liability or responsibility whatsoever shall be held by
AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SLP5025U
Your Ref: SFM3389U

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER Defam.		\$ 1,325.50
2	2	REAR BUMPER SIDE RETAINER ?		\$ 118.00
3	1	REAR REINFORCEMENT ?		\$ 589.90
4	1	REAR END PANEL ?		\$ 822.80
5	1	REAR END PANEL INNER GARNISH X		\$ 437.20
6	1	BOOT R		\$ 1,965.00
7	2	BOOT HINGE X		\$ 260.00
8	1	BOOT EMBLEM VNEC		\$ 210.00
9	1	REAR BOOT LOCK UPPER X		\$ 365.50
10	1	REAR BOOT LOCK LOWER X		\$ 355.10
			SUB TOTAL	\$ 6,450.00
			LESS 20%	\$ 1,290.00
			TOTAL AMOUNT	\$ 5,160.00

Our Ref: SLP5025U
Your Ref: SFM3389U

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	2	REAR REVERSE SENSOR ?		\$ 280.00
2	1 SET	REAR BUMPER CLIPS VNEC		\$ 30 80.00
3	1	REAR END PANEL SEALANT ?		\$ 80.00
			SUB TOTAL	\$ 420.00
			TOTAL PARTS COST	\$ 5,580.00

Our Ref: SLP5025U
Your Ref: SFM3389U

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 400 1,200.00
2	TOWING CHARGE	\$ 120.00 X
3	TO REMOVE AND REFIX AIRCON CONDENSOR AND RADIATOR	\$ -
4	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 250.00 X
	TO CONDUCT HEADLAMP FOCUS	\$ -
	TO CONDUCT WHEEL ALIGNMENT	\$ -
	LABOR FOR UNDERCARRIDGE	\$ -
5	REMOVE AND REFIX REAR WINDSCREEN	\$ -

6	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$	200.00	X
7	TO REMOVE / INSTALL REAR REVERSE SENSOR ?	\$	180.00	
8	TO REMOVE / INSTALL REAR BOOT MACHANISM	\$	200.00	X
9	TO REMOVE / REFIX UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$	-	
10	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$	-	
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$	400 1,000.00	
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS ?	\$	200.00	
13	TO VACUUM, WAXING & CLEAN	\$	100.00	X
14	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$	30 200.00	
TOTAL BEFORE GST		\$	9,230.00	
GST 7%		\$	646.10	
TOTAL (PARTS & LABOUR):		\$	9,876.10	

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$10,100.00** for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

Sebastian
21/5/18.

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint

90036121

sebastianyong@lkkauto.com

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23/5/2018

Survey Details:

Date of loss	17-May-18
Date of appointment	21-May-18
Date of survey	21-May-18
Location of survey	Auto Insure Pte Ltd

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLP 5025U
Make and Model	MAZDA3 SEDAN 1.5 AT EU6 - 1496cc
Date of registration	7-Jun-17
Excess	
Market Value	\$ 73,000.00
Parf Rebate	\$ 48,300.00
Nett Loss	\$ 24,700.00

Repair details:

Initial Estimate	\$ 9,230.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,259.20
Check items (estimate)	\$ 1,964.56
Labour	\$ 830.00
Total	\$ 4,053.76
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>3 days</u>
---------------------------	---------------



Service Request Details

Claim

S8M00HP8

Reference

None 

Loss Date

May 17, 2018

Request Date

May 21, 2018

Due Date

May 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

21052018 @ 1:39pm
Geradine vehin
Sabashun

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLP5025U

Make

TPVD MAZDA

Service Address

...

Primary Contact/Insured

ANG ENG CHOON
61 KAMPONG ARANG ROAD, #07-02A, 438181, Singapore
96733138
reggy.yanpl@gmail.com

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:RE: Re:SEEKING MANDATE APPROVAL FOR S8M00HP8

Type

🔗 Question

Message

PLS PROCEED

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFM 3389U (Insd veh)	Model:	MAZDA 3
	SLP 5025U (TP veh)		
Date of Accident:	17/05/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	9,876.10
Final Repair Cost	:	\$	1,904.60
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	284.00 4 days
LTA / GIA Search Fee	:	\$	31.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 2,219.60

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	AUTO INSURE PTE. LTD.	: \$ 2,219.60

NUR SHAQILAH BTE ABDOL
WAHAB

15/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009321/Sha3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: KIAN CHUAN

Date : 15-01-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 3389U	Veh. Inspected	SLP 5025U
Policy No.	VPA/P1691568	Coverage (\$)	0.00
Claim No.	S8M00HP8	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	21/05/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0158721	Colour	GREY
Odometer	64947	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	TOYO	6 mm
L/H Front Tyre	205/60R16	TOYO	6 mm
R/H Rear Tyre	205/60R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/05/2018	Inspection Date	21/05/2018
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5025U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,326.50	1,075.00
2	REAR BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	118.00	-
1	REAR REINFORCEMENT (CONSISTENT)	NOT NECESSARY	589.90	-
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	822.80	-
1	REAR END PANEL INNER GARNISH (CONSISTENT)	NOT NECESSARY	437.20	-
1	BOOT (CONSISTENT)	TO REPAIR SEE LABOUR	1,965.00	-
2	BOOT HINGE (CONSISTENT)	NOT NECESSARY	260.00	-
1	BOOT EMBLEM (CONSISTENT)	NECESSARY	210.00	75.00
1	REAR BOOT LOCK UPPER (CONSISTENT)	NOT NECESSARY	365.50	-
1	REAR BOOT LOCK LOWER (CONSISTENT)	NOT NECESSARY	355.10	-
	LESS 20% DISCOUNT		-1,290.00	-230.00
			5,160.00	920.00
SPECIAL NETT ITEMS				
2	REAR REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			420.00	30.00
LABOUR				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF BOOT.		1,200.00	400.00
	TOWING CHARGE.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX AIRCON CONDENSOR AND RADIATOR. (NPA)	NOT NECESSARY	-	-
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.	NOT NECESSARY	250.00	-
	TO CONDUCT HEADLAMP FOCUS. (NPA)	NOT NECESSARY	-	-
	TO CONDUCT WHEEL ALIGNMENT. (NPA)	NOT NECESSARY	-	-
	LABOUR FOR UNDERCARRIAGE. (NPA)	NOT NECESSARY	-	-
	REMOVE AND REFIX REAR WINDSCREEN. (NPA)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM18009321/Sha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.	NOT NECESSARY	200.00	-
	TO REMOVE / INSTALL REAR REVERSE SENSOR.	NOT NECESSARY	180.00	-
	TO REMOVE / INSTALL REAR BOOT MECHANISM.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIX UPHOLSTERY, GARNISH AND ATTACHMENT PARTS. (NPA)	NOT NECESSARY	-	-
	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT. (NPA)	NOT NECESSARY	-	-
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		1,000.00	400.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO VACUUM, WAXING & CLEAN.	NOT NECESSARY	100.00	-
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTION.		200.00	30.00
			3,650.00	830.00
GRAND TOTAL			9,230.00	1,780.00
RECOMMENDED COST OF REPAIRS				1,780.00

Report Ref No. CC4/ASM18009321/Sha3s2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.