

INS. CASE OWNER:

CC 4 / QBE 1800

9324 / Sha32

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

17,150.00 (14 days) Reduction: 27 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia: 100

Repair Cost:

SS

17,150.00

(3 VEH. O.C.; OLD CMT)

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

1,400.00 x 14 days

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

18,857.45

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

SS

18,857.45

Name 1:

CARL MOTOR & ENTERPRISE CENTRE PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

REF:

9324 / Sha3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1A days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLM4333C

Yr Regn:

21/1/1994

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz S280

G.C.

2799

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp Reading

97342

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WOB 1400282A-1750/6

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45 ZR18

Maxxis

R:

"

Sumi

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/5/18

D.O.I.

18/5/18

Survey held at

Carl Auto

Des. of Damages: Fty / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

U/S 217,450.00
CRAB: 16,400.50 / 27.1%

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Survey Fee:

Transportation:

) S+RS: SI

) Photos

) Other:

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18009324/Sha3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 22-05-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 4425B	Veh. Inspected	SLM 4333C	
Policy No.	8-V0014273-MVA-R001	Coverage (\$)	0.00	
Claim No.	VC011481	Excess (\$)	0.00	
Assign From		Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/05/2018	Inspection Date	18/05/2018	
Survey held at	CARL MOTOR & ENTERPRISE CENTRE 38 WOODLANDS IND. PK E1 #05-10 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

CARL MOTOR & ENTERPRISE CENTRE PTE LTD

No. 38 Woodlands Ind. Park E 1 #05-10

Singapore 757700

Tel: 63666171 Fax: 63666805

Co. Reg. No: 199901512 Z

18 May 2018

QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay #29-10

South Tower

Singapore 048583

Tel: 64771184

e-mail: joyce.foo@qbe.com

Attention: Motor Claim (3 Party Claim)

Dear Sir/Mdm

M/BENZ WDB 140 - Veh No: SLM 4333 C

(Accident Involving SLM 4333 C, GY 4191 R and YP 4425 B on 14.05.2018 along SLE TWDS CTE)

Nett items:

1.	1 pc	Bonnet. <i>✓ DT</i>		\$ 2,525.00
2.	1 pc	Bonnet lock. <i>✓ JM</i>		74.00
3.	1 pc	Bonnet sponge. <i>✓ NEC</i>		176.00
4.	2 pcs	Bonnet stopper. <i>✓ NEC</i>	@ \$45.00	90.00
5.	1 pc	Bonnet pull handle. <i>✓ JM</i>		65.00
6.	1 pc	Grille. <i>✓ CRK</i>		697.00
7.	1 pc	Front bumper. <i>✓ CRK</i>		2,027.00
8.	1 pc	Front bumper sponge. <i>X NN</i>		120.00
9.	2 pcs	Front bumper side bracket - L & R. <i>X NW</i>	@ \$ 120.00	240.00
10.	2 pcs	Front bumper moulding - L & R. <i>✓ NEC</i>	@ \$ 160.00	320.00
11.	2 sets	Front & rear bumper clips. <i>✓ NEC</i>	@ \$ 60.00	120.00
12.	2 pcs	Head lamp - L & R. <i>✓ CRK</i>	@ \$ 996.00	1,992.00
13.	1 pc	Head lamp lower garnish - <i>LH. RH CRK ✓</i>		68.00
14.	2 pcs	Head lamp panel - L & R. <i>✓ Defomg</i>	@ \$ 159.00	318.00
15.	2 pcs	Side lamp - L & R. <i>✓ CRK</i>	@ \$ 160.00	320.00
16.	1 pc	Radiator. <i>✓ DT</i>		518.00
17.	1 pc	Radiator top panel. <i>✓ Defomg</i>		151.00
18.	1 pc	Radiator top panel garnish. <i>✓ CRK</i>		110.00
19.	1 pc	Radiator fan blade. <i>✓ CRK</i>		130.00
20.	1 pc	Radiator fan cowling. <i>✓ CRK</i>		145.00
21.	1 pc	Air-con. condenser. <i>✓ DT</i>		851.00
22.	2 pcs	Air-con. fan motor. <i>✓ DMG</i>	@ \$ 269.00	538.00
23.	2 pcs	Air-con. fan cowling. <i>✓ CRK</i>	@ \$ 52.00	104.00
24.	1 pc	Air-con. fan cowling protector. <i>✓ CRK</i>		160.00
25.	1 pc	Rear bumper. <i>✓ CRK</i>		2,530.00
26.	1 pc	Rear bumper sponge. <i>✓ CRK</i>		98.00
27.	2 pcs	Rear bumper moulding - L & R. <i>✓ NEC</i>	@ \$ 123.00	246.00
28.	1 pc	Rear bumper centre moulding. <i>✓ NEC</i>		159.00
29.	2 pcs	Taillamp - L & R. <i>✓ CRK</i>	@ \$ 480.00	960.00
30.	1 set	Reverse sensor. <i>✓ DMG</i>		920.00
31.	1 pc	Rear lid. <i>✓ DT</i>		1,065.00
32.	1 pc	Rear end panel reflector. <i>✓ CRK</i>		350.00
33.	1 pc	Rear lid lock. <i>✓ JM</i>		695.00
34.	1 pc	Rear lid catch. <i>✓ DMG</i>		308.00
35.	1 pc	Rear lid weatherstrip. <i>TN</i>		92.00

CARL MOTOR & ENTERPRISE CENTRE PTE LTD
 No. 38 Woodlands Ind. Park E 1 #05-10
 Singapore 757700
 Tel: 63666171 Fax: 63666805
 Co. Reg. No: 199901512 Z

18 May 2018

QBE Insurance (Singapore) Pte Ltd
 1 Raffles Quay #29-10
 South Tower
 Singapore 048583
 Tel: 64771184
 e-mail: joyce.foo@qbe.com
 Attention: Motor Claim (3 Party Claim)

Dear Sir/Mdm

M/BENZ WDB 140 - Veh No: SLM 4333 C

(Accident Involving SLM 4333 C, GY 4191 R and YP 4425 B on 14 05 2018 along SLE TWDS CTE

B/forwards from page 1

Nett items:

36.	1 pc	Rear lid "C C" logo. ✓	\$ 24.00
37.	1 pc	Rear lid "S 320" emblem. ✓	58.00
38.	1 pc	Rear lid "star" emblem. ✓	78.00
39.	1 pc	Rear end panel. ✓ DT	835.00
40.	1 pc	Rear end panel top garnish. ✓ CRK	68.00
			\$20,345.00
Less 10%			- 2,034.50
			\$18,310.50

S/nett:

41.	1 set	Front & rear number plate.	80.00
42.	1 pc	Coolant. ✓ NEC	60.00

Labour Charges:

43.	To remove & install Air-con. & fill gas.	150 180.00
44.	Workmanship for knocking & welding.	1800 2,880.00
45.	Respray painting.	1800 2,500.00
		\$ 23,930.50

Ng Khim Lee
 Director
 Hp: 96182026



Sebastian.
 22/5/18.

Lump Sum Repair -
 - Photo After Paint -
 Pg. 2
 90036121

sebastian.jiang@lkkauto.com

19985
 10%
 17986.5
 + 100
 + 3750
 21836.5
 20%
 17469.20

L/S: \$ 17450 @ 14 days
 confirmed.

14 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: VC011481
Our ref: CC4/QBE18009324/Sha3

Date: 21.05.2018

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLM 4333C

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.05.2018 at the premises of M/s Carl Motor & Enterprise Centre Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	23,930.50
Revised Estimate Amount	: S\$	21,836.50
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	21,836.50

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 14 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 21 May, 2018 7:52 PM
To: assignments
Subject: FW: Pre - repair inspection - SLM 4333 C (your client vehicle no: YP 4425 B accident on 14.5.2018) [VC011481]
Attachments: YP4425B-140518.pdf

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Sebastian.

From: Joyce Foo [mailto:joyce.foo@qbe.com]
Sent: Friday, 18 May, 2018 4:15 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: Pre - repair inspection - SLM 4333 C (your client vehicle no: YP 4425 B accident on 14.5.2018) [VC011481]

Our Ref. VC011481

Hi

Please arrange TP's survey – direct settlement.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Carl Motor [mailto:carlmtr@singnet.com.sg]

Sent: Friday, 18 May, 2018 3:35 PM

To: Joyce Foo <joyce.foo@qbe.com>

Subject: RE: Pre - repair inspection - SLM 4333 C (your client vehicle no: YP 4425 B accident on 14.5.2018) [VC011481]

Dear Mdm

Please arrange M/s. LKK Auto Consultants P L to survey vehicle SLM 4333 C.

Kindly let us have your approval and reply.

Thank you for your kind assistance.

Best Regards

Ricky Ng

Carl Mtr & Ent. Ctr P L

Tel: 63666171 Hp: 96182026

From: Joyce Foo <joyce.foo@qbe.com>

Sent: Friday, May 18, 2018 8:07 AM

To: carlmtr@singnet.com.sg

Cc: claims-singapore@qbe.com

Subject: FW: Pre - repair inspection - SLM 4333 C (your client vehicle no: YP 4425 B accident on 14.5.2018) [VC011481]

Our ref : VC011481

Dear Sirs/Madam

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Priority Services
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

We are agreeable to proceed with direct settlement subject to our surveyor's recommendation on COR, LOU/LOR per benchmark.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Info SINGAPORE
Sent: Thursday, 17 May, 2018 5:17 PM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>
Subject: FW: Pre - repair inspection - SLM 4333 C (your client vehicle no: YP 4425 B accident on 14.5.2018)

Hi All

Attached please find motor claim notification/survey request for your attention.

Regards
Grace Wong

From: Carl Motor [<mailto:carlmtr@singnet.com.sg>]
Sent: Thursday, 17 May, 2018 3:48 PM
To: Info SINGAPORE <info.sing@qbe.com>
Cc: motorclaim@qbe.com
Subject: Pre - repair inspection - SLM 4333 C (your client vehicle no: YP 4425 B accident on 14.5.2018)

Dear Sir / Mdm

Attached, please find SLM 4333 C, Letter of " Pre-repair Inspection" and SAS for your reference.

Please arrange to survey our client vehicle.

Thank you.

Best Regards
Ricky Ng
Carl Mtr & Ent. Ctr P L
Tel: 63666171 Hp: 96182026

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE18009324/Sha3s2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 08-03-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 4425B	Veh. Inspected	SLM 4333C
Policy No.	8-V0014273-MVA-R001	Coverage (\$)	0.00
Claim No.	VC011481	Excess (\$)	0.00
Assign From	JOYCE FOO	Assign Date	18/05/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ S280	c.c	2799
Engine No.	HIDDEN	Year of Reg.	1994
Chassis No.	WDB1400282A175016	Colour	SILVER
Odometer	97342	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45ZR18	MAXXIS	6 mm
L/H Front Tyre	225/45ZR18	MAXXIS	6 mm
R/H Rear Tyre	225/45ZR18	SUMITOMO	6 mm
L/H Rear Tyre	225/45ZR18	SUMITOMO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/05/2018	Inspection Date	18/05/2018
Survey held at	CARL MOTOR & ENTERPRISE CENTRE 38 WOODLANDS IND. PK E1 #05-10 SINGAPORE 757700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 4333C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET (N)	DENTED	2,525.00	2,525.00
1	BONNET LOCK (N)	JAMMED	74.00	74.00
1	BONNET SPONGE (N)	NECESSARY	176.00	176.00
2	BONNET STOPPER @ \$45.00 (N)	NECESSARY	90.00	90.00
1	BONNET PULL HANDLE (N)	JAMMED	65.00	65.00
1	GRILLE (N)	CRACKED	697.00	697.00
1	FRONT BUMPER (N)	CRACKED	2,027.00	2,027.00
1	FRONT BUMPER SPONGE (N)	NOT NECESSARY	120.00	-
2	FRONT BUMPER SIDE BRACKET - L & R @ \$120.00 (N)	NOT NECESSARY	240.00	-
2	FRONT BUMPER MOULDING - L & R @ \$160.00 (N)	NECESSARY	320.00	320.00
2	SETS FRONT & REAR BUMPER CLIPS @ \$60.00 (N)	NECESSARY	120.00	120.00
2	HEAD LAMP - L & R @ \$996.00 (N)	CRACKED	1,992.00	1,992.00
1	HEAD LAMP LOWER GARNISH - RH (N)	CRACKED	68.00	68.00
2	HEAD LAMP PANEL - L & R @ \$159.00 (N)	DEFORMED	318.00	318.00
2	SIDE LAMP - L & R @ \$160.00 (N)	CRACKED	320.00	320.00
1	RADIATOR (N)	DENTED	518.00	518.00
1	RADIATOR TOP PANEL (N)	DEFORMED	151.00	151.00
1	RADIATOR TOP PANEL GARNISH (N)	CRACKED	110.00	110.00
1	RADIATOR FAN BLADE (N)	CUT	130.00	130.00
1	RADIATOR FAN COWLING (N)	CRACKED	145.00	145.00
1	AIR-CON, CONDENSER (N)	DENTED	851.00	851.00
2	AIR-CON. FAN MOTOR @ \$269.00 (N)	DAMAGED	538.00	538.00
2	AIR CON. FAN COWLING @ \$52.00 (N)	CRACKED	104.00	104.00
1	AIR-CON. FAN COWLING PROTECTOR (N)	CRACKED	160.00	160.00
1	REAR BUMPER (N)	CRACKED	2,530.00	2,530.00
1	REAR BUMPER SPONGE (N)	CRACKED	98.00	98.00
2	REAR BUMPER MOULDING - L & R @ \$123.00 (N)	NECESSARY	246.00	246.00
1	REAR BUMPER CENTRE MOULDING (N)	NECESSARY	159.00	159.00
2	TAILLAMP - L & R @ \$480.00 (N)	CRACKED	960.00	960.00
1	SET REVERSE SENSOR (N)	DAMAGED	920.00	920.00
1	REAR LID (N)	DENTED	1,065.00	1,065.00

Report Ref No. CC4/QBE18009324/Sha3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL REFLECTOR (N)	CRACKED	350.00	350.00
1	REAR LID LOCK (N)	JAMMED	695.00	695.00
1	REAR LID CATCH (N)	DAMAGED	308.00	308.00
1	REAR LID WEATHERSTRIP (N)	TORN	92.00	92.00
1	REAR LID "C C" LOGO (N)	NECESSARY	24.00	24.00
1	REAR LID "S 320" EMBLEM (N)	NECESSARY	58.00	58.00
1	REAR LID "STAR" EMBLEM (N)	NECESSARY	78.00	78.00
1	REAR END PANEL (N)	DENTED	835.00	835.00
1	REAR END PANEL TOP GARNISH (N)	CRACKED	68.00	68.00
	LESS 10% DISCOUNT		-2,034.50	-1,998.50
			18,310.50	17,986.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT & REAR NUMBER PLATE (SN)	BROKEN	80.00	40.00
1	COOLANT (SN)	NECESSARY	60.00	60.00
			140.00	100.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL AIR-CON & FILL GAS.		180.00	150.00
	WORKMANSHIP FOR KNOCKING & WELDING.		2,800.00	1,800.00
	RESPRAY PAINTING.		2,500.00	1,800.00
			5,480.00	3,750.00
	GRAND TOTAL		23,930.50	21,836.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,450.00

Report Ref No. CC4/QBE18009324/Sha3s2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.