

CARL MOTOR & ENTERPRISE CENTRE PTE LTD

No. 38 Woodlands Ind. Park E 1 #05-10

Singapore 757700

Tel: 63666171 Fax: 63666805

Co. Reg. No: 199901512 Z

h

18 May 2018

QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay #29-10
South Tower
Singapore 048583
Tel: 64771184
e-mail: joyce.foo@qbe.com
Attention: Motor Claim (3 Party Claim)

Dear Sir/Mdm

M/BENZ WDB 140 – Veh No: SLM 4333 C

(Accident Involving SLM 4333 C, GY 4191 R and YP 4425 B on 14.05.2018 along SLE TWDS CTE)

Nett items:

1.	1 pc	Bonnet. ✓ DT		\$ 2,525.00
2.	1 pc	Bonnet lock. ✓ JM		74.00
3.	1 pc	Bonnet sponge. ✓ NEC		176.00
4.	2 pcs	Bonnet stopper. ✓ NEC	@ \$45.00	90.00
5.	1 pc	Bonnet pull handle. ✓ JM		65.00
6.	1 pc	Grille. ✓ CRK		697.00
7.	1 pc	Front bumper. ✓ CRK		2,027.00
8.	1 pc	Front bumper sponge. X		120.00
9.	2 pcs	Front bumper side bracket – L & R. X	@ \$ 120.00	240.00
10.	2 pcs	Front bumper moulding – L & R. ✓ NEC	@ \$ 160.00	320.00
11.	2 sets	Front & rear bumper clips. ✓ NEC	@ \$ 60.00	120.00
12.	2 pcs	Head lamp – L & R. ✓ CRK	@ \$ 996.00	1,992.00
13.	1 pc	Head lamp lower garnish – LH. RH CRK ✓		68.00
14.	2 pcs	Head lamp panel – L & R. ✓ Defom	@ \$ 159.00	318.00
15.	2 pcs	Side lamp – L & R. ✓ CRK	@ \$ 160.00	320.00
16.	1 pc	Radiator. ✓ DT		518.00
17.	1 pc	Radiator top panel. ✓ Defom		151.00
18.	1 pc	Radiator top panel garnish. ✓ CRK		110.00
19.	1 pc	Radiator fan blade. ✓ CRK		130.00
20.	1 pc	Radiator fan cowling. ✓ CRK		145.00
21.	1 pc	Air-con. condenser. ✓ DT		851.00
22.	2 pcs	Air-con. fan motor. ✓ DMG	@ \$ 269.00	538.00
23.	2 pcs	Air-con. fan cowling. ✓ CRK	@ \$ 52.00	104.00
24.	1 pc	Air-con. fan cowling protector. ✓ CRK		160.00
25.	1 pc	Rear bumper. ✓ CRK		2,530.00
26.	1 pc	Rear bumper sponge. ✓ CRK		98.00
27.	2 pcs	Rear bumper moulding – L & R. ✓ NEC	@ \$ 123.00	246.00
28.	1 pc	Rear bumper centre moulding. ✓ NEC		159.00
29.	2 pcs	Taillamp – L & R. ✓ CRK	@ \$ 480.00	960.00
30.	1 set	Reverse sensor. ✓ DMG		920.00
31.	1 pc	Rear lid. ✓ DT		1,065.00
32.	1 pc	Rear end panel reflector. ✓ CRK		350.00
33.	1 pc	Rear lid lock. ✓ JM		695.00
34.	1 pc	Rear lid catch. ✓ DMG		308.00
35.	1 pc	Rear lid weatherstrip. TN		92.00

CARL MOTOR & ENTERPRISE CENTRE PTE LTD

No. 38 Woodlands Ind. Park E 1 #05-10

Singapore 757700

Tel: 63666171 Fax: 63666805

Co. Reg. No: 199901512 Z

18 May 2018

QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay #29-10
South Tower
Singapore 048583
Tel: 64771184
e-mail: joyce.foo@qbe.com
Attention: Motor Claim (3 Party Claim)

Dear Sir/Mdm

M/BENZ WDB 140 – Veh No: SLM 4333 C

(Accident Involving SLM 4333 C, GY 4191 R and YP 4425 B on 14.05.2018 along SLE TWDS CTE)

B/forwards from page 1

\$19,282.00

Nett items:

36.	1 pc	Rear lid "C C" logo. ✓	\$ 24.00
37.	1 pc	Rear lid "S 320" emblem. ✓	58.00
38.	1 pc	Rear lid "star" emblem. ✓	78.00
39.	1 pc	Rear end panel. ✓	835.00
40.	1 pc	Rear end panel top garnish. ✓	68.00
			<u>\$20,345.00</u>
		Less 10%	<u>- 2,034.50</u>
			<u>\$18,310.50</u>

S/nett:

41.	1 set	Front & rear number plate.	Go 80.00
42.	1 pc	Coolant. ✓	60.00

Labour Charges:

43.	To remove & install Air-con. & fill gas.	150 180.00
44.	Workmanship for knocking & welding.	1800 2,800.00
45.	Respray painting.	1800 2,500.00
		<u>\$ 23,930.50</u>

Ng Khim Lee
Director
Hp: 96182026



Sebastian.
22/5/18.

- Imp Sun Repair.
- Photo After Paint.
Pg. 2
90036121

sebastianyeang@lkkauto-con.

14 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: