

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

21-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1012 T

1 pc	CRDI emblem <i>— nee</i>	\$	27.00
1 pc	Kia emblem <i>X na</i>	\$	29.00
1 pc	Rear bumper <i>— Refractal</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X su</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X su</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X su</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X su</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X su</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X su</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X su</i>	\$	36.00
		\$	1,915.00
Less 10%		\$	191.50
		\$	1,723.50

S/NETT

1 set	Rear bumper clips <i>— nee</i>	\$	48.00
1 set	Reverse sensor <i>— sheld</i>	\$	280.00
<i>Rear Bootlid lower garnish sticker — ne \$100</i>			200
Towing Fee		\$	50.00 <i>✓</i>
Sundry		\$	50.00 <i>20</i>
To dismantle / replace/test reverse sensor to new bumper and reset to the same		\$	120.00 <i>20</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>X 17</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel		\$	700.00 <i>300</i>
<i>X</i> To putty and spray painting on rear bumper, end panel, Bootlid lower garnish		\$	600.00 <i>360</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>X 17</i>
		\$	3,871.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in a display
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action shall be taken
- Supplementary items must be resurveyed and priced

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin (LKK)

22/5/18 1026h

2 Pys

PIP

Before Part p ltr

24/5/18
cancel 2/5 \$1400/20/18