

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0606/2018/GW
Date : 24-May-18

Kindly arrange for survey.

Your insured vehicle no. GBD 6883 J

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Dept

Fax: 6296 2706

Owner's Name : ShuSuke Tsukioka
Address : 91 Grange Rd
#02-03
Singapore 249613
Telephone : 96608992
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SKJ 7354 A**
Model Code : Audi A6 C7 Avant 2.0 TFSI
Model / Year : May-13
Engine No : CDN 331992
Chassis No : WAUZZZ4G5DN121783
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-May-18
Place of Accident : At The End Of Orchard BLVD Before Grange Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 7354 A.

S/N	Nature of Jobs			Estimated Charges	
1	To remove and transfer rear parking aid. Check function.	S/N	\$	280.00	✓
2	To renew rhs 1/4 glass To facillitate fender renewal.	S/N	\$	300.00	✓
3	To remove and transfer rhs rear door's multi lock system and power window devices.	S/N	\$	280.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment .	S/N	\$	1,400.00	✓
5	To remove and reinstall rear seat , back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts, dislodge roof liner and disengage curtain airbag etc.	S/N	\$	1,400.00	✓
6	To dismatle rhs rear door , rhs side member trim and rear bumper. Cut out and weld rhs rear fender. Repair outer wheel house. Renew rhs rear door, rhs side member trim and rear bumper. Reinstall all parts removed.		\$	6,300.00	✓

~~6,300.00~~

5600

8x700
= 5600

- 8 To renew rhs rear rim and carry out wheel alignment.
- 9 To carry out diagnostic check.

\$

~~6,000.00~~

4600

46.00

TOTAL LABOUR CHARGES

•

9

16,432.00

Handle = 50

Side member $700 \times 6 = 4200$
 Trunk $\frac{1}{2} \times 700 = 350$

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 7354 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-RH <i>dent</i>	\$ 3,211.00	✓
2	DOOR ATTACHMENT PARTS ?	\$ 106.00	?
3	REAR DOOR OUTER DOOR SEAL-RH <i>me</i>	\$ 202.00	✓
4	BONDING AGENT ?	\$ 43.00	?
5	CLEANING SOLUTION ?	\$ 64.00	?
6	REAR DOOR CATCH-RH <i>me</i>	\$ 105.00	✓
7	REAR DOOR SEAL-RH <i>me</i>	\$ 162.00	✓
8	REAR DOOR HANDLE-RH <i>Regis</i>	\$ 393.00	✓
9	REAR SIDE PANEL-RH <i>Distorted</i>	\$ 3,038.00	✓
10	REAR WHEEL HOUSING LINER-RH <i>me</i>	\$ 246.00	✓
11	WHEEL HOUSING LINER-RH <i>me</i>	\$ 68.00	✓
12	REAR SIDE WINDOW -RH <i>me</i>	\$ 446.00	✓
13	PRIMER <i>me</i>	\$ 19.00	✓
14	REAR SIDE WINDOW TRIM STIPRS-RH ?	\$ 222.00	?
15	REAR SIDE MEMBER TRIM-RH <i>Regis</i>	\$ 752.00	✓
16	CLIP ATTACHMENT PARTS <i>me</i>	\$ 91.00	✓
17	ADHESIVE TAPE ATTACHMENT PARTS <i>me</i>	\$ 14.00	✓
18	REAR STONE GUARD FILM-RH <i>me</i>	\$ 102.00	✓
19	DOUBLE SIDED ADHESIVE TAPE-RH <i>me</i>	\$ 53.00	✓
20	REAR BUMPER COVER <i>dent</i>	\$ 2,205.00	✓
TOTAL SPARE PARTS		\$ 11,542.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 7354 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR BUMPER STICKY PAD <i>me</i>	4 \$ 20.00	✓
22	REAR BUMPER FIXING PARTS	\$ 236.00	✓
23	REAR BUMPER LOWER GUIDE SECTION-RH	\$ 46.00	✓
24	REAR BUMPER GUIDE SECTION-RH	\$ 28.00	x
25	CONNECTING PIECE ?	\$ 11.00	?
26	REAR ALUMINIUM RIM-RH <i>wt</i>	\$ 726.00	✓
27	LED TAIL LIGHT <i>lt</i>	\$ 1,094.00	✓
28	1/4 GLASS SEALANT ?	S/N \$ 100.00	✓
29	ACRYLIC SEALER	S/N \$ 180.00	✓
30	CAVITY WAX <i>me</i>	S/N \$ 140.00	✓
31	STONE CHIP	S/N \$ 180.00	✓
32	METAL FILLER POWDER <i>me</i>	S/N \$ 280.00	✓
33	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 14,983.00	
TOTAL LABOUR CHARGES		: \$ 16,432.00	
GRAND TOTAL		: \$ 31,415.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling.
Surveyed Date : 30/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 14 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant