

22/03/2002

ASS. REC. BY:

REF: CS/FCI18009344/Ksd307

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Eileen Lee

of FCI

Date/Time: 22/05/2018 @ 5:05 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 95K

Insured: SHA 7738J

at Workshop m/s Trans-cab

Tel: G287 6666

of No. 2 AMK sf-63

Policy No:

Claim No: D18004050MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/05/2018

23/05/2018

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time: 5:20pm @ 22/5/18

Person Contacted:

Candy

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 95K - C03/FCI13018534/Kybk3

DOA: 19/07/2013

SHA 7738J - X

25/05/18 @ 15:35 p.m Revised PA to Eileen Lee (FCI) v.i.a email.

ASS. REC. BY:

REF: K021

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cob

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S110 95K Yr Regn: 08.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Renault Logan c.c. 1995

Colour: h-white / w A/C: Insured / Std / NI / NA

Sp. Reading: 341446 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIFIABL 15AUC 282163

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front 8 mm Rear 7 mm

R/Bal. 8 mm R/Bal. 7 mm

L/Bal. 8 mm L/Bal. 7 mm

D.O.A. 18/5/18 D.O.I. 24/5/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>25/5</u>	<u>File pass to Catherine</u>
<u>20/09/12</u>	<u>Confirmed P/P \$6,455.16 @ 4 days with Kenneth. (\$43,461.31 Red - 87%)</u>

Date/Time, File Pass to? 21/09/12  : Prell. Report  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Report Format :

Lump Sum / I.B.I. (\$) 6,455.16 P/P

Days Of Repair: 4

Resurvey No. of Trlp: 1

Add Fee:  : Site Insp (\$ )  : Interview (\$ )  : Tech Invs (\$ )  : Weekend (\$ )

Survey Fee:

Transportation: 50

S - RS. SI 50

Fixturs 20

Others 590

TOTAL 810

<u>1.0 x 15 = 600</u>
<u>170 + 600</u>
<u>50</u>
<u>50</u>
<u>20</u>
<u>590</u>
<u>810</u>

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	21-05-2018	<b>Our Ref No.</b> D18004050MFSH
<b>Accident Date</b>	18-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA7738J	<b>Third Party Vehicle.</b> SHD95K
<b>Survey Location</b>	NO. 2 ANG MO KIO STREET 63	
<b>Contact Person.</b>	CANDY KONG	
<b>Contact No.</b>	62876666/ 0	<b>Fax No.</b> 62571330
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	TRANS-CAB AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	EILEEN LEE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240593)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18004050MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & TRANS-C/
<b>Workshop Name</b>	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	<b>Survey Location &amp; Contact Details</b>	NO. 2 ANG MO KIO STREET 63 <b>Mobile:</b> 0 , <b>Phone:</b> 62876666 , <b>Fax:</b> 62571330 <b>EmailId:</b> CANDY.KONG@TRANSCAB.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHA7738J	<b>TP Vehicle No</b>	SHD95K
<b>PRI Recieved Date</b>	22-05-2018 05:51:33 PM	<b>Surveyor Appointed Date</b>	22-05-2018 05:04:04 PM	<b>Surveyor Accept Date</b>	22-05-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	22-05-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI180093447X

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-05-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7738J	Veh. Inspected	SHD 95K
Policy No.		Coverage (\$)	0.00
Claim No.	D18004050MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	23/05/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	ce
R/H Front Tyre			
L/H Front Tyre			
R/H Rear Tyre			
L/H Rear Tyre			

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	18/05/2018	Inspection Date	2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS	
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED	

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD95K
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 May 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002652
Chassis No.:	VF1ABL15AUC282163
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Aug 2015
First Registration Date:	14 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,236.00
COE Rebate Amount:	\$32,832.00
<b>Total Rebate Amount:</b>	<b>\$47,830.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 May 2018

OK

## Shirley Hiew (LKK Auto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Thursday, 20 September 2018 5:42 PM  
**To:** ShirleyHiew@lkkauto.com  
**Cc:** 'Candy Kong'  
**Subject:** FW: TCS REF: AAD1805-173--Accident involving SHD 95K & SHA 7738J on 18.05.18  
**Attachments:** ESTIMATE MARKED.pdf; IMG\_0095.JPG; IMG\_0096.JPG

Hi Shirley

We confirmed the amount \$6,455.16 (before GST).

Enclosed the before paint photos for your action.

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]  
**Sent:** Thursday, 20 September, 2018 9:51 AM  
**To:** [candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)  
**Cc:** [waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)  
**Subject:** TCS REF: AAD1805-173--Accident involving SHD 95K & SHA 7738J on 18.05.18

Hi Candy,

Please Confirm final fig \$6,455.16 @ 4 days of repairs before GST.

Kindly send us resurvey before paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 25 May 2018 3:35 PM  
**To:** 'Nivitha (LKK Auto)'; 'Claim Workflow System'; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; 'SUR'  
**Subject:** RE: SURVEY ASSESSMENT - D18004050MFSH/1  
**Attachments:** SHD 95K - Preli Advise.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHD 95K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 22 May 2018 5:21 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004050MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Tuesday, 22 May 2018 5:04 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [EILEENLEE@MSFIRSTCAPITAL.COM.SG](mailto:EILEENLEE@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004050MFSH/1

Dear Sir/Mdm,

We refer to the above reference.  
Please find attached the necessary documents for survey.  
Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004050MFSH

Date: 25 May 2018

Our Ref: CS/FCI18009344/Ksd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 95K.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/05/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>49,916.47</u> .
Revised Estimate Amount	: S\$ <u>6,455.16</u> .
"Check" Items Amount	: S\$ <u>406.71</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 4 Days

Yours faithfully,  
Kenneth Kong  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/05/2018 08:56
Date Of Accident	18/05/2018 20:55
Exact Location Of Accident	KJE SLIP ROAD TOWARDS BRICKLAND ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD95K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN POH JIONG
NRIC No	S0476120J
Date Of Birth	12/10/1944
Occupation	OUTDOOR
Date Of Driving Pass	25/08/1964
Driving Experience	53 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93252808
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 499C TAMPINES AVENUE 9 #07-252
Postcode	523499
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 18.05.2018 at about 2055hours, I was travelling straight along KJE slip road towards Brickland Road when I slow down to check for the road clearance. While stationary, suddenly I felt an impact. Vehicle B (SHA7738J) hit onto my taxi's rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7738J
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach G.A Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 95K**

AAD1805-173

*Not Authorized  
Recovery By paint*

Vehicle No.:	<b>SHD 95K</b>
Chassis No.:	VF1ABL15AUC282163
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	18.5.2018
Third Party Insurer :	<b>FCIL</b>

<b>PART</b>		<b>LIST</b>	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>na/na</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>DIY</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>su</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>su</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>su</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>su</i> 135.97 ✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>su</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>su</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>su</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>su</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>su</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>su</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
19	1 BOOT BADGE	\$	<i>na</i> 225.36
20	1 BOOT STRUT LH	\$	<i>su</i> 276.08
21	1 BOOT STRUT RH	\$	<i>su</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>su</i> 586.45
25	1 BOOT SWITCH	\$	<i>su</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>su</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>su</i> 221.81

**Trans-cab Auto Services Pte Ltd**

AAD1805-173

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 95K**

30	1 DOOR PANEL REAR LH	\$	<i>R</i>	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i>	671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sm</i>	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sm</i>	671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Sm</i>	543.47	
37	1 TAILLAMP RH	\$	<i>Sm</i>	552.55	
38	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	
39	1 TAILLAMP LH	\$	<i>Sm</i>	552.55	
40	1 TAILLAMP PANEL LH	\$	<i>R</i>	986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i>	404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sm</i>	612.21	X
45	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	X
46	1 EXHAUST CAP REAR	\$	<i>R</i>	230.49	X
47	1 FUEL FLAP L70Y	\$	<i>Sm</i>	343.57	X
<b>TOTAL</b>		<b>\$</b>		<b>39,057.17</b>	
<b>10%</b>		<b>\$</b>		<b>3,905.72</b>	
		<b>\$</b>		<b>35,151.45</b>	

**Special Nett**

1	1SET PARKING AID	\$	<i>Short</i>	700.00	✓
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	X
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	X
14	1 BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1805-173

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 95K**

16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	}
17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	
19	1 TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
20	1 TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
22	1 WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i>	385.00	
25	1 SPARE TYRE	\$	<i>sn</i>	330.00	X

**TOTAL \$ 2,225.02**

**TOTAL PARTS \$ 37,376.47**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>7</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>4</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>7</i> 170.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1805-173**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 95K**

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	601
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	NA X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	NA X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	NA X
To check steering geometry and computer wheel alignment	\$	220.00	NA X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	NA X
<b>TOTAL</b>	<b>\$</b>	<b>12,540.00</b>	12926

**Over All Total \$ 49,916.47**

**(PART-BY-PART)**

**Repair Days**

**20 DAYS**

4 days

50296-05

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009344/Ksd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHA 7738J	Veh. Inspected
	Policy No.	D-18088936MFSH	Coverage (\$)
	Claim No.	D18004050MFSH	Excess (\$)
	Assign From	EILEEN LEE	Assign Date
			22/05/2018
2. Vehicle Particulars & Condition			
	Make & Model	RENAULT LATITUDE (A)	c.c
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.	VF1ABL15AUC282163	Colour
	Odometer	341446	Steering
	Brakes	IN ORDER	Modification
	General	GOOD	NIL
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	215/60 R16	GITI
	L/H Front Tyre	215/60 R16	GITI
	R/H Rear Tyre	215/60 R16	FALKEN
	L/H Rear Tyre	215/60 R16	FALKEN
			Balance
			8 mm
			8 mm
			7 mm
			7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	18/05/2018	Inspection Date
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111	
24/05/2018			
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 95K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/FCI18009344/Ksd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-3,905.72	-464.46
			35,151.43	4,180.16
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00

Report Ref No. CS/FC118009344/Ksd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	865.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00





GRAND TOTAL		50,296.45	6,455.16
-------------	--	-----------	----------

RECOMMENDED COST OF REPAIRS			6,455.16
-----------------------------	--	--	----------

Report Ref No. CS/FCI18009344/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.