

INS. CASE OWNER:

CC 4/161800

9351 / Rina322

LKK:

IDAC:

Surveyor:

RANM

DOI:

ASSIGNMENT

Date / Time:

21/5/2018

Registered in Merimen:

23/05/2018

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR7937P

Name of Insured:

Lim Chng Heng

Insured Tel No.:

HP: 91051240

Excess Sec II :SS

D.O.A: 20/5/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

191284634254

Policy No.:

1700052479

Make / Model:

Mazda 2

Place of Accident:

SLP Rd at Lorong 2 Twa Payrh

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLP4165E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Lim Tan



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
31/5/18	SLP4165E - X; SLR7937P - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
25/6/18	no body pick up, OI call back (confirmed accident statement, informed TP claim and HCD USUA, agreed to settle and award the HCD 1544. send letter to OI.	Call OI: 25/6/2018 - PR	
		After call ltr to OI: 26/6/18 - ac	
		Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
30/07/18	SEND 1st OFFER TO TP.	Final Repair Bill:	
31/07/18	TP ACCEPTED OFFER.	Car Rental Invoice:	
	the body IN ORDER.	Towing Invoice:	
	TO CLOSE.	LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

RECEIVED 07 AUG 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: 49	SS 2,450.00 (6 days)	Reduction: 20 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 30/07/18	Confirm with: RICHARD	Email ☐ Call ☐
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.: 27	If NO or B 28, Ass. Lia:
Repair Cost: (w/acc)	SS 2,621.50		(OI later - ENJOYED TP)
Loss of Rental (LOR):	SS 500.00 (5 days) X \$100.00		
Loss of Use (LOU):	SS - (\$ x days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐			[Tick only one]
GIA/LTA Search	SS -		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 3,121.50	Global Sum SS: -	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 3,121.50	Name 1:	LIM TAN MOTOR PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	-
Payee 3: (Strike if N.A.)	SS -	Name 3:	-

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$320.00

Surveyor

Panne

REF:

JUN 4351 / Ruk

4376A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLP 4165E

at Workshop m/s

LIM TAN

of

SIN MIND INSURANCE #03-09/10

Insured:

A/LH

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Richard

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

14K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP 4165E

Yr Regn:

2008 / Auk

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic 1.8 LA

c.c

1799

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

116525

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMF016308521969K

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

20/05/18

D.O.I.

22/05/18

Survey held at

LIM TAN

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Lg \$2,450.00

(CRSD: \$959.12 / 20%)

MV: \$14,000.00 (est)

LTA: \$10,550.00 (est)

NBT: \$3,450.00 (est)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18009351/R1ha3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 23-05-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 7937P	Veh. Inspected	SLP 4165E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	23/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/05/2018	Inspection Date	22/05/2018	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ESTIMATE TO REPAIR

VEHICLE NO. : SLP 4165 E
MAKE : HONDA
MODEL : CIVIC 1.8L A
YEAR : 2008
CHASSIS NO : JHMF16308S219694

SURVEYOR NAME	:	
DATE OF SURVEY	:	21.05.2018
TIME OF SURVEY	:	11.15am

DATE : 21-May-18
DATE OF ACCIDENT : 20-May-18
THIRD PARTY REF : SLR 7937 E / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 638.00
2 pcs	Rear Bumper Bracket		\$ 13.90		\$ 27.80
2 pcs	Rear Bumper Retainer		\$ 14.90		\$ 29.80
1 pc	Rear End Panel				\$ 300.80
1 pc	Rear End Panel Garnish				\$ 60.80
1 pc	Rear Boot Lid				\$ 610.70
1 pc	Rear Boot Lock				\$ 194.50
1 pc	Rear Boot Rubber				\$ 97.60
1 pc	Rear Boot Centre Emblem				\$ 25.70
1 pc	Rear Boot CIVIC Emblem				\$ 29.10
1 pc	Rear Boot 1.8 I-VTEC Emblem				\$ 34.10
					\$ 2,048.90
	Less 20%				\$ 409.78
					\$ 1,639.12
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
	To putty & spray painting.				\$ 600.00
	To check rear wiring and water leakage.				\$ 30.00
	To anti-rust.				\$ 40.00
	Labour Charges.				\$ 600.00
					\$ 3,409.12
TG-RA/-	TOTAL				\$ 3,409.12

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issue
4/90010068
6 days
4/5
22/05/18 21130
Resurvey after repair

Lim Tan Motor Pte Ltd

Bldg 178 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Website: www.LTM.sg
Co. Reg. No. 199307277D GST Reg. No. M2-0019088-0

Catherine Chong (LKK Auto)

From: Chan, Yoke Shi <yokeshi.chan@aig.com>
Sent: Monday, 21 May, 2018 3:01 PM
To: admin-a@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene
Subject: - Pre repair inspection request - SLP4165E VS SLR7937P (OI) DOA: 20/05/2018
Attachments: SecureMessageAtt.html



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-05-28 15:01 +08 to read your message.
After that, open the attachment.

[More Info](#)

21/05/2018 @ 4:01pm
Lim Tan veh in
Richard.
Rasul

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

Vic (LKKAUTO)

From: Mandy <mandy@lrm.sg>
Sent: Tuesday, 31 July, 2018 9:57 AM
To: Vic (LKKAUTO)
Cc: Admin A; Hsiao Tong (LKKAUTO); 'richard'; jianning; venus@lrm.sg
Subject: RE: Acceptance Of Settlement / Status - SLP4165E Third Party Claim against AIG ***
LKK REF: CC4/AIG18009351/R1ha3
Attachments: 1844_001.pdf

WITHOUT PREJUDICE

Dear Vic,

Enclosed please find the duly signed, endorsed and completed DV for your Mandate's early payment.

Thank you and regards,

Mandy Lim

Lim Tan Motor Pte Ltd

www.LTM.sg

+65 6452 0893 (Office)

+65 6458 9127 (Facsimile)

Like us in Facebook!!

www.facebook.com/LTMsg

www.facebook.com/LTM.Performance.Singapore



LIM TAN MOTOR PTE LTD 林陈摩哆私人有限公司

COMPANY REGISTRATION NO: 199307277D GST REGISTRATION NO: M2-0119086-0

MAIN OFFICE / WORKSHOP

BLK 176 SIN MING DRIVE
SIN MING AUTOCARE #03-09/10/06
SINGAPORE 575721

TEL: +65 6452 0893 FAX: +65 6458 9127

EMAIL: SALES@LTM.SG

Operating Hours: Mon – Fri 9am – 6 pm

24hrs Helpline: +65 64520893

BRANCH

BLK 9 SECTOR C #01-38/40/42
SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644

TEL: +65 6452 2135 FAX: +65 6452 2159

Sat 9am – 5pm

WWW.LTM.SG



IMPORTANT NOTICE

This email, including all attachments may contain confidential or legally privileged information.

The sending of this email to any person other than the intended recipient is not a waiver of confidentiality or privilege of the information. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]

Sent: Monday, July 30, 2018 3:43 PM

To: Mandy <mandy@lrm.sg>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; richard <richard@lrm.sg>

Subject: RE: Pending Offer / Status - SLP4165E Third Party Claim against AIG *** LKK REF: CC4/AIG18009351/R1ha3

Without Prejudice

Dear Mandy,

We refer to the below email.

Purely for an amicable settlement on a without admission of liability to our Insured's part, we offer settlement as follows:

Cost of Repair (w/gst)	\$ 2,621.50
Loss of Rental (\$100 x 5 days)	\$ 500.00
TOTAL	\$ 3,121.50

If agreeable, kindly chop and sign the attached DV and forward to us a copy together with the **Rental Receipt/Invoice** for payment processing.

The above amount is to be made payable to LIM TAN MOTOR PTE LTD.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: richard [<mailto:richard@ltm.sg>]

Sent: Monday, 30 July, 2018 9:43 AM

To: Vic (LKKAuto); Mandy

Cc: Admin A; Hsiao Tong (LKKAuto); mandy@ltm.sg

Subject: RE: Pending Offer / Status - SLP4165E Third Party Claim against AIG *** LKK REF: CC4/AIG18009351/R1ha3

Importance: High

WITHOUT PREJUDICE

Our ref : **LTP052018/048 (SLP 4165 E)**

Dear Vic,

In reference to our email to you dated 9th July 2018, please advised if your principal had given any mandate / offer to the above claim.

We appreciate your early revert soonest.

Thank you and regards,

Richard Ang

Claims Executive
Lim Tan Motor Pte Ltd

www. LTM.sg

+65 6452 0893 (Office)

+65 6458 9127 (Facsimile)

+65 8484 5418 (Mobile)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2018 Edit Reg		21 May 2018 00:00 Edit Adj Rpt	\$2,450.00 Edit Estimates	\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM CHING HANG , ID: S0092701E, Tel: +6591051240		
Main Claimant:	KANG MUI KHENG PATRICIA , ID: S6944376A		
Vehicle Reg. No.:	SLP4165E	Date of Loss:	20/05/2018 14:00 - :59 [117 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1912846342SG	Policy/Cover Note No.:	1700052479 (Comprehensive)
Vehicle Reg. No. (Insured):	SLR7937P	Policy No. (Claimant):	5091706183
		Excess:	
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/06/2018]		
Driver/Custodian (Insured):	LIM CHING HANG (), NRIC: S0092701E, Tel: +6591051240		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SLP4165E (1912846342SG)**
[SLR7937P]

TP

KANG MUI KHENG PATRICIA

May 20 2018 2:00PM

[LIM CHING HANG]

Lim Tan Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Letters/Correspondences

1 per page ☐

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	☐

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 09:08	Odometer Reading	 Load JPG ☐	☒
2	26/06/18 09:08	Chassis Number	 Load JPG ☐	☒
3	26/06/18 09:08	General View	 Load JPG ☐	☒
4	26/06/18 09:08	General View	 Load JPG ☐	☒
5	26/06/18 09:08	General View	 Load JPG ☐	☒
6	26/06/18 09:08	General View	 Load JPG ☐	☒
7	26/06/18 09:08	General View	 Load JPG ☐	☒
8	26/06/18 09:08	General View	 Load JPG ☐	☒
9	26/06/18 09:08	General View	 Load JPG ☐	☒
10	26/06/18 09:08	General View	 Load JPG ☐	☒
11	26/06/18 09:08	General View	 Load JPG ☐	☒
12	26/06/18 09:08	General View	 Load JPG ☐	☒
13	26/06/18 09:08	General View	 Load JPG ☐	☒
14	26/06/18 09:08	General View	 Load JPG ☐	☒
15	26/06/18 09:08	General View	 Load JPG ☐	☒
16	26/06/18 09:08	General View	 Load JPG ☐	☒
17	26/06/18 09:08	General View	 Load JPG ☐	☒
18	26/06/18 09:08	General View	 Load JPG ☐	☒
19	26/06/18 09:08	General View	 Load JPG ☐	☒
20	26/06/18 09:08	General View	 Load JPG ☐	☒
21	26/06/18 09:08	General View	 Load JPG ☐	☒
22	26/06/18 09:08	General View	 Load JPG ☐	☒
23	26/06/18 09:08	General View	 Load JPG ☐	☒
24	26/06/18 09:08	General View	 Load JPG ☐	☒
25	26/06/18 09:08	General View	 Load JPG ☐	☒
26	26/06/18 09:08	General View	 Load JPG ☐	☒
27	26/06/18 09:08	General View	 Load JPG ☐	☒
28	26/06/18 09:08	General View	 Load JPG ☐	☒
29	26/06/18 09:08	General View	 Load JPG ☐	☒
30	26/06/18 09:08	General View	 Load JPG ☐	☒
31	26/06/18 09:08	General View	 Load JPG ☐	☒
32	26/06/18 09:08	General View	 Load JPG ☐	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	26/06/18 09:08	General View	Load JPG	✓
34	26/06/18 09:08	General View	Load JPG	✓
35	26/06/18 09:08	General View	Load JPG	✓
36	26/06/18 09:08	General View	Load JPG	✓
37	26/06/18 09:08	General View	Load JPG	✓
38	26/06/18 09:28	Reinspection Photo	Load JPG	✓
39	26/06/18 09:28	Reinspection Photo	Load JPG	✓
40	26/06/18 09:28	Reinspection Photo	Load JPG	✓
41	26/06/18 09:28	Reinspection Photo	Load JPG	✓
42	26/06/18 09:28	Reinspection Photo	Load JPG	✓
43	26/06/18 09:28	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/05/18 11:00	ACKNOWLEDGEMENT EMAIL TO AIG DD 21.05.2018	Load PDF	
2	23/05/18 11:00	EMAIL FROM AIG DD 21.05.2018	Load PDF	
3	23/05/18 11:00	TP ESTIMATE	Load PDF	
4	23/05/18 11:00	TP GIA REPORT	Load PDF	
5	27/05/18 14:35	TP ESTIMATE - MARKED	Load PDF	
6	26/06/18 09:22	LETTER TO OI	Load PDF	
7	04/09/18 10:42	AUTHORISATION TO ACT	Load PDF	
8	04/09/18 10:42	RELEASE VOUCHER	Load PDF	
9	04/09/18 10:42	RENTAL RECEIPT	Load PDF	
10	04/09/18 10:42	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/05/18 12:38	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR7937P (Insd veh)	Model:	HONDA CIVIC 1.8 L (A)
	SLP4165E (TP veh)		
Date of Accident:	20/05/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,647.76
Final Repair Cost	:	\$	2,621.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	3,121.50
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Lim Tan Motor Pte Ltd	:	\$ 3,121.50
2)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

04 Sep
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18009351/R1HA3S2**Date:** 04/09/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700052479
Claimant Vehicle No :	SLP4165E	Insured Vehicle No :	SLR7937P
Date of Loss:	20/05/2018	Nature of Claim:	TP
		Claim No:	1912846342SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP4165E	Engine No:	R18A13042445
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16308S219694
Reg. Date:	19/08/2008 (Man. Year: 2008)	Odometer:	116525 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,839.12	1,790.48	48.64	2.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	1,270.00	300.00	19.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,409.12	3,060.48	348.64	10.23
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	3,409.12	2,450.00	959.12	28.13
+ GST 7.00/7.00% (S\$)	238.64	171.50	67.14	28.13
Nett Amount (S\$)	3,647.76	2,621.50	1,026.26	28.13
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		3,121.50		

INSPECTION

Date of Assignment:	21/05/2018	
Date Inspected:	22/05/2018 Inspected At:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	6.0 days	

9/4/2018

Adjuster Report

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	638.00 FL	*638.00 FL
2	2		*REAR BUMPER BRACKET	Necessary	27.80 FL	*27.80 FL
3	2		*REAR BUMPER RETAINER	Necessary	29.80 FL	*29.80 FL
4	1		*REAR END PANEL	Bent	300.80 FL	*300.80 FL
5	1		*REAR END PANEL GARNISH	Not Necessary	60.80 FL	*- FL
6	1		*REAR BOOT LID	Bent	610.70 FL	*610.70 FL
7	1		*REAR BOOT LOCK	Bent	194.50 FL	*194.50 FL
8	1		*REAR BOOT RUBBER	Cut	97.60 FL	*97.60 FL
9	1		*REAR BOOT CENTRE EMBLEM	Necessary	25.70 FL	*25.70 FL
10	1		*REAR BOOT CIVIC EMBLEM	Necessary	29.10 FL	*29.10 FL
11	1		*REAR BOOT 1.8 I-VTEC EMBLEM	Necessary	34.10 FL	*34.10 FL
12	1		*SET REAR BUMPER SENSOR	Distorted	200.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	2,248.90	2,188.10
- List Item Discount on L Items 20.00/20.00% (S\$)	409.78	397.62
Total Parts (S\$)	1,839.12	1,790.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINTING.	New	800.00	600.00
2	TO CHECK REAR WIRING AND WATER LEAKAGE.	New	30.00	30.00
3	TO ANTI-RUST.	New	60.00	40.00
4	LABOUR CHARGES.	New	680.00	600.00
Gross Labour Cost (\$\$)			1,570.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >