

ESTIMATE TO REPAIR

VEHICLE NO. : SLP 4165 E
 MAKE : HONDA
 MODEL : CIVIC 1.8L A
 YEAR : 2008
 CHASSIS NO : JHMF16308S219694

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 21-May-18
 DATE OF ACCIDENT : 20-May-18
 THIRD PARTY REF : SLR 7937 E / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 638.00
2 pcs	Rear Bumper Bracket		\$ 13.90		\$ 27.80
2 pcs	Rear Bumper Retainer		\$ 14.90		\$ 29.80
1 pc	Rear End Panel				\$ 300.80
1 pc	Rear End Panel Garnish				\$ 60.80
1 pc	Rear Boot Lid				\$ 610.70
1 pc	Rear Boot Lock				\$ 194.50
1 pc	Rear Boot Rubber				\$ 97.60
1 pc	Rear Boot Centre Emblem				\$ 25.70
1 pc	Rear Boot CIVIC Emblem				\$ 29.10
1 pc	Rear Boot 1.8 I-VTEC Emblem				\$ 34.10
					\$ 2,048.90
	Less 20%				\$ 409.78
					\$ 1,639.12
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
	To putty & spray painting.				\$ 800.00
	To check rear wiring and water leakage.				\$ 30.00
	To anti-rust.				\$ 60.00
	Labour Charges.				\$ 680.00
TG-RA/-	TOTAL				\$ 3,409.12

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0