	From (Person): Julie Manaubat of	NMENT (Office) AGI Date/Time: 23/05/20180 10:170
	Estimated Cost	Bill to:
	OD FP WS/TP RES / OD RES / EVA / INV / M	하다 경기 그들은
	To Inspect Vehicle No. SkZ 50	91L SJZ 6003 Y
	at Workshop m/s Jack Cars E	rerprise Tel: 92206746
	of BIK 3007 ybi Road	1 # 01-450
	Policy No:	Claim No: C16001617 /AH
*	Sum Insured:	Excess:
	Make of Veh: (Client's Record)	D.O.A. 22 05 2018
	CA / REV / REP. / REV 24 HRS (up)	H.O.D. Endorsement:
	Date/Time: 10:33cm@ 23/5/18 Person Contact	ed: there Vehicle IN/OUT)
	The second secon	
	- Latti	ate
	3kZ 5091L - NA CTILES	50 9352/h4 DUA: 22/05/266
	3) 26003 Y- CS/AXAIR	015469/T/9d1 BOA: 17/08/2013
	The second secon	

ASSIGNMENT

From: Date:	Veh No: SKZ5091L - Yr Regn: 206, Jan -
Estimated Cost:	Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Honder VC201 c.c 1496.
at Workshop m/s	Colour While A/C: Insured / Std / NI / NA
of	Sp.Reading 52946 . T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: RUIII10304 .
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil / S/Rim / STD A/Rim or
e ^e	Tyre Size: F: 2.5/60816-
(Policy Condition)	R: 215/60R16
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes_or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 30/05/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Jack Cas.
CA I DEV I DED I 24 UDS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OU	т
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	6
TP Budget Rirect.	
V	
RECEIVED	2 3 NOV 2018
RECLIVED	2 1107 2010
	*
Oate/Time, File Pass to? : Preli. Report	Days Of Repair: ()
23 UTUDIST SEFINAL Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	ee: : Site Insp (\$)s +Rssi
¥	: Interview (\$) Photos 450
Report Format:	: Tech, Invs (\$) Others
Lump Sum / (B): (\$ 10230.80)	:Weekend (\$)
	TOTAL

Nivitha (LKK Auto)

Sent on behalf of Albert

From:

Sent:

To:

Cc:

Subject:

Hi Team

Thank you, -Julie

Attachments:

Greetings Ms. Julie ,
Attached would be the amended PRI for your kind perusal.
As for the surveyor , kindly engage LKK.
Kindly revert.
Thank You.
Best Regards , S.Thanaletchumi (Ms) JACK CARS ENTERPRISE PTE LTD Office : 67488824 Mobile : 92206746 Fax : 67488834 Email : thana@jackcars.com.sq
On Wed, May 23, 2018 at 8:56 AM, Julie Mangubat < julie.m@budgetdirect.com.sg wrote:
WITHOUT PREJUDICE
Dear Ms Thana
Please advise your choice of surveyor.

Julie Mangubat <julie.m@budgetdirect.com.sg>

FW: PRI of SKZ5091L | Our ref: C10001617/AH

Wednesday, 23 May 2018 10:17 AM

Albert Hong

PRI FORM.pdf

Please accept TPPD survey and survey in a without prejudice basis.

Workshop contact details: Ms Thana | Contact no: 92206746

From: Thanaletchumi Santerashigaram <thana@jackcars.com.sg>

Sent: Wednesday, 23 May, 2018 9:27 AM

Subject: Re: PRI of SKZ5091L

To: Julie Mangubat <julie.m@budgetdirect.com.sg>

Note: TP owner is only available today, if possible survey the vehicle today.

SUR; admin-d@lkkauto.com; assignments

- LKK
- FormTeam

In addition, we noticed that the owner of the vehicle is different from your client's GIA report.	Please confirm who
owns the car.	

Thank you,

-Julie

From: Thanaletchumi Santerashigaram < thana@jackcars.com.sg>

Sent: Tuesday, 22 May, 2018 6:08 PM
To: Claims <<u>claims@budgetdirect.com.sg</u>>

Subject: PRI of SKZ5091L

Greetings,

Attached would be the PRI of SKZ5091L for your kind perusal.

Kindly revert.

Thank You.

Best Regards,

S.Thanaletchumi (Ms)

JACK CARS ENTERPRISE PTE LTD

Office: 67488824

Mobile: 92206746

Fax : 67488834

Email: thana@jackcars.com.sg

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.





Our ref

: 2018.JC.SKZ5091L

Your ref

: SJZ6003Y

22ND MAY 2018

PLEASE REPLY VIA EMAIL(thana@jackcars.com.sg)

Budget Direct Insurance
190 Clemenceau Avenue
#03-01
Singapore Shopping Centre
Singapore 239924
Attn: Motor Claims Dept
2 DAY'S PRE-REPAIR NOTICE

	udget Direct Insurand 1L inspected as follo	
Signature	Signature	Signature
Date/Time:	Date/Time:	Date/Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURER FOR PRE-REPAIR NOTICE CLAIMANT: ANG SIEW ENG RACHEL ACCIDENT INVOLVING SKZ5091L & SJZ6003Y ON 22ND MAY 2018 ALONG VANDA ROAD EXITING

INTO ENG NEO AVENUE

We refer to the above matter wherein we are instructed to act for ANG SIEW ENG RACHEL, the owner of vehicle no. SKZ5091L.

Our Client's vehicle **SKZ5091L** is available as follows; <u>please call prior appointment</u> for the prerepair inspection:

Jack Cars Enterprise Pte Ltd

Blk 3007 Ubi Road 1, #01-450, Singapore 408701 Tel: 67488824 (Ms S.Thanaletchumi)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards, S.Thanaletchumi Claims Manager Jack Cars Enterprise Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	22/05/2018 17:34	
Date Of Accident	22/05/2018 07:50	
Exact Location Of Accident	THOMPSON ROAD TOWARDS TOA PAYOH (PIE C	HANGI AIRPOR
Country/State of Loss	SINGAPORE	
C	ETAILS OF OWN VEHICLE	S. C. Valle
Vehicle Registration Number	SKZ5091L	
Insured/Policyholder		
Name Of Registered Owner	ANG SIEW ENG RACHEL	
NRIC No	S7020975F	
Email Address	MOSHI2606@YAHOO.COM	
Mobile Phone No	(LOCAL) +65-97980030	
Alternative Phone No	OFFICE-97980030	
Vehicle Particulars		
Manufacturer	HONDA	
Model	VEZEL-1.5 1.5X CVT (A)	
Exact Purpose for which vehicle was being used at time of accident	PERSONAL	
Are you claiming under your own insurance policy for repair to your vehicle?	NO	
If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	PRIVATE CAR	
Insurance Company		
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.	
Type Of Coverage	COMPREHENSIVE	
Fleet Policy	NO	
Policy Number	A28876292	
Cover Note Number		
Driver		
Name of Driver	ANG SIEW ENG RACHEL	
		The state of the s

Driver		
Name of Driver	ANG SIEW ENG RACHEL	
NRIC No	S7020975F	100 Year 100 Billion
Date Of Birth	26/06/1970	
Occupation	INDOOR	
Date Of Driving Pass	20/11/1996	
Driving Experience	21 YEARS AND 6 MONTHS	
Gender	FEMALE	
Mobile Number	(LOCAL) +65-97980030	(University)
Fax Number		
Contact Number	OFFICE-97980030	1111111
EMail Address	MOSHI2606@YAHOO.COM	

Address

B/539 BUKIT BATOK STREET 52

#07-581

Postcode

2365

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

----- REFER TO ATTACHMENT -----

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

RECORDING WITH OWNER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJZ6003Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PC2328L

GOODS VEHICLE

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the petalls of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 essociation of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the longment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetery Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the surpose(s) and the surpose(s) are the s
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (III) carrying out and/or dealing with my instructions or responding to any enquities by mo;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

lif

Policyholder's Signature Date & Time: NA.

Driver's Signature (If driver is not the policyholder) Date & Time: JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-448 / 450 / 452 SINGAPORE 408701 TEL: 6748 8824 FAX: 6748 8834

Reporting Centre Personnel's Signature Name: NRIC/FIN No.: SKETCH PLAN

REFER TO REMENTED

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	On	57 /02	2018	97	aranj	075	O HBS	1 10	nort 20	eeung
arong	THR	mpson	ROOD	τυνώ	LD3	Τοα	Payor	(PIE	CHangi	AIRPORT)
/ yva	J 1710	ring a	LEFT	Tuk	.n.					
& ALL	OFF	0 84	00en	THO	cor	infront	OF	me	Johnes	Brake
an Ti	He P	LDESTY(an tro	ossing	eaus	ng n	10 70	OYPLY	my	brake
as we	LL ·	1 man	agep.	TO 5	ОР	00 -	Time .	PT	THE	Same
point	OF	Time	1	FULT	a	HORD	Imp	act	on 浙	THE
Y 60'A	of r	ny car	cau	ising	my	car	To	8urge	forwo	KD UND
HT T	[He	Vettece	6 /V	FRONT	90	me (JK 232	8L).	THE (ar Behind
Me 18	SJZ	6003	ano	my	(UV	regist	ration	humbe	er skt	5091 L .
The second	2222							1401/ 0	ADA CORP.	CODICE DIE I'

DECLARATION

I/We declare the foregoing particulars are true in every respect.


hy

MA

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time: JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-448 / 450 / 452
SINGAPORE 408701
TEL: 6748 8824 FAX: 6748 8834

Reporting Centre Personnel's Signature Name: NRIC/FIN No.: Google, Inc.

Street View Nov 2017



Thomson Rd



ESTIMATE

DATE OF ACCIDENT: 22/05/2018

VEHICLE: SKZ5091L

MAKE & MODEL : HONDA VEZEL

INSURANCE: BUDGET DIRECT INSURANCE

SURVEYOR : LKK

	PARTS	CONDITION	COST
1.	FRONT BUMPER Dela		\$ 950
2.	FRONT BUMPER GRILLE		\$ 420
3.	FRONT BUMPER LOWER GRILLE Area		\$ 200
4.	FRONT BUMPER TOP GARNISH - A Galle Col	_d	\$ 550
5.	FRONT BUMPER TOP GRILLE CHROME GARNISH	Fin Cd	\$ 150
6.	FRONT BUMPER BRACKET - LEFT 2		\$ 80
7.	FRONT BUMPER BRACKET - RIGHT		\$ 80
8.	FRONT BUMPER CENTRE BRACKET		\$ 110
9.	FRONT SUPPORT BEAM Bed		\$ 1050
10.	BONNET Buckle		\$ 1550
11.	BONNET HINGE - LEFT 2 Bent		\$ 55
12.	BONNET HINGE - RIGHT		\$ 55
13.	HEADLAMP - LEFT cauled		\$ 1050
14.	HEADLAMP - RIGHT Can Cd	l-One	\$ 1050
15.	HEADLAMP BRACKET (UPPER) - LEFT		\$ 85
16.	HEADLAMP BRACKET (UPPER) - RIGHT		\$ 85
17.	HEADLAMP BRACKET (LOWER) - LEFT Con Cod		\$ 100
18.	HEADLAMP BRACKET (LOWER) - RIGHT Concleed	2005-1E	\$ 100
19.	REAR BOOT LID On storted		\$ 2200
20.	REAR BUMPER	10 Per 10	\$ 860
21.	REAR BUMPER WEATHERSTRIP Lot	- Consulty	\$ 420



22.	REAR UNDERCARRIAGE COVER TO A		\$,450
3.	REAR END PANEL PISTO REPLIED		\$ 720
24.	REAR END PANEL COVER WAS		\$ 160
25.	REAR RIGHT WHEEL ARCH		\$ 280
26.	EXHAUST #1 ~		\$ 1200
27.	SPARE TYRE COMPARTMENT SPONGE Could		\$ 750
28.	LEFT TAILGATE LIGHT - INNER ZHILL		\$ 475
29.	LEFT TAILGATE LIGHT - OUTER	0011	\$ 855
30.	REAR RELAY SENSOR & SOCKET end	8116	\$ 200
		6972.80	
	SPECIAL NETT	0	
1.	CLIPS AL-		\$ 150
2.	REAR WINDSCREEN SEALANT ML		\$ 220
3.	REVERSE SENSOR Page		\$ 200
4.	NUMBER PLATE & NUMBER PLATE COVER - BELT	le*	\$.95
	10.00 / 10.00 / 10.00		
5.	FRONT NUMBER PLATE BRACKET AH M	>00	\$ 110
5.		380.	\$ 110
5.		380.	\$ 110
5. 1.	FRONT NUMBER PLATE BRACKET At M	380.	\$ 110
	FRONT NUMBER PLATE BRACKET At M. LABOUR	380.	
1.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY	380.	\$ 2450
1.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	380.	\$ 2450 \$ 285 0
1.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS TO CHECK WIRING & REWIRING	380.	\$ 2450 \$ 2850 \$ 120 \$ 150
1. 2. 3.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS TO CHECK WIRING & REWIRING TO REMOVE AND REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL REAR BOOT	380.	\$ 2450 \$ 2850 \$ 120 \$ 150
1. 2. 3.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS TO CHECK WIRING & REWIRING TO REMOVE AND REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	380.	\$ 2450 \$ 2850 \$ 120 \$ 150 \$ 180
1. 2. 3. 4.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS TO CHECK WIRING & REWIRING TO REMOVE AND REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY TO REMOVE & REPLACE REAR BOOT	380.	\$ 2450 \$ 2850 \$ 120 \$ 150 \$ 180 \$ 350
1. 22. 33. 41. 55. 57.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS TO CHECK WIRING & REWIRING TO REMOVE AND REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY TO REMOVE & REPLACE REAR BOOT TO CHECK LIGHTING SYSTEM FOR ANY LEAKAGE	380.	\$ 2450 \$ 2850 \$ 120 \$ 150 \$ 180 \$ 350 \$ 120
1. 2. 3. 4. 5.	LABOUR TO PUTTY & SPRAY PAINT OF AFFECTED AREA TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS TO CHECK WIRING & REWIRING TO REMOVE AND REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY TO REMOVE & REPLACE REAR BOOT TO CHECK LIGHTING SYSTEM FOR ANY LEAKAGE TO REMOVE & REPLACE FRONT BONNET	380.	\$ 2450 \$ 2850 \$ 120 \$ 150 \$ 180 \$ 350 \$ 120 \$ 320

2.790



PARTS - 20% :	\$ 13,032
SPECIAL NETT:	\$ 775
LABOUR :	\$ 7,000
TOTAL:	\$ 20,807
7% GST :	\$ 1,456.49
GRAND TOTAL :	\$ 22,263.49

Adrian hing -PP. \$\frac{1}{45} 30/05/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey bufor safter spray painting
- To display changed part(s) duning resurvey
- Parts prices at thectro confirming.
- Third party sur. on a "Adnout Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementing: 88 total: 10230.80 (P/P).





SUPPLEMENTARY

DATE OF ACCIDENT: 22/05/2018

VEHICLE: SKZ5091L

MAKE & MODEL: HONDA VEZEL

INSURANCE: BUDGET DIRECT ASIA

SURVEYOR: LKK

	PARTS	CONDITION	COST
1.	REAR BUMPER RELECTORS THE COMPANY		\$ 220
	PARTS - 20%:	\$ 176	
	7% GST :	\$ 12.32	
277	GRAND TOTAL :	\$ 188.32	

HES.

110

38



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18009354/Atd3n2

190 CI		URANCE) 'ENUE #03-01 NG CENTRESINGAPORE	Date: 28-11-2018 Code: AGI			
		Policy Particular	s :- THIRD PARTY CLAI	M		
1.	Insured Veh.	SJZ 6003Y	Veh. Inspected	SKZ 5091L		
_	Policy No.	332 33331	Coverage (\$)	0.00		
_	Claim No.	C10001617/AH	Excess (\$)	0.00		
_	Assign From	JULIE MANGUBAT	Assign Date	23/05/2018		
2.	According to the second		ticulars & Condition			
	Make & Model	HONDA VEZEL	c.c	1496		
_	Engine No.	HIDDEN	Year of Reg.	2016		
\rightarrow	Chassis No.	RU11110304	Colour	WHITE		
\neg	Odometer	52946	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Cond	itions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm		
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm		
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm		
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm		
4.	R. S. S.	Descrip	tion of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE F ETAILS.	REAR PORTION.			
5.		Gene	ral Information			
	Accident Date	22/05/2018	Inspection Date	30/05/2018		
	Survey held at	JACK CARS ENTERPRISE P	TE LTD			
	BLK 3007 UBI ROAD 1 #01-450 SINGPORE 408700					
5a.	Remarks					
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS,	VITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.		
5b.	The second second		te Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 5091L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	950.00	880.00
1	FRONT BUMPER GRILLE	CRACKED	420.00	420.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	200.00	
	FRONT GRILLE	CRACKED	550.00	550.00
1	FRONT GRILLE GARNISH	CRACKED	150.00	150.00
1	FRONT BUMPER BRACKET-LEFT	NECESSARY	80.00	35.00
1	FRONT BUMPER BRACKET-RIGHT	NECESSARY	80.00	35.00
1	FRONT BUMPER CENTRE BRACKET	NOT NECESSARY	110.00	
	FRONT BUMPER BEAM	BENT	1,050.00	321.00
1	BONNET	BUCKLED	1,550.00	895.00
4	BONNET HINGE-LEFT	BENT	55.00	55.00
1	BONNET HINGE-RIGHT	BENT	55.00	55.00
1	HEADLAMP-LEFT	CRACKED	1,050.00	1,050.00
-1	HEADLAMP-RIGHT	CRACKED	1,050.00	1,050.00
1	HEADLAMP BRACKET (UPPER)-LEFT	CRACKED	85.00	85.00
্ৰ	HEADLAMP BRACKET (UPPER)-RIGHT	CRACKED	85.00	85.00
	HEADLAMP BRACKET (LOWER)-LEFT	CRACKED	100.00	100.00
	HEADLAMP BRACKET (LOWER)-RIGHT	CRACKED	100.00	100.00
	REAR BOOT LID	DISTORTED	2,200.00	1,100.00
- 4	REAR BUMPER	DEFORMED	860.00	860.00
- 1	REAR BUMPER WEATHERSTRIP	CUT	420.00	135.00
-	REAR UNDERCARRIAGE COVER	TORN	450.00	285.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	720.00	2.7
-	REAR END PANEL COVER	DEFORMED	160.00	160.00
	REAR RIGHT WHEEL ARCH	NOT NECESSARY	280.00)
	EXHAUST	NOT NECESSARY	1,200.00)
-	SPARE TYRE COMPARTMENT SPONGE	CRACKED	750.00	225.00
	LEFT TAILGATE LIGHT-INNER	NOT NECESSARY	475.00	
-	LEFT TAILGATE LIGHT-OUTER	NOT NECESSARY	855.00	
	REAR RELAY SENSOR & SOCKET	CRACKED	200.00	85.00
- 2	REAR BUMPER REFLECTORS (ADDITIONAL)	O/S CRACKED	220.00	110.00
	LESS 20% DISCOUNT		-3,302.00	-1,765.20
			13,208.00	7,060.80

Report Ref No. CS/AGI18009354/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	CLIPS (SN)	NECESSARY	150.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	220.00	60.00
1	REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
1	NUMBER PLATE & NUMBER PLATE COVER-FRONT (SN)	BENT	95.00	60.00
1	FRONT NUMBER PLATE BRACKET (SN)	NOT NECESSARY	110.00	
	The American Control of the Am		775.00	380.00
	LABOUR			
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		2,450.00	1,150.00
	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		2,850.00	1,150.00
	TO CHECK WIRING & REWIRING.		120.00	60.00
	TO REMOVE AND REINSTALL REAR WINDSCREEN.		150.00	120.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.		180.00	180.00
	TO REMOVE & REPLACE REAR BOOT.	NOT NECESSARY	350.00	-
	TO CHECK LIGHTING SYSTEM FOR ANY LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE & REPLACE FRONT BONNET.	NOT NECESSARY	320.00	-
	TO REMOVE & REPLACE REVERSE SENSOR.		120.00	50.00
	TO REMOVE AND REINSTALL TAILGATE COMPONENTS.		220.00	80.00
	TO REMOVE AND REINSTALL HEADLAMP COMPONENTS.	NOT NECESSARY	120.00	
	The state of the s		7,000.00	2,790.00
	GRAND TOTAL		20,983.00	10,230.80

Г	DECOMMENDED COST OF DEDAIDS	40 220 90
L	RECOMMENDED COST OF REPAIRS	10,230.80

Report Ref No. CS/AGI18009354/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.