

Surveyor  
Merimen

Turkish

## ASSIGNMENT (Office)

From (Person):

Jaemine lok

of

MSG

Date/Time

23/5/18 @ 9:54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 3659L

Insured:

SJL 1324C

at Workshop m/s:

Performance Motor

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

829026757 MCX

Claim No:

559064

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/06/2018

CA / REV / REP. / REV 24 HRS

Camp

H.O.D. Endorsement:

Date/Time:

11:16am @ 23/5/18

Person Contacted:

caroline

Vehicle

IN/OUT

Date/Time

Action/Instruction

( Estimate

SLE 3659L-x

SJL 1324C-CC3/MSG17023873/Svbe 2

Doq: 13/12/17

24/5/18

Send preli revised by merimen

25/7/18

Final fig \$ 6766.40 Confirmed by email (Ref 11,740.55, 6319)

*Sam*

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s

of \_\_\_\_\_

Insured

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value \_\_\_\_\_

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh / No: *SLE36592* Yr Regn: *2016 July*

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *BMW 4201*

Colour: *Black* A/C Insured / Std / NI / NA

Sp. Reading: *21152* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *275/45 R18*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU *PIR* / SUMI /

TOYO / YOKO or

Front

R/Bal. *6* mm

L/Bal. *6* mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. *6* mm

L/Bal. *6* mm

D.O.I. *23/5/18*

Survey held at *pmc*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Frt N/S, U/C*  
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 25 JUL 2018

Copy/Time, File Pass to:

☐

Preli. Report

II

☐

Final Report

Copy/Time, File Return to:

*25/7 - typist*

Days Of Repair: *6*

Resurvey No. of Trip: *1*

Add Fee: ☐ Site Insp. \$5

☐ Interview \$5

☐ Tech. Insp. \$5

☐ Workshop \$5

Survey Fee

Transportation

*1 S-P \$4*

*2 Poles*

*2 Poles*

Report Format:

*merimen*

Lump Sum / LB 1: *6766.40*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009366/T1vd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-05-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 1324C	Veh. Inspected	SLE 3659L
Policy No.	B29026757MCX	Coverage (\$)	0.00
Claim No.	559064	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	23/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	20/05/2018	Inspection Date	23/05/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		23 May 2018 09:54 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	DIVINE LIMOUSINE PTE LTD, Co. Reg. No.: 201528899W			
Main Claimant:	FOO MAY LIN, ID: S1767478A			
Vehicle Reg. No.:	SLE3659L	Date of Loss:	20/05/2018 12:00 - :59 [22 Months and 1 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 559064	Policy/Cover Note No.:	B29026757MCX (Comprehensive) Coverage: 25/09/2017 - 16/11/2018	
Vehicle Reg. No. (Insured):	SJL1324C	Policy No. (Claimant):		
		Excess:		
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/05/2018]			
Driver/Custodian (Insured):	CHOO CHEE MING (), NRIC: S0056725F, Tel: +6590097786			
Adj Asg. Remarks:	ON WP TP request LKK Auto to inspect. Liability 100%			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jasmine Lok Kheng Kwei	Date: 24 May 2018

**Preliminary Advice**

Insured Vehicle No	: SJL1324C		
TP Vehicle No	: SLE3659L	Accident Date	: 20/05/2018
Make	: BMW 420I COUPE	Assignment Date	: 23/05/2018
Date of Inspection	: 23/05/2018	Est. Duration of Repair	: 6.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,494.35
Revised Amount	:S\$	6,744.80
Check Items (Estimated)	:S\$	10,487.55
Total	:S\$	17,323.50
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/05/2018 16:29
Date Of Accident	20/05/2018 12:25
Exact Location Of Accident	ORCHARD RD RED LIGHT TURNING TO BUYONG RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE3659L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FOO MAY LIN
NRIC No	S1767478A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96745459
Alternative Phone No	OFFICE-96745459

### Vehicle Particulars

Manufacturer	BMW
Model	420IA
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	FOO MAY LIN
NRIC No	S1767478A
Date Of Birth	20/03/1968
Occupation	INDOOR
Date Of Driving Pass	21/01/1988
Driving Experience	30 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96745459
Fax Number	
Contact Number	OFFICE-96745459
Email Address	NOEMAIL

Address	10 NORFOLK RD #02-12
Postcode	219014
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL1324C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOO CHEE MING
NRIC/Passport Number	S0056725F
Contact Number	900097786
Address	BLK 888A TAMPINES ST 81 #12-1072
Postcode	521888
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


15 May, 2018 10:22 AM


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

21/05/18 (12.30pm)

  
 Reposing Centre Personnel's Signature  
 Stamp:  
 URAIC/PDR No.:



### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Red Light Orchard Rd turning to Bayong Road  
SJC 1324C on extreme left lane  
SLE 3659L on second left turn lane  
Once Red light turn green, SLE365L start to move forward  
to turn left, SJC 1324C did not see on his right  
and not suppose to come to my lane. He said he  
wanted to go straight but was a turning lane.  
His car hit on my front left

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

Time: 21/05/18 (12.30pm)

SLE3659L

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

21 MAY 2018

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

① 5.40pm  
# Car LN #

Estimate No. : b1 47013  
Date Estimated : 21/05/2018  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

**- ESTIMATE REPAIR FOR -**

Foo May Lin  
10 Norfolk Road  
#02-12

Singapore 219014

**- ACCOUNT - 40000**

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE3659L	G382625	19/07/2016	420iA GC	0

DESCRIPTIONVALUE

To tow accident vehicle to PML workshop.

✓ 195.00

To replace front left fender including to remove and instal  
l front bumper for painting and to knock out dented area  
caused by the accident

✓ 1700 2,550.00

To respray front bumper and front left fender

✓ 1730 1,923.00

To carry out body cavity preservation.  
(Per panel).

✓ 600 118.00

To remove and install front suspension for inspection and  
replace damaged parts.

un X 2256? photo 2,655.00

To check steering geometry and conduct wheel alignment  
according to BMW specification (2x)

✓ 902 1,062.00

To replace tyre and wheel rim including balancing. (1x).

✓ 80 94.00

To check electrical wiring systems at the front section  
for proper function including adjustments of headlights.

✓ 150 177.00

Sundries.

NW

80 ? 150.00

Total Labour 1: 8,924.00

DESCRIPTIONQTY PRICVALUE

FRT AXLE SUPPORT

1 1,317.15

? 1,317.15

LH WISHBONE

1 262.20

? 262.20

LH TENSION STRUT W/HYDRAULIC MOUNT

1 262.20

? 262.20

WHEEL HUB WITH BEARING FRT

1 465.75

? 465.75

# FRT LH CARRIER

1 439.10

? 439.10

HEX BOLT WITH WASHER M8X30

10 5.40

? 54.00

FRT GUIDE SUPPORT

1 232.00

? 232.00

# FRT SPRING STRUT

1 484.55

? 484.55

N

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190886 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No.	: b1 47013	Page No. :	2 of 2
Date Estimated	: 21/05/2018		
Prepared By	: Han Kwan Yong		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE3659L	G382625	19/07/2016	420iA GC	0

DESCRIPTION	QTY	PRIC	VALUE
LH TIE ROD	1	282.35	282.35
# EXCH STEERING BOX ELECTR. Ⓢ	1	3,583.40	3,583.40
# ALLOY RIM 8JX18 DOUBLE SPK S	1	1,089.10	1,089.10
HUB CAP WITH CHROME EDGE (BMW)	1	24.30	24.30
FRT LH FENDER	1	682.50	682.50
MODEL LETTERING SIDE (SPORT LINE)	1	45.20	45.20
GROMMET	2	0.75	1.50
# FRT LH COVER WHEEL ARCH	1	115.60	115.60
COVER BOTTOM LH	1	115.60	115.60
# AIR DUCT SIDE LH	1	44.35	44.35
PLAQUE 82MM	1	69.50	69.50
Total Parts :			9,570.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Client No. \_\_\_\_\_

Date & Time 23/5/18 Excess \$0

Surveyor's Name Tanfah Sign [Signature]

Surveyor's Tel 97495249 Authorized Yes / No

Authorized Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR [Signature] P.M. Yes / No

Surveyor's Email tanfah@hkauto.com

No. of Working Days Recommended 6 days

[Signature]  
30/5/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by \_\_\_\_\_

Signature \_\_\_\_\_

Dt. \_\_\_\_\_

18,506.95

Labour 1	:	8,924.00
Parts	:	9,570.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,294.60
Grand Total	:	19,788.95

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 10740155W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47013  
Date Estimated : 21/05/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Foo May Lin  
10 Norfolk Road  
#02-12

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 219014

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLE3659L	G382625	19/07/2016	420iA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To tow accident vehicle to PML workshop.	195.00		195.00	
To replace front LH fender and attachments include making good the front bumper and knocking out dents caused by the accident.	1700.00		1,700.00	
To respray front bumper and front LH fender	1730.00		1,730.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)	902.00		902.00	
To replace wheel rim include balancing (1x)	80.00		80.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	4.00		12.60
ALLOY RIM 8JX18 DOUBLE SPK STY 397	1,089.10	1.00		1,089.10
FRT LH FENDER	682.50	1.00		682.50
MODEL LETTERING SIDE (SPORT LINE)	45.20	1.00		45.20

### # SUPPLEMENTARY ITEMS

Total Labour :	4,937.00
Total Parts :	1,829.40
Total Labour & Parts :	6,766.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,766.40
GST @7%:	473.65
Grand Total :	7,240.05

# Performance Motors Limited

A member of the Sino-Datby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 47013  
Date Estimated : 21/05/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Foo May Lin  
10 Norfolk Road  
#02-12

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 219014

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLE3659L	G382625	19/07/2016	420iA GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# ADJUSTABLE BLIND RIVET *	3.15	4.00		12.60
----------------------------	------	------	--	-------

Total Labour :	
Total Parts :	12.60
Total Labour & Parts :	12.60

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 25 July 2018 1:48 PM  
**To:** 'Keith Leo Chi Yung'; PBSP; Taufikh (LKKAuto); SUR  
**Subject:** RE: FINAL REPORT / SLE3659L

Dear Caroline,

WITHOUT PREJUDICE

Confirmed amount \$6,766.40 before GST

Repair days: 6 days

**Kindly send Final invoice and all supporting documents to MSIG**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>

**Sent:** Wednesday, 25 July 2018 10:35 AM

**To:** PBSP <pml-pbsp@sime-darby.com.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

**Subject:** RE: FINAL REPORT / SLE3659L

As requested

Warm Regards

Keith Leo  
Body & Paint  
DDI: 6319 0172  
FAX: 6479 4601



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

**From:** PBSP

**Sent:** Monday, 23 July, 2018 4:55 PM

**To:** Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; Taufikh (LKKAUTO) <[taufikh@lkkauto.com](mailto:taufikh@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Cc:** Keith Leo Chi Yung <[keith.leo.chiyung@simedarby.com.sg](mailto:keith.leo.chiyung@simedarby.com.sg)>

**Subject:** Re: FINAL REPORT / SLE3659L

Dear Keith

Please assist to send photographs to the surveyor.

Thank you.

Regards,  
Caroline

---

**From:** Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Sent:** Monday, 23 July 2018 9:56:43 AM

**To:** PBSP; Taufikh (LKKAUTO); SUR

**Cc:** Keith Leo Chi Yung

**Subject:** RE: FINAL REPORT / SLE3659L

Dear Caroline,

Kindly provides us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>

**Sent:** Saturday, 21 July 2018 11:34 AM

**To:** Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** FINAL REPORT / SLE3659L

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,937.00

Total Parts : 1,829.40

Total Labour & Parts : 6,766.40

Repair days: 6

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		23 May 2018 09:54 <a href="#">Edit Adj Rpt</a>	<b>\$56,766.40</b> <a href="#">Edit Estimates</a>	<b>\$56,766.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>DIVINE LIMOUSINE PTE LTD</b> , Co. Reg. No.: 201528899W								
Main Claimant:	<b>FOO MAY LIN</b> , ID: S1767478A								
Vehicle Reg. No.:	<b>SLE3659L</b>	Date of Loss:	20/05/2018 12:00 - :59 [22 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 559064</b>	Policy/Cover Note No.:	B29026757MCX (Comprehensive) Coverage: 25/09/2017 - 16/11/2018						
Vehicle Reg. No. (Insured):	<b>SJL1324C</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 22/06/2018]								
Driver/Custodian (Insured):	CHOO CHEE MING (), NRIC: S0056725F, Tel: +6590097786								
Adj Asg. Remarks:	ON WP TP request LKK Auto to inspect. Liability 100%								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLE3659L (559064)**  
**[SJL1324C]**  
**TP**  
**FOO MAY LIN**  
**May 20 2018 12:00PM**  
**[DIVINE LIMOUSINE PTE LTD]**  
**Performance Motors Limited**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail		Print
1	22/05/18 19:17	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: SC - Reg. No: SJL1324C, Claimant: DIVINE LIMOUSINE PTE LTD</small>	1	Load HTM	
No	Finalized On		Thumbnail		Print
1	24/05/18 15:19	<b>LKK Auto Consultants Pte Ltd (HQ)</b> <b>Adjuster Immediate Advice</b>	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail		Print
		<b>LKK Auto Consultants Pte Ltd (HQ)</b>			
1	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
19	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
20	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
21	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
22	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
23	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
24	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
25	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
26	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
27	24/05/18 17:37	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
28	25/07/18 13:20	<b>Reinspection Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
29	25/07/18 13:20	<b>Reinspection Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
30	25/07/18 13:20	<b>Reinspection Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
---------------	--	--	--	------------	-------------------------------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/05/18 19:16	TP EST BILL & ACCDT REPORT		Load PDF	
2	22/05/18 19:17	E-FILE REPORT (SLE3659L) <small>From: SC - Reg. No: SJL1324C, Claimant: DIVINE LIMOUSINE PTE LTD</small>		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/08/18 10:27	SUPPLEMENTARY PART		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009366/T1VD3Q2

Date: 01/08/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29026757MCX

Claimant Vehicle No: SLE3659L

Insured Vehicle No: SJL1324C

Date of Loss: 20/05/2018

Nature of Claim: TP

Claim No: 559064

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLE3659L

Make &amp; Model: BMW 420i COUPE, 2.0 AT D/AB HID SR NAV M SPORT (A)

Engine No: 23249538B48B20A

Reg. Date: 19/07/2016 (Man. Year: 2016)

Chassis No: WBA4D32060G382625

Colour: Black

Odometer: 21152 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,732.95	1,909.40	7,823.55	80.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,774.00	4,857.00	3,917.00	44.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,506.95</b>	<b>6,766.40</b>	<b>11,740.55</b>	<b>63.44</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,295.49</b>	<b>473.65</b>	<b>821.84</b>	<b>63.44</b>
<b>Nett Amount (S\$)</b>	<b>19,802.44</b>	<b>7,240.05</b>	<b>12,562.39</b>	<b>63.44</b>

## INSPECTION

Date of Assignment: 23/05/2018

Date Inspected: 23/05/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
<b>Parts:</b>	M1-COUPE	BMW 420I COUPE 2.0 AT D/AB HID SR NAV M SPORT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE3659L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT AXLE SUPPORT	Not Necessary	1,317.15 FS	*- FS
3	1		*LH WISHBONE	Not Necessary	262.20 FS	*- FS
4	1		*LH TENSION STRUT W/HYDRAULIC MOUNT	Not Necessary	262.20 FS	*- FS
5	1		*WHEEL HUB WITH BEARING FRT	Not Necessary	465.75 FS	*- FS
6	1		*FRT LH CARRIER	Not Necessary	439.10 FS	*- FS
7	10		*HEX BOLT WITH WASHER M8X30	Not Necessary	54.00 FS	*- FS
8	1		*FRT GUIDE SUPPORT	Not Necessary	232.00 FS	*- FS
9	1		*FRT SPRING STRUT	Not Necessary	484.55 FS	*- FS
10	1		*LH TIE ROD	Not Necessary	282.35 FS	*- FS
11	1		*EXCH STEERING BOX ELECTR	Not Necessary	3,583.40 FS	*- FS
12	1		*ALLOY RIM 8JX18 DOUBLE SPK S	Dented	1,089.10 FS	*1,089.10 FS
13	1		*HUB CAP WITH CHROME EDGE (BMW)	Not Necessary	24.30 FS	*- FS
14	1		*FRT LH FENDER	Bent	682.50 FS	*682.50 FS
15	1		*MODEL LETTERING SIDE (SPORT LINE)	Necessary	45.20 FS	*45.20 FS
16	2		*GROMMET	Not Necessary	1.50 FS	*- FS
17	1		*FRT LH COVER WHEEL ARCH	Not Necessary	115.60 FS	*- FS
18	1		*COVER BOTTOM LH	Not Necessary	115.60 FS	*- FS
19	1		*AIR DUCT SIDE LH	Not Necessary	44.35 FS	*- FS
20	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
21	4		*ADJUSTABLE BLIND RIVET	Necessary	12.60 FS	*12.60 FS
Total Parts (S\$)					9,732.95	1,909.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
2	TO REPLACE FRONT LEFT FENDER INCLUDING TO REMOVE AND INSTALL FRONT BUMPER FOR PAINTING AND TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
3	TO RESPRAY FRONT BUMPER AND FRONT LEFT FENDER	New	1,923.00	1,730.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
5	TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND REPLACE DAMAGED PARTS	New	2,655.00	0.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	1,062.00	902.00
7	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
8	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,774.00</b>	<b>4,857.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >