

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 28 May 2018

Preliminary Advice

Insured Vehicle No : SGU3917S
TP Vehicle No : SJS6898T
Make : BMW 730LI
Date of Inspection : 23/05/2018
Inspection At : PERFORMANCE MOTORS LIMITED (ALEXANDRA)
303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE
SINGAPORE 159941

Accident Date : 18/05/2018
Assignment Date : 22/05/2018
Est. Duration of Repair : 10.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,898.75
Revised Amount	:S\$	13,070.65
Check Items (Estimated)	:S\$	5,104.10
Total	:S\$	18,174.75

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.