

ASS. REC. BY:

REF:

CS/CTI18009370/T19d3<sup>n2</sup>

Special Instruction:

Surveyor  
Menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

23/5/18 @ 11:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 4422 X

Insured:

SGL 1418B

at Workshop m/s

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

DMPCS N1512131803

Claim No:

8NM18D02568C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/05/2018

CA / REV / REP. / REV 24 HRS

(wp)

26062018

H.O.D. Endorsement:

Date/Time:

11:48am @ 23/5/18

Person Contacted:

Conline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate Han.
	SLX 4422 X - X
	SGL 1418 B - X.
12/10/18 @ 2:41p	confirmed with Caroline final fig @ 10485.55, 5 days. (Red @ 3662.10, 26%).

No  
photo  
upload

14/8

Tanp

REF: CTL

# ASSIGNMENT

From: Date: 13082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 4422X  
at Workshop m/s: Performana  
of: 308 Alexandra Rd

Insured

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Han

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLX4422X Yr Regn: 2018 March.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520I cc: 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 5625 T/Radio: Insured / Std / NI / NA

Eng/No: WBAJA12070W C08842.

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18 R: 215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal: G mm Rear R/Bal: 6 mm

L/Bal: G mm L/Bal: 6 mm

D.O.A. D.O.I. 13/8/18

Survey held at: JMC Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FA 9/3

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 12 OCT 2018

Date/Time. File Pass to? ☐ : Preli. Report

1) 12/10 12pm ☐ : Final Report

Date/Time. File Return to?

2)

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Insp. (\$

☐ Weekend (\$

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1) S + RD: \$

2) Photos:

3) Other:

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$ 10485.55

220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18009370/T1qd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-05-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGL 1418B	Veh. Inspected	SLX 4422X
Policy No.	DMPCSN1512131803	Coverage (\$)	0.00
Claim No.	SNM18D02568C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	23/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	19/05/2018	Inspection Date	13/08/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018		23 May 2018 11:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	<b>SIME DARBY SERVICES PTE LTD</b>
Vehicle Reg. No.:	<b>SLX4422X</b>
Date of Loss:	19/05/2018 00:00 - :59
Claim Type:	<b>TP / SNM18D02568C02</b>
Policy/Cover Note No.:	DMPCSN1512131803
Vehicle Reg. No. (Insured):	<b>SGL1418B</b>
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 04/06/2018]</b>
Adj Asg. Remarks:	EST \$15,137.99, CASE WITH SJE.

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Shiau Chan (LKKAUTO)**

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 12 October 2018 2:41 PM  
**To:** 'PBSP'; Taufikh (LKKAUTO); SUR  
**Subject:** RE: FINAL REPORT / SLX4422X

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$10,485.55 before GST and 5 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, 5 October 2018 1:07 PM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT / SLX4422X

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,181.00  
Total Parts : 6,304.55  
Total Labour & Parts : 10,485.55

Repair days: 5

Thank you.

Regards,  
Caroline

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/05/2018 14:24
Date Of Accident	19/05/2018 13:00
Exact Location Of Accident	CLUNNY COURT CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX4422X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIME DARBY SERVICES P.L
Co Reg No	S197501065W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93839308

### Vehicle Particulars

Manufacturer	BMW
Model	520I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	HARYATI POSTON
NRIC No	S7246856B
Date Of Birth	21/12/1972
Occupation	INDOOR
Date Of Driving Pass	20/05/2002
Driving Experience	15 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93839308
Fax Number	
Contact Number	
Email Address	GRAHAMYATI@GMAIL.COM

Address	33 LLYOD RAOD #05-05
Postcode	239106
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL1418B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAY LING POW
NRIC/Passport Number	S7212873G
Contact Number	96228494/98483480
Address	9 HOLLAND HILL #09-01
Postcode	278738
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

15 May, 2018 10:22 AM

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:  
22/05/18 (1.03pm)

  
Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:



15 May, 2018 10:22 AM

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


SLX 4422 was parked at Currey Court Carpark on Saturday 19th May at about 1pm. When I returned from my shopping I noticed some scratches to the vehicle. I was informed by the security guard that another vehicle had damaged my vehicle as they drove off their car out of the lot.

Name of offender: Ling 96228494  
 Contact: Kevin 98483480  
 Vehicle # SGL 1418B.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Police Officer's Signature  
 Date & Time:

  
 Driver's Signature  
 (if driver is not the policy holder)  
 Date & Time: 22/05/18 (1030 PM)  
 515

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/Fin No.:

Tues 26/06 @ 10am  
 58R / Mon 13/04 @ 8.30am  
 58R

SLX4422X

BMW Dealer  
**Performance Motors Limited**  
 A member of the Sime Darby Group  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770	280, Kampong Arang Road East Coast Centre Singapore 436180 Tel. 63190888 (AfterSales) Fax. 63449773	315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)
---	---	---

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

22 MAY 2018

(a) 6pm

Estimate No. : b1 47035	Page No. : 1 of 2
Date Estimated : 22/05/2018	
Prepared By : Han Kwan Yong	

<b>- ESTIMATE REPAIR FOR -</b> Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942	<b>- ACCOUNT - 40000</b> Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX4422X	WC08842	28/03/2018	520i	0

DESCRIPTION	VALUE
To replace front bumper & attachments, front right fender, right headlight inner support bracket including to knock out dented area caused by the accident	1700 / 2,550.00
To respray front bumper and front right fender	1730 / 1,923.00
To carry out body cavity preservation. (Per panel).	100 ? / 118.00
To replace right headlight including program and conduct tests for proper function.	451 / 531.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 / 177.00
Sundries.	rec ? / 150.00

Total Labour 1: **5,449.00**

DESCRIPTION	QTY	PRIC	VALUE
C CLIP FOR PLASTIC NUT	10	1.00	? 10.00
FRT RH SIDE PANEL BRACKET 1	1	53.55	btv? 53.55
FRT RH SIDE PANEL ALUMINIUM	1	906.50	Rx 906.50
GRILLE AIR INLET OPEN RH (LINES)	1	87.35	? 87.35
RH PROTECTIVE STRIP LINES (SPORT)	1	49.70	unt? 49.70
IMPACT ABSORBER TOP	1	58.75	? 58.75
FRT IMPACT ABSORBER BOTTOM	1	32.05	? 32.05
FRT BUMPER BOTTOM CARRIER	1	380.40	? 380.40
RH FOG LAMP SUPPORT	1	77.95	? 77.95
GUIDE TOP RH	1	34.55	? 34.55
RH BUMPER GUIDE	1	16.15	? 16.15
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,290.35	de 1,290.35
FRT RH GRILLE (M/SPORT)	1	132.50	nn x 132.50
LETTERING (SPORT LINE)	1	45.20	rec 45.20
PLAQUE 82MM	1	69.50	nn x 69.50
GROMMET	2	0.75	nn x 1.50

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 47035  
Date Estimated : 22/05/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX4422X	WC08842	28/03/2018	520i	0

## DESCRIPTION

PLUG  
RH HEADLIGHT MOUNTING  
FRT RH WHEEL ARCH FRT SECTION COVER  
RH COVER BOTTOM  
RH HEADLIGHT LED AHL HIGH (ICON LIG  
RH FOG LIGHT LED

QTY	PRIC	VALUE
10	1.05	10.50
1	136.80	136.80
1	128.40	128.40
1	66.25	66.25
1	4,703.95	4,703.95
1	406.75	406.75

Total Parts : 8,698.65

## Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time 13/8/2018 Excess S\$ \_\_\_\_\_  
Surveyor's Name \_\_\_\_\_ Sign \_\_\_\_\_  
Surveyor's Tel 97495744 Authorised Yes / No  
Authorised Date \_\_\_\_\_ Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No  
Surveyor's E-mail tanjun@phoenix.com  
No. of Working Days Recommend 5 days

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,449.00
Parts	:	8,698.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	990.34
Grand Total	:	15,137.99

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47035  
Date Estimated : 22/05/2018  
Prepared By : Han Kwan Yong

Page No. :

### REPAIR FOR -

Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre

Singapore 159942

### - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLX4422X	WC08842	28/03/2018	520i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include making good the front RH fender and knocking out dents caused by the accident	1700.00		1,700.00	
To respray front bumper and front RH fender	1730.00		1,730.00	
To replace RH LED AHL headlight include programming and conducting tests for proper function	451.00		451.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH SIDE PANEL BRACKET 1	53.55	1.00		53.55
RH PROTECTIVE STRIP LINES (SPORT)	49.70	1.00		49.70
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,290.35	1.00		1,290.35
LETTERING (SPORT LINE)	45.20	1.00		45.20
PLUG	1.05	10.00		10.50
RH HEADLIGHT LED AHL HIGH (ICON LIG	4,855.25	1.00		4,855.25

### # SUPPLEMENTARY ITEMS

Total Labour :	4,181.00
Total Parts :	6,304.55
Total Labour & Parts :	10,485.55
Deduction for Excess :	
Total Repair Costs less Excess:	10,485.55
GST @7%:	733.99
Grand Total :	11,219.54

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18009370/T1QD3N2

Date: 15/10/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1512131803
Claimant Vehicle No :	SLX4422X	Insured Vehicle No :	SGL1418B
Date of Loss:	19/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02568C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLX4422X	Engine No:	21675154B48B20A
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBAJA120X0WC08842
Reg. Date:	28/03/2018 (Man. Year: 2017)	Odometer:	5625 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,999.95	6,454.55	2,545.40	28.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,299.00	4,031.00	1,268.00	23.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,298.95</b>	<b>10,485.55</b>	<b>3,813.40</b>	<b>26.67</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,000.93</b>	<b>733.99</b>	<b>266.94</b>	<b>26.67</b>
<b>Nett Amount (S\$)</b>	<b>15,299.88</b>	<b>11,219.54</b>	<b>4,080.34</b>	<b>26.67</b>

## INSPECTION

Date of Assignment:	23/05/2018	
Date Inspected:	13/08/2018	Inspected At:
		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2018)
<b>Parts:</b> 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLX4422X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*C CLIP FOR PLASTIC NUT	Not Necessary	10.00 FS	*- FS
2	1		*FRT RH SIDE PANEL BRACKET 1	Bent	53.55 FS	*53.55 FS
3	1		*FRT RH SIDE PANEL ALUMINIUM	Repair	906.50 FS	*- FS
4	1		*GRILLE AIR INLET OPEN RH (LINES)	Not Necessary	87.35 FS	*- FS
5	1		*RH PROTECTIVE STRIP LINES (SPORT)	Cut	49.70 FS	*49.70 FS
6	1		*IMPACT ABSORBER TOP	Not Necessary	58.75 FS	*- FS
7	1		*FRT IMPACT ABSORBER BOTTOM	Not Necessary	32.05 FS	*- FS
8	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	380.40 FS	*- FS
9	1		*RH FOG LAMP SUPPORT	Not Necessary	77.95 FS	*- FS
10	1		*GUIDE TOP RH	Not Necessary	34.55 FS	*- FS
11	1		*RH BUMPER GUIDE	Not Necessary	16.15 FS	*- FS
12	1		*FRT BUMPER PANEL PRIMED (PMA/PDC)	Deformed	1,290.35 FS	*1,290.35 FS
13	1		*FRT RH GRILLE (M/SPORT)	Not Necessary	132.50 FS	*- FS
14	1		*LETTERING (SPORT LINE)	Necessary	45.20 FS	*45.20 FS
15	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
16	2		*GROMMET	Not Necessary	1.50 FS	*- FS
17	10		*PLUG	Necessary	10.50 FS	*10.50 FS
18	1		*RH HEADLIGHT MOUNTING	Not Necessary	136.80 FS	*- FS
19	1		*FRT RH WHEEL ARCH FRT SECTION COVER	Not Necessary	128.40 FS	*- FS
20	1		*RH COVER BOTTOM	Not Necessary	66.25 FS	*- FS
21	1		*RH HEADLIGHT LED AHL HIGH (ICON LIG)	Cracked	4,855.25 FS	*4,855.25 FS
22	1		*RH FOG LIGHT LED	Not Necessary	406.75 FS	*- FS
23	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
					<b>Total Parts (\$\$)</b>	<b>8,999.95 6,454.55</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS,FRONT RIGHT FENDER,RIGHT HEADLIGHT INNER SUPPORT BRACKET INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY FRONT BUMPER AND FRONT RIGHT FENDER	New	1,923.00	1,730.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	-
4	TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENRS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			5,299.00	4,031.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >