

ASS. REC. BY:

REF: C8/FCI18009372/TI sd3/22
Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Sithum

of

FCI

Date/Time: 23/5/18 @ 5.35am

Estimated Cost:

Bill to:

OD (TI) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S/G 183A

Insured:

8HC 07 22P

at Workshop m/s

Performance Motor

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

D18504070 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/05/2018

CA / REV / REP. / REV 24 HRS Cup?

H.O.D. Endorsement:

Date/Time: 10:11am @ 23/5/18

Person Contacted:

caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	S/G 183A - X
	8HC 722P - C03/EQ116022512/H1ua3g.2
13/8/18-	called caroline vehicle still not in yet
3/9/18	Email preli revised to FCI

DOA: 21/11/16

Tanph

REF:


FCI

ADDITIONAL

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 5561831A Yr Regn: 2012 Dec.
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 730LE 1998
 Colour: Black A/C: Insured / Std / Nil / NA
 Sp. Reading: 15547 T/Ratio: Insured / Std / Nil / NA
 Eng/No: WSA 7E020904245381
 C/No: _____
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/50R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 28/8/18 c/can.
 Survey held at: PM2
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

05/11/18 Confirmed P/P \$ 3,600.85 @ 3 days with Tanph
 (\$ 3,445.20 Red - 49%)

RECEIVED 13 NOV 2018

Date/Time: File Pass to? 13/11/18
 Typist
 Date/Time: File Return to? ☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Serv. (\$)
☐ Workshop (\$)

Survey Fee
 Transportation

150
50
50
25
275

Report Format :

Lump Sum / I.B.E. (\$ 3,600.85 / P/P)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004070MFSH

Our ref: CS/FCI18009372/T1sd3

Date: 3/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJG 183A


We thank you for your instruction on 23/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/8/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED and have the following to report:-

Workshop Estimate Amount	: S\$7,046.05
Revised Estimate Amount	: S\$3,520.85
"Check" Items Amount	: S\$1,694.20
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-05-2018	Our Ref No.	D18004070MFSH
Accident Date	20-05-2018	Claim Type.	Third Party
Insured Vehicle	SHC0722P	Third Party Vehicle.	SJG183A
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE		
Contact Person.	CAROLINE		
Contact No.	63190174/ 0	Fax No.	64794601
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240619)



PRI Documents



Close



PRI Header Details

Claim No	D18004070MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0722P	TP Vehicle No	SJG183A
PRI Recieved Date	22-05-2018 03:09:44 PM	Surveyor Appointed Date	22-05-2018 05:34:47 PM	Surveyor Accept Date	23-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-05-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 13 November 2018 12:00 PM
To: 'PBSP'
Cc: Taufikh (LKKAuto); SUR; 'Sharon Heng L K'; 'Toh Jing Xuan'; 'Keith Leo Chi Yung'
Subject: RE: FINAL REPORT / SJG183A

Dear Caroline,

Confirmed final fig of \$ 3,600.85 @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Heng L K [mailto:sharon.heng.leekun@sime-darby.com.sg]
Sent: Tuesday, 13 November 2018 10:45 AM
To: PBSP <pml-pbsp@sime-darby.com.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>; Toh Jing Xuan <toh.jing.xuan@sime-darby.com.sg>
Cc: Taufikh (LKKAuto) <taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINAL REPORT / SJG183A

Dear Taufikh

Please find attach photos for your perusal :

Best Regards

Sharon Heng
PML – Body and Paint
DID : 63190123
Fax : 64743229

From: PBSP
Sent: Monday, 12 November, 2018 4:05 PM
To: Shirley Hiew (LKK Auto); Keith Leo Chi Yung; Sharon Heng L K; Toh Jing Xuan
Cc: Taufikh (LKKAuto); SUR
Subject: Re: FINAL REPORT / SJG183A

Dear Sharon / Jing Xuan

Please assist to forward photographs since Keith is not in office this week.

Thank you.

Regards,
Caroline

From: PBSP

Sent: Thursday, 8 November 2018 1:54:18 PM

To: Shirley Hiew (LKK Auto); Keith Leo Chi Yung

Cc: Taufikh (LKKAuto); SUR

Subject: Re: FINAL REPORT / SJG183A

Dear Keith

Please assist to forward photographs to the surveyor.
Photographs not in our shared folder.

Thank you.

Regards,
Caroline

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Thursday, 8 November 2018 10:37:11 AM

To: PBSP

Cc: Taufikh (LKKAuto); SUR

Subject: RE: FINAL REPORT / SJG183A

Hi Caroline,

Kindly provide us the before paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Tuesday, 9 October 2018 2:22 PM

To: taufikh@lkkauto.com; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / SJG183A

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00

Total Parts : 1,586.85

Total Labour & Parts : 3,600.85

Repair days: 3

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 3 September 2018 3:31 PM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004070MFSH/1, SJG 183A
Attachments: SJG 183A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJG 183A
Date of survey: 28/8/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 23 May 2018 2:13 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004070MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 22 May 2018 5:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004070MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

21 MAY 2018

ESTIMATE

Estimate No. : b1 47016
Date Estimated : 21/05/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Lim Hock Leong
14 Sunrise Lane

Singapore 806475

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG183A	G245381	12/12/2017	730Li	0

DESCRIPTION

To replace rear bumper assembly & all attachments
cause by accident.

850 2,550.00

Painting on rear bumper assembly

934 1,038.00

To check electrical wiring systems at the rear section
for proper function.

150 177.00

Sundries.

7.00 80.00

Total Labour 1: 3,845.00

DESCRIPTION

REAR BUMPER ADAPTER
REAR BUMPER CARRIER
REAR BUMPER CENTRE GUIDE
REAR BUMPER CENTRE GUARD
BUMPER GUARD REAR
REAR BUMPER COVER
TRIM REAR PRIMED
REAR BUMPER PANEL PRIMED (PDC/PMA)
REAR BUMPER TOWING EYE COVER PRIMED
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC
1	77.65
1	898.50
1	51.50
1	84.20
1	102.95
1	107.05
1	216.45
1	1,586.85
1	55.70
4	5.05

VALUE
? 77.65
? 898.50
? 51.50
? 84.20
? 102.95
? 107.05
? 216.45
de 1,586.85
? 55.70
? 20.20

Total Parts : 3,201.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47016
Date Estimated : 21/05/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG183A	G245381	12/12/2017	730Li	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date of Time 27/8/18 Excess SS _____
 Surveyor's Name Taufik Sign *Taufik*
 Surveyor's Tel 97495749 Authorised Yes / No
 Anticipated Cost _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No
 Surveyor's E-mail taufik@lkkauto.com
 Recommended Working Days Recommend 3 days

7046.05

Labour 1	:	3,845.00
Parts	:	3,201.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	493.22
Grand Total	:	7,539.27

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47016
Date Estimated : 21/05/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Lim Hock Leong
14 Sunrise Lane

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 806475

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE		
SJG183A	G245381	12/12/2017	730Li	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper in removing attachments to facilitate repairs include knocking out dents caused by the accident				850.00		850.00
To spray paint rear bumper				934.00		934.00
To check electrical wiring systems at the rear section for proper function.				150.00		150.00
Sundries.				80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,586.85	1.00		1,586.85

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,586.85
Total Labour & Parts :	3,600.85
Deduction for Excess :	
Total Repair Costs less Excess:	3,600.85
GST @7%:	252.06
Grand Total :	3,852.91



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009372/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 722P	Veh. Inspected	SJG 183A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004070MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 730Li	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA7E02090G245381	Colour	BLACK	
Odometer	15547	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	PIRELLI	6 mm	
L/H Front Tyre	245/50 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/05/2018	Inspection Date	28/08/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 183A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER ADAPTER (SN)	NOT NECESSARY	77.65	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	898.50	-
1	REAR BUMPER CENTRE GUIDE (SN)	NOT NECESSARY	51.50	-
1	REAR BUMPER CENTRE GUARD (SN)	NOT NECESSARY	84.20	-
1	BUMPER GUARD REAR (SN)	NOT NECESSARY	102.95	-
1	REAR BUMPER COVER (SN)	NOT NECESSARY	107.05	-
1	TRIM REAR PRIMED (SN)	NOT NECESSARY	216.45	-
1	REAR BUMPER PANEL PRIMED (PDC/PMA)(SN)	DEFORMED	1,586.85	1,586.85
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	NOT NECESSARY	55.70	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	20.20	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			3,281.05	1,666.85
LABOUR				
	TO REPLACE REAR BUMPER ASSEMBLY & ALL ATTACHMENTS CAUSED BY ACCIDENT.		2,550.00	850.00
	PAINTING ON REAR BUMPER ASSEMBLY.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			3,765.00	1,934.00
GRAND TOTAL			7,046.05	3,600.85
RECOMMENDED COST OF REPAIRS				3,600.85

Report Ref No. CS/FCI18009372/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.