

ASS. REC. BY:

REF

CS/MSG18009373/ Tl rd3<sup>57</sup>

Special Instruction:

Surveyor

Merimen

## ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MS/G

Date/Time:

23/5/18 @ 10:54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 9229R

Insured:

SJX7383D

at Workshop m/s

Performance Motor

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

A80406837 MCX

Claim No:

559085

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/05/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

11:15am @ 23/5/18

Person Contacted:

Caroline

Vehicle IN /

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLV 9229R - X

SJX7383D - X

5/6/18

Send preli revised by merimen

13/7/18

Final fig \$3404.05 confirmed by email (Red 2147, 3990)

REF: MS1G

## ASSIGNMENT

From:

Date:

04/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLV 9229R  
Performance

at Workshop m/s:

of 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Kevin

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

Date:

Person Contacted:

Vehicle: IN / OUT

Kevin

Date / Time

Action / Instruction

Veh No:

SLV 9229K

Yr Regn:

2017 Sep

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216i GT cc. 1499

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

20/90

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WB A2D920205F91 382

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

0

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/1/18 @ 1645.

Survey held at

PML

Des. of Damages: Frt

Rear

/

O/S

/

N/S

/

U/C

/

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 13 JUL 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

13/7 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$) :

3404.05

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) \$ - RS - \$

) Photos

) Charts

TOTAL

150
10

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		23 May 2018 10:54 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YU YEO CONSTRUCTION PTE LTD, Co. Reg. No.: 200010052C		
Main Claimant:	NG WEE HENG, ID: S7734195A		
Vehicle Reg. No.:	SLV9229R	Date of Loss:	21/05/2018 06:00 - :59 [7 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559085	Policy/Cover Note No.:	A80406837MCX (Comprehensive) Coverage: 06/07/2017 - 05/07/2018
Vehicle Reg. No. (Insured):	SJX7383D	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/05/2018]		
Driver/Custodian (Insured):	WANG HAOCHEN (), NRIC: S9670156Z, Tel: +6592708539		
Adj Asg. Remarks:	TP agree on SJE - pls appoint LKK Auto. Liability - 100% Contact Person - Caroline / 6319 0174. Thanks!		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong Chew Shong	Date: 05 Jun 2018

**Preliminary Advice**

Insured Vehicle No	: SJX7383D	Accident Date	: 21/05/2018
TP Vehicle No	: SLV9229R	Assignment Date	: 23/05/2018
Make	: BMW 216I	Est. Duration of Repair	: 3.00
Date of Inspection	: 04/06/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,551.05
Revised Amount	:S\$	2,900.25
Check Items (Estimated)	:S\$	778.00
Total	:S\$	3,678.25
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/05/2018 18:25
Date Of Accident	21/05/2018 06:40
Exact Location Of Accident	PUNGGOL WALK TO PUNGGOL FIELD (SLIP RD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV9229R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG WEE HENG
NRIC No	S7734195A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94310359
Alternative Phone No	OFFICE-94310359

### Vehicle Particulars

Manufacturer	BMW
Model	216i GT
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN850317
Cover Note Number	

### Driver

Name of Driver	NG WEE HENG
NRIC No	S7734195A
Date Of Birth	21/11/1977
Occupation	INDOOR
Date Of Driving Pass	03/06/1997
Driving Experience	20 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94310359
Fax Number	
Contact Number	OFFICE-94310359
Email Address	NOEMAIL

Address	BLK 128 PUNGGOL WALK #09-11
Postcode	828775
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : LIM SIOK CHENG GENDER: : FEMALE
Passenger 2	NAME: : VIVIENNE NG GENDER: : FEMALE
Passenger 3	NAME: : VEYES NG GENDER: : MALE
Passenger 4	NAME: : MAID GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX7383D
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WANG HAO CHEN

NRIC/Passport Number	S9670156Z
Contact Number	92708539
Address	BLK 134 PUNGGOL WALK #03-22
Postcode	828778
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	1

15 May, 2018 10:22 AM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 21/5/18 1630


Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Kevin Leong  
NRIC/FIN No.:

# Sketch Plan Pg. 2

15 May, 2018 10:22 AM

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21st May 2018 at around 0640am, I was travelling at Punggol walk turning toward Punggol field on my left. While turning left on the faster lane, I came to an stop because of on comingorry. Suddenly, ~~red~~ vehicle number SJX7383D knock my ~~rear~~ vehicle from behind. Please refer to video clip.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/5/18 1630hrs

Driver's Signature

(If driver is not the policyholder)

Date & time:

Reporting Centre Personnel's Signature

Name: Kevin Leong

NRIC/FIN No.

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

22 MAY 2018

Estimate No. : b1 47033  
Date Estimated : 22/05/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -  
Ng Wee Heng (Huang Weixiong)  
128 Punggol Walk  
#09-11

Singapore 828775

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV9229R	5E91382	27/09/2017	216i G TOURER	0

## DESCRIPTION

To replace rear bumper assembly &amp; all attachments cause by accident.

Painting on rear bumper assembly

To check electrical wiring systems at the rear section for proper function.

Sundries.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting ✓
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation ✓
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company ✓

Acknowledged by Repairer

Signature:

Date:

## VALUE

850 2,550.00  
934 1,038.00  
150 177.00  
7 80.00

Total Labour 1: 3,845.00

## DESCRIPTION

REAR BUMPER CARRIER  
SUPPORT  
RR BUMPER LH INNER SIDE GUIDE  
RR BUMPER RH INNER SIDE GUIDE  
REAR BUMPER PANEL PRIMED (PDC)  
SET MOUNTS PDC SENSOR REAR  
REAR BUMPER TOWING FLAP EYE PRIMED  
DECOUPING RING PDC TORQUE CONVERTER

## QTY PRIC

1 423.80  
1 59.25  
1 65.90  
1 65.90  
1 966.25  
1 62.95  
1 41.80  
4 5.05

## VALUE

423.80  
59.25  
65.90  
65.90  
966.25  
62.95  
41.80  
20.20

Total Parts : 1,706.05

5551.05

Customer's Name: \_\_\_\_\_  
Reg. No. 46113C 1645  
Chassis No. 5E91382  
Engine No. \_\_\_\_\_  
Date of Birth: \_\_\_\_\_  
Signature: \_\_\_\_\_  
Stamp: \_\_\_\_\_  
Address: \_\_\_\_\_  
City: \_\_\_\_\_  
State: \_\_\_\_\_  
Postcode: \_\_\_\_\_  
Phone: \_\_\_\_\_  
Fax: \_\_\_\_\_  
Email: \_\_\_\_\_  
Website: \_\_\_\_\_  
Notes: \_\_\_\_\_

Labour 1	:	3,845.00
Parts	:	1,706.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	388.57
Grand Total	:	5,939.62

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47033  
Date Estimated : 22/05/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Ng Wee Heng (Huang Weixiong)  
128 Punggol Walk  
#09-11

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 828775

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SLV9229R	5E91382	27/09/2017	216i G TOURER	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachment include knocking out dents caused by the accident			850.00		850.00
To spray paint rear bumper			934.00		934.00
To check electrical wiring systems at the rear section for proper function.			150.00		150.00
Sundries.			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	423.80	1.00		423.80
REAR BUMPER PANEL PRIMED (PDC)	966.25	1.00		966.25

### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,390.05
Total Labour & Parts :	3,404.05
Deduction for Excess :	
Total Repair Costs less Excess:	3,404.05
GST @7%:	238.28
Grand Total :	3,642.33

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 13 July 2018 10:25 AM  
**To:** 'PBSP'; Taufikh (LKKAuto); SUR  
**Subject:** RE: FINAL REPORT / SLV9229R

Dear Caroline,

WITHOUT PREJUDICE

Confirmed amount \$3404.05 before GST @ 3 working days.

**Final invoice and all supporting documents sent over to MSIG**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Thursday, 12 July 2018 2:29 PM  
**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT / SLV9229R

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00  
Total Parts : 1,390.05  
Total Labour & Parts : 3,404.05

Repair days: 3

Thank you.

Regards,  
Caroline

C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		23 May 2018 10:54 <a href="#">Edit Adj Rpt</a>	<b>S\$3,404.05</b> <a href="#">Edit Estimates</a>	<b>S\$3,404.05</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YU YEO CONSTRUCTION PTE LTD, Co. Reg. No.: 200010052C			
Main Claimant:	NG WEE HENG, ID: S7734195A			
Vehicle Reg. No.:	SLV9229R	Date of Loss:	21/05/2018 06:00 - :59 [7 Months and 24 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 559085	Policy/Cover Note No.:	A80406837MCX (Comprehensive) Coverage: 06/07/2017 - 05/07/2018	
Vehicle Reg. No. (Insured):	SJX7383D	Policy No. (Claimant):		
		Excess:		
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/06/2018]			
Driver/Custodian (Insured):	WANG HAOCHEN (), NRIC: S9670156Z, Tel: +6592708539			
Adj Asg. Remarks:	TP agree on SJF - pls appoint LKK Auto. Liability - 100% Contact Person - Caroline / 6319 0174. Thanks!			

### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




## Claim Documents



























**\*SLV9229R (559085)**  
**[SJX7383D]**  
**TP**  
**NG WEE HENG**  
**May 21 2018 6:00AM**  
**[YU YEO CONSTRUCTION PTE LTD]**  
**Performance Motors Limited**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/18 10:07	<b>Video - Accident - TP</b> From:SC - Reg. No: SJX7383D, Claimant: YU YEO CONSTRUCTION PTE LTD	 Load AVI	

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/18 10:07	<b>Accident Statement</b> From:SC - Reg. No: SJX7383D, Claimant: YU YEO CONSTRUCTION PTE LTD	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 13:57	<b>Adjuster Immediate Advice</b>	 Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	05/06/18 10:51	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	13/07/18 10:19	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
23	13/07/18 10:19	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
24	13/07/18 10:19	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
25	13/07/18 10:19	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
26	13/07/18 10:19	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

Video				✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/18 10:07	<b>SLV9229R E FILE REPORT</b> From: SC - Reg. No: SJX7383D, Claimant: YU YEO CONSTRUCTION PTE LTD	Load PDF	
2	23/05/18 10:08	<b>Estimate - CI - NRIC &amp; DL</b>	Load PDF	
3	23/05/18 10:08	<b>Email from TP on PRI &amp; liability</b>	Load PDF	
4	23/05/18 10:39	<b>TP Agree on SJE</b>	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009373/T1VD3S2

Date: 17/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80406837MCX

Claimant Vehicle No: SLV9229R

Insured Vehicle No: SJX7383D

Date of Loss: 21/05/2018

Nature of Claim: TP

Claim No: 559085

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV9229R

Make &amp; Model: BMW 216I, 1.5 D GT LED (A)

Engine No: 34275059B38A15A

Reg. Date: 27/09/2017 (Man. Year: 2017)

Chassis No: WBA2D920205E91382

Colour: Black

Odometer: 20190 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size:

205/60R16

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,786.05	1,470.05	316.00	17.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	1,934.00	1,831.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,551.05</b>	<b>3,404.05</b>	<b>2,147.00</b>	<b>38.68</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>388.57</b>	<b>238.28</b>	<b>150.29</b>	<b>38.68</b>
<b>Nett Amount (S\$)</b>	<b>5,939.62</b>	<b>3,642.33</b>	<b>2,297.29</b>	<b>38.68</b>

INSPECTION

Date of Assignment: 23/05/2018

Date Inspected: 04/06/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2018)
<b>Parts:</b>	M1-MPV	BMW 216I 1.5 D GT LED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV9229R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CARRIER	Bent	423.80 FS	*423.80 FS
2	1		*SUPPORT	Not Necessary	59.25 FS	*- FS
3	1		*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	65.90 FS	*- FS
4	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	65.90 FS	*- FS
5	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	966.25 FS	*966.25 FS
6	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.95 FS	*- FS
7	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Repair	41.80 FS	*- FS
8	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
9	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>1,786.05</b>	<b>1,470.05</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ASSEMBLY & ALL ATTACHMENTS CAUSE BY ACCIDENT.	New	2,550.00	850.00
2	PAINTING ON REAR BUMPER ASSEMBLY.	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (S\$)			3,765.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >