

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Katherine Wong Chew Shong	Date:	05 Jun 2018
<u>Preliminary Advice</u>			

Insured Vehicle No	: SJX7383D		
TP Vehicle No	: SLV9229R	Accident Date	: 21/05/2018
Make	: BMW 216I	Assignment Date	: 23/05/2018
Date of Inspection	: 04/06/2018	Est. Duration of Repair	: 3.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,551.05
Revised Amount	:S\$	2,900.25
Check Items (Estimated)	:S\$	778.00
Total	:S\$	3,678.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐	The vehicle is economical/not economical for repair.
☒	The above survey was conducted on a 'without prejudice' basis.