

Trans-cab Auto Services Pte Ltd**AAD1805-186**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 640L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 640L

VF1ABL15AUC283264

RENAULT

LATITUDE

20.5.2018

AIG

PART		LIST	
1	1 BUMPER COVER REAR ✓	\$	1,108.46
2	1 BUMPER LOWER REAR ✓	\$	768.84
3	1 BUMPER BRACKET CTR REAR X	\$	113.47
4	1 BUMEP R BRACKET SIDE RH REAR X	\$	135.97
5	1 BUMEP R RETAINER RH REAR X	\$	44.99
6	1 BUMPER REFLECTOR RH X	\$	43.61
7	1 BUMEP R BRACKET SIDE LH REAR X	\$	135.97
8	1 BUMEP R RETAINER LH REAR X	\$	44.99
9	1 BUMPER REFLECTOR LH X	\$	43.61
10	1 BUMPER BEAM REAR X X X	\$	777.52
11	1 BUMPER BEAM BRACKET LH REAR X	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR X	\$	225.95
13	1 BOOT REAR X	\$	2,872.68
14	1 BOOT FINISHER X	\$	470.06
15	1 BOOT WHEATERSTRIP X	\$	323.05
16	1 BOOT REFLECTOR LAMP LH X	\$	493.35
17	1 BOOT REFLECTOR LAMP RH X	\$	493.35
18	1 BOOT BADGE 'RENAULT' X	\$	225.36
19	1 BOOT BADGE X	\$	225.36
20	1 BOOT STRUT LH X	\$	276.08
21	1 BOOT STRUT RH X	\$	276.08
22	1 BOOT HINGE LH X	\$	367.84
23	1 BOOT HINGE RH X	\$	367.84
24	1 BOOT INNER TRIM X	\$	586.45
25	1 BOOT SWITCH X	\$	168.13
26	1 BOOT LOCK X	\$	202.67
27	1 BOOT LOCK CATCH X	\$	74.40
28	2 LICENCE PLATE LAMP X	\$	50.52
29	2 BOOT RUBBER PLUG X	\$	221.81

Trans-cab Auto Services Pte Ltd**AAD1805-186**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 640L

30	1 DOOR PANEL REAR LH	X	\$	2,844.66
31	1 FENDER PANEL INNER TRIM REAR LH	X	\$	671.45
32	1 FENDER PANEL REAR LH	X	\$	3,299.13
33	1 WHEELARCH REAR LH	X	\$	543.47
34	1 FENDER PANEL INNER TRIM REAR RH	X	\$	671.45
35	1 FENDER PANEL REAR RH	X	\$	3,299.13
36	1 WHEELARCH REAR RH	X	\$	543.47
37	1 TAILLAMP RH	X	\$	552.55
38	1 TAILLAMP PANEL RH	X	\$	986.70
39	1 TAILLAMP LH	X	\$	552.55
40	1 TAILLAMP PANEL LH	X	\$	986.70
41	1 OUTER PANEL REAR (End Panel)	X	\$	1,471.77
42	1 OUTER PANEL REAR (End Panel)TRIM	X	\$	404.56
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	X	\$	2,189.88
44	1 SPARE WHEEL PANEL TRIM	X	\$	612.21
45	1 EXHAUST REAR	X	\$	7,489.05
46	1 EXHAUST CAP REAR	X	\$	230.49
47	1 FUEL FLAP L70Y	X	\$	343.57
TOTAL				\$ 39,057.17
10%				\$ 3,905.72
				\$ 35,151.45

Specical Nett

1	1SET PARKING AID		\$	700.00 ^{KR}
2	1SET REAR BUMPER CLIP	—	\$	66.00
3	1SET BUMPER BRACKET CTR CLIP	X	\$	33.00
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X	\$	10.00
5	1SET BUMPR RETAINER RH CLIP RR	X	\$	20.00
6	1SET BUMPR BRACKET SIDE CLIP LH RR	X	\$	10.00
7	1SET BUMPR RETAINER CLIP LH RR	X	\$	20.00
8	1SET BUMPER LOWER REAR RIVET	—	\$	22.00
9	1SET BUMPER LOWER REAR CLIP	—	\$	66.00
10	1 EXHAUST MOUNTING REAR	X	\$	17.82
11	1SET BOOT FINISHER CLIP	X	\$	24.20
12	1 BOOT STICKER "Trans-cab"	X	\$	30.00
13	1 BOOT STICKER "6555-3333"	X	\$	30.00
14	1 BOOT INNER TRIM CLIP	X	\$	45.00
15	1SET FENDER WHEELARCH REAR RH CLIP	X	\$	35.00

Trans-cab Auto Services Pte Ltd**AAD1805-186**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 640L

16	1SET FENDER WHEELARCH REAR LH CLIP	X	\$	35.00
17	1 FENDER INNER TRIM CLIP LH	X	\$	28.00
18	1 FENDER INNER TRIM CLIP LH	X	\$	28.00
19	1 TAILLAMP CLIP RH	X	\$	5.00
20	1 TAILLAMP CLIP LH	X	\$	5.00
21	2 REAR WINDSCREEN SELANT	X	\$	80.00
22	1 WINDSCREEN MOULDING	X	\$	100.00
23	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	X	\$	385.00
25	1 SPARE TYRE	X	\$	330.00

TOTAL \$ 2,225.02**TOTAL PARTS \$ 37,376.47****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 200
To Rust-Proofing Of The Affected Areas.	\$	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 20
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1805-186**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 640L

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00 X
TOTAL	\$	12,540.00

Over All Total \$ 49,916.47**(PART-BY-PART)****Repair Days****20 DAYS**

Kalvin C/Cy
22/5/18 1600 hrs
2 days.
P/P
Before paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: