

ASS. REC. BY:

REF: CS/CTU8009381/Usbn2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

Mehmet

From (Person): Jowyn Tay of CT Date/Time: 23/05/2018 117pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 6873X Insured: SJK 2233E

at Workshop m/s: Pogusue @ SME Tel: 8338 8418

of BTK 1 Kaki Bukit Ave 6 #02-15

Policy No: DMHCSN 1815461800 Claim No: SNM18D02589C02

Sum Insured: Excess:

Make of Veh: D.O.A. 17052018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time: 23/05/2018 210pm Person Contacted: Gan Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 6873X - x
	SJK 2233E - (06 / AXA) 11/01/164 / mlybg2 DUA: 050914

(08/11/13) wef

ASS REC BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 6873X

at Workshop n/s Sme

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR6873X Yr Regn: 8. 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 'A'

Make: Toyota prius Hybrid 1788

Colour: white A/C: insured / Std / Nil / NA

Sp. Reading: 95070 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTDKAB3FU003569914

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 17/5/18 D.O.I. 30/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L.H. O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/8/18 Confirmed L/S \$2550 with AH ying.

(\$1,440.15 Red - 36%)

Date/Time, File Pass to?

12/08/18

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS \$1

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$ 2,550.00 L/S)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018		23 May 2018 13:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: GRAB RENTALS PTE LTD									
Vehicle Reg. No.: SLR6873X Date of Loss: 17/05/2018 00:00 - :59									
Claim Type: TP / SNM18D02569C02 Policy/Cover Note No.: DMHCSN1815461800									
Vehicle Reg. No. (Insured): SJK2233E Policy No. (Claimant):									
Excess: \$50.00									
Repairer: Pegasus @ Sme (HQ) 1 Kaki Bukit Ave 6 #02-15, Autobay @ Kaki bukit, 417883 Kaki Bukit - Tel: 83388418									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/06/2018]									
Adj Asg. Remarks: EST \$4269.46, ASSIGN MARCUS CHUA AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

Vehicle Details

Vehicle No.: SLR6873X

Vehicle to be Exported: No

Intended De-registration Date: 30 Jul 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8 CVT

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 2ZRS084747

Chassis No.: JTDKB3FU003569914

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$31,008.00

Original Registration Date: 24 Aug 2017

First Registration Date: 24 Aug 2017

Transfer Count: 0

Actual ARF Paid: \$5,412.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Aug 2027

PARF Rebate Amount: \$4,059.00

Intended COE Rebate Details

COE Expiry Date: 23 Aug 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,001.00

COE Rebate Amount: \$45,323.00

Total Rebate Amount: \$49,382.00

Message

The information contained herein is correct as at 30 Jul 2018

OK



GST / ROC Company No : 201101753C

Third Party Insurer : CHINA

Insured's Veh No : SJK2233E

Date of accident : 17/05/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/05-1019

Quotation Date : 19/05/2018

Estimate To Repair

TOYOTA PRIUS

Vehicle No :

SLR6873X

Chassis No :

JTDKB3FU003569914

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	FRT BUMPER <i>Deep cut</i>	\$565.60
2	1PC	FRT BUMPER RETAINER RH <i>Self</i>	\$82.90
3	10PC	FRT BUMPER CLIPS <i>see</i>	\$55.00
4	1PC	RH HEADLAMP <i>h/b one</i>	\$2,858.90
5	1PC	FRT RH FOG LAMP <i>17</i>	\$522.80
6	1PC	FRT BUMPER LOWER GRILLE <i>11</i>	\$195.00
			\$4,280.20
LESS 25%			\$1,070.05
			\$3,210.15
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$30.00
2		LABOUR CHARGE	\$300.00
3		SPRAY PAINTING	\$450.00
Total			\$780.00
Sub Total			\$3,990.15
GST (7.00%)			\$279.31
Total			\$4,269.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118009381/USBN2

Date: 17/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1815461800
Claimant Vehicle No :	SLR6873X	Insured Vehicle No :	SJK2233E
Date of Loss:	17/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02569C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR6873X	Engine No:	2ZRS084747
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU003569914
Reg. Date:	24/08/2017 (Man. Year: 2017)	Odometer:	95070 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,210.15	2,671.80	538.35	16.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	540.00	240.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,990.15	3,211.80	778.35	19.51
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	3,990.15	2,550.00	1,440.15	36.09
+ GST 7.00/7.00% (S\$)	279.31	178.50	100.81	36.09
Nett Amount (S\$)	4,269.46	2,728.50	1,540.96	36.09

INSPECTION

Date of Assignment: 23/05/2018

Date Inspected: 30/07/2018 Inspected At:

Pegasus @ Sme (HQ)
1 Kaki Bukit Ave 6 #02-15, Autobay @
Kaki bukit
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2018)
Parts: 144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR6873X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deep Cut	565.60 FL	*565.60 FL
2	1		*FRT BUMPER RETAINER RH	Bent	82.90 FL	*82.90 FL
3	10		*FRT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
4	1		*RH HEADLAMP	Holder Cracked	2,858.90 FL	*2,858.90 FL
5	1		*FRT RH FOG LAMP	Not Necessary	522.80 FL	*- FL
6	1		*FRT BUMPER LOWER GRILLE	Not Necessary	195.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,280.20	3,562.40
- List Item Discount on L Items 25.00/25.00% (S\$)	1,070.05	890.60
Total Parts (S\$)	3,210.15	2,671.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	300.00	220.00
3	SPRAY PAINTING	New	450.00	300.00
Gross Labour Cost (S\$)			780.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >