

AIG SINGAPORE PTE LTD78 Shenton Way
#07-16
Singapore 079120**ESTIMATE**VEHICLE NO. : SGS6938Y
CHASSIS NO : MR053HY4204218998
MAKE / MODEL : TOYOTA VIOS 1.5E A
DATE OF ACCIDENT : 16th MAY 2018 @ 1205hrs

YOUR INSURED VEHICLE NUMBER : S1913CD

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>Price</u>	<u>Total Price</u>
FRONT BUMPER	1	\$ 550.00	\$ 550.00 DE-
RH FRONT FENDER	1	\$ 200.00	\$ 200.00 Bu-
RH FRONT WHEEL HOUSING	1	\$ 300.00	\$ 300.00 Repair
RH FRONT WHEEL HOUSING COVER	1	\$ 40.00	\$ 40.00 DE-
RH FRONT WHEEL HOUSING CLIP	10	\$ 3.00	\$ 30.00 Bu-
RH FRONT FENDER LAMP	1	\$ 30.00	\$ 30.00 Bu-
RH FRONT DOOR ASSY	1	\$ 898.00	\$ 898.00 Bu-
RH FRONT DOOR OUTER PANEL	1	\$ 500.00	\$ 500.00 X
RH FRONT DOOR PROTECTOR	1	\$ 60.00	\$ 60.00 DE-
RH FRONT DOOR WINDOW REGULATOR	1	\$ 150.00	\$ 150.00 ?
RH FRONT DOOR WINDOW MOTOR	1	\$ 178.00	\$ 178.00 ?
RH FRONT DOOR REMOTE LOCK	1 SET	\$ 258.00	\$ 258.00 ?
RH FRONT PILLAR	1	\$ 275.00	\$ 275.00 Repair
RH REAR DOOR ASSY	1	\$ 898.00	\$ 898.00 Rt-
RH REAR DOOR OUTER PANEL	1	\$ 500.00	\$ 500.00 X
RH REAR DOOR PROTECTOR	1	\$ 60.00	\$ 60.00 Sur-
RH REAR DOOR WINDOW REGULATOR	1	\$ 150.00	\$ 150.00 ?
RH REAR DOOR WINDOW MOTOR	1	\$ 178.00	\$ 178.00 ?

RH FR Tyre rim - sur / 300 s/n

Total Parts \$ 5,255.00**LABOUR CHARGES**TO SPRAY PAINT ON THE AFFECTED AREAS
TO REPAIR, REMOVE & REPLACE ALL THE DAMAGE ITEMS

\$	2,000.00	1100
\$	2,500.00	1200
Total Labour	\$ 4,500.00	

Sub Total \$ 9,755.00Prepared By : -
Lynn Ahmad
Motorway Car Care Centre Pte Ltd
TEL: 6571 9625
FAX : 6278 5535
EMAIL: lynn@motorway.com.sg
WEBSITE: www.motorway.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:Rasul
Hp 90000068
11 days
4/5
24/05/18 @ 1415
Resurvey after repair