

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0604/2018/GW
Date : 24-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lam Hoi Peng(Lin Kai Bin)
Address : 46 Eastwood Drive

Telephone : HP +65 945206666
Type of Claim : Third Party Claims

Policy No. :

Vehicle No : **SFR 8068 L**

Model Code : Audi Q5 3.2 FSI Qu

Model / Year : Feb-10

Engine No : CAL 055034

Chassis No : WAUZZZ8R9AA060324

Mileage : -

Date In :

Liability : -

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 17/05/2018

Place of Accident : East Coast Park Service Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFR 8068 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500.	
3	To respray rear bumper.	\$ 900.00 550	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 8068 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Del d</i>	\$ 1,786.00	✓
2	REAR BUMPER SPOILER <i>Del d</i>	\$ 762.00	✓
3	REAR BUMPER COVER <i>Ne New</i>	\$ 632.00	✗
4	REAR BUMPER FIXING PARTS <i>Ne New</i>	\$ 143.00	✗
5	REAR BUMPER GUIDE SECTION-LH/RH <i>Ne New</i>	2 \$ 92.00	✗
6	REAR BUMPER SENSOR <i>Ne New</i>	2 TBC	✗
7	REAR BUMPER CARRIER <i>Ne New</i>	\$ 571.00	✗
8	SUNDRIES <i>?</i>	\$ 200.00	?
TOTAL SPARE PARTS		: \$ 4,186.00	
TOTAL LABOUR CHARGES		: \$ 2,422.00	
GRAND TOTAL		: \$ 6,608.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 30/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant