

Sheet1

ZEN WERKZ LLP

BLOCK 3 KAKI BUKIT ROAD 1 #03-04 EUNOS TECHNOLINK
SINGAPORE 415935

Tel : (65) 67428117 HP: 92712214 Fax: (65) 67428117

TAN LAY NAH LINDA
Blk 3 Kaki Bukit Road 1
#03-04 Eunost Technolink
Singapore 415935

TP111 Beran

22nd MAY 2018

WBAFP32040C867787

Accident date: 20th MAY 2018

Estimated repair cost for vehicle no: SKP2627P BMW 523I '11

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear Boot Lid Number Plate		\$50.00 ✓
2	1	Rear Boot Lid Inner Lock		\$225.00 ✓
3	1	Rear boot lid emble logo		\$85.00 ✓
4	1	Rear boot lid inner rubber		\$225.00 ✓
5	2	Rear tail lamp RH cracked	\$595.00	\$1,190.00 595.
6	4	Rear tail lamp clips Not Nec	\$10.00	\$40.00 x
7	1	Rear tail lamp panel-RH		\$0.00 x
8	1	Rear End Panel Top Garnish		\$368.00 x
9	10	Rear end panel top garnish clips	\$5.00	\$50.00 x
10	1	Rear Bumper Deformed		\$1,667.20 1532
11	2	Rear Bumper Side Bracket Nec	\$78.00	\$156.00 ✓
12	4	Rear Bumper reverse sensor 2 piece damaged	\$250.00	\$1,000.00 500
13	2	Rear Bumper Side Reflector RH missing	\$88.00	\$176.00 88
14	1	Rear Bumper lower garnish Deformed		\$450.00 ✓
15	8	Rear bumper clips Nec	\$5.00	\$40.00 ✓
16	1	Rear bumper center top bracket crumpled		\$126.00 ✓
17	1	Rear Bumper reinforcement Bent		\$780.00 698
18	1	Rear Bumper towing cover Missing		\$68.00 ✓
19	2	rear exhaust chome pipe Not Nec	\$135.00	\$270.00 x
Subtotal :-				\$6,966.20

4253

A040-3>

Labour charges

To Remove & refix cushion

\$150.00 X

To Remove & refix rear exhaust

\$250.00 X

To Remove & refix Front & Rear reverse Sensor

\$150.00 60

Tuff kote

\$150.00 X

To Check Wiring System

\$80.00 30

Panel beating

\$1,000.00 300

Spray painting

\$1,000.00 400

Subtotal :- \$2,780.00

Total:- \$9,746.20

total 4830.35
h/s 3850.
03 Days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: