



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2006265
INV Date 11/09/2020
Reference CC4/EQI18009392/Gga3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 4872X
Insured Veh. YL 88M
Claim No. DM18HO01310/JT
Policy No. DMCPHQ18-001228
Accident Date 16/05/2018
Inspection Date 22/05/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18009392/Gga3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 11-09-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YL 88M	Veh. Inspected	SLU 4872X
	Policy No.	DMCPHQ18-001228	Coverage (\$)	0.00
	Claim No.	DM18HO01310/JT	Excess (\$)	0.00
	Assign From	JANET	Assign Date	21/05/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA C-HR	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZYX102081540	Colour	YELLOW
	Odometer	38304	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/05/2018	Inspection Date	22/05/2018
	Survey held at	ALLSWELL MOTOR TRADERS 100 JALAN SULTAN #02-41 SULTAN PLAZA SINGAPORE 199001		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 4872X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LOWER REAR BUMPER	DEFORMED	1,219.00	650.00
1	REAR REINFORCEMENT BAR	NOT NECESSARY	599.10	-
	LESS 25% DISCOUNT		-	-162.50
			1,818.10	487.50
	<u>LABOUR</u>			
	DISMANTLE/ASSEMBLY OF LOWER REAR BUMPER/REINFORCEMENT BAR.		160.00	160.00
	SPRAY PAINTING OF LOWER REAR BUMPER.	NOT NECESSARY	360.00	-
			520.00	160.00
GRAND TOTAL			2,338.10	647.50

RECOMMENDED COST OF REPAIRS				647.50
------------------------------------	--	--	--	---------------

Report Ref No. CC4/EQ118009392/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 4872X

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 4872X

RE-INSPECTION

