





CASE OWNER: Stacy | CC4 / AXA1800 2397, Aeb39 | **LKK:** ADAC

Surveyor: Adrian | **DOI:** 21/5/18 | **Assignment:** 21/5/18 | **Date / Time:** 21/5/18

Pre-assign / CCU / FTE: SHC 5789P | **Registered in Merimen:** 21/5/18


Insured Vehicle No.: SHC 5789P | **Claim No.:** 1047252
Name of Insured: TRANS-CAR SERVICES PTE | **Policy No.:** VPX / P166520
Insured Tel No.: HP: 16/5/18 | **Make / Model:** RENAULT
Excess Sec II :SS \$5000 | **D.O.A.:** 16/5/18 | **Place of Accident:** AYE TMS JUNCTION
Is driver the owner? (YES / ☒ NO) | **Nature of Accident:** _____
If NO, Driver Name / Age: NH KHON KHWE | **OI GIA REPORT:** ☒ YES / NO : **TP GIA REPORT:** ☒ YES / NO
Driver Tel No.: _____ | **(V/L: YES / NO)** _____ | **Insured Liability:** _____ % | **Final ? Yes / No** _____

SLT 73480 → _____ → _____ → _____ → _____

 **INSRS:** _____ | **WSP:** WMT | **Tel:** _____ | **Liability:** _____ | **RMKS:** _____
 **INSRS:** _____ | **WSP:** _____ | **Tel:** _____ | **Liability:** _____ | **RMKS:** _____
 **INSRS:** _____ | **WSP:** _____ | **Tel:** _____ | **Liability:** _____ | **RMKS:** _____
 **INSRS:** _____ | **WSP:** _____ | **Tel:** _____ | **Liability:** _____ | **RMKS:** _____

Date/Time		STAGE	DATE / PIC
<u>21/5/18</u>	<u>21/5/18</u>	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	<u>21/5/18</u>
		After call ltr to OI:	
		Documentation Check List:	
		Notification ltr (if non-pickup):	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE | **Date/Time:** _____ | **Sent By:** _____

FINALIZATION | **Date/Time:** _____ | **Confirm with:** _____ | **Confirm by:** _____

Repair Cost: 45 SS 8,800 (10 days) **Reduction:** 60 % | **Email:** ☐ | **Call:** ☐

FINAL SETTLEMENT | **Date/Time:** 18.09.18 | **Confirm with:** CHOT | **Email:** ☒ | **Call:** ☐

Final Liability: \$100 (Agreed / Assessed) **BOLA S/N No.:** 27 | **If NO or B 28, Ass. Lia:** _____
Repair Cost: SS 8,800.00 | **LOD REPAIR ENDS TP.**
Loss of Rental (LOR): SS 1,120.00 (7 days) x 160
Loss of Use (LOU): SS - (5 x days)
Loss of Income (LOI): SS - (5 x days)
LOR only ☒ **LOU only** ☐ **LOR + LOU** ☐ **LOR + LOI** ☐ | **(Tick only one)**
GIA/LTA Search: SS 1.45
Medical: SS -
Disbursement: SS - (e.g. Tow/Independent)
Legal Cost: SS -

Total: SS 9,921.45 | **Global Sum SS:** _____

FINAL PAYMENT | **Date/Time:** 16.9.18 | **Confirm with:** CHOT | **Email:** ☒ | **Call:** ☐

Payee 1: SS 9,921.45 | **Name 1:** RENTAL CAR SERVICE PTE LTD
Payee 2: (Strike if N.A.) SS - | **Name 2:** _____
Payee 3: (Strike if N.A.) SS - | **Name 3:** _____

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 15 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT348D Yr Regn: 2017 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey c.c. 2356Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 19934 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRC1880HC204923Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17BS / DUN / EXNOVA / 6Y / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mmD.O.A. _____ D.O.I. 22/05/18Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPAXA</u>
	<u>43: + 8,800 (RED) -> 13,242.40 (60%)</u>
	<u>MV 143K</u>
	<u>PV 613K</u>
	<u>Nett 81TK</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

49791



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA18009397/Aeb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 23-05-2018	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 5789P	Veh. Inspected	SLT 7348D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/05/2018	Inspection Date	22/05/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

CHENG SOO SOON

19/05/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA/A

Notes

JHMRC1880HC204923

Accident date: 18/05/2018

Estimated repair cost for vehicle no: SLT7348D HONDA ODYSSEY 2.4 A '17

CHASSIS: JHMRC1880HC204923

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,549.20 <i>1149</i>
2	2	Rear Boot Lid Hinge <i>New</i>	\$50.80	\$101.60 <i>+</i>
3	2	Rear Boot Lid Shock Absorber <i>New</i>	\$165.80	\$331.60 <i>+</i>
4	1	Rear Boot Lid Emblem Logo <i>New</i>		\$28.90 <i>✓</i>
5	1	Rear Boot Lid Centre Odyssey Reflector <i>At</i>		\$225.90 <i>✓</i>
6	2	Rear Boot Lid Side Reflector <i>cracked</i>	\$378.20	\$756.40 <i>✓</i>
7	1	Rear Boot Lid Number Plate <i>New</i>		\$50.00 <i>+</i>
8	2	Rear Boot Lid Number Plate Lamp <i>New</i>	\$38.50	\$77.00 <i>x</i>
9	1	Rear Boot Lid Lower Chrome Moulding <i>cracked</i>		\$295.80 <i>✓</i>
10	1	Rear Boot Lid Camera <i>Dmgd</i>		\$680.00 <i>450.50</i>
11	1	Rear Boot Lid Inner Lock <i>Dmgd</i>		\$189.20 <i>✓</i>
12	1	Rear Boot Lid Inner Rubber <i>At</i>		\$115.40 <i>✓</i>
13	1	Rear Boot Lid Inner Trim Board <i>Deformed</i>		\$328.90 <i>✓</i>
14	8	Rear Boot Lid Inner Trim Board Clip <i>New</i>	\$6.50	\$52.00 <i>30</i>
15	1	Rear Boot Lid Windscreen Seal <i>3 pieces</i>		\$109.50 <i>✓</i>
16	2	Rear Boot Lid Windscreen Side Moulding <i>3 pieces</i>	\$85.40	\$170.80 <i>✓</i>
17	2	Rear Tail Lamp <i>New</i>	\$821.80	\$1,643.60 <i>+</i>
18	2	Rear Tail Lamp Lower Cover <i>Deformed</i>	\$275.30	\$550.60 <i>✓</i>
19	2	Rear Tail Lamp Lower Cover Retainer <i>New</i>	\$25.50	\$51.00 <i>+</i>
20	1	Rear Bumper <i>Deformed</i>		\$757.20 <i>✓</i>
21	10	Rear Bumper Clip <i>New</i>	\$6.50	\$65.00 <i>30</i>
22	2	Rear Bumper Side Retainer <i>New</i>	\$28.50	\$57.00 <i>✓</i>
23	2	Rear Bumper Side Reflector <i>cracked</i>	\$75.40	\$150.80 <i>75.40</i>
24	4	Rear Bumper Reverse Sensor <i>Dmgd</i>		\$380.00 <i>✓</i>
25	1	Rear End Panel Outer <i>Dented</i>		\$651.20 <i>✓</i>
26	1	Rear End Panel Top Garnish <i>Deformed</i>		\$205.80 <i>✓</i>
27	1	Rear End Panel Lock Sensor <i>cracked</i>		\$95.60 <i>✓</i>
28	2	Rear Fender Inner Trim Board <i>Deformed</i>	\$849.10	\$1,698.20 <i>✓</i>

1370.50

29	16	Rear Fender Inner Trim Board Clip <i>New</i>	\$6.50	\$104.00	60
30	1	Rear Spare Tyre Panel <i>Repair</i>		\$989.60	x
31	1	Rear Spare Tyre Panel Trim <i>new</i>		\$750.60	x
32	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00	200(SN)
33	1	Rear Seat Cushion Assy <i>Deland</i>		\$2,800.00	+550/50
		Buzzer Assy <i>included</i>		44.20	
			7677.60 SN 1200		
			6142.08		
Subtotal :-				\$16,462.40	

Labour charges

To remove & refit rear windscreen	\$120.00	100
Gum	\$50.00	
To remove & refit cushion	\$380.00	80
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear windscreen & boot lid camera	\$380.00	50
To check wiring	\$100.00	30
Tuff kote	\$150.00	50
Towing Fee	\$100.00	2
Panel beating	\$2,400.00	1400
Spray painting	\$1,800.00	1200
Subtotal :-	\$5,580.00	

Total:- \$22,042.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 10352.08
1/5: 881K (15%)
10 days

881K

10 days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4979I

Vehicle Details

Vehicle No.: SLT7348D
Vehicle to be Exported: Yes
Intended De-registration Date: 18 May 2018
Vehicle Make: HONDA
Vehicle Model: ODYSSEY 2.4 EX-S CVT
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: K24W72041715
Chassis No.: JHMRC1880HC204923
Maximum Power Output: 129.0 kW (172 bhp)
Open Market Value: \$27,460.00
Original Registration Date: 09 Nov 2017
First Registration Date: 09 Nov 2017
Transfer Count: 0
Actual ARF Paid: \$30,444.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Nov 2027
PARF Rebate Amount: \$22,833.00

Intended COE Rebate Details

COE Expiry Date: 08 Nov 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$48,109.00
COE Rebate Amount: \$38,487.00
Total Rebate Amount: \$61,320.00

The information contained herein is correct as at 18 May 2018

OK

Print Sent Message

This mail is associated with :

***SLT7348D (C0473752)**
[SHC5789P]
TP
CHENG SOO SOON
May 18 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
New Hock Teck Motor Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 10/09/2018 15:58 PM.
To jas.tan@axa.com.sg
CC AXA_SG; ashersng@lkkauto.com
Subject [MANDATE REQUEST] Re: C0473752 - SHC5789P - SLT7348D

Hi Sir,

We refer to the above matter.

The accident occurred when insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer at \$9,927.45 (all-in),

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG

To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com

CC: AXA_SG

Sent On: 10/08/2018 08:54 AM

Subject: C0473752 - SHC5789P - SLT7348D



Hi,

Please update IA and status of the claim.

Regards

Jas

AXA Insurance Ltd Ltd
100 Robinson Road, #10-01, AXA Tower
Singapore 068901
Telephone: (65) 6741-4108
Fax: (65) 6741-4108
Email: jas.tan@axa.com.sg
Website: www.axa.com.sg
AXA Singapore Pte Ltd
100 Robinson Road, #10-01, AXA Tower
Singapore 068901

Print Received Message

This mail is associated with :

***SLT7348D (C0473752)**
[SHC5789P]

TP

CHENG SOO SOON

May 18 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

New Hock Teck Motor Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 11/09/2018 11:45 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9927.45) - SLT7348D - Claim Handler: Jas Tan

Approved:9927.45.

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)



In consideration for your agreement to repair my motor vehicle registration no. SLT7348D and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 18 day of 05 20 17.

Signature	:	<u></u>
Name	:	<u>Cheong Soo Soon</u>
ID No.	:	<u>511549791</u>
Address	:	<u></u>
Witness Signature	:	<u></u>
Witness Name	:	<u>Chew Ywe Yim</u>
Witness ID	:	<u>5822661871</u>
Witness Address	:	<u>1 Kaki Bukit Avenue 6 #01-43</u> <u>Singapore 417883</u>

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1806-0130 / SLT7348D
Your Ref : SHC5789P
Date : 25th June 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

WITHOUT PREJUDICE

Dear Sirs,

**RE: ACCIDENT INVOLVING SLT7348D & SHC5789P AT AYE TOWARDS TUAS BEFORE CLEMENTI
AVE 2 EXIT ON 18.05.2018, 07:45HR**

We are instructed by **CHENG SOO SOON** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SLT7348D** was damaged by vehicle **SHC5789P** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 8,800.00
2) Loss of Rental for 07 days	\$ 1,260.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 10,067.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$10,067.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,



NEW HOCK TECK MOTOR PTE LTD

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 7 June 2018 5:51 PM
To: 'claims@transcab.com.sg'
Cc: 'carrisaalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHC 5789P & SLT 7348D ALONG/AT AYE TOWARDS JURONG ON 18/05/2018

07 JUNE 2018

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA18009397/Aeb3
YOUR REF : P1680520 (SHC 5789P)
ACCIDENT INVOLVING SHC 5789P & SLT 7348D ALONG/AT AYE TOWARDS JURONG ON 18/05/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy. We also wish to advise that there is an excess of **S\$5000.00** attached with Third Party Claims.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to cst@axa.com.sg **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons

in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm or cst@axa.com.sg. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com |

fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This is a computer generated letter and no signature is required.

cc Motor Claims Department
AXA Insurance Pte Ltd

LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd

Kaki Bukit Avenue 6

Blk 1 #01-43

Singapore 417883

Dear Sir,

Accident on

18/05/2018, 0745

Involving Vehicles

SLT 7348D, SHC 5789P

Along

AYE (turn) before Clementi Ave 2

I/We, the registered owner/driver of vehicle registration no: _____
have involved in the above accident.

SLT 7348D

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.


I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, _____, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature

(Company's stamp if applicable)

Name: _____

NRIC No.: _____

Date: _____



redefining / insurance



CLAIM REF : C0473752
INSURED : TRANS-CAB SERVICES PTE LTD

WITHOUT PREJUDICE

By the undersigned on behalf of the Insured

By the undersigned on behalf of the Insurer

Witnessed by the undersigned on behalf of the Insured

Witnessed by the undersigned on behalf of the Insurer

DISCHARGE VOUCHER

We/I [CHENG SOO SOON, NRIC NO. S1154979I] hereby agree to accept the sum of dollars [NINE THOUSAND NINE HUNDRED TWENTY SEVEN AND CENTS FORTY FIVE ONLY.] [S\$9,927.45] paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [SHC 5789P] as a result of an accident along [AYE (TUAS) BEFORE CLEMENTI AVE 2 EXIT] on [18/05/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SLT 7348D].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said insurer, owner and/or driver of vehicle no. [SHC 5789P] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SHC 5789P].

Dated this 09 day of 10 2018

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

S1154979I

Occupation/ Business

[Blank]

Address

7 Jurong East St 32 #18-07 Singapore 609480

Telephone No.

96222612

Witness's Name

[Signature]

Witness's Signature

[Signature]

Witness's NRIC No.

[Blank]

NEW HOCK TECK MOTOR PTE LTD
1 Kaki Bukit Ave 6, Bk C #01-43
Autobay@Kaki Bukit Singapore 417883
Tel: 6747 9241 Fax: 6741 7276
Email: admin@nhtmotor.com
UEN: 201718370K



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#B1-01,

Singapore 068811

Client: CHENG SOO SOON

Invoice No : NPL1806-0130

Date : 25-Jun-18

Date of Accident : 18-May-18

Vehicle No. : SLT7348D

Model Type : Honda Odyssey

Descriptions		Amount
Lump Sum Repair Cost		8,800.00
Total		8,800.00

SIN DOLLARS: EIGHT THOUSAND AND EIGHT HUNDRED ONLY





INFINITYCARS PTE. LTD.

Address: 351 Jurong East Street 31 #01-79 Singapore 600351
 Call / SMS / Whatsapp: 98188106 / 91460452 / 81684353
 Co. Reg. No: 201810501N
 Email: infinitycars88@gmail.com

VEHICLE RENTAL AGREEMENT

No. RA 0001

HIRER/MAIN DRIVER'S PARTICULARS		VEHICLE HANDOVER / TAKEOVER	
Name: CHENG SOO SOON		Vehicle No: SLZ 5799 J	
Address: 7 JURONG EAST ST 32 #18-07 SINGAPORE 609480		Odometer Reading:	
Tel No: H/P No: 9622 2612		Make & Model: MERCEDES E200K	
NRIC No: S11549791 D/Licence No: 001914335 B		OUT Date: 18/05/2018 OUT Time: 12/5	
Date of Birth: 16/11/1956 Date of Issue: 20/11/2010		HIRE Expiry Date: 25/01/2018 Time Expiry: 12/5	
Nationality: SINGAPOREAN Place of Issue: SINGAPORE		CashCard Value: \$ -	
Occupation: Driving Exp: 41 YEARS		Petrol Reading: E 3 BARS H F 	
SECONDARY DRIVER'S PARTICULARS		No Smoking in Car: No Cigarette Smoke Smell	
Name:		Spare Tyre & Tools Kit: ✓	
Address:		Car Accessories: ✓	
Tel No: H/P No:		Car Condition: Damage Key	
NRIC No: D/Licence No:		X = Scratch	
Date of Birth: Date of Issue:		O = Dent	
Nationality: Place of Issue:			
Occupation: Driving Exp:			
REFUNDABLE DEPOSIT: NIL			
RENTAL CHARGES			
Daily @\$	180		
Weekly @\$	-		
Monthly @\$	-		
Others @\$	-		
Delivery Service	-		
Extension	-		
Total Rental Fee \$	1260		
<p>Hirer is responsible for the first \$ 2000 excess For collision / damage to first party. (i.e) INFINITYCARS PTE. LTD. Vehicles (Including Windscreen) and also first \$ 2000 excess for collision/damage to third party's vehicles for each and every accident/damage.</p> <p>Hirer/Main Driver's Signature </p>		 	
		<p>Take Over Vehicle</p> <p>Name: </p> <p>Signature: </p> <p>Return Vehicle</p> <p>Returned Date:</p> <p>Returned Time:</p>	
		<p>FOR OFFICIAL USE</p> <p>Acknowledged by: </p> <p>Return Deposit</p> <p>Bank:</p> <p>Account:</p>	

I / We agree to the terms and condition above, overleaf and that all information given is true and correct in all respect.
 My/Our driving licence(s) is/are current and not disqualified from driving.

[> Back to OneMotoring](#)

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 18 May 2018 / 11:01:54

Receipt Date/Time : 18 May 2018 / 11:01:54

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180518-000639

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHC5789P

As at 18 May 2018/07:45:00

Insurance Co: AXA INSURANCE PTE LTD

1 Insurance Enquiry - SHC5789P

Enquiry Fee

20180518110123032403

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

xxxxxxxxxxxx4469	Credit Card:	7.45
	Visa/MasterCard	

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING


















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 May 2018		22 May 2018 19:53 Edit Adj Rpt	S\$8,800.00 Edit Estimates	S\$8,800.00 View Rpt		Pending for Survey Report Cancel Case

















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Main Claimant:	CHENG SOO SOON, ID: S11549791								
Vehicle Reg. No.:	SLT7348D	Date of Loss:	18/05/2018 00:00 - :59 [6 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0473752	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHC5789P	Policy No. (Claimant):	10790186						
		Excess:	S\$5,000.00						
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bldg C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Jas Tan - 6880 4844]								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LXX Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/06/2018]								
Driver/Custodian (Insured):	NG CHOON CHWEE (63 / Male), NRIC: S1108237H								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (11/09/2018): Alert - Adj Mandate Approved (S\$9927.45) - SLT7348D - Claim Handler: Jas Tan AXA_SG (10/06/2018): C0473752 - SHC5789P - SLT7348D 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





















Claim Documents

*SLT7348D (C0473752)
[SHC5789P]
TP
CHENG SOO SOON
May 18 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters / Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
2	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
3	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
4	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
5	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
6	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
7	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
8	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
9	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
10	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
11	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
12	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
13	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
14	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
15	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
16	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
17	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
18	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
19	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
20	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
21	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
22	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
23	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
24	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
25	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
26	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
27	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
28	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
29	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
30	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
31	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
32	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
33	26/07/18 16:29		General View												1	Load JPG		<input checked="" type="checkbox"/>		
34	26/07/18 16:29		General View												1	Load JPG				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/18 16:29	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	26/07/18 16:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	26/07/18 16:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	26/07/18 16:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	26/07/18 16:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	10/09/18 15:57	LKK Survey Photo	 Load PDF	
129	10/09/18 15:57	LKK Resurvey Photo	 Load PDF	
130	10/09/18 15:57	LKK Resurvey Photo	 Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 12:07	WORKSHOP_ABS	 Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
2	18/05/18 12:07	GIA SHC5789P INSD_ABS		Load PDF	
3	18/05/18 12:08	EMAIL_ABS		Load PDF	
4	21/05/18 08:51	EMAIL		Load PDF	
5	21/05/18 10:19	EMAIL		Load PDF	
6	21/05/18 15:29	EMAIL		Load PDF	
7	22/05/18 12:17	EMAIL		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/05/18 12:06	TP GIA REPORT		Load PDF	
2	07/06/18 17:51	LETTER TO OI		Load PDF	
3	31/07/18 15:04	LKK Survey Photo		Load PDF	
4	31/07/18 15:04	LKK Resurvey Photo		Load PDF	
5	31/07/18 15:04	LKK Resurvey Photo		Load PDF	
6	21/08/18 16:06	RENTAL RECEIPT		Load PDF	
7	21/08/18 16:06	LTA SEARCH		Load PDF	
8	10/09/18 15:53	LTA REBATE		Load PDF	
9	10/09/18 15:53	Immediate Advice with Mandate		Load PDF	
10	10/09/18 15:53	TP ESTIMATE - MARKED		Load PDF	
11	17/10/18 15:48	WORKSHOP INVOICE		Load PDF	
12	17/10/18 15:48	AUTHORISATION TO ACT FORM		Load PDF	
13	17/10/18 15:48	DISCHARGE VOUCHER		Load PDF	
14	17/10/18 15:48	LOD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5789P (Insd veh)	Model:	RENAULT LATITUDE 2.0 CVT
	SLT7348D (TP veh)		ABS (A)
Date of Accident:	18/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	22,086.60
Final Repair Cost	:	\$	8,800.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	1,120.00 7 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	9,927.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks: _____

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:	\$ 9,927.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

17 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18009397/AEB3Q2

Date: 17/10/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle
No: SLT7348D

Insured Vehicle No:

SHC5789P

Date of Loss: 18/05/2018

Nature of Claim:

TP

Claim No: C0473752

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT7348D

Make & Model: RENAULT LATITUDE, 2.0 CVT ABS (A)

Engine No: K24W72041715

Reg. Date: 09/11/2017 (Man. Year: 2017)

Chassis No: JHMRC1880HC204923

Colour: Grey

Odometer: 9931 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,506.60	7,342.08	9,164.52	55.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	3,010.00	2,570.00	46.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,086.60	10,352.08	11,734.52	53.13
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	22,086.60	8,800.00	13,286.60	60.16
+ Car Rental (7.0 x S\$160.00/day) (S\$)		1,120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,927.45		

INSPECTION

Date of Assignment: 22/05/2018

Date Inspected: 22/05/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2018)
Parts:	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7348D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID (CONSISTENT)	Dented	1,549.20 F	*1,149.00 FL
2	2		*REAR BOOT LID HINGE (CONSISTENT)	Not Necessary	101.60 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORNER (CONSISTENT)	Not Necessary	331.60 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO (CONSISTENT)	Necessary	28.90 F	*28.90 FL
5	1		*REAR BOOT LID CENTRE ODYSSEY REFLECTOR	Cut	225.90 F	*225.90 FL
6	2		*REAR BOOT LID SIDE REFLECTOR (CONSISTENT)	Cracked	756.40 F	*756.40 FL
7	1		*REAR BOOT LID NUMBER PLATE (CONSISTENT)	Not Necessary	50.00 F	*- FL
8	2		*REAR BOOT LID NUMBER PLATE LAMP (CONSISTENT)	Not Necessary	77.00 F	*- FL
9	1		*REAR BOOT LID LOWER CHROME MOULDING (CONSISTENT)	Cracked	295.80 F	*295.80 FL
10	1		*REAR BOOT LID CAMERA (CONSISTENT)	Damaged	680.00 FS	*450.00 FS
11	1		*REAR BOOT LID INNER LOCK (CONSISTENT)	Damaged	189.20 F	*189.20 FL
12	1		*REAR BOOT LID INNER RUBBER (CONSISTENT)	Cut	115.40 F	*115.40 FL
13	1		*REAR BOOT LID INNER TRIM BOARD (CONSISTENT)	Deformed	328.90 F	*328.90 FL
14	8		*REAR BOOT LID INNER TRIM BOARD CLIP (CONSISTENT)	Necessary	52.00 F	*30.00 FL
15	1		*REAR BOOT LID WINDSCREEN SEAL (CONSISTENT)	Necessary	109.50 F	*109.50 FL
16	2		*REAR BOOT LID WINDSCREEN SIDE MOULDING (CONSISTENT)	Necessary	170.80 F	*170.80 FL
17	2		*REAR TAIL LAMP (CONSISTENT)	Not Necessary	1,643.60 F	*- FL
18	2		*REAR TAIL LAMP LOWER COVER (CONSISTENT)	Deformed	550.60 F	*550.60 FL
19	2		*REAR TAIL LAMP LOWER COVER RETAINER (CONSISTENT)	Not Necessary	51.00 F	*- FL
20	1		*REAR BUMPER (CONSISTENT)	Deformed	757.20 F	*757.20 FL
21	10		*REAR BUMPER CLIP (CONSISTENT)	Necessary	65.00 F	*30.00 FL
22	2		*REAR BUMPER SIDE RETAINER (CONSISTENT)	Necessary	57.00 F	*57.00 FL
23	1		*REAR BUMPER SIDE REFLECTOR (CONSISTENT)	N/S Cracked	150.80 F	*75.40 FL
24	4		*REAR BUMPER REVERSE SENSOR (CONSISTENT)	Damaged	380.00 F	*380.00 FL
25	1		*REAR END PANEL OUTER (CONSISTENT)	Dented	651.20 F	*651.20 FL
26	1		*REAR END PANEL TOP GARNISH (CONSISTENT)	Deformed	205.80 F	*205.80 FL
27	1		*REAR END PANEL LOCK SENSOR (CONSISTENT)	Cracked	95.60 F	*95.60 FL
28	2		*REAR FENDER INNER TRIM BOARD (CONSISTENT)	Deformed	1,698.20 F	*1,370.80 FL
29	16		*REAR FENDER INNER TRIM BOARD CLIP (CONSISTENT)	Necessary	104.00 F	*60.00 FL
30	1		*REAR SPARE TYRE PANEL (CONSISTENT)	Repair	989.60 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*REAR SPARE TYRE PANEL TRIM (CONSISTENT)	Not Necessary	750.60 F	*- FL
32	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT (CONSISTENT)	Necessary	450.00 FS	*200.00 FS
33	1		*REAR SEAT CUSHION ASSY (CONSISTENT)	Deformed	2,800.00 FS	*550.00 FS
34	1		*BUZZER ASSY (CONSISTENT)	Cracked	44.20 F	*44.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,506.60	8,877.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,535.52

Total Parts (\$\$)	16,506.60	7,342.08
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	100.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIT CUSHION	New	380.00	80.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE & REFIT REAR WINDSCREEN & BOOT LID CAMERA	New	380.00	50.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	50.00
8	TOWING FEE	New	100.00	0.00
9	PANEL BEATING	New	2,400.00	1,400.00
10	SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			5,580.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >